




Structurally Deficient Bridges on the National Highway System Virginia - Congressional District 07



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 112 structurally deficient NHS bridges in Virginia, 8 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	5012	MIDLOTHN TRNPK WBL	0.26 FR 667 & 0.61 TO 707
2	8581	I-64 WBL	1.30 FR 623 & .33 FR CO.L
3	8580	Interstate-64 EBL	1.14 FR 623 & .33 TO ECL
4	9774	RAMP E OF I-64	0.3 TO 64 WBL & 0.1 TO 33
5	9777	WBL ROUTE 0064	0.4 FR 33 & 0.54 WCL RICH
6	9776	EBL ROUTE 0064	0.4 FR 33 & 0.55 WCL RICH
7	9469	Mechanicsville Tnp	0.06 TO HENRICO CO
8	10015	Mechanicsville Tnp	0.8 SPRNGDLE & 0.12 HNRCO
9	10016	Mechanicsville Tnp	0.7 SPRNGDLE & 0.2 HNRCO
10	10014	MECHANICSVILLE TPK	0.8 SPRNGDLE & 0.08 HNRCO
11	9431	WBL ROUTE 0295	1.21 TO 627 & 0.12 TO 360