


Shorts C-23A "Sherpa"
July 30, 2000
Clearwater NF - Frog Lake Fire
Smokejumper/Cargo deployment





Cargo box like the one involved in the mishap

Scuff mark where box hit the side of the aircraft.



- Aircraft repaired and back in service August 2nd.
- Safety Alert (No.2000-11) issued on August 3rd regarding para-cargo load inspections and procedures.
- We dodged a bullet due to outstanding pilot reaction and professionalism

Cessna T337C
May 15, 2000
Lincoln NF
Fire Detection
Two Fatalities



Overhead view of mishap site



This is the forward engine propeller

This is the aft engine propeller



Bell 212
August 30, 2000
Bridger-Teton NF
Enos Fire Crew Transport



Preliminary information indicates that the landing gear failed. The skid manufacturer has issued an Alert Service Bulletin.





Bell 206L-4
September 21, 2000
Sawtooth NF
Rehab

The helicopter suffered extensive damage to the main rotor blades from striking dead snags. It was enroute to a helispot with an external load hooked to the belly.

