



Note:

1. All motors have direct total control from the computer.
2. Lung assembly is heated to 37°C.
3. All measurements are available as averages or instantaneous.

