

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 26

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 26

Facility Name: Farley 1 Docket (050- 00348)

Details	Department	Work Type	Docket/Report
Communication / IR			
161 - Communication LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2006-009
161 - Communication LTA	Z - Other / Unknown	Z - Other / Unknown	050-00348/2006-009
Number of Items for this Docket: 2			
Percent of Total for this Docket: 8			
<hr/>			
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2006-009
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			
<hr/>			
Oversight / IR			
130 - Inadequate suprevison / command and control	F - Fuel Handling	R - Refueling	050-00348/2006-003
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			
<hr/>			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	I - Instrumentation & Control	S - Surveillance	050-00348/2006-009
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00348/2006-009
111 - Procedure / reference document technical content	M - Mechanical	S - Surveillance	050-00348/2006-009
Number of Items for this Docket: 3			
Percent of Total for this Docket: 12			
<hr/>			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	F - Fuel Handling	R - Refueling	050-00348/2006-003
140 - Problem not completely or accurately identified	M - Mechanical	M - Maintenance / Repair	050-00348/2006-009
140 - Problem not completely or accurately identified	O - Operations	O - Control Room Ops	050-00348/2006-002
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2006-009
143 - Tracking / trending LTA	M - Mechanical	S - Surveillance	050-00348/2006-009
144 - Audit / self-assessment / effectiveness review LTA	O - Operations	O - Control Room Ops	050-00348/2005-005
145 - Causal development LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2006-009
145 - Causal development LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2006-009
Number of Items for this Docket: 8			
Percent of Total for this Docket: 31			

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 26

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 26

Facility Name: Farley 1 Docket (050- 00348)

Details	Department	Work Type	Docket/Report
Training / IR			
102 - Individual knowledge LTA	O - Operations	O - Control Room Ops	050-00348/2006-002
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			
Work Planning & Practices / IR			
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2006-009
187 - Action implementation LTA	M - Mechanical	T - Testing	050-00348/2006-009
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2006-009
188 - Work practice or craft skill LTA	O - Operations	O - Control Room Ops	050-00348/2005-005
188 - Work practice or craft skill LTA	O - Operations	O - Control Room Ops	050-00348/2005-005
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2006-009
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	O - Control Room Ops	050-00348/2006-002
190 - Failure to stop work / non-conservative decision making	M - Mechanical	T - Testing	050-00348/2006-009
194 - Housekeeping LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2006-003
Number of Items for this Docket: 9			
Percent of Total for this Docket: 35			
Procedures & Reference Document / LER			
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00348/2006-002-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			
Total Items for this Docket: 26			
