

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 17

National Average: 41

2x National Average: 82

National Median: 24

Average for Selected Dockets: 17

Facility Name: North Anna 2 Docket (050- 00339)

Details	Department	Work Type	Docket/Report
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00339/2007-004
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	D - Emergency Planning	D - Emergency Drill	050-00339/2006-005
140 - Problem not completely or accurately identified	M - Mechanical	M - Maintenance / Repair	050-00339/2007-002
144 - Audit / self-assessment / effectiveness review LTA	D - Emergency Planning	D - Emergency Drill	050-00339/2006-005
146 - Evaluation LTA	G - Engineering	G - Design	050-00339/2006-005
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00339/2007-004
147 - Individual corrective action LTA	E - Electrical	M - Maintenance / Repair	050-00339/2006-005
Number of Items for this Docket: 6			
Percent of Total for this Docket: 35			
Work Planning & Practices / IR			
185 - Procedural adherence LTA	D - Emergency Planning	D - Emergency Drill	050-00339/2006-005
185 - Procedural adherence LTA	E - Electrical	S - Surveillance	050-00339/2007-002
185 - Procedural adherence LTA	M - Mechanical	Q - Fire Protection	050-00339/2007-004
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00339/2007-002
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00339/2006-005
Number of Items for this Docket: 5			
Percent of Total for this Docket: 29			
Human-System Interface & Environmnt / LER			
173 - Physical conditions LTA	M - Mechanical	M - Maintenance / Repair	050-00339/2007-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
Procedures & Reference Document / LER			
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00339/2007-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
Work Planning & Practices / LER			
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00339/2007-001-00
189 - Recognition of adverse condition / questioning attitude LTA	L - Licensing / regulatory affairs	A - Administrative	050-00339/2007-001-00

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 17
National Average: 41
2x National Average: 82
National Median: 24
Average for Selected Dockets: 17

Facility Name: North Anna 2 Docket (050- 00339)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / LER			
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	O - Control Room Ops	050-00339/2007-001-00
Number of Items for this Docket: 3			
Percent of Total for this Docket: 18			

Total Items for this Docket: 17
