

March 31, 2000

Mr. Oliver D. Kingsley
President, Nuclear Generation Group
Commonwealth Edison Company
ATTN: Regulatory Services
Executive Towers West III
1400 Opus Place, Suite 500
Downers Grove, IL 60515

SUBJECT: PLANT PERFORMANCE - BRAIDWOOD NUCLEAR POWER STATION

Dear Mr. Kingsley:

The purpose of this letter is to communicate our assessment of your performance and to inform you of our planned inspections at your facility. On March 6, 2000, we completed a Plant Performance Review (PPR) of Braidwood. We conduct these reviews to develop an integrated overview of the safety performance of each operating nuclear power plant. We use the results of the PPR in planning and allocation inspection resources and as inputs to our senior management meeting (SMM) process. This PPR evaluated inspection results and safety performance information for the period from February 1, 1999, through January 31, 2000, but emphasized the last 6 months to ensure that our assessment reflected your current performance. Our most recent summary of plant performance at Braidwood was provided to you in a letter dated March 26, 1999, and was discussed with you in a public meeting on May 27, 1999.

The NRC has been developing a revised reactor oversight process that will replace our existing inspection and assessment processes, including the PPR, the SMM, and the Systematic Assessment of License Performance (SALP). We recently completed a pilot program for the revised reactor oversight process at nine participating sites and are making necessary adjustments based on feedback and lessons learned. We plan to begin initial implementation of the revised reactor oversight process industry-wide, including your facility, on April 2, 2000.

This PPR reflects continued process improvements as we make the transition into the revised reactor oversight process. You will notice that the following summary of plant performance is organized differently from our previous performance summaries. Instead of characterizing our assessment results by SALP functional area, we are organizing the results into the strategic performance areas embodied in the revised reactor oversight process. In addition, we have considered the historical performance indicator data that you submitted in January 2000 in conjunction with the inspection results in assessing your performance. The results of this PPR were used to establish the inspection plan in accordance with the new risk-informed inspection program (consisting of baseline and supplemental inspections). Although this letter incorporates some terms and concepts associated with the new oversight process, it does not reflect the much broader changes in inspection and assessment that will be evident after we have fully implemented our revised reactor oversight process.

During the last 6 months, both Braidwood units operated at or near full power. We have not identified any significant performance issues during this assessment period in the reactor safety, radiation safety, and safeguards strategic performance areas, and note that Braidwood continues to operate in a safe manner. In the safeguards strategic performance area, your staff had previously notified us of changes in your external threat response strategy. We had previously discussed with your staff a regional initiative inspection to evaluate these changes. Therefore, we plan to conduct only baseline inspections at your facility with an additional regional initiative inspection to evaluate significant changes in the external threat response strategy as noted in the attached inspection plan.

Enclosure 1 contains a historical listing of plant issues, referred to as the Plant Issues Matrix (PIM), that were used during this PPR process to arrive at our integrated view of your performance trends. The PIM for this assessment is grouped by the prior SALP functional areas of operations, maintenance, engineering, and plant support, although the future PIM will be organized along the cornerstones of safety as described in the revised reactor oversight process. The attached PIM includes items summarized from inspection reports or other docketed correspondence between the NRC and Commonwealth Edison regarding Braidwood. We did not document all aspects of licensee programs and performance that may be functioning appropriately. Rather, we only documented issues that we believe warrant management attention or represent noteworthy aspects of performance. In addition, the PPR may also have considered some predecisional and draft material that does not appear in the attached PIM, including observations from events and inspections that had occurred since our last inspection report was issued, but had not yet received full review and consideration. We will make this material publically available as part of the normal issuance of our inspection reports and other correspondence.

Enclosure 2 lists our planned inspections for the period of April 2000 through March 2001 at Braidwood to allow you to resolve scheduling conflicts and personnel availability in advance of our inspector arrival onsite. The inspection schedule for the latter half of the period is more tentative and may be adjusted in the future due to emerging performance issues at Braidwood or other Region 3 facilities. Routine resident inspections are not listed due to their ongoing and continuous nature.

O. Kingsley

-3-

We will inform you of any changes to the inspection plan. If you have any questions, please contact me at 630 829-9637.

Sincerely,

/RA/

Michael J. Jordan, Chief
Reactor Projects Branch 3
Division of Reactor Projects

Docket Nos. 50-456, 50-457
License Nos. NPF-72, NPF-77

- Enclosures: 1. Plant Issues Matrix
- 2. Inspection Plan

See Attached Distribution

DOCUMENT NAME: G:\PPR LETTERS\BRAI INSPPLN10.WPD

To receive a copy of this document, indicate in the box "C" = Copy w/o att/encl "E" = Copy w/att/encl "N" = No copy

OFFICE	RIII						
NAME	Jordan:dp/co						
DATE	03/31/00						

OFFICIAL RECORD COPY

cc w/encls: D. Helwig, Senior Vice President, Nuclear Services
C. Crane, Senior Vice President, Nuclear Operations
H. Stanley, Vice President, Nuclear Operations
R. Krich, Vice President, Regulatory Services
DCD - Licensing
T. Tulon, Site Vice President
K. Schwartz, Station Manager
T. Simpkin, Regulatory Assurance Supervisor
M. Aguilar, Assistant Attorney General
State Liaison Officer
Chairman, Illinois Commerce Commission
C. Adelman, Will County Executive/
Board Chairman
B. Ward, Will County Sheriff
D. Gould, Will County Emergency Management
Coordinator/Director
The Honorable Arthur Schultz
J. Mezera, Joliet City Manager
J. Church, Kendall County Board Chairman
R. Randall, Kendall County Sheriff
D. Kaufman, Grundy County Board Chairman
J. L. Olson, Grundy County Sheriff
Grundy County Emergency Management
Coordinator/Director
The Honorable Robert T. Feeney
The Honorable Keith Flatness
The Honorable Thomas J. McKinney
The Honorable John Jensen
The Honorable Elmer Rolando
The Honorable Richard Girot
The Honorable William Weidling
The Honorable Wayne Chesson
M. T. Gibson, Channahon Village Administrator
The Honorable Bertha J. Hofer
G. C. Holmes, Shorewood Village Administrator
The Honorable James Clementi
The Honorable Marchel Michael
The Honorable Donald Green
INPO

Distribution:

WES (E-Mail)

M. Satorius, OEDO w/encls

Chief, NRR/DISP/PIPB w/encls

T. Boyce, NRR w/encls

G. Dick, Project Mgr., NRR w/encls

J. Caldwell, RIII w/encls

B. Clayton, RIII w/encls

R. Lickus, RIII w/encls

SRI Braidwood w/encls

DRP w/encls

DRS w/encls

RIII PRR w/encls

PUBLIC IE-01 w/encls

Docket File w/encls

GREENS