August 31, 2006

Mr. Christopher M. Crane President and Chief Nuclear Officer Exelon Nuclear Exelon Generation Company, LLC 4300 Winfield Road Warrenville, IL 60555

SUBJECT: MID-CYCLE PERFORMANCE REVIEW AND INSPECTION PLAN -

BRAIDWOOD STATION

Dear Mr. Crane:

On August 7, 2006, the NRC staff completed its performance review of the Braidwood Station for the first half of the calendar year 2006 assessment cycle. Our technical staff reviewed performance indicators (PIs) for the most recent quarter and inspection results over the previous 12 months. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility.

This performance review and enclosed inspection plan do not include physical protection information. A separate letter designated and marked as "Exempt from Public Disclosure in Accordance with 10 CFR 2.390" will include the physical protection review and resultant inspection plan.

Plant performance for the most recent quarter was within the Regulatory Response column of the NRC's Action Matrix based on one inspection finding being classified as having low to moderate significance (White) in the public radiation safety cornerstone. The White finding and related violation were finalized in a letter dated June 29, 2006, and were related to the failure to perform adequate and timely radiological evaluations following historical unplanned radioactive leaks from the station's blowdown line vacuum breakers. This failure impacted the station's ability to assess the environmental impact from the releases, to mitigate the releases, properly account for public impact, and adequately control licensed material. A supplemental inspection using Inspection Procedure 95001, "Supplemental Inspection for One or Two White Inputs in a Strategic Performance Area," is tentatively planned to be conducted in the fourth quarter of 2006, pending the completion of your planned corrective actions.

The enclosed inspection plan details the inspections, less those related to physical protection scheduled through March 31, 2008. Significant inspections planned include a "Unit 2 ISI and Temporary Instruction 150 Reactor Pressure Vessel Head and Vessel Head Penetration Nozzle Inspection" in October 2006, a "Problem Identification and Resolution Inspection" in November 2006, and a "Modifications/50.59 Inspection" in January 2007. In addition, the resident inspectors plan to perform Temporary Inspections 2515/169, "Mitigating Systems Performance Index (MSPI) Verification," in September 2006, and 2515/166, "Pressurized

C. Crane -2-

Water Reactor Containment Sump Blockage," to be completed on Unit 1 in October 2007, and Unit 2 in spring 2008. The inspection plan is provided to allow for the resolution of any scheduling conflicts and personnel availability issues well in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The inspections in the last 9 months of the inspection plan are tentative and may be revised at the end-of-cycle review.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS), accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html (the Public Electronic Reading Room).

If circumstances arise which cause us to change the inspection plan, we will contact you to discuss the change as soon as possible. Please contact Richard A. Skokowski at (630) 829-9620 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

/RA/

Mark A. Satorius, Director Division of Reactor Projects

Docket Nos. 50-456; 50-457 License Nos. NPF-72; NPF-77

Enclosure:

Braidwood Station Inspection/Activity Plan

DISTRIBUTION: See next page

C. Crane -2-

Water Reactor Containment Sump Blockage," to be completed on Unit 1 in October 2007, and Unit 2 in spring 2008. The inspection plan is provided to allow for the resolution of any scheduling conflicts and personnel availability issues well in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The inspections in the last 9 months of the inspection plan are tentative and may be revised at the end-of-cycle review.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS), accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html (the Public Electronic Reading Room).

If circumstances arise which cause us to change the inspection plan, we will contact you to discuss the change as soon as possible. Please contact Richard A. Skokowski at (630) 829-9620 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

/RA/

Mark A. Satorius, Director Division of Reactor Projects

Docket Nos. 50-456; 50-457 License Nos. NPF-72; NPF-77

Enclosure:

Braidwood Station Inspection/Activity Plan

DISTRIBUTION: See next page

DOCUMENT NAME:G:\Branch TSS\ALL MOC\midcycle 2005 to 2006\braidwood\Braidwood\Braidwood MOC Letter 2006.wpd X Publicly Available \quad \text{Non-Publicly Available} \quad \text{Sensitive} \text{X Non-Sensitive}

To receive a copy of this document, indicate in the concurrence box "C" = Copy without attach/encl "E" = Copy with attach/encl "N" = No copy

OFFICE	RIII		RIII			
NAME	RSkokowski:dtp		MSatorius			
DATE	08/30/06		08/31/06	•		

C.Crane -3-

cc w/encl: Site Vice President - Braidwood Station

Plant Manager - Braidwood Station

Regulatory Assurance Manager - Braidwood Station

Chief Operating Officer

Senior Vice President - Nuclear Services Vice President - Operations Support

Vice President - Licensing and Regulatory Affairs

Director Licensing

Manager Licensing - Braidwood and Byron Senior Counsel, Nuclear, Mid-West Regional

Operating Group

Document Control Desk - Licensing

Assistant Attorney General

Illinois Emergency Management Agency

State Liaison Officer

Chairman, Illinois Commerce Commission

Will County Executive Will County Sheriff

Director, Will County Emergency Management

Agency

Mayor of Joliet

City Manager of Joliet

Kendall County Board Chairman

Kendall County Sheriff

Grundy County Board Chairman

Grundy County Sheriff

Grundy County Emergency Management Agency

Mayor of Morris

Minooka Village President

Mayor of Coal City

Mayor of Carbon Hill

Mayor of Diamond

Mayor of Braidwood

Mayor of Wilmington

Channahon Village President

Channahon Village Administrator

Mayor of Shorewood

Shorewood Village Administrator

Mayor of Elwood

Mayor of Braceville

Mayor of Kankakee

INPO

C. Crane -4-

ADAMS Distribution:

DXC1

TEB

JBH1

RidsNrrDirslpab

JLC1

GEG

KGO

RML2

SRI Braidwood

DRPIII

DRSIII

PLB1

TXN

Page 1 of 2

12:55:38

08/30/2006

Braidwood

Inspection / Activity Plan 09/01/2006 - 03/31/2008

Report 22

Unit				No. of Staff	Planned Dates		Inspection
Number	Inspection Acti	ivity	Title	on Site	Start	End	Туре
	ISI - E	BRAID	WOOD UNIT 2 ISI & TI-150 INSPECTION	2			
2	IP 2515/150		Reactor Pressure Vessel Head and Vessel Head Penetration Nozzles (NRC ORDER EA-03-		10/16/2006	11/03/2006	Safety Issues
2	IP 7111108P		Inservice Inspection Activities - PWR		10/16/2006	11/03/2006	Baseline Inspections
	OUTAGE - A	ACCES	S CONTROL, ALARA	1			
1,2	IP 7112101		Access Control to Radiologically Significant Areas		10/16/2006	10/20/2006	Baseline Inspections
1, 2	IP 7112102		ALARA Planning and Controls		10/16/2006	10/20/2006	Baseline Inspections
1, 2	IP 71151		Performance Indicator Verification		10/16/2006	10/20/2006	Baseline Inspections
	H/S - F	HEAT S	SINK INSPECTION	1			
1,2	IP 7111107B		Heat Sink Performance		11/06/2006	11/11/2006	Baseline Inspections
	PI&R - F	PROBL	EM IDENTIFICATION AND RESOLUTION	3			
1,2	IP 71152B		Identification and Resolution of Problems		11/27/2006	12/15/2006	Baseline Inspections
	MOD5059 - N	MODIFI	CATIONS/50.59 INSPECTION	2			
1,2	IP 7111102		Evaluation of Changes, Tests, or Experiments		01/08/2007	01/26/2007	Baseline Inspections
1,2	IP 7111117B		Permanent Plant Modifications		01/08/2007	01/26/2007	Baseline Inspections
	EP BI - E	BASEL	INE EP INSPECTION	1			
1,2	IP 7111402		Alert and Notification System Testing		01/22/2007	01/26/2007	Baseline Inspections
1,2	IP 7111403		Emergency Response Organization Augmentation Testing		01/22/2007	01/26/2007	Baseline Inspections
1,2	IP 7111405		Correction of Emergency Preparedness Weaknesses and Deficiencies		01/22/2007	01/26/2007	Baseline Inspections
1,2	IP 71151		Performance Indicator Verification		01/22/2007	01/26/2007	Baseline Inspections
	BI - N	MATER	IAL PROCESSING AND TRANSPORATION	1			
1,2	IP 7112202		Radioactive Material Processing and Transportation		02/12/2007	02/16/2007	Baseline Inspections
	71122.01 - F	RAD EF	FFLUENTS	1			
1, 2	IP 7112201		Radioactive Gaseous and Liquid Effluent Treatment and Monitoring Systems		04/30/2007	05/04/2007	Baseline Inspections
1,2	IP 71151		Performance Indicator Verification		04/30/2007	05/04/2007	Baseline Inspections
	71121.01 - A	ACCES	S CONTROL	2			
1, 2	IP 7112101		Access Control to Radiologically Significant Areas		06/11/2007	06/15/2007	Baseline Inspections
	CDBI - C	COMPO	DNENT DESIGN BASES INSPECTION	5			
1,2	IP 7111121		Component Design Bases Inspection		07/23/2007	08/24/2007	Baseline Inspections
	71111.11 - L	LIC OP	ERATOR REQUAL PROGRAM EVALUATION	2			
1, 2	IP 7111111B		Licensed Operator Requalification Program		08/27/2007	08/31/2007	Baseline Inspections
	71122.03 - F	REMP A	AND RAM CONTROL	1			
1, 2	IP 7112203		Radiological Environmental Monitoring Program (REMP) And Radioactive Material Control P		08/27/2007	08/31/2007	Baseline Inspections
	71121.02 - A	ALARA	- OUTAGE	1			
1, 2	IP 7112102		ALARA Planning and Controls		10/08/2007	10/19/2007	Baseline Inspections

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.

Page 2 of 2

08/30/2006 12:55:38

Braidwood

Inspection / Activity Plan

Report 22 09/01/2006 - 03/31/2008

Unit				No. of Staff	Planned Dates		Inspection		
Number	Inspection Activity		Title		on Site	Start	End	End Type	
	ISI	- ISI BAS	SELINE INSPECTION		1				
1	IP 7111108F	o	Inservice Inspection Activities - PWR			10/08/2007	10/26/2007	Baseline Inspections	
	FY 2008	- BRAID	WOOD INIT PREP 11/2007		2				
1	W90172		OL - INITIAL EXAM - BRAIDWOOD - NOV/DEC 2007			11/12/2007	11/16/2007	Not Applicable	
	MAINRULE	- MAINT	ENANCE RULE INSPECTION		2				
1, 2	IP 7111112E	3	Maintenance Effectiveness			11/26/2007	11/30/2007	Baseline Inspections	
	FY 2008	- BRAID	WOOD INIT EXAM 12/2007		2				
1	W90172		OL - INITIAL EXAM - BRAIDWOOD - NOV/DEC 2007			12/03/2007	12/14/2007	Not Applicable	
	HEATSINK	- HEAT	SINK INSPECTION		1				
1, 2	IP 7111107E	3	Heat Sink Performance			02/04/2008	02/08/2008	Baseline Inspections	
	ВІ	- OUTAG	GE ACCESS CONTROL AND ALARA		1				
1	IP 7112101		Access Control to Radiologically Significant Areas			03/17/2008	03/21/2008	Baseline Inspections	
1	IP 7112102		ALARA Planning and Controls			03/17/2008	03/21/2008	Baseline Inspections	