

March 3, 2008

Mr. Charles G. Pardee
Chief Nuclear Officer and
Senior Vice President
Exelon Nuclear
Exelon Generation Company, LLC
4300 Winfield Road
Warrenville, IL 60555

SUBJECT: ANNUAL ASSESSMENT LETTER - BRAIDWOOD STATION, UNITS 1 AND 2
(05000456/2008001; 05000457/2008001)

Dear Mr. Pardee:

On February 13, 2008, the NRC staff completed its performance review of Braidwood Station, Units 1 and 2. Our technical staff reviewed performance indicators (PIs) for the most recent quarter and inspection results for the period from January 1 through December 31, 2007. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility.

This performance review and enclosed inspection plan do not include security information. A separate letter designated and marked as "Official Use Only - Security Related Information" will include the security cornerstone review and resultant inspection plan.

Overall, Braidwood Station Units 1 and 2 operated in a manner that preserved public health and safety and fully met all cornerstone objectives. Plant performance for the most recent quarter was within the Licensee Response column of the NRC's Action Matrix, based on all inspection findings being classified as having very low safety significance (Green) and all PIs indicating performance at a level requiring no additional NRC oversight (Green). Therefore, we plan to conduct reactor oversight process (ROP) baseline inspections at your facility.

While plant performance for the most recent quarter is within the Licensee Response column of the Action Matrix, there was a safety significant inspection finding affecting the first quarter of the assessment cycle. Specifically, Units 1 and 2 were in the Regulatory Response Column of the NRC's Action Matrix for the first quarter of CY 2007 based on one White finding in the Public Radiation Safety Cornerstone for the failure to perform adequate and timely radiological evaluations following historical unplanned radioactive leaks from the station's blow-down line vacuum breakers. On December 31, 2006, we were notified by your staff of your readiness for the NRC to conduct a supplemental inspection to review the actions taken to address the White finding in the Public Radiation Safety Cornerstone. We conducted Supplemental Inspection Procedure 95001 during the week of January 29, 2007. Based on the results of this inspection, no findings of significance were identified.

The enclosed inspection plan details the inspections, including baseline and other infrequently conducted inspections, less those related to security, scheduled through June 30, 2009. The inspection plan is provided to allow for the resolution of any scheduling conflicts and personnel availability issues well in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The inspections in the last nine months of the inspection plan are tentative and may be revised at the mid-cycle review.

In accordance with 10 CFR 2.390 of the NRC's Rules of Practice, a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

If circumstances arise which cause us to change this inspection plan, we will contact you to discuss the change as soon as possible. Please contact Richard Skokowski at 630-829-9620 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

/RA/

Cynthia D. Pederson, Director
Division of Reactor Projects

Docket Nos. 50-456; 50-457
License Nos. NPF-72; NPF-77

Enclosure: Braidwood Inspection/Activity Plan

DISTRIBUTION
See next page

Letter to C. Pardee from C. Pederson dated March 3, 2008

SUBJECT: ANNUAL ASSESSMENT LETTER - BRAIDWOOD STATION, UNITS 1 AND 2
(05000456/2008001; 05000457/2008001)

cc w/encl: Site Vice President - Braidwood Station
Plant Manager - Braidwood Station
Regulatory Assurance Manager - Braidwood Station
Chief Operating Officer and Senior Vice President
Senior Vice President - Midwest Operations
Senior Vice President - Operations Support
Vice President - Licensing and Regulatory Affairs
Director - Licensing and Regulatory Affairs
Manager Licensing - Braidwood, Byron and LaSalle
Associate General Counsel
Document Control Desk - Licensing
Assistant Attorney General
Illinois Emergency Management Agency
J. Klinger, State Liaison Officer
Chairman, Illinois Commerce Commission
Will County Executive
Will County Sheriff
Director, Will County Emergency Management
Agency
Mayor of Joliet
City Manager of Joliet
Kendall County Board Chairman
Kendall County Sheriff
Grundy County Board Chairman
Grundy County Sheriff
Grundy County Emergency Management Agency
Mayor of Morris
Minooka Village President
Mayor of Coal City
Mayor of Carbon Hill
Mayor of Diamond
Mayor of Braidwood
Mayor of Wilmington
Channahon Village President
Channahon Village Administrator
Mayor of Shorewood
Shorewood Village Administrator
Mayor of Elwood
Mayor of Braceville
Mayor of Kankakee
INPO

Letter to C. Pardee from C. Pederson dated March 3, 2008

SUBJECT: ANNUAL ASSESSMENT LETTER - BRAIDWOOD STATION, UNITS 1 AND 2
(05000456/2008001; 05000457/2008001)

DISTRIBUTION:

TEB

MLC

RidsNrrDirslpab

JLC1

MAS

JKH3

KGO

RML2

SRI Prairie Island

DRPIII

DRSIII

PLB1

TXN

ROPreports@nrc.gov (inspection reports, final SDP letters, any letter with an IR number)

The enclosed inspection plan details the inspections, including baseline and other infrequently conducted inspections, less those related to security, scheduled through June 30, 2009. The inspection plan is provided to allow for the resolution of any scheduling conflicts and personnel availability issues well in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The inspections in the last nine months of the inspection plan are tentative and may be revised at the mid-cycle review.

In accordance with 10 CFR 2.390 of the NRC's Rules of Practice, a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

If circumstances arise which cause us to change this inspection plan, we will contact you to discuss the change as soon as possible. Please contact Richard Skokowski at 630-829-9620 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

Cynthia D. Pederson, Director
Division of Reactor Projects

Docket Nos. 50-456; 50-457
License Nos. NPF-72; NPF-77

Enclosure: Braidwood Inspection/Activity Plan

DISTRIBUTION
See next page

DOCUMENT NAME: G:\Branch TSS\ALL EOC\EOC CY 2007\EOC Letters\Braidwood EOC Letter.doc

See Previous Concurrences

Publicly Available Non-Publicly Available Sensitive Non-Sensitive

To receive a copy of this document, indicate in the concurrence box "C" = Copy without attach/encl "E" = Copy with attach/encl "N" = No copy

OFFICE	RIII		RIII		RIII			
NAME	JBartleman:dtp		RSkokowski		CPederson			
DATE	02/26/08		02/27/08		02/27/08			

OFFICIAL RECORD COPY

BRAI
Inspection / Activity Plan
03/01/2008 - 06/30/2009

Inspection Activity	Title	No. of Staff on Site	Planned Dates		Inspection Type
			Start	End	
2515/166 - TI 2515/166 PWR SUMP INSPECTION		1			
IP 2515/166	Pressurized Water Reactor Containment Sump Blockage [NRC GENERIC LETTER 2004-02]		03/31/2008	04/04/2008	Safety Issues
BI RP - RADIATION PROTECTION BASELINE INSPECTION		1			
IP 7112103	Radiation Monitoring Instrumentation and Protective Equipment		03/10/2008	03/14/2008	Baseline Inspections
BI ENG - UNIT 2 INSERVICE INSPECTION/TI 172		2			
IP 2515/172	Reactor Coolant System Dissimilar Metal Butt Welds		04/21/2008	05/16/2008	Generic Safety Inspectio
IP 7111108P	Inservice Inspection Activities - PWR		04/21/2008	05/16/2008	Baseline Inspections
2515/171 - TI 2515/171 B5B PHASE 2 AND 3		2			
IP 2515/171	VERIFICATION OF SITE SPECIFIC IMPLEMENTATION OF B.5.B PHASE 2 & 3 MITIGATING STRATEGIES		03/24/2008	03/28/2008	Generic Safety Inspectio
BI RP - RADIATION PROTECTION BASELINE INSPECTION		1			
IP 7112101	Access Control to Radiologically Significant Areas		04/28/2008	05/02/2008	Baseline Inspections
IP 7112102	ALARA Planning and Controls		04/28/2008	05/02/2008	Baseline Inspections
BI ENG - TRIENNIAL HEAT SINK INSPECTION		1			
IP 7111107B	Heat Sink Performance		06/23/2008	06/27/2008	Baseline Inspections
2515/172 - TI 2515/172 RCS WELD INSPECTION		1			
IP 2515/172	Reactor Coolant System Dissimilar Metal Butt Welds		08/18/2008	08/22/2008	Generic Safety Inspectio
BI ENG - ENGINEERING MODIFICATIONS / 50.59 INSP.		3			
IP 7111102	Evaluation of Changes, Tests, or Experiments		08/25/2008	09/12/2008	Baseline Inspections
IP 7111117B	Evaluations of Changes, Tests, or Experiments & Permanent Plant Modifications		08/25/2008	09/12/2008	Baseline Inspections
BI RP - RADIATION PROTECTION BASELINE INSPECTION		1			
IP 7112202	Radioactive Material Processing and Transportation		09/22/2008	09/26/2008	Baseline Inspections
IP 71151-BI01	Reactor Coolant System Activity		09/22/2008	09/26/2008	Baseline Inspections
IP 71151-OR01	Occupational Exposure Control Effectiveness		09/22/2008	09/26/2008	Baseline Inspections
IP 71151-PR01	RETS/ODCM Radiological Effluent		09/22/2008	09/26/2008	Baseline Inspections
BI PI&R - BIENNIAL PI&R INSPECTION		3			
IP 71152B	Identification and Resolution of Problems		10/06/2008	10/24/2008	Baseline Inspections
BI EP - EP EXERCISE INSPECTION / PI VERIFICATION		3			
IP 7111401	Exercise Evaluation		11/17/2008	11/21/2008	EP Baseline Inspection
IP 71151-EP01	Drill/Exercise Performance		11/17/2008	11/21/2008	Baseline Inspections
IP 71151-EP02	ERO Drill Participation		11/17/2008	11/21/2008	Baseline Inspections
IP 71151-EP03	Alert & Notification System		11/17/2008	11/21/2008	Baseline Inspections
BI ENG - TRIENNIAL FIRE PROTECTION INSPECTION		3			
IP 7111105T	Fire Protection [Triennial]		01/26/2009	02/13/2009	Baseline Inspections
BI ENG - FIRE PROTECTION INFO GATHERING TRIP		3			
IP 7111105T	Fire Protection [Triennial]		01/12/2009	01/16/2009	Baseline Inspections

BRAI
Inspection / Activity Plan
03/01/2008 - 06/30/2009

Inspection Activity	Title	No. of Staff on Site	Planned Dates		Inspection Type
			Start	End	
BI RP	- RADIATION PROTECTION BASELINE INSPECTION	1			
IP 7112201	Radioactive Gaseous and Liquid Effluent Treatment and Monitoring Systems		02/23/2009	02/27/2009	Baseline Inspections
BI ENG	- ENGINEERING INSERVICE INSPECTION	2			
IP 2515/172	Reactor Coolant System Dissimilar Metal Butt Welds		04/06/2009	04/24/2009	Generic Safety Inspecti
IP 7111108P	Inservice Inspection Activities - PWR		04/06/2009	04/24/2009	Baseline Inspections
BI RP	- RADIATION PROTECTION BASELINE INSPECTION	1			
IP 7112101	Access Control to Radiologically Significant Areas		04/13/2009	04/17/2009	Baseline Inspections
IP 7112102	ALARA Planning and Controls		04/13/2009	04/17/2009	Baseline Inspections
BI RP	- RADIATION PROTECTION BASELINE INSPECTION	1			
IP 7112203	Radiological Environmental Monitoring Program (REMP) And Radioactive Material Control Program		06/22/2009	06/26/2009	Baseline Inspections
IP 71151-BI01	Reactor Coolant System Activity		06/22/2009	06/26/2009	Baseline Inspections
IP 71151-OR01	Occupational Exposure Control Effectiveness		06/22/2009	06/26/2009	Baseline Inspections
IP 71151-PR01	RETS/ODCM Radiological Effluent		06/22/2009	06/26/2009	Baseline Inspections