

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

March 4, 2002

Garry L. Randolph, Senior Vice President and Chief Nuclear Officer Union Electric Company P.O. Box 620 Fulton, Missouri 65251

SUBJECT: ANNUAL ASSESSMENT - CALLAWAY PLANT (REPORT 50-483/02-01)

Dear Mr. Randolph:

On February 13, 2002, the NRC staff completed its end-of-cycle plant performance assessment of Callaway Plant. The end-of-cycle review for Callaway Plant involved the participation of all technical divisions in evaluating performance indicators (PIs) for the most recent quarter and inspection results for the period from April 1 through December 31, 2001. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility. This will provide you an opportunity to prepare for these inspections and to inform us of any planned inspections which may conflict with your plant activities.

As discussed in our previous annual assessment letter, dated May 29, 2001, this inspection and assessment cycle consisted of three quarters (i.e., the second, third, and fourth quarters of Calendar Year 2001) instead of the usual four quarters. This change was implemented in order to align the inspection and assessment cycle with the calender year beginning on January 1, 2002.

Overall, Callaway Plant operated in a manner that preserved public health and safety, and fully met all cornerstone objectives. Plant performance for the final quarter was within the Regulatory Response Column of the NRC's Action Matrix, based on a White finding in the Mitigating Systems Cornerstone. This finding involved an essential service water pump which was inoperable for approximately 132 hours. However, the significance of an unresolved item in NRC Inspection Report 50-483/01-06 is still under review. This December 2001 issue involves an auxiliary feedwater pump failure and includes potential common cause implications. A supplemental inspection was conducted by the NRC office during the week of February 25, 2002, to assess the adequacy of your evaluation of this risk significant performance issue. The results of this inspection will be documented in NRC Inspection Report 50-483/02-08.

While plant performance for the last two quarters was within the Regulatory Response Column of the Action Matrix, plant performance during the first quarter of the assessment cycle was in the Degraded Cornerstone Column of the Action matrix. This was based on three White findings, identified in the third quarter of 2000, that related to Callaway Plant's failure to maintain radiation doses as low as reasonably achievable. A supplemental inspection was

performed during April and May 2001. The NRC concluded that your staff had performed a thorough evaluation of the causes that led to job doses that were not as low as reasonably achievable, and they correctly identified the extent of the condition. We also determined that appropriate corrective actions were identified and implemented by your staff to address the root causes.

Separately, on May 14, 2001, the staff issued a Severity Level III Notice of Violation and Proposed Imposition of a \$55,000 Civil Penalty in accordance with the enforcement policy. Contrary to 10 CFR 50.7, Union Electric and one of its contract organizations discriminated against a security officer and a training instructor for having engaged in protected activity. Currently, the staff is reviewing your denial of this violation.

Immediately following the terrorist attacks on the World Trade Center and the Pentagon, the NRC issued safeguards advisories recommending that nuclear power plant licensees go to the highest level of security, and all promptly did so. With continued uncertainty about the possibility of additional terrorist activities, the Nation's nuclear power plants, including Callaway Plant, remain at a high level of security. On February 25, 2002, the NRC issued an Order to all nuclear power plant licensees, requiring them to take certain additional interim compensatory measures to address the generalized high-level threat environment. These additional compensatory requirements will provide the NRC with reasonable assurance that public health and safety and the common defense and security continue to be adequately protected in the current generalized high-level threat environment. These requirements will remain in effect pending notification from the Commission that a significant change in the threat environment occurs or until the Commission determines that other changes are needed following a more comprehensive re-evaluation of current safeguards and security programs. To date we have monitored Union Electric Company's actions in response to the terrorist attacks through a series of audits. With the issuance of the Order, we will evaluate Union Electric Company's compliance with these interim requirements.

The enclosed inspection plan details the inspections scheduled through March 31, 2003. The inspection plan is provided to minimize the resource impact on your staff and to allow for scheduling conflicts and personnel availability to be resolved in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The last 6 months of the inspection plan are tentative and may be revised at the Midcycle Review meeting. Also, your facility will be inspected in accordance with Temporary Instruction 2515/145, "Circumferential Cracking of Reactor Pressure Vessel Head Penetration Nozzles (NRC Bulletin 2001-01)."

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html (the Public Electronic Reading Room).

If circumstances arise which cause us to change this inspection plan, we will contact you to discuss the change as soon as possible. Please contact David Graves at (817) 860-8141 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

/RA/

Ellis W. Merschoff Regional Administrator

Dockets: 50-483 Licenses: NPF-30

Enclosure:

Callaway Plant Inspection/Activity Plan

cc w/enclosure: Professional Nuclear Consulting, Inc. 19041 Raines Drive Derwood, Maryland 20855

John O'Neill, Esq. Shaw, Pittman, Potts & Trowbridge 2300 N. Street, N.W. Washington, D.C. 20037

Mark A. Reidmeyer, Regional Regulatory Affairs Supervisor Regulatory Affairs AmerenUE P.O. Box 620 Fulton, Missouri 65251

Manager - Electric Department Missouri Public Service Commission 301 W. High P.O. Box 360 Jefferson City, Missouri 65102

Ronald A. Kucera, Deputy Director for Public Policy Department of Natural Resources 205 Jefferson Street Jefferson City, Missouri 65101 Otto L. Maynard, President and Chief Executive Officer Wolf Creek Nuclear Operating Corporation P.O. Box 411 Burlington, Kansas 66839

Dan I. Bolef, President
Kay Drey, Representative
Board of Directors Coalition
for the Environment
6267 Delmar Boulevard
University City, Missouri 63130

Lee Fritz, Presiding Commissioner Callaway County Courthouse 10 East Fifth Street Fulton, Missouri 65251

J. V. Laux, Manager Quality Assurance AmerenUE P.O. Box 620 Fulton, Missouri 65251

Jerry Uhlmann, Director State Emergency Management Agency P.O. Box 116 Jefferson City, Missouri 65101

Gary McNutt, Director Section for Environmental Public Health P.O. Box 570 Jefferson City, Missouri 65102-0570

John D. Blosser, Manager Regulatory Affairs AmerenUE P.O. Box 620 Fulton, Missouri 65251

The Honorable Vernon McKague Mayor of Chamois Star Route Chamois, Missouri 65024 Elmer Senevey Presiding Commissioner Osage County Courthouse P.O. Box 826 Linn, Missouri 65051

Richard Zeilman
Emergency Management
Director
Osage County Courthouse
P.O. Box 826
Linn, Missouri 65051

Carl Fowler Sheriff, Osage County Osage County Courthouse P.O. Box 826 Linn, Missouri 65051

Tim Diemler
Emergency Preparedness
Director
Callaway County/Fulton
P.O. Box 817
Fulton, Missouri 65251

Dennis Crane Sheriff, Callaway County P.O. Box 817 Fulton, Missouri 65251

Charles Korman
Presiding Commissioner
Montgomery County Courthouse
211 East Third
Montgomery City, Missouri 63361

Bob Bishop Emergency Management Director Montgomery County Courthouse 211 East Third Montgomery City, Missouri 63361

Robert Davis Sheriff, Montgomery County Montgomery County Courthouse 211 East Third Montgomery City, Missouri 63361 Charles Schlottach Presiding Commissioner Gasconade County Courthouse 119 East First Street Hermann, Missouri 65041

Richard Hudson
Emergency Preparedness
Director
Gasconade County Courthouse
P.O. Box 295
Hermann, Missouri 65041

Glenn Ebker Sheriff, Gasconade County Gasconade County Courthouse 119 East First Street Hermann, Missouri 65041

Fay Owsley
Gasconade County Public
Administrator
Gasconade County Courthouse
119 East First Street
Hermann, Missouri 65041

The Honorable Robert Craghead Mayor of Fulton Fulton City Hall P.O. Box 130 Fulton, Missouri 65251

Charles Latham Chief of Police Fulton City Hall P.O. Box 130 Fulton, Missouri 65251

William Johnson Fulton City Administrator Fulton City Hall P.O. Box 130 Fulton, Missouri 65251

The Honorable Samuel Birk Mayor of Morrison Route 1 Morrison, Missouri 65061 The Honorable Tom Shackelford Mayor of Mokane P.O. Box 41 Mokane, Missouri 65059

The Honorable Steve Wehrle Mayor of Rhineland P.O. Box 384 Rhineland, Missouri 65069

Robert Rankin Eastern District Commissioner Callaway County Courthouse 10 East 5th Street Fulton, Missouri 65251

Rodney Garnett Western District Commissioner Callaway County Courthouse 10 East 5th Street Fulton, Missouri 65251

Lee Fritz Presiding Commissioner Callaway County Courthouse 10 East 5th Street Fulton, Missouri 65251 Electronic distribution from ADAMS by RIV:

Regional Administrator (EWM)

DRP Director (KEB)

DRS Director (ATH)

Senior Resident Inspector (VGG)

Branch Chief, DRP/B (WDJ)

Senior Project Engineer, DRP/B (RAK1)

Staff Chief, DRP/TSS (PHH)

RITS Coordinator (NBH)

B. Henderson, PAO (BWH)

W. A. Maier, RSLO (WAM)

C. J. Gordon (CJG)

DRS Branch Chiefs (GMG, ATG, CSM)

W. D. Travers, EDO (WDT)

M. Johnson, Chief, NRR/DIPM/IIPB (MRJ1)

R. K. Frahm, PPR Program Manager, NRR/DIPM/IIPB (RKF)

B. A. Boger, Associate Dir. for Inspection and Programs (BAB2)

B. W. Sheron, Associate Dir. for Project Licensing and Technical Analysis (BWS)

J. Shea, Chief, Regional Operations Staff, OEDO (JWS1)

S. Richards, NRR Project Director (SAR)

S. Dembek, Chief, Section 2, NRR/DLPM (SXD)

J. Donohew, Project Manager (JND)

RidsNrrDipmlipb

Hard Copy:

Records Center, INPO

S:\DRP\DRPDIR\EOC 2002\Assessment Letters\CWY.wpd

DIV/C-DDD/D	D.DDC	ID-DDD	IDDA	IDΛ
RIV:C:DRP/B	D:DRS	D:DRP	DRA	RA
DNGraves;df	ATHowell	KEBrockman	TPGwynn	EWMerschoff
/RA/	/RA/	/RA/		/RA/
2/26/02	2/27/02	3/4/02	NA	3/4/02

Page 1 of 2

03/04/2002 13:13:12

Report 22

Callaway Inspection / Activity Plan

03/01/2002 - 03/30/2003

Unit No. of Staff **Planned Dates** Inspection Number Title on Site Start End Type Inspection Activity PBB-SUP1 - SUPP INSPECTION 95002 3 1 IP 95002 Inspection For One Degraded Cornerstone Or Any Three White Inputs In A Strategic Performar 02/25/2002 03/01/2002 Supplemental Progran PSB-RP7 - ALARA PLANNING AND CONTROLS 1 1 IP 7112102 ALARA Planning and Controls 03/04/2002 03/08/2002 Baseline Inspections **EMB** - SSD&PC INSPECTION 5 IP 7111121 Safety System Design and Performance Capability 05/10/2002 1 05/06/2002 Baseline Inspections IP 7111121 Safety System Design and Performance Capability 05/20/2002 05/24/2002 **Baseline Inspections** - 50.59 **EMB** 1 IP 7111102 1 Evaluation of Changes, Tests, or Experiments 06/10/2002 06/14/2002 **Baseline Inspections** OB-IN - INITIAL EXAM PREP WEEK 2 X02225 CALLAWAY INITIAL EXAM (08/02) 1 07/08/2002 07/12/2002 Not Applicable **OB-IN** INITIAL EXAM 4 1 X02225 CALLAWAY INITIAL EXAM (08/02) 07/29/2002 08/02/2002 Not Applicable PSB-EP1 - EP PROGRAM BASELINE INSPECTION IP 7111402 Alert and Notification System Testing 08/05/2002 08/09/2002 Baseline Inspections IP 7111403 **Emergency Response Organization Augmentation Testing** 08/05/2002 08/09/2002 Baseline Inspections IP 7111404 Emergency Action Level and Emergency Plan Changes 08/05/2002 08/09/2002 Baseline Inspections IP 7111405 Correction of Emergency Preparedness Weaknesses and Deficiencies 08/05/2002 08/09/2002 **Baseline Inspections** IP 71151 Performance Indicator Verification 08/05/2002 08/09/2002 **Baseline Inspections** - ALARA RP-3 1 IP 7112102 ALARA Planning and Controls 08/26/2002 08/30/2002 1 Baseline Inspections RP-1 - ACRSA AND PIV 1 IP 7112101 Access Control to Radiologically Significant Areas 10/21/2002 10/25/2002 Baseline Inspections IP 71151 Performance Indicator Verification 10/21/2002 10/25/2002 **Baseline Inspections EMB** - ISI 1 IP 7111108 Inservice Inspection Activities 10/28/2002 11/01/2002 Baseline Inspections 1 **EMB** - ISI/SG 1 IP 7111108 Inservice Inspection Activities 11/18/2002 11/22/2002 Baseline Inspections 1 TI 145 - TI 2515/145 2 IP 2515/145 Circumferential Cracking of Reactor Pressure Vessel Head Penetration Nozzles (NRC Bulletin 1 11/18/2002 11/22/2002 Safety Issues PSB-S1 ACCESS AUTH/CONTROL, SEC PLAN AND PIV 1 IP 7113001 Access Authorization Program (Behavior Observation Only) 12/02/2002 12/06/2002 Baseline Inspections IP 7113002 Access Control (Search of Personnel, Packages, and Vehicles: Identification and Authorization 12/02/2002 12/06/2002 **Baseline Inspections** IP 7113004 Security Plan Changes 12/02/2002 12/06/2002 **Baseline Inspections**

This report does not include INPO and OUTAGE activities.

This report shows only on-site and announced inspection procedures.

Page 2 of 2 03/04/2002

Report 22

13:13:12

Callaway

Inspection / Activity Plan

03/01/2002 - 03/30/2003

Unit Number	Inspection Activity		Title	No. of Staff on Site	Planne Start	d Dates End	Inspection Type
	PSB-S1	- ACCES	SS AUTH/CONTROL, SEC PLAN AND PIV	1			
1	IP 71151		Performance Indicator Verification		12/02/2002	12/06/2002	Baseline Inspections
	PBB-PIR	- CW PII	RINSPECTION	4			
1	IP 71152E	3	Identification and Resolution of Problems		12/02/2002	12/13/2002	Baseline Inspections