

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION I 475 ALLENDALE ROAD KING OF PRUSSIA, PENNSYLVANIA 19406-1415

August 31, 2006

Mr. David A. Christian Sr. Vice President and Chief Nuclear Officer Dominion Resources 5000 Dominion Boulevard Glenn Allen, VA 23060-6711

SUBJECT: MID-CYCLE PERFORMANCE REVIEW AND INSPECTION PLAN -MILLSTONE STATION UNITS 2 AND 3

Dear Mr. Christian:

On August 8, 2006, the NRC staff completed its performance review of Millstone Station Units 2 and 3 for the first half of the calendar year 2006 assessment cycle. Our technical staff reviewed performance indicators (PIs) for the most recent quarter and inspection results over the previous twelve months. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility.

This performance review and enclosed inspection plan do not include physical protection information. A separate letter designated and marked as "Exempt from Public Disclosure in accordance with 10 CFR 2.390" will include the physical protection review and resultant inspection plan.

Plant performance for the most recent quarter at Millstone Unit 2 was within the Regulatory Response column of the NRC's Action Matrix, based on all inspection findings being classified as having very low safety significance (Green) and a White PI for Scrams with a Loss of Normal Heat Removal (LONHR). On May 15, 2006, we were notified by your staff of your readiness for the NRC to conduct a supplemental inspection to review the actions taken to address the LONHR Scram PI. Therefore, we plan to conduct supplemental inspection 95001 beginning on September 11, 2006.

Plant performance for the most recent quarter at Millstone Unit 3 was within the Licensee Response column of the NRC's Action Matrix, based on all inspection findings being classified as having very low safety significance (Green) and all PIs indicating performance at a level requiring no additional NRC oversight (Green). Therefore, we plan to conduct reactor oversight process (ROP) baseline inspections at Unit 3.

The enclosed inspection plan details the inspections, less those related to physical protection, scheduled through March 31, 2008. In addition to baseline inspections, we plan on conducting two other inspections for activities related to the Unit 2 pressurizer installation and independent spent fuel storage facility operations. The inspection plan is provided to allow for the resolution of any scheduling conflicts and personnel availability issues well in advance of inspector arrival

D. A. Christian

onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The inspections in the last nine months of the inspection plan are tentative and may be revised at the end-of-cycle review.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html (the Public Electronic Reading Room).

If circumstances arise which cause us to change the inspection plan, we will contact you to discuss the change as soon as possible. Please contact Paul Krohn at 610-337-5120 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

/RA/

Brian E. Holian, Director Division of Reactor Projects

Docket Nos.: 50-336, 50-423 License Nos.: DPR-65, NPF-49

Enclosure: Millstone Units 2 and 3 Inspection/Activity Plan

D. A. Christian

cc w/encl:

- J. A. Price, Site Vice President, Millstone Station
- C. L. Funderburk, Director, Nuclear Licensing and Operations Support
- D. W. Dodson, Supervisor, Station Licensing
- L. M. Cuoco, Senior Counsel
- C. Brinkman, Manager, Washington Nuclear Operations

J. Roy, Director of Operations, Massachusetts Municipal Wholesale Electric Company

- First Selectmen, Town of Waterford
- B. Sheehan, Co-Chair, NEAC
- E. Woollacott, Co-Chair, NEAC
- E. Wilds, Director, State of Connecticut SLO Designee
- J. Buckingham, Department of Public Utility Control
- G. Proios, Suffolk County Planning Dept.
- R. Shadis, New England Coalition Staff
- G. Winslow, Citizens Regulatory Commission (CRC)
- S. Comley, We The People
- D. Katz, Citizens Awareness Network (CAN)
- R. Bassilakis, CAN
- J. M. Block, Attorney, CAN
- P. Eddy, Electric Division, Department of Public Service, State of New York
- P. Smith, President, New York State Energy Research and Development Authority
- J. Spath, SLO Designee, New York State Energy Research and Development Authority Institute of Nuclear Power Operations

Distribution w/encl: VIA E-MAIL:

S. Collins, RA M. Dapas, DRA B. Holian, DRP D. Lew, DRP A. Blough, DRS M. Gamberoni, DRS S. Schneider, Senior Resident Inspector E. Bartels, Resident OA P. Krohn, DRP S. Barber, DRP B. Sosa, RI OEDO D. Roberts, NRR V. Nerses, NRR E. Miller, NRR D. Screnci, PAO J. Rogge, DRS L. Doerflein, DRS M. Sykes, DRS R. Lorson, DRS D. Jackson, DRS J. White, DRS Region I Docket Room (with concurrences)

SUNSI Review Complete: <u>PGK</u> (Reviewer's Initials)

DOCUMENT NAME: S:\ROP 7 Mid Cycle Review\2006 ROP7 Mid-Cycle Letters\MILLSTONE Station 2006 Midcycle letter.wpd

After declaring this document "An Official Agency Record" it will be released to the Public. To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure

$\mathbf{E} = \mathbf{C}$ opy with attachment/enclosure $\mathbf{N} = \mathbf{N}\mathbf{C}$ copy								
0	RI/DRP	RI/DRP	RI/DRI	D				

OFFICE	RI/DRP	RI/DRP		RI/DRP	RI/DRP	
NAME	SBarber/GSB	Mschneider/PGK fo	r	PKrohn/PGK	BHolian/BE	Н
DATE	08/11/2006	08/30/06		08/30/06	08/31/06	

OFFICIAL RECORD COPY

Page 1 of 3

08/31/2006 09:43:36

Millstone Inspection / Activity Plan 07/01/2006 - 03/31/2008

Unit	l			No. of Staff Planned Da		Dates Inspection	
Number	Inspection Activity	Title	on Site	Start	End	Туре	
	60855.1 - OPERA	ATION OF AN ISFSI	3				
2,3	IP 60855.1	Operation of an Independent Spent Fuel Storage Installation at Operating Plants		05/01/2006	09/15/2006	Other Routine	
	7111111B - L.O. RI	EQUAL.PROG.(FOCUS U2)+P/F RVW	2				
2,3	IP 7111111B	Licensed Operator Requalification Program		09/04/2006	09/08/2006	Baseline Inspections	
	50003 - PRESS	SURIZER REPLACEMENT	1				
2	IP 50003	Pressurizer Replacement Inspection		08/01/2006	08/04/2006	Safety Issues	
2	IP 50003	Pressurizer Replacement Inspection		08/20/2006	08/24/2006	Safety Issues	
2	IP 50003	Pressurizer Replacement Inspection		10/01/2006	10/04/2006	Safety Issues	
2	IP 50003	Pressurizer Replacement Inspection		11/06/2006	11/10/2006	Safety Issues	
2	IP 50003	Pressurizer Replacement Inspection		11/20/2006	11/22/2006	Safety Issues	
	ISFSI - ISFSI		2				
2,3	IP 60855.1	Operation of an Independent Spent Fuel Storage Installation at Operating Plants		07/01/2006	08/31/2006	Other Routine	
	7111107B - U2: HE	AT SINK	1				
2	IP 7111107B	Heat Sink Performance		07/10/2006	07/14/2006	Baseline Inspections	
	TI-169 - MSPI V	/ERIFICATION	1				
2,3	IP 2515/169	Mitigating Systems Performance Index Verification		08/04/2006	09/01/2006	Safety Issues	
	95001 - SCRAI	IS WITH LOSS OF NORMAL HEAT REMOVAL	2				
2	IP 95001	Supplemental Inspection For One Or Two White Inputs In A Strategic Performance Area		09/11/2006	09/15/2006	Supplemental Prograi	
	7112202 - PUB R	AD SAFETY - RADWASTE	1				
2,3	IP 7112202	Radioactive Material Processing and Transportation		09/18/2006	09/22/2006	Baseline Inspections	
	7111108P - INSER	VICE INSPECTION - UNIT 2	1				
2	IP 7111108P	Inservice Inspection Activities - PWR		10/10/2006	10/13/2006	Baseline Inspections	
2	IP 7111108P	Inservice Inspection Activities - PWR		10/23/2006	10/27/2006	Baseline Inspections	
	7112102 - OCC R	AD SAFETY - ALARA	1				
2, 3	IP 7112102	ALARA Planning and Controls		11/13/2006	11/17/2006	Baseline Inspections	
	TI-166 - UNIT 2	CONTAINMENT SUMP MODS INSPECTION	1				
2	IP 2515/166	Pressurized Water Reactor Containment Sump Blockage [NRC GENERIC LETTER 2004-02]		11/13/2006	11/17/2006	Safety Issues	
	7111112B - MAINT	ENANCE RULE	1				
2,3	IP 7111112B	Maintenance Effectiveness		11/27/2006	12/01/2006	Baseline Inspections	
	7111107 - U3 BIE	NNIAL HEAT SINK INSP	2				
2,3	IP 7111107B	Heat Sink Performance		01/08/2007	01/12/2007	Baseline Inspections	
	3/12 EXM - U3 OP	3					
3	U01638	MILLSTONE 3 INITIAL EXAM (FY07)		02/12/2007	02/16/2007	Not Applicable	
3	U01638	MILLSTONE 3 INITIAL EXAM (FY07)		03/12/2007	03/23/2007	Not Applicable	

This report does not include INPO and OUTAGE activities. This report shows only on-site and announced inspection procedures. Page 2 of 3

08/31/2006 09:43:36

Report 22

_

Millstone Inspection / Activity Plan 07/01/2006 - 03/31/2008

Unit			No. of Staff	Planned Dates		Inspection	
Number	Inspection Activity	Title	on Site	Start End		Туре	
	7112101 - OCC R	AD SAFETY	1				
2,3	IP 7112101	Access Control to Radiologically Significant Areas		02/12/2007	02/16/2007	Baseline Inspections	
	7111108P - IN-SEF	RVICE INSPECTION - UNIT 3	1				
3	IP 7111108P	Inservice Inspection Activities - PWR		04/09/2007	04/20/2007	Baseline Inspections	
	7112102 - OCC R	AD SAFETY - ALARA	1				
2,3	IP 7112102	ALARA Planning and Controls		04/23/2007	04/27/2007	Baseline Inspections	
	TI-166 - CONT	AINMENT SUMP MODIFICATIONS - UNIT 3	1				
3	IP 2515/166	Pressurized Water Reactor Containment Sump Blockage [NRC GENERIC LETTER 2004-02]		04/23/2007	04/29/2007	Safety Issues	
	7112201 - PUB R	AD SAFETY - RETS	1				
2,3	IP 7112201	Radioactive Gaseous and Liquid Effluent Treatment and Monitoring Systems		06/04/2007	06/08/2007	Baseline Inspections	
	7111111B - L.O. R	EQUAL.PROG.(FOCUS U3)+P/F RVW	3				
2,3	IP 7111111B	Licensed Operator Requalification Program		09/10/2007	09/14/2007	Baseline Inspections	
	71114 - EP PR	GM INSP	1				
2,3	IP 7111402	Alert and Notification System Testing		09/10/2007	09/14/2007	Baseline Inspections	
2,3	IP 7111403	Emergency Response Organization Augmentation Testing		09/10/2007	09/14/2007	Baseline Inspections	
2,3	IP 7111404	Emergency Action Level and Emergency Plan Changes		09/10/2007	09/14/2007	Baseline Inspections	
2,3	IP 7111405	Correction of Emergency Preparedness Weaknesses and Deficiencies		09/10/2007	09/14/2007	Baseline Inspections	
2,3	IP 71151-EP01	Drill/Exercise Performance		09/10/2007	09/14/2007	Baseline Inspections	
2,3	IP 71151-EP02	ERO Drill Participation		09/10/2007	09/14/2007	Baseline Inspections	
2,3	IP 71151-EP03	Alert & Notification System		09/10/2007	09/14/2007	Baseline Inspections	
	TRI FIRE - TRIEN	NIAL FIRE PROTECTION INSPECTION	3				
3	IP 7111105T	Fire Protection [Triennial]		09/17/2007	09/21/2007	Baseline Inspections	
3	IP 7111105T	Fire Protection [Triennial]		10/01/2007	10/05/2007	Baseline Inspections	
	7112103 - OCC R	AD SAFETY - INSTRUMENTS	1				
2,3	IP 7112103	Radiation Monitoring Instrumentation and Protective Equipment		09/24/2007	09/28/2007	Baseline Inspections	
		AD SAFETY - REMP	1				
2,3	IP 7112203	Radiological Environmental Monitoring Program (REMP) And Radioactive Material Control Pro		10/15/2007	10/19/2007	Baseline Inspections	
		AND 50.59	4				
2,3	IP 7111102	Evaluation of Changes, Tests, or Experiments		11/05/2007	11/09/2007	Baseline Inspections	
2,3	IP 7111117B	Permanent Plant Modifications		11/05/2007	11/09/2007	Baseline Inspections	
		NIAL FIRE PROTECTION INSPECTION	3				
2	IP 7111105T	Fire Protection [Triennial]		01/14/2008		Baseline Inspections	
2	IP 7111105T	Fire Protection [Triennial]		01/28/2008	02/01/2008	Baseline Inspections	
		AD SAFETY - ACCESS	1				
2,3	IP 7112101	Access Control to Radiologically Significant Areas		02/11/2008	02/15/2008	Baseline Inspections	
Т	This report does not include	INPO and OUTAGE activities.					

This report does not include INPO and OUTAGE activities. This report shows only on-site and announced inspection procedures. Page 3 of 3

08/31/2006 09:43:36 Report 22

Millstone Inspection / Activity Plan 07/01/2006 - 03/31/2008

Un						No. of Staff			Inspection
Num	ber	Inspection Activity			Title	on Site	Start	End	Туре
		71152B	- PI&R			4			
2,3	3	IP 71152B		Identification and Resolution of Problems			02/11/2008	02/15/2008	Baseline Inspections
2,3	3	IP 71152B		Identification and Resolution of Problems			02/25/2008	02/29/2008	Baseline Inspections
		2/11EXAM	- U2 OPE	RATOR LICENSING INITIAL EXAMS		3			
2		U01634		MILLSTONE 2 INITIAL EXAM (FY08)			03/11/2008	03/14/2008	Not Applicable

This report does not include INPO and OUTAGE activities. This report shows only on-site and announced inspection procedures.