

## UNITED STATES NUCLEAR REGULATORY COMMISSION

## REGION IV 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-4005

March 4, 2003

Gregg R. Overbeck, Senior Vice President, Nuclear Arizona Public Service Company P.O. Box 52034 Phoenix, Arizona 85072-2034

SUBJECT: ANNUAL ASSESSMENT LETTER - PALO VERDE NUCLEAR GENERATING

STATION (REPORT 50-528/03-01; 50-529/03-01; 50-530/03-01)

Dear Mr. Overbeck:

On February 6, 2003, the NRC completed its end-of-cycle plant performance assessment of the Palo Verde Nuclear Generating Station. The end-of-cycle review for Palo Verde involved the participation of all technical divisions in evaluating performance indicators for the most recent quarter and inspection results for the period from January 1 through December 31, 2002. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility so that you will have an opportunity to prepare for these inspections and to inform us of any planned inspections that may conflict with your plant activities.

Overall, Palo Verde operated in a manner that preserved public health and safety and fully met all cornerstone objectives. Plant performance for the most recent quarter, as well as for the first three quarters of the assessment cycle, was within the Licensee Response Column of the NRC's Action Matrix, based on all inspection findings being classified as having very low safety significance (Green) and all performance indicators indicating performance at a level requiring no additional NRC oversight (Green). Therefore, we plan to conduct only baseline inspections at your facility through March 31, 2004.

The enclosed inspection plan details the inspections scheduled through March 31, 2004. In addition to the normal baseline inspections, the schedule contains some additional inspection associated with our review of your Unit 2 steam generator replacement activities. We also plan to conduct Temporary Instruction 2515/150, Revision 1, "Reactor Pressure Vessel Head and Vessel Head Penetration Nozzles," on Units 1 and 2 to confirm satisfactory implementation of NRC Bulletin 2002-02. The inspection plan is provided to minimize the resource impact on your staff and to allow for scheduling conflicts and personnel availability to be resolved in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The inspections in the last six months of the inspection plan are tentative and may be revised at the midcycle review meeting.

As you are aware, since the terrorist attacks on September 11, 2001, the NRC has issued several Orders and threat advisories to enhance security capabilities and improve guard force readiness. We have conducted inspections to review your implementation of these

requirements and have monitored your actions in response to changing threat conditions. For calendar year 2003, we plan to continue these inspections and conduct portions of the security baseline inspection program, as well as perform additional inspections to evaluate your compliance with new requirements that may be ordered. Based on our final determinations in this regard, we will notify you of any inspection plan changes.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosure, and your response will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <a href="http://www.nrc.gov/reading-rm/adams.html">http://www.nrc.gov/reading-rm/adams.html</a> (the Public Electronic Reading Room).

If circumstances arise which cause us to change this inspection plan, we will contact you to discuss the change as soon as possible. Please contact me at 817-860-8137 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

## /RA/

Linda Joy Smith, Chief Project Branch D Division of Reactor Projects

Dockets: 50-528

50-529

50-530

Licenses: NPF-41

NPF-51 NPF-74

Enclosure:

Palo Verde Nuclear Generating Station Inspection/Activity Plan

cc w/enclosure: Steve Olea Arizona Corporation Commission 1200 W. Washington Street Phoenix, Arizona 85007

Douglas K. Porter, Senior Counsel Southern California Edison Company Law Department, Generation Resources P.O. Box 800 Rosemead, California 91770 Chairman
Maricopa County Board of Supervisors
301 W. Jefferson, 10th Floor
Phoenix, Arizona 85003

Aubrey V. Godwin, Director Arizona Radiation Regulatory Agency 4814 South 40 Street Phoenix, Arizona 85040

Craig K. Seaman, Director Regulatory Affairs/Nuclear Assurance Palo Verde Nuclear Generating Station Mail Station 7636 P.O. Box 52034 Phoenix, Arizona 85072-2034

Hector R. Puente Vice President, Power Generation El Paso Electric Company 2702 N. Third Street, Suite 3040 Phoenix. Arizona 85004

Terry Bassham, Esq. General Counsel El Paso Electric Company 123 W. Mills El Paso, Texas 79901

John W. Schumann Los Angeles Department of Water & Power Southern California Public Power Authority P.O. Box 51111, Room 1255-C Los Angeles, California 90051-0100

John Taylor Public Service Company of New Mexico 2401 Aztec NE, MS Z110 Albuquerque, New Mexico 87107-4224

Jarlath Curran Southern California Edison Company 5000 Pacific Coast Hwy. Bldg. DIN San Clemente, California 92672 Robert Henry Salt River Project 6504 East Thomas Road Scottsdale, Arizona 85251

Brian Almon
Public Utility Commission
William B. Travis Building
P.O. Box 13326
1701 North Congress Avenue
Austin, Texas 78701-3326

Michael Austin, Director Arizona Division of Emergency Management 5636 East McDowell Road Building 101 Phoenix, Arizona 85008-3495

Federal Emergency Management Agency Jeff Griffin, Regional Director 1111 Broadway, Suite 1200 Oakland, California 94607-4052

Mayor Ron Drake 525 North Central Avondale, Arizona 85323

Mayor Dustin Hull 100 North Apache Road Buckeye, Arizona 85326

Mayor Jose Delgado P.O. Box 26 El Mirage, Arizona 85335

Mayor Elaine Scruggs 5850 West Glendale Avenue Glendale, Arizona 85301

Mayor William Arnold 119 North Litchfield Road Goodyear, Arizona 85338

Mayor J. Woodson Thomas 244 West Wigwam Blvd. Litchfield Park, Arizona 85340 Mayor John Keegan 8401 West Monroe Street Peoria, Arizona 85345

Mayor Skip Rimsza 200 West Washginton Phoenix, Arizona 85007

Mayor Joan Shafer 12425 West Bell Road Surprise, Arizona 85374

Mayor Adolfo Gamez 9555 West Van Buren Street Tolleson, Arizona 85353

Mayor Daphne Green 12030 Clubhouse Square Youngtown, Arizona 85363

Institute of Nuclear Power Operations (INPO) 700 Galleria Parkway SE Atlanta, Georgia 30339-5943 Electronic distribution by RIV:

Regional Administrator (EWM)

DRP Director (ATH)

DRS Director (DDC)

Resident Inspector (GXW2)

Branch Chief, DRP/D (LJS)

Project Engineer, DRP/D (ELC1)

Staff Chief, DRP/TSS (PHH)

RITS Coordinator (NBH)

V. L. Dricks, PAO (VLD)

W. A Maier, RSLO (WAM)

C. J. Gordon (CJG)

DRS Branch Chiefs (TWP, ATG, CSM)

W. D. Travers, EDO (WDT)

C. A. Carpenter, Chief, NRR/DIPM/IIPB (CAC)

R. K. Frahm, PPR Program Manager, NRR/DIPM/IIPB (RKF)

R. W. Borchardt, Associate Dir. for Inspection and Programs (RWB1)

B. Sheron, Associate Dir. for Project Licensing and Technical Analysis (BWS)

S. Morris, Acting Chief, Regional Operations Staff, OEDO (SAM1)

H. Berkow, NRR Project Director (HNB)

S. Dembek, Chief, Section 2, NRR/DLPM (SXD)

J. Donohew, NRR Project Manager (JND)

RidsNrrDipmlipb

## S:\DRP\DRPDIR\EOC 2003\Assessment Letters\PV.wpd

<u> </u>			* **	
RIV:C:DRP/D	D:DRS	D:DRP	Signature	
LJSmith;df;vlh	DDChamberlain	ATHowell	LJSmith	
/RA/	/RA/	/RA/	/RA/	
2/28/03	2/28/03	3/2/03	3/3/03	

Page 1 of 2

03/05/2003

07:37:23

Palo Verde **Inspection / Activity Plan** 03/02/2003 - 03/31/2004

Report 22

Part	Unit			No. of Staff	Staff Planned Dates		Inspection		
1,2,3	Number	Inspection Activity	Title	on Site	Start	End	Туре		
1,2   1,2		PSB-EP1 - EP EXERCISE INSPECTION 3							
1,23	1, 2, 3	IP 7111401	Exercise Evaluation		03/10/2003	03/14/2003	Baseline Inspections		
Part   Description   Part	1, 2, 3	IP 7111404	Emergency Action Level and Emergency Plan Changes		03/10/2003	03/14/2003	Baseline Inspections		
P   P   P   P   P   P   P   P   P   P	1, 2, 3	IP 71151	Performance Indicator Verification		03/10/2003	03/14/2003	Baseline Inspections		
		EMB - ISI IN	SPECTION U3	1					
Pari	3	IP 7111108P	Inservice Inspection Activities - PWR		04/14/2003	04/25/2003	Baseline Inspections		
Part   Maintenance Effectiveness   1		2515/150 - PWR	RPV HEAD CRACKING - BULLETIN 2002-02	1					
1,2,3	3	IP 2515/150	Reactor Pressure Vessel Head and Vessel Head Penetration Nozzles (NRC Bulletin 2002-0		04/14/2003	04/18/2003	Safety Issues		
The content of the		EMB - BIEN	NIAL MR INSPECTION	1					
1,2,3	1, 2, 3				04/28/2003	05/02/2003	Baseline Inspections		
1,2,3   P 7111   T   Fire Protection   PREP   R		EMB - TRIEI	NNIAL FIRE PROTECTION	5					
No.	1, 2, 3	IP 7111105T	Fire Protection		06/16/2003	06/20/2003	Baseline Inspections		
1	1, 2, 3				06/30/2003	07/04/2003	Baseline Inspections		
2   X02251   PALO VERDE - UNIT 2 EXAM (07/03)   07/17/2003   07/17/2		OB-IN - INITIA	AL EXAM PREP	3					
3		X02249	PALO VERDE - UNIT 1 EXAM (07/03)		07/07/2003		• •		
NB-IN	2	X02250	PALO VERDE - UNIT 2 EXAM (07/03)		07/07/2003	07/11/2003	Not Applicable		
1	3		,		07/07/2003	07/11/2003	Not Applicable		
2			AL EXAMS	4					
No.	1	X02249	PALO VERDE - UNIT 1 EXAM (07/03)		07/21/2003	07/25/2003	Not Applicable		
SGR-P         - U-2 SG REPLACEMENT PREP ACTIVITIES         1           2         IP 50001         Steam Generator Replacement Inspection         08/01/2003         09/20/2003         Other Routine           PSB-S1         - SECURITY BASELINE INSPECTION         1           1, 2, 3         IP 7113002         Access Control (Search of Personnel, Packages, and Vehicles: Identification and Authorizati         09/08/2003         09/12/2003         Baseline Inspections           1, 2, 3         IP 7113003         Response to Contingency Events (Protective Strategy and Implementation of Protective St	2	X02250	PALO VERDE - UNIT 2 EXAM (07/03)		07/21/2003	07/25/2003	Not Applicable		
2   IP 50001   Steam Generator Replacement Inspection   D8/01/2003   O9/20/2003   Other Routine	3				07/21/2003	07/25/2003	Not Applicable		
PSB-S1         - SECURITY BASELINE INSPECTION         1           1,2,3         IP 7113002         Access Control (Search of Personnel, Packages, and Vehicles: Identification and Authorizat         09/08/2003         09/12/2003         Baseline Inspections           1,2,3         IP 7113003         Response to Contingency Events (Protective Strategy and Implementation of Protective Strategy         09/08/2003         09/12/2003         Baseline Inspections           1,2,3         IP 71151         Performance Indicator Verification         09/08/2003         09/12/2003         Baseline Inspections           2         IP 50001         Steam Generator Replacement Inspection         09/26/2003         12/27/2003         Other Routine           1,2,3         IP 7112101         Access Control to Radiologically Significant Areas         1         10/06/2003         10/10/2003         Baseline Inspections           1,2,3         IP 7112101         Access Control to Radiologically Significant Areas         10/06/2003         10/10/2003         Baseline Inspections           1,2,3         IP 71151         Performance Indicator Verification         10/06/2003         10/10/2003         Baseline Inspections           1,2,3         IP 71151         Performance Indicator Verification         10/06/2003         10/10/2003         Baseline Inspections           1,2,3		SGR-P - U-2 S	G REPLACEMENT PREP ACTIVITIES	1					
1, 2, 3	2		·		08/01/2003	09/20/2003	Other Routine		
1, 2, 3 IP 7113003 Response to Contingency Events (Protective Strategy and Implementation of Protective Strategy and Implementation of 9/9/8/2003 09/12/2003 Baseline Inspections of 9/08/2003 09/12/2003 Descriptions of 9/08/200				1					
1, 2, 3       IP 71151       Performance Indicator Verification       09/08/2003       09/12/2003       Baseline Inspections         SGR2       - U-2 SG REPLACEMENT INSPECTIONS       1         2       IP 50001       Steam Generator Replacement Inspection       09/26/2003       12/27/2003       Other Routine         ACCESSPI       - ACRSA/PI       1       1       1         1, 2, 3       IP 7112101       Access Control to Radiologically Significant Areas       10/06/2003       10/10/2003       Baseline Inspections         1, 2, 3       IP 71151       Performance Indicator Verification       10/06/2003       10/10/2003       Baseline Inspections         1, 2, 3       IP 71151       Performance Indicator Verification       10/06/2003       10/10/2003       Baseline Inspections         TI -150       - PWR RPV HEAD CRACKING- BULLETIN 2002-02       1		IP 7113002			09/08/2003	09/12/2003	Baseline Inspections		
SGR2       - U-2 SG REPLACEMENT INSPECTIONS       1         2       IP 50001       Steam Generator Replacement Inspection       09/26/2003       12/27/2003       Other Routine         ACCESSPI       - ACRSA/PI       1         1, 2, 3       IP 7112101       Access Control to Radiologically Significant Areas       10/06/2003       10/10/2003       Baseline Inspections         1, 2, 3       IP 71151       Performance Indicator Verification       10/06/2003       10/10/2003       Baseline Inspections         TI -150       - PWR RPV HEAD CRACKING- BULLETIN 2002-02       1	1, 2, 3	IP 7113003	Response to Contingency Events (Protective Strategy and Implementation of Protective Stra		09/08/2003	09/12/2003	Baseline Inspections		
2 IP 50001 Steam Generator Replacement Inspection 09/26/2003 12/27/2003 Other Routine  ACCESSPI - ACRSA/PI 1  1, 2, 3 IP 7112101 Access Control to Radiologically Significant Areas 10/06/2003 10/10/2003 Baseline Inspections 1, 2, 3 IP 71151 Performance Indicator Verification 10/06/2003 10/10/2003 Baseline Inspections 1 - 150 - PWR RPV HEAD CRACKING- BULLETIN 2002-02 1	1, 2, 3	IP 71151	Performance Indicator Verification		09/08/2003	09/12/2003	Baseline Inspections		
ACCESSPI       - ACRSA/PI       1         1, 2, 3       IP 7112101       Access Control to Radiologically Significant Areas       10/06/2003       10/10/2003       Baseline Inspections         1, 2, 3       IP 71151       Performance Indicator Verification       10/06/2003       10/10/2003       Baseline Inspections         TI -150       - PWR RPV HEAD CRACKING- BULLETIN 2002-02       1				1					
1, 2, 3 IP 7112101 Access Control to Radiologically Significant Areas 1, 2, 3 IP 71151 Performance Indicator Verification 10/06/2003 10/10/2003 Baseline Inspections 11 -150 - PWR RPV HEAD CRACKING- BULLETIN 2002-02 1	2				09/26/2003	12/27/2003	Other Routine		
1, 2, 3 IP 71151 Performance Indicator Verification 10/06/2003 10/10/2003 Baseline Inspections TI -150 - PWR RPV HEAD CRACKING- BULLETIN 2002-02 1				1					
TI -150 - PWR RPV HEAD CRACKING- BULLETIN 2002-02 1					10/06/2003	10/10/2003	Baseline Inspections		
	1, 2, 3				10/06/2003	10/10/2003	Baseline Inspections		
2 IP 2515/150 Reactor Pressure Vessel Head and Vessel Head Penetration Nozzles (NRC Bulletin 2002-0 10/13/2003 10/17/2003 Safety Issues				1					
	2	IP 2515/150	Reactor Pressure Vessel Head and Vessel Head Penetration Nozzles (NRC Bulletin 2002-0		10/13/2003	10/17/2003	Safety Issues		

Page 2 of 2 03/05/2003 07:37:23 Palo Verde Inspection / Activity Plan 03/02/2003 - 03/31/2004

Report	22
--------	----

Unit			No. of Staff	Planned		Inspection
Number	Inspection Activity	Title	on Site	Start	End	Type
	EMB - ISI & S	G INSPECTIONS U2	1			_
2	IP 7111108P	Inservice Inspection Activities - PWR		10/13/2003	10/17/2003	Baseline Inspections
2	IP 7111108P	Inservice Inspection Activities - PWR		11/03/2003	11/07/2003	Baseline Inspections
	ALARA2 - ALAR	A	1			
1, 2, 3	IP 7112102	ALARA Planning and Controls		11/17/2003	11/21/2003	Baseline Inspections
	PSB-EP1 - EP PR	OGRAM INSPECTION	1			
1, 2, 3	IP 7111402	Alert and Notification System Testing		02/02/2004	02/06/2004	Baseline Inspections
1, 2, 3	IP 7111403	Emergency Response Organization Augmentation Testing		02/02/2004	02/06/2004	Baseline Inspections
1, 2, 3	IP 7111404	Emergency Action Level and Emergency Plan Changes		02/02/2004	02/06/2004	Baseline Inspections
1, 2, 3	IP 7111405	Correction of Emergency Preparedness Weaknesses and Deficiencies		02/02/2004	02/06/2004	Baseline Inspections
1, 2, 3	IP 71151	Performance Indicator Verification		02/02/2004	02/06/2004	Baseline Inspections
	EMB - SAFETY SYS. DESIGN AND PERF. CAPABILITY		4			
1, 2, 3	IP 7111121	Safety System Design and Performance Capability		03/01/2004	03/05/2004	Baseline Inspections
1, 2, 3	IP 7111121	Safety System Design and Performance Capability		03/15/2004	03/19/2004	Baseline Inspections
	EMB - CHAN	GES, TESTS & EXPERIMENTS	1			
1, 2, 3	IP 7111102	Evaluation of Changes, Tests, or Experiments		03/01/2004	03/05/2004	Baseline Inspections