

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION II

SAM NUNN ATLANTA FEDERAL CENTER 61 FORSYTH STREET SW SUITE 23T85 ATLANTA, GEORGIA 30303-8931

August 30, 2004

Carolina Power and Light Company
ATTN: Mr. John W. Moyer
Vice President
H. B. Robinson Steam Electric
Plant, Unit 2
3851 West Entrance Road
Hartsville, SC 29550

SUBJECT: MID-CYCLE PERFORMANCE REVIEW AND INSPECTION PLAN - H. B.

ROBINSON STEAM ELECTRIC PLANT

Dear Mr. Moyer:

On August 4, 2004, the NRC staff completed its mid-cycle plant performance assessment of the H. B. Robinson Steam Electric Plant. The mid-cycle review for Robinson involved the participation of all technical divisions in evaluating performance for the first half of the calendar year 2004 assessment cycle. The process included a review of performance indicators (PIs) for the most recent quarter and inspection results over the previous twelve months. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility. This will allow you an opportunity to prepare for these inspections and to inform us of any planned inspections that may conflict with your plant activities. This performance review and the enclosed inspection plan do not include physical protection information. A separate mid-cycle performance review letter, designated and marked as "Proprietary Information in accordance with 10 CFR 2.390(d)(1)", will include the physical protection review and a resultant inspection plan.

Plant performance for the most recent quarter was within the Licensee Response Column of the NRC's Action Matrix, based on all inspection findings being classified as having very low safety significance (Green) and all PIs indicating performance at a level requiring no additional NRC oversight (Green). Therefore, we plan to conduct only baseline inspections at your facility through March 31, 2006. We also plan on conducting several inspections which are not part of the routine baseline inspection program. These inspections include a review of the reactor vessel upper head replacement project, construction and operations inspections of the two independent spent fuel storage installations, and a review of your activities in response to Generic Letter 89-13, "Service Water System Problems Affecting Safety-Related Equipment.".

In addition, on April 7, 2004, the NRC issued a Notice of Violation and Proposed Imposition of Civil Penalty - \$88,000, to Carolina Power and Light Company (CP&L), in accordance with the "General Statement of Policy and Procedures for NRC Enforcement Actions," (Enforcement Policy), NUREG-1600. This Severity Level II violation involved employment discrimination contrary to the requirements of 10 CFR 50.7, "Employee Protection,". CP&L discriminated

CP&L 2

against a corporate site access authorization superintendent, when the individual was terminated from his employment on April 26, 1999, for engaging in a protected activity. CP&L had previously provided corrective action on this matter in a letter dated March 19, 2004, and on April 29, 2004, paid the civil penalty.

The enclosed inspection plan details the inspections, less those related to physical protection, scheduled through March 31, 2006. The inspection plan is provided to minimize the resource impact on your staff and to allow for scheduling conflicts and personnel availability to be resolved in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The inspections in the last twelve months of the inspection plan are tentative and may be revised at the end-of-cycle review meeting.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html (the Public Electronic Reading Room).

If circumstances arise which cause us to change the inspection plan, we will contact you to discuss the change as soon as possible. Please contact me at (404) 562-4530 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

/RA/

Paul E. Fredrickson, Chief Reactor Projects Branch 4 Division of Reactor Projects

Docket No. 50-261, Docket No. 72-3 Licensee No. DPR-23, License No. SNM-2502

Enclosure: Robinson Inspection/Activity Plan

cc w/encl: (See page 3)

CP&L 3

cc w/encls:
William C. Noll
Director, Site Operations
Carolina Power & Light Company
H. B. Robinson Steam Electric Plant
Electronic Mail Distribution

Daniel G. Stoddard
Plant General Manager
Carolina Power & Light Company
H. B. Robinson Steam Electric Plant
Electronic Mail Distribution

Chris L. Burton, Manager Performance Evaluation and Regulatory Affairs CPB 9 Electronic Mail Distribution

C. T. Baucom, Supervisor Licensing/Regulatory Programs Carolina Power & Light Company H. B. Robinson Steam Electric Plant Electronic Mail Distribution

J. F. Lucas, Manager Support Services - Nuclear Carolina Power & Light Company H. B. Robinson Steam Electric Plant Electronic Mail Distribution

Henry J. Porter, Director
Div. of Radioactive Waste Mgmt.
Dept. of Health and Environmental
Control
Electronic Mail Distribution

R. Mike GandyDivision of Radioactive Waste Mgmt.S. C. Department of Health and Environmental ControlElectronic Mail Distribution

Beverly Hall, Acting Director
Division of Radiation Protection
N. C. Department of Environment,
Health and Natural Resources
Electronic Mail Distribution

Steven R. Carr Associate General Counsel - Legal Dept. Progress Energy Service Company, LLC Electronic Mail Distribution

John H. O'Neill, Jr. Shaw, Pittman, Potts & Trowbridge 2300 N. Street, NW Washington, DC 20037-1128

Peggy Force
Assistant Attorney General
State of North Carolina
Electronic Mail Distribution

Chairman of the North Carolina Utilities Commission c/o Sam Watson, Staff Attorney Electronic Mail Distribution

Robert P. Gruber Executive Director Public Staff - NCUC 4326 Mail Service Center Raleigh, NC 27699-4326

Public Service Commission State of South Carolina P. O. Box 11649 Columbia, SC 29211

Institute of Nuclear Power Operations 700 Galleria Parkway SE Atlanta, GA 30339-5943 Page 1 of 2

14:10:38

08/30/2004 Report 22

Robinson

Inspection / Activity Plan

09/01/2004 - 03/31/2006

Unit			No. of Staff	Planned Dates		Inspection		
Number	Inspection Activity	Title	on Site	Start	End	Туре		
	EB1-TFP - FIRE PROTECTION-TRIENNIAL 4							
2	IP 7111105T	Fire Protection		08/30/2004	09/03/2004	Baseline Inspections		
	OL EXAM - INITIA	AL EXAM	3					
2	V23218	ROBINSON/EXAMS AT POWER FACILITIES		08/30/2004	09/03/2004	Not Applicable		
	EB2ISFSI - ISFSI	I CONSTRUCTION / OPERATION	3					
2	IP 60853	On-Site Fabrication Of Components And Construction On An ISFSI		10/04/2004	10/08/2004	Other Routine		
2	IP 60855	Operation Of An ISFSI		10/04/2004	10/08/2004	Other Routine		
	PB4-PI&R - PROI	BLEM IDENTIFICATION & RESOLUTION	3					
2	IP 71152B	Identification and Resolution of Problems		10/04/2004	10/08/2004	Baseline Inspections		
	PB4-PI&R - PROI	BLEM IDENTIFICATION AND RESOLUTION	3					
2	IP 71152B	Identification and Resolution of Problems		10/18/2004	10/22/2004	Baseline Inspections		
	EB2TI159 - REVI	EW OF GENERIC LETTER 89-13	4					
2	IP 2515/159	Review of Generic Letter 89-13: Service Water System Problems Affecting Safety-Related E		10/24/2004	10/28/2004	Safety Issues		
	OL EP - EP IN	ISPECTION	1					
2	IP 7111402	Alert and Notification System Testing		12/13/2004	12/17/2004	Baseline Inspections		
2	IP 7111403	Emergency Response Organization Augmentation Testing		12/13/2004	12/17/2004	Baseline Inspections		
2	IP 7111404	Emergency Action Level and Emergency Plan Changes		12/13/2004	12/17/2004	Baseline Inspections		
2	IP 7111405	Correction of Emergency Preparedness Weaknesses and Deficiencies		12/13/2004	12/17/2004	Baseline Inspections		
2	IP 71151	Performance Indicator Verification		12/13/2004	12/17/2004	Baseline Inspections		
	EB1SSDPC - SSDF	PC PRE-INSPECTION VISIT	2					
2	IP 7111121	Safety System Design and Performance Capability		01/17/2005	01/21/2005	Baseline Inspections		
	PS-RP - RP P	UBLIC AND ISFSI	3					
2	IP 60855.1	Operation of an Independent Spent Fuel Storage Installation at Operating Plants		01/31/2005	02/04/2005	Other Routine		
2	IP 7112103	Radiation Monitoring Instrumentation and Protective Equipment		01/31/2005	02/04/2005	Baseline Inspections		
2	IP 7112201	Radioactive Gaseous and Liquid Effluent Treatment and Monitoring Systems		01/31/2005	02/04/2005	Baseline Inspections		
2	IP 7112203	Radiological Environmental Monitoring Program		01/31/2005	02/04/2005	Baseline Inspections		
2	IP 71151	Performance Indicator Verification		01/31/2005	02/04/2005	Baseline Inspections		
	OL RQ - REQI	UAL INSPECTION	2					
2	IP 7111111B	Licensed Operator Requalification Program		02/14/2005	02/18/2005	Baseline Inspections		
	EB1SSDPC - SSDPC		5					
2	IP 7111121	Safety System Design and Performance Capability		02/14/2005	02/19/2005	Baseline Inspections		
2	IP 7111121	Safety System Design and Performance Capability		02/28/2005	03/04/2005	Baseline Inspections		
	60854 - ISFSI	1						
2	IP 60854	Preoperational Testing Of An ISFSI		06/20/2005	06/24/2005	Other Routine		

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.

Page 2 of 2

2

IP 7111117B

08/30/2004 14:10:38

Neport 22

Robinson

Inspection / Activity Plan 09/01/2004 - 03/31/2006

Unit			No. of Staff	Planne	d Dates	Inspection
Number	Inspection Activity	Title	on Site	Start	End	Туре
	EB2 HEAD - REAC	TOR HEAD REPLACEMENT	2			
2	IP 71007	Reactor Vessel Head Replacement Inspection		08/15/2005	08/19/2005	Other Routine
2	IP 71007	Reactor Vessel Head Replacement Inspection		09/05/2005	09/07/2005	Other Routine
	EB2-ISI - ISI		1			
2	IP 7111108P	Inservice Inspection Activities - PWR		09/06/2005	09/09/2005	Baseline Inspections
	PS - RP - RP OC	CUPATIONAL	1			
2	IP 7112101	Access Control to Radiologically Significant Areas		09/12/2005	09/16/2005	Baseline Inspections
2	IP 7112102	ALARA Planning and Controls		09/12/2005	09/16/2005	Baseline Inspections
	EB2SGISI - STEAM GENERATOR ISI					
2	IP 7111108P	Inservice Inspection Activities - PWR		09/19/2005	09/23/2005	Baseline Inspections
	EB2-MODS - MODIFICATIONS/10CFR50.59					
2	IP 7111102	Evaluation of Changes, Tests, or Experiments		01/30/2006	02/03/2006	Baseline Inspections

Permanent Plant Modifications