

## UNITED STATES NUCLEAR REGULATORY COMMISSION

## REGION II

SAM NUNN ATLANTA FEDERAL CENTER 61 FORSYTH STREET SW SUITE 23T85 ATLANTA, GEORGIA 30303-8931

March 31, 2000

Florida Power and Light Company
ATTN: Mr. T. F. Plunkett
President - Nuclear Division
P. O. Box 14000

Juno Beach, FL 33408-0420

SUBJECT: PLANT PERFORMANCE REVIEW - TURKEY POINT NUCLEAR PLANT

The purpose of this letter is to communicate our assessment of your performance and to inform you of our planned inspections at your facility. On February 25, 2000, we completed a Plant Performance Review (PPR) of Turkey Nuclear Plant. We conduct these reviews to develop an integrated overview of the safety performance of each operating nuclear power plant. We use the results of the PPR in planning and allocating inspection resources and as inputs to our senior management meeting (SMM) process. This PPR evaluated inspection results and safety performance information for the period from February 1, 1999 through January 31, 2000, but emphasized the last six months to ensure that our assessment reflected your current performance. Our most recent summary of plant performance at Turkey Nuclear Plant was provided to you in a letter dated October 13, 1999.

The NRC has been developing a revised reactor oversight process that will replace our existing inspection and assessment processes, including the PPR, the SMM, and the Systematic Assessment of Licensee Performance (SALP). We recently completed a pilot program for the revised reactor oversight process at nine participating sites and are making necessary adjustments based on feedback and lessons learned. We plan to begin initial implementation of the revised reactor oversight process industry-wide, including your facility, on April 2, 2000.

This PPR reflects continued process improvements as we make the transition into the revised reactor oversight process. Instead of characterizing our assessment results by SALP functional area, we are organizing the results into the strategic performance areas embodied in the revised reactor oversight process. In addition, we have considered the historical performance indicator data that you submitted in January 2000 in conjunction with the inspection results in assessing your performance. The results of this PPR were used to establish the inspection plan in accordance with the new risk-informed inspection program (consisting of baseline and supplemental inspections). Although this letter incorporates some terms and concepts associated with the new oversight process, it does not reflect the much broader changes in inspection and assessment that will be evident after we have fully implemented our revised reactor oversight process.

During the last six months, Turkey Point Unit 3 operated at or near full power with the exception of a two day period to repair a turbine control valve. Unit 4 operated at or near full power with the exception of a three day period due to a feedwater valve problem.

FPL 2

We have not identified any significant performance issues during this assessment period and note that Turkey Point continues to operate in a safe manner. Therefore, we plan to conduct only baseline inspections at your facility as noted in the attached inspection plan.

Enclosure 1 contains a historical listing of plant issues, referred to as the Plant Issues Matrix (PIM), that were used during this PPR process to arrive at our integrated view of your performance trends. The PIM for this assessment is grouped by the prior SALP functional areas of operations, maintenance, engineering and plant support, although the future PIM will be organized along the cornerstones of safety as described in the revised reactor oversight process. The attached PIM includes items summarized from inspection reports or other docketed correspondence regarding Turkey Nuclear Plant. We did not document all aspects of licensee programs and performance that may be functioning appropriately. Rather, we only documented issues that we believe warrant management attention or represent noteworthy aspects of performance. In addition, the PPR may also have considered some predecisional and draft material that does not appear in the attached PIM, including observations from events and inspections that had occurred since our last inspection report was issued, but had not yet received full review and consideration. We will make this material publically available as part of the normal issuance of our inspection reports and other correspondence.

Enclosure 2 lists our planned inspections for the period April 2000 through March 2001 at Turkey Nuclear Plant to allow you to resolve scheduling conflicts and personnel availability in advance of our inspector arrival onsite. The inspection schedule for the latter half of the period is more tentative and may be adjusted in the future due to emerging performance issues at Turkey Nuclear Plant or other Region II facilities. Routine resident inspections are not listed due to their ongoing and continuous nature.

We will inform you of any changes to the inspection plan. If you have any questions, please contact me at 404/562-4540.

Sincerely,

## /RA/

Leonard D. Wert, Chief Reactor Projects Branch 3 Division of Reactor Projects

Docket Nos. 50-250, 50-251 License Nos. DPR-31, DPR-41

Enclosures: 1. Plant Issues Matrix

2. Inspection Plan

cc w/encls: (See page 3)

cc w/encls:

Plant General Manager Turkey Point Nuclear Plant

Florida Power and Light Company

9760 SW 344th Street

Florida City, FL 33035

R. J. Hovey Site Vice President

**Turkey Point Nuclear Plant** 

FPL 3

Florida Power and Light Company 9760 SW 344th Street Florida City, FL 33035

Steve Franzone
Licensing Manager
Turkey Point Nuclear Plant
Florida Power and Light Company
Electronic Mail Distribution

John Gianfrancesco, Manager Administrative Support & Special Projects Florida Power & Light Company Electronic Mail Distribution

J. A. Stall
Vice President - Nuclear Engineering
Florida Power & Light Company
P. O. Box 14000
Juno Beach, FL 33408-0420

M. S. Ross, Attorney Florida Power & Light Electronic Mail Distribution

Attorney General Department of Legal Affairs The Capitol Tallahassee, FL 32304

William A. Passetti Bureau of Radiation Control Department of Health Electronic Mail Distribution County Manager Metropolitan Dade County Electronic Mail Distribution

Joe Myers, Director Division of Emergency Preparedness Department of Community Affairs Electronic Mail Distribution

Curtis Ivy
Acting City Manager of Homestead
Electronic Mail Distribution

FPL 4

## **Distribution w/encls**:

S. Collins, NRR

J. Zwolinski, NRR

W. Dean, NRR

K. Jabbour,

C. Thomas, NRR

G. Tracy, EDO

R. Borchardt, OE

L. Wert, RII

S. Rudisail, RII

**PUBLIC** 

NRC Resident Inspector U.S. Nuclear Regulatory Commission P. O. Box 6090 Jensen Beach, FL 34957-2010

OFFICE	RII:DRP	RII:DRS	RII:DRS	RII:DRS	RII:DRS		
SIGNATURE	SR	AB	EGIRARD for	HC	FWRIGHT for		
NAME	SRudisail	ABelisle	KLandis	HChristensen	KBarr		
DATE	3/28/00	3/24/00	3/28/00	3/28/00	3/30/00		
COPY?	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO