

## Attachment A

### Threatened and Endangered Species Correspondence

- J. A. Thomas, Enercon Services, Inc., to D. Stillwell, Field Supervisor, U.S. Fish and Wildlife Service, November 22, 2006.
- J. A. Thomas, Enercon Services, Inc., to D. VanLuven, Director, New York Natural Heritage Program, November 22, 2006.
- J. A. Thomas, Enercon Services, Inc., to M. Colligan, Assistant Regional Administrator for Protected Resources, National Marine Fisheries Service, November 22, 2006.
- R. A. Niver, U.S. Fish and Wildlife Service, to J. A. Thomas, Enercon Services, Inc., December 6, 2006.
- N. B. Conrad, New York Natural Heritage Program, to J. A. Thomas, Enercon Services, Inc., December 22, 2006 [Redacted].
- M. Colligan, Assistant Regional Administrator for Protected Resources, National Marine Fisheries Service, to J. A. Thomas, Enercon Services, Inc., January 23, 2007.
- M. Colligan, Assistant Regional Administrator for Protected Resources, National Marine Fisheries Service, to J. A. Thomas, Enercon Services, Inc., March 19, 2007.



**ENERCON SERVICES, INC.**

*An Employee Owned Company*

5100 E. Skelly Drive, Suite 450  
Tulsa, OK 74135  
(918) 665-7693  
(918) 665-7232 - Fax

November 22, 2006

Mr. David Stillwell  
Field Supervisor  
U.S. Fish and Wildlife Service  
New York Field Office  
3817 Luker Road  
Cortland, NY 13045

RE: Entergy Nuclear Indian Point  
Indian Point Units 2 and 3

Dear Mr. Stillwell:

Entergy Nuclear Indian Point 2, LLC and Entergy Nuclear Indian Point 3, LLC (hereafter referred to as "Entergy"), the owner of Indian Point Units 2 and 3 (Indian Point) is in the process of completing an application to be filed with the Nuclear Regulatory Commission (NRC) for a potential 20 year renewal of Indian Point's operating licenses. Enercon is gathering information on Entergy's behalf relative to this potential license renewal.

Indian Point is located on the eastern bank of the Hudson River at Indian Point in the Village of Buchanan in upper Westchester County, New York. The exact location of the site is latitude 41°16'11" and longitude 73°57'8". The entire site is owned by Entergy and contains approximately 239 acres, bounded on the north, south, and east by privately owned land and on the west by the Hudson River.

The NRC requires that Entergy's application for license renewal at Indian Point, "assess the impact of the proposed action." In an effort to ascertain any potential concerns that could arise as a result of license renewal at Indian Point, Enercon is requesting any information you may have regarding potential impacts to threatened or endangered species, or other species of interest in the vicinity of Indian Point (see attached map and photos).

In the event of license renewal at Indian Point, it is not anticipated there would be any alterations to current plant operations and maintenance activities would be limited to previously disturbed areas on site. License renewal at Indian Point would not require the expansion of existing facilities or additional land disturbances.

If you have any questions, please contact me at (918) 665-7693 or through my email address, [jthomas@enercon.com](mailto:jthomas@enercon.com).

Sincerely,

James A. Thomas  
Client Services Manager

JAT

































