

## **1Q/2003 ROP Performance Indicators Summary**







Vogtle 1	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G
Vogtle 2	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G
Waterford 3	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G
Watts Bar 1	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G
Wolf Creek 1	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G	G

**Legend :** R=Red      W=White      T=Thresholds under development      N=Not Applicable  
 Y=Yellow      G=Green      I=Insufficient data to calculate PI      U=Unique Design

IE01 = Unplanned Scrams per 7000 Critical Hours	IE02 = Scrams with Loss of Normal Heat Removal
IE03 = Unplanned Power Changes	MS01 = Emergency AC Power System
MS02 = High Pressure Injection System	MS03 = Heat Removal System
MS04 = Residual Heat Removal System	MS05 = Safety System Functional Failures
BI01 = Reactor Coolant System Specific Activity	BI02 = Reactor Coolant System Leakage
EP01 = Drill/Exercise Performance	EP02 = ERO Drill Participation
EP03 = Alert and Notification System	OR01 = Occupational Exposure Control Effectiveness
PR01 = RETS/ODCM Radiological Effluent	PP01 = Protected Area Equipment
PP02 = Personnel Screening Program	PP03 = FFD/Personnel Reliability Program

▲ [Inspection Findings Summary](#) | [Action Matrix Summary](#) | [Reactor Oversight Process](#)

Last modified : April 30, 2003