

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 26

National Average: 41

2x National Average: 82

National Median: 24

Average for Selected Dockets: 26

Facility Name: South Texas 1 Docket (050- 00498)

Details	Department	Work Type	Docket/Report
Human-System Interface & Environmnt / IR			
173 - Physical conditions LTA	E - Electrical	M - Maintenance / Repair	050-00498/2007-002
173 - Physical conditions LTA	H - Health Physics	H - Health Physics	050-00498/2007-003
173 - Physical conditions LTA	H - Health Physics	H - Health Physics	050-00498/2007-003
Number of Items for this Docket: 3			
Percent of Total for this Docket: 12			
<hr/>			
Oversight / IR			
130 - Inadequate supervision / command and control	H - Health Physics	H - Health Physics	050-00498/2007-003
130 - Inadequate supervision / command and control	M - Mechanical	M - Maintenance / Repair	050-00498/2007-002
Number of Items for this Docket: 2			
Percent of Total for this Docket: 8			
<hr/>			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	E - Electrical	F - Modification	050-00498/2007-004
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00498/2007-002
111 - Procedure / reference document technical content	M - Mechanical	S - Surveillance	050-00498/2007-004
Number of Items for this Docket: 3			
Percent of Total for this Docket: 12			
<hr/>			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	E - Electrical	M - Maintenance / Repair	050-00498/2006-005
143 - Tracking / trending LTA	M - Mechanical	M - Maintenance / Repair	050-00498/2007-003
Number of Items for this Docket: 2			
Percent of Total for this Docket: 8			
<hr/>			
Work Planning & Practices / IR			
182 - Work package quality LTA	E - Electrical	F - Modification	050-00498/2007-004
183 - Pre-job activities LTA	E - Electrical	F - Modification	050-00498/2007-004
183 - Pre-job activities LTA	M - Mechanical	M - Maintenance / Repair	050-00498/2006-005
185 - Procedural adherence LTA	E - Electrical	M - Maintenance / Repair	050-00498/2007-002
185 - Procedural adherence LTA	H - Health Physics	H - Health Physics	050-00498/2006-005
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00498/2007-002
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00498/2007-003
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00498/2007-004
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00498/2007-003
188 - Work practice or craft skill LTA	H - Health Physics	H - Health Physics	050-00498/2006-005

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 26

National Average: 41

2x National Average: 82

National Median: 24

Average for Selected Dockets: 26

Facility Name: South Texas 1 Docket (050- 00498)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / IR			
188 - Work practice or craft skill LTA	H - Health Physics	H - Health Physics	050-00498/2006-005
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00498/2007-003
197 - Self-check LTA	E - Electrical	M - Maintenance / Repair	050-00498/2007-002
Number of Items for this Docket: 13			
Percent of Total for this Docket: 50			
<hr/>			
Communication / LER			
160 - No communication / information not communicated	Z - Other / Unknown	G - Design	050-00498/2007-003-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			
<hr/>			
Training / LER			
101 - Training process problem	I - Instrumentation & Control	M - Maintenance / Repair	050-00498/2007-003-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			
<hr/>			
Work Planning & Practices / LER			
187 - Action implementation LTA	I - Instrumentation & Control	M - Maintenance / Repair	050-00498/2007-003-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			
<hr/>			
Total Items for this Docket: 26			
