

2000 Human Factors Information System Report for Plant Docket 346

Combined IR/ER/LER Report
Docket: 50-346 DAVIS-BESSE

Total Number of Hits in Date Range: 55
From 01/01/2000 to 12/31/2000
2x National Average: 144

Details	Department	Work Type	Docket/Report
Communications IR			
Number of items: 1			
Percent of total: 1.82			
53-Communication LT	O-Operations	V-Troubleshooting	50-346/1999016
	O-Operations		
Communications ER			
Number of items: 0			
Percent of total: 0			
Communications LER			
Number of items: 0			
Percent of total: 0			
Human-System Interface and Environm IR			
Number of items: 2			
Percent of total: 3.64			
65-Information Cont	O-Operations	O-Control Room Ops	50-346/1999016
65-Information Cont	O-Operations	B-Bal of Plant Ops	50-346/1999016
Human-System Interface and Environm ER			
Number of items: 0			
Percent of total: 0			
Human-System Interface and Environm LER			
Number of items: 0			
Percent of total: 0			
Management and Supervision IR			
Number of items: 2			
Percent of total: 3.64			
40-Individual Corre	G-Engineering	Z-Other	50-346/2000007
36-Scheduling and p	W-Work Control / Sc	M-Maint / Repair	50-346/2000009
Management and Supervision ER			
Number of items: 0			
Percent of total: 0			
Management and Supervision LER			
Number of items: 0			
Percent of total: 0			
Organizational Issues IR			
Number of items: 0			
Percent of total: 0			
Organizational Issues ER			
Number of items: 0			
Percent of total: 0			
Organizational Issues LER			
Number of items: 0			
Percent of total: 0			
Procedures and Reference Document IR			
Number of items: 7			
Percent of total: 12.73			

Human Factors Information System Report

12-Procedure techni G-Engineering G-Design 50-346/2000007
 Page: 1 Date:06/03/2002

Combined IR/ER/LER Report
 Docket: 50-346 DAVIS-BESSE

Total Number of Hits in Date Range: 55
 From 01/01/2000 to 12/31/2000
 2x National Average: 144

Details	Department	Work Type	Docket/Report
Procedures and Reference Document IR			
Number of items: 7			
Percent of Total: 12.73			
11-No procedure / r	G-Engineering	G-Design	50-346/2000007
12-Procedure techni	Z-Other	T-Testing	50-346/2000013
12-Procedure techni	Z-Other	T-Testing	50-346/2000013
12-Procedure techni	Z-Other	Z-Other	50-346/2000013
12-Procedure techni	Z-Other	Z-Other	50-346/2000013
12-Procedure techni	Z-Other	Z-Other	50-346/2000013
Procedures and Reference Document ER			
Number of items: 0			
Percent of total: 0			
Procedures and Reference Document LER			
Number of items: 2			
Percent of total: 3.64			
13-Procedure has hu	P-Procedure Writers	P-Procedure Dev	50-346/200000400
11-No procedure / r	O-Operations	B-Bal of Plant Ops	50-346/200000500
Training IR			
Number of items: 1			
Percent of total: 1.82			
03-Training process	T-Training	Z-Other	50-346/2000012
Training ER			
Number of items: 0			
Percent of total: 0			
Training LER			
Number of items: 0			
Percent of total: 0			
Work Factors IR			
Number of items: 30			
Percent of total: 54.55			
86-Work untimely	O-Operations	Z-Other	50-346/1999016
84-Non-conserv. dec	O-Operations	M-Maint / Repair	50-346/1999016
84-Non-conserv. dec	O-Operations	M-Maint / Repair	50-346/1999016
91-Verification / p	O-Operations	M-Maint / Repair	50-346/1999016
91-Verification / p	O-Operations	M-Maint / Repair	50-346/1999016
84-Non-conserv. dec	O-Operations	V-Troubleshooting	50-346/1999016
93-Awareness or att	O-Operations	V-Troubleshooting	50-346/1999016
91-Verification / p	O-Operations	V-Troubleshooting	50-346/1999016
91-Verification / p	O-Operations	B-Bal of Plant Ops	50-346/1999016
93-Awareness or att	O-Operations	B-Bal of Plant Ops	50-346/1999016
93-Awareness or att	O-Operations	Q-Fire Protection	50-346/1999016
93-Awareness or att	O-Operations	Q-Fire Protection	50-346/1999016
93-Awareness or att	G-Engineering	G-Design	50-346/1999016
91-Verification / p	O-Operations	B-Bal of Plant Ops	50-346/2000001
83-Work practice or	O-Operations	B-Bal of Plant Ops	50-346/2000001
84-Non-conserv. dec	O-Operations	O-Control Room Ops	50-346/2000001
93-Awareness or att	O-Operations	B-Bal of Plant Ops	50-346/2000001

Page: 2 Date:06/03/2002

Combined IR/ER/LER Report
 Docket: 50-346 DAVIS-BESSE

Total Number of Hits in Date Range: 55
 From 01/01/2000 to 12/31/2000

2x National Average: 144

Details	Department	Work Type	Docket/Report
Work Factors IR			
Number of items: 30			
Percent of Total: 54.55			
84-Non-conserv. dec	O-Operations	O-Control Room Ops	50-346/2000003
93-Awareness or att	E-Electrical	T-Testing	50-346/2000003
92-Self check LTA	E-Electrical	T-Testing	50-346/2000003
93-Awareness or att	O-Operations	B-Bal of Plant Ops	50-346/2000004
93-Awareness or att	G-Engineering	G-Design	50-346/2000007
93-Awareness or att	G-Engineering	G-Design	50-346/2000007
84-Non-conserv. dec	G-Engineering	G-Design	50-346/2000007
84-Non-conserv. dec	G-Engineering	G-Design	50-346/2000007
93-Awareness or att	G-Engineering	F-Modification	50-346/2000007
93-Awareness or att	G-Engineering	F-Modification	50-346/2000007
93-Awareness or att	Z-Other	A-Administrative	50-346/2000008
84-Non-conserv. dec	W-Work Control / Sc	M-Maint / Repair	50-346/2000009
81-Work Package Qua	G-Engineering	G-Design	50-346/2000010

Work Factors ER			
Number of items: 5			
Percent of total: 9.09			
93-Awareness or att	T-Training	Z-Other	50-346/2000301
93-Awareness or att	T-Training	Z-Other	50-346/2000301
93-Awareness or att	T-Training	Z-Other	50-346/2000301
93-Awareness or att	T-Training	Z-Other	50-346/2000301
93-Awareness or att	T-Training	A-Administrative	50-346/2000301

Work Factors LER			
Number of items: 5			
Percent of total: 9.09			
81-Work Package Qua	G-Engineering	F-Modification	50-346/200000300
91-Verification / p	E-Electrical	S-Surveillance	50-346/200000400
92-Self check LTA	E-Electrical	S-Surveillance	50-346/200000400
92-Self check LTA	O-Operations	B-Bal of Plant Ops	50-346/200000500
91-Verification / p	O-Operations	B-Bal of Plant Ops	50-346/200000500

Page: 3 Date:06/03/2002

[End of File for Plant Docket 346 (2000)]
