

**MODERNIZATION
PROGRAM
LIAISON OFFICE**

DEFINITIONS:

(Dust) - This activity could possibly generate dust.

(IAQ) - This activity could possibly be a source of Indoor Air Quality concerns.

(Noise) - This activity could generate noise.

(ACM) - Asbestos containment material.

If any of the above conditions becomes an irritant, please call 208.7560 immediately.

What is SMACNA?

SMACNA is an acronym for the Sheet Metal and Air Conditioning Contractor's National Association. NIOSH has requested that construction complies with these guidelines. It is important to note that no industry standard exists for the percentile of compliance. GSA conducts a daily checks of the construction area to ensure the contractor is in compliance with these guidelines.

**GSA CONTRACTOR'S
COMPLIANCE WITH
SMACNA GUIDELINES.**

**RESULTS
FOR THE
PERIOD
02-16-09 to 02-20-09**

**99%
Green**

Behind the Barricade

Plan of the Week

FEB. 23 - MAR. 01, 2009

Modernization Activities Wing 3

Wing 3

7th Floor

East/West

- Plaster patching
- Lead abatement of FCU's
- Insulate 5 pipe system
- Test FCU 5 pipe system
- Sprinkler hydro test
- Painting window frames
- Installing windows
- Soffit and shaft close-in inspections
- Install exterior shaft pipes, conduit and duct
- Lead abatement at windows
- Install CMU privacy wall in restroom

6th Floor

East/West

- Plaster patching
- Lead abatement of FCU's
- Test FCU 5 pipe system
- Install exterior shaft pipes, conduit and duct
- Sprinkler pipe rough-in at offices
- Demo window sashes
- Install window protection
- Install CMU privacy wall in restroom
- Insulate 5 pipe system
- Start fire stopping
- Sprinkler hydro test

Mechanical- Floor

East/West

- Secure area with monitors, card readers
- Concrete infill of perimeter chases
- Set Air Handler Units
- Prime and (1) coat ceiling and walls
- Installing MEP pipe/duct/sprinkler
- Installing CMU at Rms. M405,307,309,311

5th Floor

East/West

- Framing soffits, shafts, plaster patching
- Lead abatement
- R/I lighting conduit
- Sprinkler pipe rough-in at offices

4th Floor

East/West

- Framing soffits, shafts, plaster patching
- Install exterior insulation
- Abatement
- Tear down containment

3rd Floor

East/West

- Abatement
- Tear down containment
- Remove left over debris
- Framing soffits, shafts, plaster patching
- Install exterior insulation

2nd Floor

East/West

- Set up containment
- Demo chases
- ACM removal

1st Floor

East/West

- Remove left over debris

Cafeteria

- ACM Finals
- ACM set ups in Kitchen area

Elevator 13/14

- Removing old elevator equipment for renovation