



# RED ZONES ARE NO ZONES


## FOR MINING WITH REMOTE CONTROL CONTINUOUS MINERS

Tramming To Next Place




NOTE:  
THESE DRAWINGS DO NOT SUPERCEDE  
ANY STATE OR FEDERAL REQUIREMENT


Pillaring:  
Left Cut




Pillaring:  
Right Cut




Pillaring:  
End Cut




Beginning First Sump




Sump First Side




Repositioning Miner




Right Sump



Beginning To  
Cut Crosscut



First Cut Right  
Crosscut



First Cut Left  
Crosscut

