after the effective date of this AD, perform a detailed inspection to detect contamination of the pitot-TAT relays and clean the relay/ connector pins and sockets, in accordance with the Accomplishment Instructions ("PART I") of the service bulletin. If any contamination remains after cleaning: Prior to further flight, replace each contaminated relay, relay socket, and relay socket contact with a new part, in accordance with the service bulletin.

Note 2: For the purposes of this AD, a detailed inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

Inspection of FADEC Interface Resistor Modules

(b) For airplanes identified in paragraph 1.A.(3) ("PART III") of EMBRAER Service Bulletin 145–30–0032, Change 02, dated December 3, 2001: Within 400 flight hours after the effective date of this AD, perform a detailed inspection to detect contamination (including moisture and corrosion) of the left- and right-hand FADEC electronic interface resistor modules, in accordance with the Accomplishment Instructions of EMBRAER Service Bulletin 145–76–0003, dated April 22, 2002. Then do the applicable corrective actions specified in paragraphs (b)(1) and (b)(2) of this AD.

(1) If any contamination is found during the inspection: Before further flight, clean the resistor modules and/or their respective electrical connector pins, in accordance with Service Bulletin 145–76–0003, dated April 22, 2002.

(2) If any contamination remains after cleaning the modules and pins as specified in paragraph (b)(1) of this AD: Before further flight, replace the modules and connectors with new parts, as applicable, in accordance with Service Bulletin 145–76–0003, dated April 22, 2002.

(3) Following accomplishment of any corrective action specified in paragraph (b)(1) or (b)(2) of this AD: Before further flight, perform the ohmic resistance test of the leftand right-hand FADEC electronic interface resistor modules, and accomplish applicable troubleshooting procedures, in accordance with Service Bulletin 145–76–0003, dated April 22, 2002.

Console Panel Sealing

(c) For airplanes identified in paragraph 1.A.(2) ("PART II") of EMBRAER Service Bulletin 145–30–0032, Change 02, dated December 3, 2001: Before further flight following accomplishment of the requirements of paragraph (a) of this AD, modify the seal between the cockpit console panels and the storm window by applying PVC foam adhesive tape and sealant, in accordance with the Accomplishment Instructions ("PART II") of the service bulletin.

Protective Sheet Installation

(d) For airplanes identified in paragraph 1.A.(3) ("PART III") of EMBRAER Service Bulletin 145–30–0032, Change 02, dated December 3, 2001: Before further flight following accomplishment of the requirements of paragraph (b) of this AD, install new protective sheets at the relay supports in accordance with the Accomplishment Instructions ("PART III") of the service bulletin.

Alternative Methods of Compliance

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 4: The subject of this AD is addressed in Brazilian airworthiness directives 2001– 05–01R1, dated February 6, 2002, and 2002– 10–03, dated October 24, 2002.

Issued in Renton, Washington, on February 21, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. 03–4738 Filed 2–27–03; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Coast Guard

33 CFR Part 117

[CGD07-02-147]

RIN 2115-AE47

Drawbridge Operation Regulations; Commercial Boulevard Bridge (SR 870), Atlantic Intracoastal Waterway, mile 1059.0, Lauderdale-by-the-Sea, Broward County, FL

AGENCY: Coast Guard, DOT. **ACTION:** Notice of proposed rulemaking.

SUMMARY: The Coast Guard proposes to change the operating regulations of the Commercial Boulevard bridge (SR 870) across the Atlantic Intracoastal Waterway, mile 1059.0 in Lauderdale-

by-the-Sea, Florida. This proposed rule would require the bridge to open on signal, except that from 7 a.m. to 6 p.m. daily, the bridge would be required to open only on the hour, 20 minutes after the hour, and 40 minutes after the hour. This action is intended to improve the movement of vehicular traffic while providing for the reasonable needs of navigation.

DATES: Comments and related material must reach the Coast Guard on or before April 29, 2003.

ADDRESSES: You may mail comments and related material to Commander (obr), Seventh Coast Guard District, 909 S.E. 1st Avenue, Room 432, Miami, FL 33131. Comments and material received from the public, as well as documents indicated in this preamble as being available in the docket, are part of the docket and are available for inspection or copying at Commander (obr), Seventh Coast Guard District, 909 S.E. 1st Avenue, Room 432, Miami, FL 33131 between 8 a.m. and 4 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Mr.

Michael Lieberum, Project Officer, Seventh Coast Guard District, Bridge Branch, at (305) 415–6744.

SUPPLEMENTARY INFORMATION:

Request for Comments

We encourage you to participate in this rulemaking by submitting comments and related material. If you do so, please include your name and address, identify the docket number for this rulemaking [CGD07-02-147], indicate the specific section of this document to which each comment applies, and give the reason for each comment. Please submit all comments and related material in an unbound format, no larger than 81/2 by 11 inches, suitable for copying. If you would like to know they reached us, please enclose a stamped, self-addressed postcard or envelope. We will consider all comments and material received during the comment period. We may change this proposed rule in view of them.

Public Meeting

We do not now plan to hold a public meeting. You may submit a request for a meeting by writing to Bridge Branch, Seventh Coast Guard District, 909 S.E. 1st Avenue, Room 432, Miami, FL 33131, explaining why one would be beneficial. If we determine that one would aid this rulemaking, we will hold one at a time and place announced by a later notice in the **Federal Register**.

Background and Purpose

On January 3, 2002, the City of Fort Lauderdale requested that the Coast Guard review the existing regulation of the Commercial Boulevard bridge (SR 870) because the City believed the existing regulations were not meeting the needs of vehicle traffic.

The existing regulation of the Commercial Boulevard bridge (SR 870), mile 1059.0, at Lauderdale-by-the-Sea, published in 33 CFR 117.261(ee), requires the draws to open on signal, except that, from November 1 through May 15, from 8 a.m. to 6 pm., Monday through Friday, the draws need open only on the hour, quarter-hour, halfhour, and three-quarter-hour, and from 8 a.m. to 6 p.m. on Saturdays, Sundays, and Federal holidays, the draws need open only on the hour, 20 minutes after the hour, and 40 minutes after the hour.

This proposed rule would make the seasonal openings effective year round. Traffic studies have shown that vehicular traffic has increased at this location year round and a seasonal schedule is no longer appropriate.

On March 18, 2002, the Coast Guard issued a temporary deviation published in the Federal Register (67 FR 11919, March 18, 2002). This deviation was effective from April 17, 2002 until July 16, 2002, and from 7 a.m. to 6 p.m., allowed the bridge to open on the hour, 20 minutes after the hour, and 40 minutes after the hour. We received 38 comments on this deviation, 31 were in favor of the 20-minute schedule and seven comments requested that the schedule be changed to an hour and half-hour schedule. Based on our evaluation of the comments received and neighboring bridge schedules, the Coast Guard proposes to make the 20minute schedule permanent. A 20minute schedule is necessary to keep vessel traffic on the waterway moving because the bridge immediately to the north of this bridge is on a 30-minute schedule and the bridge immediately to the south of this bridge is on a 20minute schedule. If this bridge were placed on a 30-minute schedule, vessels would experience a greater delay in traversing the waterway.

Discussion of Proposed Rule

This proposed rule would require the Commercial Boulevard bridge (SR 870), mile 1059.0, at Lauderdale-by-the-Sea, to open on signal; except that, from 7 a.m. to 6 p.m. daily, the draws need open only on the hour, 20 minutes after the hour, and 40 minutes after the hour.

Regulatory Evaluation

This proposed rule is not a "significant regulatory action" under

section 3(f) of Executive Order 12866 and does not require an assessment of potential costs and benefits under section 6(a)(3) of that Order. The Office of Management and Budget has not reviewed it under that Order. It is not "significant" under the regulatory policies and procedures of the Department of Transportation (DOT)(44 FR 11040, February 26, 1979). The Coast Guard expects the economic impact of this proposal to be so minimal that a full Regulatory Evaluation under paragraph 10(e) of the regulatory policies and procedures of DOT is unnecessary because this proposed rule only slightly modifies the existing bridge schedule and still provides for regular openings.

Small Entities

Under the Regulatory Flexibility Act (5 U.S.C. 601–612), we have considered whether this proposed rule would have a significant economic effect upon a substantial number of small entities. The term "small entities" comprises small business, not-for-profit organizations that are independently owned and operated and are not dominant in their fields, and governmental jurisdictions with populations of less than 50,000.

This proposed rule may affect the following entities, some of which may be small entities: the owners or operators of vessels intending to transit the Intracoastal Waterway in the vicinity of Commercial Boulevard bridge, persons intending to drive over the bridge, and nearby business owners. The Coast Guard certifies under 5 U.S.C. 605(b) that this proposed rule will not have a significant economic impact on a substantial number of small entities, because this proposed rule would only slightly modify the existing schedule and would still provide for regular openings.

If you think that your business, organization, or governmental jurisdiction qualifies as a small entity and that this proposed rule would have a significant economic impact on it, please submit a comment (see **ADDRESSES**) explaining why you think it qualifies and how and to what degree this proposed rule would economically effect it.

Assistance for Small Entities

Under section 213(a) of the Small Business Regulatory Enforcement Fairness Act of 1996 (Pub. L. 104–121), we want to assist small entities in understanding this proposed rule so that they can better evaluate its effects on them and participate in the rulemaking. If this proposed rule would affect your small business, organization, or

governmental jurisdiction and you have questions concerning its provisions or options for compliance, please consult the person listed under FOR FURTHER **INFORMATION CONTACT.** We also have a point of contact for commenting on actions by employees of the Coast Guard. Small businesses may send comments on the actions of Federal employees who enforce, or otherwise determine compliance with Federal regulations to the Small Business and Agriculture Regulatory Enforcement Ombudsman. The Ombudsman evaluates these actions annually and rates each agency's responsiveness to small business. If you wish to comment on actions by employees of the Coast Guard, call 1-888-REG-FAIR (1-888-734-3247).

Collection of Information

This proposed rule calls for no new collection of information requirements under the Paperwork Reduction Act of 1995 (44 U.S.C. 3501 -3520).

Federalism

A rule has implications for federalism under Executive Order 13132, Federalism, if it has a substantial direct effect on State or local governments and would either preempt State law or impose a substantial direct cost of compliance on them. We have analyzed this proposed rule under that Order and have determined that this rule does not have implications for federalism.

Unfunded Mandates Reform Act

The Unfunded Mandates Reform Act of 1995 (2 U.S.C. 1531–1538) requires Federal agencies to assess the effects of their discretionary regulatory actions. In particular, the Act addresses actions that may result in an expenditure by a State, local, or tribal government, in the aggregate, or by the private sector, of \$100,000,000 or more in any one year. Although this proposed rule will not result in such an expenditure, we do discuss the effects of this rule elsewhere in this preamble.

Taking of Private Property

This proposed rule will not affect a taking of private property or otherwise have taking implications under Executive Order 12630, Governmental Actions and Interference with Constitutionally Protected Property Rights.

Civil Justice Reform

This proposed rule meets applicable standards in sections 3(a) and 3(b)(2) of Executive Order 12988, Civil Justice Reform, to minimize litigation, eliminate ambiguity, and reduce burden.

Protection of Children

We have analyzed this proposed rule under Executive Order 13045, Protection of Children from Environmental Health Risks and Safety Risks. This proposed rule is not an economically significant rule and would not create an environmental risk to health or risk to safety that might disproportionately affect children.

Indian Tribal Governments

This proposed rule does not have tribal implications under Executive Order 13175, Consultation and Coordination with Indian Tribal Governments, because it would not have a substantial direct effect on one or more Indian tribes, on the relationship between the Federal Government and Indian tribes, or on the distribution of power and responsibilities between the Federal Government and Indian tribes.

Energy Effects

We have analyzed this proposed rule under Executive Order 13211, Actions **Concerning Regulations That** Significantly Affect Energy Supply, Distribution, or Use. We have determined that it is not a "significant energy action" under that order because it is not a "significant regulatory action" under Executive Order 12866 and is not likely to have a significant adverse effect on the supply, distribution, or use of energy. It has not been designated by the Administrator of the Office of Information and Regulatory Affairs as a significant energy action. Therefore, it does not require a Statement of Energy Effects under Executive Order 13211.

Environment

We have considered the environmental impact of this proposed rule and concluded that under figure 2– 1, paragraph 32(e) of Commandant Instruction M16475.1D, this proposed rule is categorically excluded from further environmental documentation. A "Categorical Exclusion Determination" is available in the docket where indicated under ADDRESSES.

List of Subjects in 33 CFR Part 117

Bridges.

For the reason discussed in the preamble, the Coast Guard proposes to amend 33 CFR part 117 as follows:

PART 117—DRAWBRIDGE OPERATION REGULATIONS

1. The authority citation for Part 117 continues to read as follows:

Authority: 33 U.S.C. 499; 49 CFR 1.46; 33 CFR 1.05–1(g); Section 117.255 also issued under authority of Pub. L. 102–587, 106 Stat. 5039.

2. Revise § 117.261(ee) to read as follows:

§117.261 Atlantic Intracoastal Waterway from St. Marys River to Key Largo.

(ee) Commercial Boulevard bridge (SR 870), mile 1059.0, at Lauderdale-by-the-Sea. The draws shall open on signal, except that, from 7 a.m. to 6 p.m. daily, the draws need open only on the hour, 20 minutes after the hour, and 40 minutes after the hour.

* * * *

Dated: February 10, 2003.

James S. Carmichael,

Rear Admiral, U.S. Coast Guard, Commander, Seventh Coast Guard District. [FR Doc. 03–4760 Filed 2–27–03; 8:45 am] BILLING CODE 4910–15–P

DEPARTMENT OF TRANSPORTATION

Coast Guard

33 CFR Part 147

[CGD08-02-045]

RIN 2115-AG54

Safety Zone for Outer Continental Shelf Facility in the Gulf of Mexico for Viasca Knoll 915

AGENCY: Coast Guard, DOT. **ACTION:** Notice of proposed rulemaking.

SUMMARY: The Coast Guard proposes to establish a safety zone around a petroleum and gas production facility in Viasca Knoll 915 of the Outer Continental Shelf in the Gulf of Mexico. The facility needs to be protected from vessels operating outside the normal shipping channels and fairways, and placing a safety zone around this facility would significantly reduce the threat of allisions, oil spills and releases of natural gas. The proposed regulation would prevent all vessels from entering or remaining in the specified area around the facility except for the following: an attending vessel; a vessel under 100 feet in length overall not engaged in towing; or a vessel authorized by the Eighth Coast Guard District Commander.

DATES: Comments and related material must reach the Coast Guard on or before April 29, 2003.

ADDRESSES: You may mail comments and related material to Commander, Eighth Coast Guard District (m), Hale Boggs Federal Bldg., 501 Magazine

Street, New Orleans, LA 70130, or comments and related material may be delivered to Room 1341 at the same address between 8 a.m. and 3:30 p.m., Monday through Friday, except Federal holidays. The telephone number is (504) 589-6271. Commander, Eighth Coast Guard District (m) maintains the public docket for this rulemaking. Comments and material received from the public, as well as documents indicated in this preamble as being available in the docket, will become part of this docket and will be available for inspection or copying at Commander, Eighth Coast Guard District (m) between 8 a.m. and 3:30 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT:

Lieutenant (LT) Karrie Trebbe, Project Manager for Eighth Coast Guard District Commander, Hale Boggs Federal Bldg., 501 Magazine Street, New Orleans, LA 70130, telephone (504) 589–6271.

SUPPLEMENTARY INFORMATION:

Requests for Comments

We encourage you to participate in this rulemaking by submitting comments and related material. If you do so, please include your name and address, identify the docket number for this rulemaking [CGD08-02-035], indicate the specific section of this document to which each comment applies, and give the reason for each comment. Please submit all comments and related material in an unbound format, no larger than $8^{1/2}$ by 11 inches, suitable for copying. If you would like to know they reached us, please enclose a stamped, self-addressed postcard or envelope. We will consider all comments and material received during the comment period. We may change this proposed rule in view of them.

Public Meeting

We do not plan to hold a public meeting. However, you may submit a request for a meeting by writing to Commander, Eighth Coast Guard District (m) at the address under **ADDRESSES** explaining why one would be beneficial. If we determine that a public meeting would aid this rulemaking, we will hold one at a time and place announced by a later notice in the **Federal Register**.

Background and Purpose

The Coast Guard proposes to establish a safety zone around a petroleum producing facility in the Gulf of Mexico: Marlin Tension Leg Platform (Marlin TLP), Viasca Knoll 915 (VK 915), located at position 29°06'27.46" N, 87°56'37.14" W.