RESEARCH TRIANGLE INSTITUTE




National Laboratory Certification Program

December 7, 1998

0519
Dr. Samuel E. Mathews
Baptist Medical Center-Toxicology Lab
9601 I-630, Exit 7
Little Rock, AR 72205-7299

Dear Dr. Mathews:


The enclosed critique was developed from the inspection reports of the inspectors who conducted the twelfth maintenance inspection of your laboratory under the National Laboratory Certification Program (NLCP). Based upon our review of these reports, the laboratory's performance in this inspection is acceptable. Before RTI will recommend continued certification of your laboratory, the laboratory must successfully complete the following corrective actions:



F. The Chain of Custody, Accessioning, and Security section



J. The Quality Control and Standards section:












N.



Dr. Mathews Page 3 of 3 12/07/98

The laboratory must submit, within 30 calendar days of receipt of this letter, documentation to demonstrate that corrective actions have been implemented to address the issues described above. In responding to these issues, please organize the material in your document in accordance with the sections and item numbers as listed in this correspondence. Once these issues have been successfully addressed, RTI will recommend to the Department of Health and Human Services (HHS) that your laboratory's certification be continued. The laboratory must also review the enclosed critique and take all necessary corrective actions. All corrective actions must be implemented within 30 days of the receipt of this correspondence and will be reviewed at the next inspection.

If you have any questions or if we can be of further assistance, please call me at (919) 541-6176 or Dr. Michael Baylor at (919) 541-7043.

Sincerely,

Susan Crumpton

NLCP Inspection Analyst

Enclosure

cc: Project Files/M12

NATIONAL LABORATORY CERTIFICATION PROGRAM

Document Review and Critique

Laboratory I.D. Number: 0519

Document No. Final

Laboratory: Baptist Medical Center

Location: Little Rock, AR

Document Reviewed: [] Application Form

[XX] Inspection Report #M12 Date: October 29, 1998

[] Other _____

Status: [] Highly Acceptable [XX] Acceptable [] Failure

Inspection reports, from the inspectors who conducted the National Laboratory Certification Program (NLCP) inspection, have been carefully reviewed and found to provide sufficient information to judge that the laboratory has met the standards required for the inspection phase of the Program, pending the submission of evidence that appropriate corrective action has been taken.

There were a number of comments and observations generated as a result of the inspection that are detailed on the following pages for the attention of the laboratory before its next inspection.

NLCP + Research Triangle Institute

Page 1

The following comments were noted, and appear in the same order as the corresponding questions in the Laboratory Inspection Report:

Section E. Standard Operating Procedures - Procedures Manual





Section F. Chain-of-Custody, Accessioning and Security



Section G. Records Audit



Section H. Personnel



Section I. Reagents





Section K. Reporting




NLCP • Research Triangle Institute

Section L. Equipment and Maintenance

Section M. Immunoassay

Section N. Gas Chromatography/Mass Spectrometry








January 7, 1999

Ms. Susan Crumpton
National Laboratory Certification Program
Research Triangle Institute
3040 Cornwallis Road
Research Triangle Park, NC 27709-2194


Dear Ms. Crumpton:

The Burnish College and the second

Enclosed with this letter is our documentation of actions taken in response to your inspection critique dated December 7, 1998. I have organized the items to correspond with your summary.







If there are any questions or if additional documentation is needed, please contact me at 501-202-2783, and we will comply as expeditiously as possible.

Samuel E. Mathews, Ph.D. Responsible Person






National Laboratory Certification Program

February 17, 1999

0519
Dr. Samuel E. Mathews
Baptist Medical Center-Toxicology Lab
9601 I-630, Exit 7
Little Rock, AR 72205-7299

Dear Dr. Mathews:

We have reviewed the material submitted in your correspondence of January 7 and February 12, 1999, provided in final response to issues raised during the twelfth maintenance inspection of your laboratory as originally outlined in our correspondence of December 7, 1999. The following is a review of the material submitted:







The laboratory submitted some original training documents concerning revised SOPs. We have made copies for our records and are returning the originals to the laboratory.

Based upon our review of the material submitted, RTI will recommend to the Department of Health and Human Services (HHS) that the laboratory continue to be certified under the National Laboratory Certification Program (NLCP). All corrective actions must be implemented within 30 days of receipt of this correspondence and will be reviewed during the next inspection.

If you have any questions or if we can be of assistance, please call me at (919) 541-6176 or Dr. Michael Baylor at (919) 541-7043.

Sincerely,

Susan D. Crumpton NLCP Inspection Analyst

cc: Project Files/M12




National Laboratory Certification Program

June 10, 1999

0519
Dr. Samuel E. Mathews
Baptist Medical Center-Toxicology Lab
9601 I-630, Exit 7
Little Rock, AR 72205-7299

Dear Dr. Mathews:

The enclosed critique was developed from the inspection reports of the inspectors who conducted the thirteenth maintenance inspection of your laboratory under the National Laboratory Certification Program (NLCP). Based upon our review of these reports, the laboratory's performance in this inspection is highly acceptable. However, the laboratory must correct/clarify the following issues raised:



RTI is recommending to the Department of Health and Human Services (HHS) that the laboratory's certification be continued based upon its acceptable performance in the inspection phase of the program. The laboratory must take steps to correct the issues cited above. The laboratory must also review the enclosed critique and take all necessary corrective actions: All corrective actions must be implemented within 30 days of receipt of this correspondence. It is not necessary for the laboratory to submit a

Dr. Mathews Page 2 of 2 06/10/99

written response to RTI. All corrective actions will be reviewed during the next inspection.

If you have any questions or if we can be of further assistance, please call me at (919) 541-6176 or Dr. Michael Baylor at (919) 541-7043.

Sincerely,

Susan Crumpton

NLCP Inspection Analyst

Enclosure

cc: Project Files/M13


NATIONAL LABORATORY CERTIFICATION PROGRAM Document Review and Critique Laboratory I.D. Number: 0519 Document No. Fina Baptist Medical Center—Toxicology Laboratory Laboratory: Location: Little Rock, AR Document Reviewed:] Application Form [XX] Inspection Report #M13 Date: 29 April 1999] Other _ Status: [XX] Highly Acceptable] Acceptable] Unacceptable] Failure

A review of the National Laboratory Certification Program (NLCP) inspection reports has been completed. It is the judgment of the reviewers that the laboratory has met the standards required for the inspection phase of the Program.

There were a number of comments and observations generated as a result of the inspection that are detailed on the following pages for the attention of the laboratory before its next inspection.

The following comments were noted, and appear in the same order as the corresponding questions in the Laboratory Inspection Report:

Section E. Standard Operating Procedures - Procedures Manual



Section F. Chain-of-Custody, Accessioning, and Security



Section G. Quality Control




Section H. Initial Tests

and the second s

Section I. Confirmatory Tests

The second secon

Section J. Records Audit



Section K. Reporting

Section L. Computers, Software, and LIMS

Section M. Equipment and Maintenance

Section N. Personnel






National Laboratory Certification Program

December 2, 1999

0519
Dr. Samuel E. Mathews
Baptist Medical Center-Toxicology Lab
9601 I-630, Exit 7
Little Rock, AR 72205-7299

Dear Dr. Mathews

The enclosed critique was developed from the inspection reports of the inspectors who conducted the fourteenth maintenance inspection of your laboratory under the National Laboratory Certification Program (NLCP). Based upon our review of these reports, the laboratory's performance in this inspection is highly acceptable. However, the inspection team had some areas of concern which are detailed in this cover letter and attached critique.



RTI is recommending to the Department of Health and Human Services (HHS) that the laboratory's certification be continued based upon its acceptable performance in the inspection phase of the program. The laboratory must take steps to correct the issues cited above. The laboratory must also review the enclosed critique and take all necessary corrective actions. All corrective actions must be implemented within 30 days of receipt of this correspondence. It is *not necessary* for the laboratory to submit a written response to RTI. All corrective actions will be reviewed during the next inspection.

Dr. Mathews Page 2 of 2 12/02/99

If you have any questions or if we can be of further assistance, please call me at (919) 541-7265 or Dr. Michael Baylor at (919) 541-7043.

Sincerely,

Deborah J. Denson NLCP Inspection Analyst

Enclosure

cc: Project Files/M14

NATIONAL LABORATORY CERTIFICATION PROGRAM

Document Review and Critique

Laboratory I.D. Number: <u>0519</u>

Document No. Final

Laboratory:

Baptist Medical Center—Toxicology Laboratory

Location:

Little Rock, AR

Document Reviewed:

[] Application Form [XX] Inspection Report #M14

4

Date: 28 October 1999

[] Other

Status:

[XX] Highly Acceptable

] Acceptable

[] Unacceptable [] Failure

A review of the National Laboratory Certification Program (NLCP) inspection reports has been completed. It is the judgment of the reviewers that the laboratory has met the standards required for the inspection phase of the Program.

There were a number of comments and observations generated as a result of the inspection that are detailed on the following pages for the attention of the laboratory before its next inspection.

The following comments were noted, and appear in the same order as the corresponding questions in the Laboratory Inspection Report:

Section E. Standard Operating Procedures - Procedures Manual




Section F. Chain-of-Custody, Accessioning, and Security




Section G. Quality Control

Section H. Initial Tests



Section I. Confirmatory Tests



Section J. Records Audit

Section K. Reporting

Section L. Computers, Software, and LIMS

Section M. Equipment and Maintenance

Section N. Personnel




National Laboratory Certification Program

June 9, 2000

0519 Dr. Samuel E. Mathews Baptist Medical Center-Toxicology Lab 9601 I-630, Exit 7 Little Rock, AR 72205-7299

Dear Dr. Mathews:

The enclosed critique was developed from the inspection reports of the inspectors who conducted the fifteenth maintenance inspection of your laboratory under the National Laboratory Certification Program (NLCP). Based upon our review of these reports, the laboratory's performance in this inspection is highly acceptable. The inspection team had some areas of concern, which are detailed in this cover letter and attached critique.







Dr. Mathews June 9, 2000 Page 2 of 2

RTI is recommending to the Department of Health and Human Services (HHS) that the laboratory's certification be continued based upon its acceptable performance in the inspection phase of the program. The laboratory must take steps to correct the issues cited above. The laboratory must also review the enclosed critique and take all necessary corrective actions. All corrective actions must be implemented within 30 days of receipt of this correspondence. It is not necessary for the laboratory to submit a written response to RTI. All corrective actions will be reviewed during the next inspection.

If you have any questions or if we can be of further assistance, please call me at (919) 541-7265 or Dr. Michael R. Baylor at (919) 541-7043.

Sincerely,

Deborah J. Denson NLCP Technical Analyst

Enclosure

cc: Project Files/M15

NATIONAL LABORATORY CERTIFICATION PROGRAM

Document Review and Critique

Laboratory I.D. Number: 0519

Document No. Final

Laboratory:

Baptist Medical Center—Toxicology Laboratory

Location:

Little Rock, AR

Document Reviewed:

[] Application Form

[XX] Inspection Report #M15 Date: 27April 2000

[] Other __

Status:

[XX] Highly Acceptable

] Acceptable

] Unacceptable


1 Failure


A review of the National Laboratory Certification Program (NLCP) inspection reports has been completed. It is the judgment of the reviewers that the laboratory has met the standards required for the inspection phase of the Program.

There were a number of comments and observations generated as a result of the inspection that are detailed on the following pages for the attention of the laboratory before its next inspection.

The following comments were noted, and appear in the same order as the corresponding questions in the Laboratory Inspection Report:

Section E. Standard Operating Procedures - Procedures Manual





Section F. Chain-of-Custody, Accessioning, and Security



Lab ID# 0519

Section H. Initial Tests



Section I. Confirmatory Tests



Section J. Records Audit




Section K. Reporting



Section L. Computers, Software, and LIMS



Section M. Equipment and Maintenance



NLCP ◆ Research Triangle Institute

Ver. Final

١

Lab ID# 0519



Section N. Personnel




National Laboratory Certification Program


December 20, 2000

0519
Dr. Samuel E. Mathews
Baptist Medical Center-Toxicology Lab
9601 I-630, Exit 7
Little Rock, AR 72205-7299

Dear Dr. Mathews:

The enclosed critique was developed from the inspection reports of the inspectors who conducted the sixteenth maintenance inspection of your laboratory under the National Laboratory Certification Program (NLCP). Based upon our review of these reports, the laboratory's performance in this inspection is highly acceptable. The inspection team had some areas of concern, which are detailed in this cover letter and attached critique.









G. The Quality Control section



K. The Reporting section



N. The Personnel section

Dr. Mathews December 20, 2000 Page 3 of 3

The laboratory must submit, within 30 calendar days of receipt of this letter, documentation to demonstrate that corrective actions have been implemented to address the issues raised. In responding to these issues, please organize the material in your document in accordance with the sections and item numbers as listed in this correspondence. Once these issues have been successfully addressed, RTI will recommend to the Department of Health and Human Services (HHS) that the laboratory's certification be continued. The laboratory must also review the enclosed critique and take all necessary corrective actions. All corrective actions must be implemented within 30 days receipt of this correspondence and will be reviewed at the next inspection.

If you have any questions or if we can be of further assistance, please call me at (919) 541-7265 or Dr. Michael R. Baylor at (919) 541-7043.

Sincerely,

Deborah J. Denson NLCP Technical Analyst

Deborah Flenson

Enclosure

cc: Project Files/M16



NATIONAL LABORATORY CERTIFICATION PROGRAM

Document Review and Critique

Laboratory I.D. Number: <u>0519</u> Document No. Final

Laboratory:

Baptist Medical Center-Toxicology Laboratory

Location:

Little Rock, AR

Document Reviewed:

] Application Form

[XX] Inspection Report # M16

] Other _____

Date: 26 October 2000

Status:

[XX] Highly Acceptable

[] Unacceptable


[] Acceptable [] Failure

A review of the National Laboratory Certification Program (NLCP) inspection reports has been completed. It is the judgment of the reviewers that the laboratory has met the standards required for the inspection phase of the Program.

There were a number of comments and observations generated as a result of the inspection that are detailed on the following pages for the attention of the laboratory before its next inspection.


The following comments were noted, and appear in the same order as the corresponding questions in the Laboratory Inspection Report:

Section E. Standard Operating Procedures - Procedures Manual




Section F. Chain-of-Custody, Accessioning, and Security






Section G. Quality Control



Section H. Initial Tests

Section I. Confirmatory Tests



Section J. Records Audit





Section L. Computers, Software, and LIMS

Section M. Equipment and Maintenance

Section N. Personnel

Page 4



Baptist

MEDICAL CENTER

9601 Interstate 630, Exit 7 Little Rock, AR 72205-7299 501 202-2000

January 20, 2001

Ms. Deborah J. Denson NLCP/RTI 3040 Cornwallis Road Research Triangle Park, NC 27709

Dear Ms. Denson:

This letter is our response to the items listed in your letter to us of December 20, 2000, reviewing issues brought up in our sixteenth maintenance inspection. As requested in your letter, the responses listed here will be presented in the same order and labeled as in your communication.





If there are any additional questions or issues to be addressed, please do not hesitate to notify me at 501-202-2783 or at

Sincerely,

Samuel E. Mathews, Ph.D., DABCC

Responsible Person






National Laboratory Certification Program

January 29, 2001

0519 Dr. Samuel E. Mathews Baptist Medical Center-Toxicology Lab 9601 I-630, Exit 7 Little Rock, AR 72205-7299

Dear Dr. Mathews:

We have reviewed the material provided in your correspondence of January 20, 2001, submitted in response to issues raised during the sixteenth maintenance inspection of your laboratory as outlined in our correspondence of December 20, 2000. The information submitted by the laboratory appears to demonstrate that appropriate corrective actions have been completed to address the issues raised. The following is a review of the material submitted:





Dr. Mathews January 29, 2001 Page 2 of 2

Based upon our review of the material submitted, RTI is recommending to the Department of Health and Human Services (HHS) that your laboratory continues to be certified under the National Laboratory Certification Program. All corrective actions must be implemented within 30 days of the receipt of this correspondence and will be reviewed during the next inspection.

If you have any questions or if we can be of further assistance, please call me at (919) 541-7265 or Michael R. Baylor, Ph.D. at (919) 541-7043.

Sincerely,

Deborat J. Denson

NLCP Technical Analyst

cc: Project Files/M16