

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 43

National Average: 43

2x National Average: 86

National Median: 21

Average for Selected Dockets: 43

Facility Name: Oconee 3 Docket (050- 00287)

Details	Department	Work Type	Docket/Report
Management and Supervision / IR			
32 - Supervision / command and control LTA	E - Electrical	M - Maint / Repair	050-00287/2004-004
40 - Individual Corrective Action LTA	E - Electrical	M - Maint / Repair	050-00287/2004-004
40 - Individual Corrective Action LTA	G - Engineering	M - Maint / Repair	050-00287/2004-009
41 - Action not begun or untimely	E - Electrical	M - Maint / Repair	050-00287/2004-004
41 - Action not begun or untimely	G - Engineering	G - Design	050-00287/2004-003
41 - Action not begun or untimely	G - Engineering	M - Maint / Repair	050-00287/2004-009
44 - Corrective Action program LTA	G - Engineering	M - Maint / Repair	050-00287/2004-011
44 - Corrective Action program LTA	G - Engineering	M - Maint / Repair	050-00287/2004-011
44 - Corrective Action program LTA	G - Engineering	V - Troubleshooting	050-00287/2004-011
47 - Root Cause LTA	G - Engineering	G - Design	050-00287/2004-011
47 - Root Cause LTA	G - Engineering	M - Maint / Repair	050-00287/2004-011
47 - Root Cause LTA	G - Engineering	M - Maint / Repair	050-00287/2004-011
48 - Audits or problem identification LTA	G - Engineering	G - Design	050-00287/2004-011
Number of Items for this Docket: 13			
Percent of Total for this Docket: 30			

Procedures and Reference Document / IR

12 - Procedure technical content LTA	G - Engineering	G - Design	050-00287/2003-005
12 - Procedure technical content LTA	G - Engineering	M - Maint / Repair	050-00287/2003-005
12 - Procedure technical content LTA	O - Operations	O - Control Room Ops	050-00287/2004-012
12 - Procedure technical content LTA	P - Procedure Writers	P - Procedure Dev	050-00287/2003-005
12 - Procedure technical content LTA	P - Procedure Writers	P - Procedure Dev	050-00287/2004-003
Number of Items for this Docket: 5			
Percent of Total for this Docket: 12			

Work Factors / IR

81 - Work Package Quality LTA	G - Engineering	F - Modification	050-00287/2004-007
83 - Work practice or craft skill LTA	E - Electrical	M - Maint / Repair	050-00287/2004-004
83 - Work practice or craft skill LTA	E - Electrical	M - Maint / Repair	050-00287/2004-004
83 - Work practice or craft skill LTA	H - Health Physics	H - Health Physics	050-00287/2003-005
83 - Work practice or craft skill LTA	M - Mechanical	H - Health Physics	050-00287/2004-004
83 - Work practice or craft skill LTA	M - Mechanical	H - Health Physics	050-00287/2004-004
83 - Work practice or craft skill LTA	M - Mechanical	H - Health Physics	050-00287/2004-004
83 - Work practice or craft skill LTA	M - Mechanical	H - Health Physics	050-00287/2004-004

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 43

National Average: 43

2x National Average: 86

National Median: 21

Average for Selected Dockets: 43

Facility Name: Oconee 3 Docket (050- 00287)

Details	Department	Work Type	Docket/Report
Work Factors / IR			
83 - Work practice or craft skill LTA	O - Operations	H - Health Physics	050-00287/2003-005
83 - Work practice or craft skill LTA	U - Unknown	H - Health Physics	050-00287/2004-004
83 - Work practice or craft skill LTA	U - Unknown	H - Health Physics	050-00287/2004-004
83 - Work practice or craft skill LTA	U - Unknown	H - Health Physics	050-00287/2004-004
92 - Self check LTA	M - Mechanical	M - Maint / Repair	050-00287/2004-002
93 - Awareness or attention LTA	M - Mechanical	M - Maint / Repair	050-00287/2004-002
93 - Awareness or attention LTA	O - Operations	H - Health Physics	050-00287/2003-005
Number of Items for this Docket: 15			
Percent of Total for this Docket: 35			
Management and Supervision / LER			
33 - Management expectations or directions LTA	M - Mechanical	M - Maint / Repair	050-00287/2004-001-00
33 - Management expectations or directions LTA	O - Operations	B - Bal of Plant Ops	050-00287/2004-004-00
Number of Items for this Docket: 2			
Percent of Total for this Docket: 5			
Procedures and Reference Document / LER			
11 - No procedure / reference documents	M - Mechanical	M - Maint / Repair	050-00287/2004-001-00
12 - Procedure technical content LTA	M - Mechanical	M - Maint / Repair	050-00287/2004-001-00
12 - Procedure technical content LTA	O - Operations	B - Bal of Plant Ops	050-00287/2004-004-00
Number of Items for this Docket: 3			
Percent of Total for this Docket: 7			
Training / LER			
02 - Training LTA	O - Operations	B - Bal of Plant Ops	050-00287/2004-004-00
02 - Training LTA	O - Operations	B - Bal of Plant Ops	050-00287/2004-004-00
Number of Items for this Docket: 2			
Percent of Total for this Docket: 5			
Work Factors / LER			
82 - Briefing, prep. or turnover LTA	O - Operations	B - Bal of Plant Ops	050-00287/2004-004-00
84 - Non-conserv. decision / Questioning LTA	O - Operations	B - Bal of Plant Ops	050-00287/2004-004-00

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

**Total Number of Hits: 43
National Average: 43
2x National Average: 86
National Median: 21
Average for Selected Dockets: 43**

Facility Name: Oconee 3 Docket (050- 00287)

Details	Department	Work Type	Docket/Report
Work Factors / LER			
92 - Self check LTA	M - Mechanical	M - Maint / Repair	050-00287/2004-001-00
Number of Items for this Docket: 3			
Percent of Total for this Docket: 7			

Total Items for this Docket: 43
