

Combined IR/ER/LER Report
Docket: 50-334 BEAVER VALLEY 1

Total Number of Hits in Date Range: 39
From 01/01/2002 to 01/01/2003
2x National Average: 58

Details	Department	Work Type	Docket/Report
Communications IR			
Number of items: 2			
Percent of total: 5.13			
53-Communication LT	I-Instrumentation & V-Troubleshooting		50-334/2001010
	I-Instrumentation &		
55-Communication Eq	D-Emergency Plannin D-Emergency Drill		50-334/2002003
	D-Emergency Plannin		
Communications ER			
Number of items: 0			
Percent of total: 0			
Communications LER			
Number of items: 1			
Percent of total: 2.56			
53-Communication LT	P-Procedure Writers P-Procedure Dev		50-412/200200300
	P-Procedure Writers		
Human-System Interface and Environm IR			
Number of items: 0			
Percent of total: 0			
Human-System Interface and Environm ER			
Number of items: 0			
Percent of total: 0			
Human-System Interface and Environm LER			
Number of items: 0			
Percent of total: 0			
Management and Supervision IR			
Number of items: 11			
Percent of total: 28.21			
40-Individual Corre	G-Engineering	Z-Other	50-334/2001010
36-Scheduling and p	W-Work Control / Sc	M-Maint / Repair	50-334/2001010
47-Root Cause LTA	G-Engineering	M-Maint / Repair	50-334/2002002
40-Individual Corre	D-Emergency Plannin	D-Emergency Drill	50-334/2002003
48-Audits or proble	Q-QA/QC	D-Emergency Drill	50-334/2002003
40-Individual Corre	G-Engineering	M-Maint / Repair	50-334/2002005
41-Action not begun	G-Engineering	M-Maint / Repair	50-334/2002005
47-Root Cause LTA	G-Engineering	G-Design	50-334/2002012
47-Root Cause LTA	G-Engineering	G-Design	50-334/2002012
47-Root Cause LTA	G-Engineering	G-Design	50-334/2002012
40-Individual Corre	G-Engineering	G-Design	50-334/2002012
Management and Supervision ER			
Number of items: 0			
Percent of total: 0			
Management and Supervision LER			
Number of items: 1			

Percent of total: 2.56

47-Root Cause LTA I-Instrumentation & V-Troubleshooting 50-334/200200200

Organizational Issues IR

Number of items: 0

Percent of total: 0

Organizational Issues ER

Number of items: 0

Percent of total: 0

Organizational Issues LER

Number of items: 0

Percent of total: 0

Procedures and Reference Document IR

Number of items: 3

Percent of total: 7.69

Page: 1 Date:05/13/2003

Combined IR/ER/LER Report

Docket: 50-334 BEAVER VALLEY 1

Total Number of Hits in Date Range: 39

From 01/01/2002 to 01/01/2003

2x National Average: 58

Details	Department	Work Type	Docket/Report
Procedures and Reference Document IR			
Number of items: 3			
Percent of Total: 7.69			
11-No procedure / r	D-Emergency Plannin	D-Emergency Drill	50-334/2002003
11-No procedure / r	D-Emergency Plannin	D-Emergency Drill	50-334/2002003
12-Procedure techni	G-Engineering	P-Procedure Dev	50-334/2002012

Procedures and Reference Document ER

Number of items: 0

Percent of total: 0

Procedures and Reference Document LER

Number of items: 6

Percent of total: 15.38

14-Document develop	P-Procedure Writers	P-Procedure Dev	50-334/200200100
12-Procedure techni	P-Procedure Writers	P-Procedure Dev	50-412/200200300
12-Procedure techni	P-Procedure Writers	P-Procedure Dev	50-412/200200300
13-Procedure has hu	P-Procedure Writers	P-Procedure Dev	50-412/200200301
12-Procedure techni	P-Procedure Writers	P-Procedure Dev	50-412/200200301
11-No procedure / r	P-Procedure Writers	P-Procedure Dev	50-412/200200301

Training IR

Number of items: 0

Percent of total: 0

Training ER

Number of items: 0

Percent of total: 0

Training LER

Number of items: 0
 Percent of total: 0

Work Factors IR

Number of items: 11
 Percent of total: 28.21

82-Briefing, prep.	G-Engineering	T-Testing	50-334/2001010
82-Briefing, prep.	G-Engineering	T-Testing	50-334/2001010
93-Awareness or att	G-Engineering	T-Testing	50-334/2001010
83-Work practice or	I-Instrumentation &	V-Troubleshooting	50-334/2001010
93-Awareness or att	I-Instrumentation &	A-Administrative	50-334/2001010
88-Tag outs LTA	W-Work Control / Sc	M-Maint / Repair	50-334/2001010
83-Work practice or	E-Electrical	M-Maint / Repair	50-334/2001010
83-Work practice or	E-Electrical	M-Maint / Repair	50-334/2001010
84-Non-conserv. dec	G-Engineering	M-Maint / Repair	50-334/2002002
88-Tag outs LTA	O-Operations	M-Maint / Repair	50-334/2002002
83-Work practice or	D-Emergency Plannin	F-Modification	50-334/2002003

Work Factors ER

Number of items: 0
 Percent of total: 0

Work Factors LER

Number of items: 4
 Percent of total: 10.26

83-Work practice or	G-Engineering	G-Design	50-334/200200100
	Page: 2	Date:05/13/2003	

Combined IR/ER/LER Report
 Docket: 50-334 BEAVER VALLEY 1

Total Number of Hits in Date Range: 39
 From 01/01/2002 to 01/01/2003
 2x National Average: 58

Details	Department	Work Type	Docket/Report
---------	------------	-----------	---------------

Work Factors LER

Number of items: 4
 Percent of Total: 10.26

84-Non-conserv. dec	O-Operations	V-Troubleshooting	50-334/200200200
92-Self check LTA	P-Procedure Writers	P-Procedure Dev	50-412/200200301
91-Verification / p	G-Engineering	P-Procedure Dev	50-412/200200301
	Page: 3	Date:05/13/2003	