TECHNICAL INSPECTION

To: Material Control Manager

F2-Electrical Department From: SECTION	_2/10/06 DATE
ALL INSPECTIONS AND EQUIPMENT CONDITION CODES (CC) ON DETERMINED BY THE UNDERSIGNED. Inspected By:	THIS FORM HAVE BEEN

REQUEST DISPOSITION INSTRUCTIONS FOR THE FOLOWING ITEMS.

ID or CP#	DESCRIPTION	DEFICIENCY	CC	PRICE
Radwaniyah Palace D9	Main Distribution Panel 100AMP	Panel is missing cable glands for termination, panel are not grounded, No dead man front or panels cover	B5 Servicenble - used , fair (w/qualificatio ns)	
LSF Office	Secondary Feeder Panel			
	Main Feeder Wire 25MM			
	Secondary Feeder Wire Circuits 2.5MM	Wire is not sized properly for the main breakers, incorrect thermal insulation coating on the wire does not meet BS or NBC 4X2.5MM no separate ground supplied to ground panel		
	220 V Outlets	21 outlets with broken covers and exposed wire jumped from outlet to outlet		
	220 V Fluorescent light Fixtures	l4 fixtures no diffusers or ballast covers, incorrect wiring light fixture being used as a junction box. Two light circuit tapped		

BROWN & ROOT PROPRIETARY DATA - SOURCE SELECTION INFORMATION -- SEE FAR 3.104

NOTE: In addition to protection under the Federal Acquisition Regulation 3.104, this document contains information which may be withheld from the public NOTE: In addition to protection under the Federal Acquisition Regulation 3.104, this document contains information which may be withheld from the public NOTE: In addition to protection under the Federal Acquisition Regulation 3.104, this document contains information with the Freedom of Information Act, 5 USC Section 552, because disclosure would cause a foresceable harm to an interest protected by one or more Exemptions with DoD 5100.7-R, and consider this information act in negarificate with DoD 5100.7-R, and consider this information act in negarificate the protected that any Government entity receiving this information act in negarificate the protection of the freedom of Information Act, 5 USC Section 552.

	off outlet circuit at the outlet	3
220 V A/C Disconnect	No disconnect for a/c unit plugged into outlet on the wall 7)	
External Light Fixtures	4 Light fixtures not working non weatherproof, exposed wiring	
 220 V Water Heater Disconnect	No disconnect present plugged into the wall outlet,3 tank not grounded	

CONDITION CODE (C	CC) DESCRIPTION
-------------------	-----------------

MANAGON COD		
A1	Serviceable - unused, good	
A2	Serviceable - unused, fair	
A3	Saviceable - unused, poor	
Λ4	Serviceable - used, good	
EA	Serviceable - used , fair	
Aδ	Serviceable - used, poor	
B1	Serviceable - unused, good (w/qualifications)	
B2	Serviceable - unused, fair (w/qualifications)	
D3	Serviceable - unused, honr (w/qualifications)	
B 4	Serviceable - used, good (w/qualifications)	
D 5	Serviceable - used, fair (w/qualifications)	
B 6	Serviceable - used, poor (w/qualifications)	·
97	Unserviceable - good, repairs required (reparable) 15% of acquisition cost	
F2	Inserviceable - fair, renairs required (reparable) 16% to 40% of acquisition	COST
F)	Unserviceable - poor, repairs required (reparable) 41% to 65% of acquisition	cost
ĦX	Unserviceable salvage (condemned)	
88	Property has no value except for its basic material content (Scrap)	
	•	

BROWN & ROOT PROPRIETARY DATA - SOURCE SELECTION INFORMATION - SEE FAR 3.104

NOTE: In addition to protection under the Federal Acquisition Regulation 3.104, this decreases contains information which may be withheld from the public because digitions as would cause a foresecable harm to an interest protected by one or more Exemptions of the Freedom of Information Act, 5 USC Sociiba 352.

Furthermore, is it requested that any Government auxily receiving this information and in secondance with Doth 5406.7-R, and consider this information as being for official act only (FOUO), and mark, handle and store this information so as to prevent unauthorized access.