

## Department of Energy

Richland Field Office P.O. Box 550 Richland, Washington 99352

95-TSD-130

SEP 29 1995

The Honorable John T. Conway Chairman Defense Nuclear Facilities Safety Board Suite 700 625 Indiana Avenue, NW Washington, D.C. 20004

Dear Mr. Conway:

COMPLETION OF REPORTING COMMITMENTS TO THE DEFENSE NUCLEAR FACILITY SAFETY BOARD (DNFSB) UNDER RECOMMENDATION 90-7

This letter is to advise the Defense Nuclear Facility Safety Board (DNFSB) that the U. S. Department of Energy, Richland Operations Office (RL), has completed the activities required to close out certain of the identified milestones developed in "Program Plan for Resolution of the Ferrocyanide Waste Tank Safety Issue at the Hanford Site" DOE/RL-94-110, in response to DNFSB Recommendation 90-7. The reports attached provide the technical basis for the determination that a particular milestone has been completed. Additional detail concerning each reported activity will be provided in the next quarterly report.

If you have any questions, please contact me on (509) 376-4550.

Sincerely,

Mary F. Jarvis, Ph.D., Project Director,

Tank Safety Analysis Division'

TSD: DHI

Enclosures

cc w/o encls:

T. P. Grumbly, EM-1, HQ

S. P. Cowan, EM-30, HQ

J. V. Antizzo, EM-37, HQ

M. A. Hunemuller, EM-38, HQ

C. O'Dell, EM-37, HQ

05 5 - 1 5 56