

Table 10. Net Withdrawals from Underground Storage, by State, 2006-2008
(Volumes in Million Cubic Feet)

State	2008							
	Total	December	November	October	September	August	July	June
Alabama	-4,452	1,582	-700	-3,208	692	715	-764	-4,056
Arkansas.....	563	1,025	82	-562	-895	-763	-737	-530
California.....	-22,777	45,873	-5,908	-13,840	-23,074	-6,874	-25,600	-34,527
Colorado.....	-2,155	4,076	1,254	-2,697	-5,921	-4,977	-4,392	-3,025
Illinois.....	-506	54,575	14,302	-36,054	-39,464	-40,321	-34,743	-36,126
Indiana.....	133	5,799	292	-2,488	-3,341	-3,743	-3,970	-3,644
Iowa.....	-2,274	22,004	466	-14,478	-15,965	-17,699	-12,800	-4,146
Kansas.....	-14,220	15,477	1,006	-3,595	-16,730	-12,807	-7,969	-11,754
Kentucky.....	4,689	16,638	3,634	-3,524	-4,390	-9,489	-9,088	-11,719
Louisiana.....	6,096	8,963	-9,063	-32,901	11,064	-17,234	-16,245	-16,344
Maryland.....	927	179	809	295	176	-2,663	-2,691	-1,156
Michigan.....	27,933	120,303	35,478	-27,433	-54,691	-74,836	-81,925	-75,403
Minnesota.....	99	198	-190	-233	-238	-301	-287	-238
Mississippi.....	-7,411	4,764	-3,144	-12,259	3,087	-4,677	-3,583	-6,718
Missouri.....	196	349	-198	-575	7	14	11	12
Montana.....	17,270	6,624	1,561	-243	-3,215	-3,303	-2,730	-1,515
Nebraska.....	-1,134	1,653	-204	-2,479	-2,288	-123	-101	-1,292
New Mexico.....	8,061	452	-2,371	-2,160	-832	692	971	1,217
New York.....	-3,171	12,780	3,743	-4,446	-8,180	-10,616	-9,500	-10,914
Ohio.....	9,118	39,227	16,367	-6,365	-17,027	-26,770	-31,157	-30,919
Oklahoma.....	-23,252	19,693	1,821	-8,242	-21,310	-17,561	-13,849	-18,107
Oregon.....	1,140	3,815	132	-2,069	-2,250	-1,527	-3,702	-2,786
Pennsylvania.....	7,595	55,061	16,716	-15,157	-32,138	-60,803	-43,437	-36,061
Tennessee.....	0	0	0	0	0	0	0	0
Texas.....	35,094	17,298	-26,566	-30,152	-31,776	5,922	8,818	4,723
Utah.....	-1,007	9,708	-4,339	-4,793	-8,384	-5,717	-3,870	-5,718
Virginia.....	-736	-249	560	-449	-346	-650	-326	-41
Washington.....	668	4,195	585	-160	-1,695	-682	-4,761	-3,957
West Virginia.....	-7,249	29,059	13,101	-8,932	-17,204	-30,318	-30,912	-22,565
Wyoming.....	2,954	3,735	-1,944	-3,216	-4,038	-2,996	-2,291	-2,125
AGA Regions								
Producing.....	479	69,254	-38,937	-93,078	-56,700	-45,713	-33,358	-51,571
Eastern Consuming.....	35,521	357,377	105,067	-122,084	-194,851	-278,017	-260,639	-233,974
Western Consuming.....	-3,808	78,223	-8,848	-27,250	-48,816	-26,378	-47,634	-53,890
Total.....	32,192	504,854	57,283	-242,413	-300,367	-350,108	-341,631	-339,435

See footnotes at end of table.

Table 10. Net Withdrawals from Underground Storage, by State, 2006-2008
(Volumes in Million Cubic Feet) – Continued

State	2008					2007		
	May	April	March	February	January	Total	December	November
Alabama	-107	-4,228	-1,842	1,783	5,681	-140	0	-1,184
Arkansas	-469	5	550	1,212	1,646	-278	1,296	152
California	-42,290	-26,643	-12,542	37,025	85,622	3,687	52,598	-3,107
Colorado	-1,328	3,410	5,095	1,684	4,667	-633	4,286	3,307
Illinois	-25,611	3	20,499	54,417	68,017	7,333	52,960	19,042
Indiana	-2,356	-354	2,094	5,101	6,742	2,419	5,437	-129
Iowa	-448	1,522	5,594	13,671	20,004	2,450	20,590	3,114
Kansas	-16,937	-2,728	867	17,748	23,201	15,355	25,597	4,934
Kentucky	-13,793	-4,806	2,363	15,689	23,173	5,440	14,377	2,590
Louisiana	-18,537	-7,422	9,280	31,445	63,091	12,923	26,066	6,085
Maryland	-1,905	-1,086	2,276	2,969	3,725	1,410	770	-286
Michigan	-70,572	-48,146	58,826	120,245	126,087	51,912	101,854	32,070
Minnesota	0	120	155	446	666	14	14	-98
Mississippi	-8,584	-1,732	222	2,224	22,989	884	10,486	6,465
Missouri	-804	235	329	571	244	-235	212	-237
Montana	-742	2,648	4,861	6,040	7,283	1,292	5,819	774
Nebraska	-1,311	620	138	1,815	2,438	-1,689	2,159	-63
New Mexico	-291	474	-994	3,592	7,311	-9,228	1,684	-521
New York	-10,722	-3,134	7,199	15,981	14,638	1,737	13,416	3,053
Ohio	-32,374	-15,961	21,267	42,406	50,423	18,711	41,157	9,832
Oklahoma	-30,164	-10,767	1,591	29,480	44,165	22,221	38,002	3,247
Oregon	-1,803	209	3,476	2,722	4,923	-2,126	1,514	162
Pennsylvania	-47,376	-27,058	42,797	75,864	79,188	42,484	63,091	12,735
Tennessee	0	0	0	0	0	0	0	0
Texas	-32,404	-26,102	17,290	49,291	78,751	4,918	31,645	7,230
Utah	-5,481	-64	6,698	8,119	12,835	-2,005	7,354	-338
Virginia	-956	-39	309	-100	1,552	1,057	650	715
Washington	-5,887	-1,241	3,387	3,158	7,726	-1,061	418	2,357
West Virginia	-27,719	-18,373	13,785	42,436	50,393	14,540	40,684	10,462
Wyoming	-951	857	3,858	5,521	6,543	-1,300	4,822	-1,047
AGA Regions								
Producing	-107,493	-52,501	26,966	136,775	246,835	46,656	134,776	26,406
Eastern Consuming	-235,947	-116,576	177,477	391,066	446,622	147,569	357,358	92,898
Western Consuming	-58,481	-20,703	14,990	64,715	130,265	-2,132	76,826	2,012
Total	-401,921	-189,780	219,433	592,557	823,722	192,093	568,959	121,316

See footnotes at end of table.

Table 10. Net Withdrawals from Underground Storage, by State, 2006-2008
(Volumes in Million Cubic Feet) – Continued

State	2007							
	October	September	August	July	June	May	April	March
Alabama	-458	-2,199	4,047	-717	-28	-1,929	-708	-1,604
Arkansas	-443	-969	-930	-723	-713	-793	280	-139
California	-21,651	-13,600	17,581	-2,609	-25,205	-38,189	-32,953	-18,028
Colorado	-1,613	-3,385	-6,589	-4,225	-3,438	-1,961	5,082	-369
Illinois	-36,610	-39,181	-33,438	-34,214	-32,789	-30,392	4,716	14,660
Indiana	-2,529	-2,916	-3,352	-4,609	-2,556	-1,783	605	1,161
Iowa	-14,935	-16,930	-13,521	-10,220	-4,703	-4,076	-797	6,649
Kansas	-4,798	-8,519	-4,128	-9,440	-8,465	-16,423	-4,103	-8,512
Kentucky	-1,779	-6,512	-3,230	-7,507	-14,485	-17,270	1,506	2,364
Louisiana	-24,418	-18,266	7,796	-21,140	-22,304	-29,300	-3,622	-9,318
Maryland	-349	165	-31	-2,421	-2,818	-1,491	-601	-403
Michigan	-34,107	-47,134	-42,343	-67,716	-73,592	-73,239	-19,371	29,447
Minnesota	-163	-204	-220	-310	-300	-9	165	293
Mississippi	-5,633	-8,124	2,328	-5,034	-8,557	-14,729	-425	-7,243
Missouri	-240	-235	-395	-1,177	8	8	609	266
Montana	-1,760	-2,321	-4,023	-4,699	-3,760	-3,720	-86	3,324
Nebraska	-788	-1,767	-2,029	-385	-1,152	-1,416	-390	-867
New Mexico	-2,037	-3,055	-1,222	-1,453	-288	-839	-1,045	-2,179
New York	-3,931	-8,518	-6,373	-10,539	-13,386	-15,477	-2,414	7,807
Ohio	-9,181	-17,690	-15,523	-27,585	-32,818	-35,332	-6,052	9,049
Oklahoma	-11,500	-11,101	2,849	-9,925	-14,494	-17,303	-8,860	-13,609
Oregon	667	-675	-1,562	-3,140	-3,422	-2,484	-159	1,236
Pennsylvania	-20,546	-31,983	-27,476	-41,672	-52,033	-67,254	-8,592	31,665
Tennessee	0	0	0	0	0	0	0	0
Texas	-43,688	-25,338	28,975	2,624	-23,976	-33,462	-29,143	-9,072
Utah	-2,429	-7,007	-6,315	-5,119	-5,886	-6,086	162	3,466
Virginia	-851	-1,118	1,139	-432	-273	-911	-257	-600
Washington	557	-2,451	223	-2,746	-2,648	-4,563	-710	-197
West Virginia	-10,442	-12,984	-14,904	-32,818	-32,734	-36,476	-10,912	8,441
Wyoming	-887	-4,176	-3,976	-3,654	-2,651	-2,640	-1,644	2,724
AGA Regions								
Producing	-92,975	-77,570	39,714	-45,808	-78,825	-114,779	-47,626	-51,677
Eastern Consuming	-136,287	-186,803	-161,476	-241,297	-263,331	-285,110	-41,951	109,640
Western Consuming	-27,277	-33,818	-4,881	-26,500	-47,311	-59,651	-30,141	-7,550
Total	-256,539	-298,191	-126,643	-313,605	-389,468	-459,540	-119,718	50,413

See footnotes at end of table.

Table 10. Net Withdrawals from Underground Storage, by State, 2006-2008
(Volumes in Million Cubic Feet) – Continued

State	2007		2006					
	February	January	Total	December	November	October	September	August
Alabama	2,785	1,854	-8,477	-770	-406	-1,186	-1,638	-1,202
Arkansas	1,095	1,609	-707	773	124	-226	-841	-539
California	27,551	61,296	13,290	39,774	5,074	-17,357	-23,147	-7,288
Colorado	1,784	6,487	2,670	5,347	-28	97	-3,784	-5,019
Illinois	54,277	68,301	-7,163	46,678	13,461	-34,007	-39,774	-35,795
Indiana	6,079	7,011	-2,891	3,414	-554	-1,950	-3,740	-3,642
Iowa	14,626	22,654	-3,563	17,622	-49	-10,970	-14,841	-15,048
Kansas	20,599	28,613	-3,407	14,320	2,375	-2,338	-17,305	-10,351
Kentucky	17,285	18,100	-3,610	7,900	2,036	-2,526	-10,299	-5,077
Louisiana	59,809	41,537	-73,895	15,316	8,106	-13,278	-29,560	-3,932
Maryland	4,162	4,715	-939	17	-1,659	486	-1,732	221
Michigan	155,685	90,358	-98,738	49,715	6,694	-11,144	-52,254	-36,131
Minnesota	432	412	-62	5	-81	-158	-202	-242
Mississippi	16,619	14,731	-9,430	-1,090	-1,817	204	-5,910	-3,442
Missouri	583	363	-548	-16	-270	-235	-471	8
Montana	5,604	6,139	-17,896	5,086	3,690	-2,504	-5,763	-5,519
Nebraska	2,013	2,995	999	1,816	1,158	698	-882	-454
New Mexico	905	824	-6,450	-126	-765	-1,208	-1,639	-484
New York	24,231	13,869	-15,072	9,592	-480	-1,941	-7,135	-4,246
Ohio	52,319	50,537	-26,685	24,453	8,034	-3,751	-17,057	-12,457
Oklahoma	27,925	36,991	-25,075	15,260	4,101	-4,264	-20,629	-4,264
Oregon	2,120	3,617	-750	1,975	1,788	706	-1,818	-314
Pennsylvania	113,682	70,867	-34,458	27,757	-8,952	9,196	-31,865	-30,651
Tennessee	0	0	16	0	0	0	0	0
Texas	44,769	54,356	-75,958	20,831	-5,877	-29,278	-40,828	20,833
Utah	8,478	11,714	-2,608	9,200	1,915	-1,611	-4,277	-5,634
Virginia	2,087	908	-974	242	-92	-176	-1,284	-24
Washington	2,370	6,329	1,128	-126	1,721	2,247	-1,380	-2,235
West Virginia	56,709	49,514	-24,423	23,291	7,800	-3,128	-13,955	-14,208
Wyoming	5,273	6,555	-5,707	5,242	538	-1,434	-3,589	-1,608
AGA Regions								
Producing	174,506	180,513	-203,400	64,513	5,841	-51,575	-118,350	-3,381
Eastern Consuming	503,738	400,192	-218,051	212,482	27,129	-59,447	-195,289	-157,505
Western Consuming	53,612	102,549	-9,935	66,504	14,617	-20,012	-43,961	-27,861
Total	731,856	683,254	-431,387	343,499	47,587	-131,034	-357,600	-188,747

See footnotes at end of table.

Table 10. Net Withdrawals from Underground Storage, by State, 2006-2008
(Volumes in Million Cubic Feet) — Continued

State	2006						
	July	June	May	April	March	February	January
Alabama	-1,773	-422	-198	-617	-607	1,252	-909
Arkansas.....	-672	-499	-496	-544	329	1,171	712
California.....	5,729	-16,715	-30,788	-22,010	25,267	31,412	23,340
Colorado.....	-4,283	-3,415	-748	3,394	2,574	7,646	889
Illinois.....	-33,696	-32,599	-26,254	1,281	30,352	58,397	44,792
Indiana.....	-3,111	-2,115	-2,326	-1,548	3,989	5,632	3,061
Iowa.....	-11,377	-5,918	-3,562	1,064	6,578	13,681	19,256
Kansas.....	-871	-7,128	-5,011	-6,224	9,402	17,855	1,868
Kentucky.....	-2,353	-10,827	-10,560	-3,958	13,974	13,409	4,669
Louisiana.....	-9,716	-24,217	-22,212	-22,800	-1,386	25,173	4,612
Maryland.....	-131	-797	-1,797	344	1,148	2,378	584
Michigan.....	-40,808	-67,606	-69,082	-45,858	44,374	80,426	42,935
Minnesota.....	-311	-191	0	81	244	740	52
Mississippi.....	4,082	-3,219	-3,262	-7,012	3,932	10,215	-2,112
Missouri.....	10	-476	11	13	562	289	29
Montana.....	-6,221	-6,451	-6,551	-3,299	2,439	4,128	3,068
Nebraska.....	114	-1,016	-1,249	-1,993	346	1,814	647
New Mexico.....	326	563	-1,149	-104	-1,216	-494	-154
New York.....	-7,460	-10,257	-11,875	-7,791	6,310	12,551	7,660
Ohio.....	-16,871	-17,586	-30,268	-21,631	7,883	30,194	22,371
Oklahoma.....	-3,489	-18,292	-15,870	-15,804	2,727	22,786	12,663
Oregon.....	-1,737	-3,204	-3,807	-711	2,165	3,233	976
Pennsylvania.....	-10,900	-39,933	-42,735	-35,025	33,080	71,749	23,822
Tennessee.....	0	0	0	0	4	4	8
Texas.....	13,653	-7,875	-31,696	-34,328	-12,715	19,677	11,644
Utah.....	-5,198	-7,708	-8,021	-2,028	2,830	7,939	9,985
Virginia.....	-112	311	-125	-15	-50	666	-315
Washington.....	284	-3,077	-3,986	46	-267	5,326	2,574
West Virginia.....	-21,495	-18,748	-30,516	-25,322	16,038	33,553	22,267
Wyoming.....	-2,195	-1,635	-3,283	-2,638	-330	2,335	2,891
AGA Regions							
Producing.....	1,540	-61,088	-79,894	-87,433	466	97,636	28,324
Eastern Consuming.....	-148,190	-207,567	-230,340	-140,440	164,586	324,742	191,787
Western Consuming.....	-13,932	-42,396	-57,184	-27,166	34,921	62,760	43,774
Total.....	-160,582	-311,050	-367,417	-255,039	199,973	485,138	263,885

Notes: This table contains total net withdrawals for each State with natural gas storage facilities. Positive numbers indicate the volume of withdrawals in excess of injections. Negative values indicate the volume of injections in excess of withdrawals. Data through 2007 are final. All other data are preliminary at this time and are not considered final until publication of the *Natural Gas Annual* for that year. EIA publishes weekly estimates of working gas in underground storage by geographical regions developed by the American Gas Association (AGA) when they published similar weekly estimates. The AGA Producing Region is Texas,

Oklahoma, Kansas, New Mexico, Louisiana, Arkansas, Alabama and Mississippi; the Eastern Consuming Region is all States east of the Mississippi River less Mississippi and Alabama, plus Iowa, Nebraska and Missouri; and the Western Consuming Region is all States west of the Mississippi River less the Producing Region and Iowa, Nebraska and Missouri.

Source: Energy Information Administration (EIA): Form EIA-191M, "Monthly Underground Gas Storage Report."