

**TABLE OF CONTENTS
AND
RECORD OF REVISIONS**

	REVISION	IMPLEMENTATION DATE
Organization and Responsibilities	16	September 10, 2008
Abbreviations and Acronyms	0	May 1, 2001
Quality Control Procedures		
QCP1 Training and Certification	10	May 1, 2001
QCP2 Balance Quality Control	11	May 1, 2001
QCP3 Preparation, Control, and Traceability of Standards	16	June 30, 2009
QCP4 Control of Laboratory Logbooks	11	May 1, 2001
QCP5 Analytical Quality Control and Sample Flow	12	June 30, 2009
QCP6 Radiochemical Contamination Control	10	May 1, 2001
QCP7 Automatic Pipette Quality Control	10	May 1, 2001
QCP8 Counting Room Quality Control	0	May 1, 2001
QCP9 pH Meter Quality Control	0	January 7, 2004
Instrument Procedures		
IP1 Electronic Calibration of Bicon Analyst Ratemeters	0	May 1, 2001
IP2 Alpha Scintillation Detector Calibration and Check-Out	0	May 1, 2001
IP3 GM Detector Calibration and Check-Out	0	May 1, 2001
Sample Preparation		
SP1 Sample Receipt	0	May 1, 2001
SP2 Sample Log-In	0	May 1, 2001
SP3 Sample Preparation	6	June 30, 2009
Analytical Procedures		
AP1 Gross Alpha and Beta for Various Matrices	15	April 20, 2007

**TABLE OF CONTENTS
AND
RECORD OF REVISIONS (Continued)**

		REVISION	IMPLEMENTATION DATE
Analytical Procedures (Continued)			
AP2	Determination of Tritium	16	April 20, 2007
AP3	Removed		
AP4	Determination of Total Radiostrontium in Environmental Samples	14	April 20, 2007
AP5	Determination of Technetium-99	17	April 20, 2007
AP6	Determination of Carbon-14 and Tritium Using the Biological Material Oxidizer	17	September 10, 2008
AP7	Determination of Radium-226 in Water and Soil Samples Using Alpha Spectroscopy	19	June 30, 2009
AP8	Radium-228 in Water	4	March 3, 2009
AP9	Determination of Carbon-14 in Water and Smears	4	April 20, 2007
AP10	Analysis of Plutonium-241 in Environmental Samples by Liquid Scintillation Analysis	3	June 15, 2007
AP11	Sequential Determination of the Actinides in Environmental Samples Using Total Sample Dissolution and Extraction Chromatography	5	June 30, 2009
AP12	Determination of Nickel-63 in Environmental Samples	6	June 15, 2007
AP13	Determination of Iron-55 in Water	5	June 15, 2007
AP14	Determination of Sulfur-35 in Solid Environmental Samples	7	June 15, 2007
AP15	Analysis of Polonium-210 in Water, Soil, Air Filters, Miscellaneous Samples, and Biota	1	June 15, 2007
AP16	Determination of Iron-55 in Soil and Other Solid Matrices	1	August 31, 2007

**TABLE OF CONTENTS
AND
RECORD OF REVISIONS (Continued)**

		REVISION	IMPLEMENTATION DATE
Counting Procedures			
CP1	Gamma Spectroscopy	17	June 30, 2009
CP2	Alpha Spectroscopy	15	June 30, 2009
CP3	Low Background Alpha/Beta Counter	2	November 7, 2003
CP4	Liquid Scintillation Analyzer (LSA)	3	November 7, 2003
Waste Procedure			
WP1	Waste Generation Procedure	0	May 1, 2001
Appendix A			
	Job Hazard Analyses	Various	December 5, 2008
Appendix B			
	Minimum Detectable Concentrations of Commonly Reported Radionuclides	0	June 30, 2009

All procedures have been reviewed and approved by:

Program Director: *Donk Poling* *for E. Abelquist* Date: *6/30/09*
 Laboratory Manager: *Dale Concha* Date: *6/30/09*
 Quality Manager: *Ann P Payne* Date: *6/30/09*