




## Structurally Deficient Bridges on the National Highway System Pennsylvania - Congressional District 08



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 591 structurally deficient NHS bridges in Pennsylvania, 66 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

| Bridge Label | Structure ID    | Bridge Description | Location Description     |
|--------------|-----------------|--------------------|--------------------------|
| 1            | 90309024000000  | BETH.PK;W.END BLVD | 2MI.S QUAKERTOWN 13K06   |
| 2            | 90309013000000  | SELLERSVILLE BYPAS | .4MI.TO LR 09104 20C05   |
| 3            | 90313007220690  | DUBLIN PIKE        | .1MI.TO LR 09082 14D02   |
| 4            | 90313009223640  | DUBLIN PIKE        | .4MI.TO LR 09083 14F03   |
| 5            | 90313018200550  | DUBLIN PIKE        | 25'TO LR 656 SPUR 15D09  |
| 6            | 90202004004480  | BUTLER PIKE        | .5MI.SOUTH TR-152 27K04  |
| 7            | 90202005000000  | BUTLER AVENUE      | CHALFONT 27K03           |
| 8            | 90611055001860  | RIVER ROAD         | 1MI.S.RIEGELSVILLE 04B02 |
| 9            | 90611051001820  | EASTON ROAD        | KINTNERSVILLE 04D06      |
| 10           | 90611038000000  | EASTON ROAD        | OTTSVILLE,TINICUM 10G08  |
| 11           | 90611034000470  | EASTON ROAD        | 2MI.S.OTTSVILLE 16J01    |
| 12           | 670063003200000 | WOODHAVEN ROAD     | EAST OF ROUTE 1 10B11    |
| 13           | 670001038029360 | ROOSEVELT BLVD.    | BUCKS COUNTY LINE 10C08  |
| 14           | 90001002035530  | LINCOLN HIGHWAY    | 1MI.N.COUNTY LINE 41E06  |
| 15           | 90001003006410  | LINCOLN HIGHWAY    | NORTH PA.TURNPIKE 41E05  |
| 16           | 90001004015570  | LINCOLN HIGHWAY    | NESHAMINY MALL 41F04     |
| 17           | 90001006010820  | NEW US-1 BY-PASS   | .5MI.N.NESHAMINY 41H02   |
| 18           | 90095037111350  | INTERSTATE 95 (SB) | 1MI.N.EDDINGTON 42B12    |
| 19           | 90095037013250  | INTERSTATE 95 (NB) | 1MI.N.EDDINGTON 42B12    |
| 20           | 90001013000000  | NEW US-1 BY-PASS   | .8MILES LR 152 37D10     |
| 21           | 90095038500000  | INTERSTATE 95 (SB) | CROYDON 42E10            |
| 22           | 90095038400000  | INTERSTATE 95 (NB) | CROYDON 42E10            |
| 23           | 90095043400000  | INTERSTATE 95 (NB) | FAIRLESS JUNCTION 37E11  |
| 24           | 90095045110930  | INTERSTATE 95 (SB) | 1MI.N.LANGHORNE 37H08    |
| 25           | 90095045011520  | INTERSTATE 95 (NB) | 1MI.N.LANGHORNE 37H08    |
| 26           | 90013017022720  | BRISTOL PIKE       | BTW.TR413;BATH RD. 42K11 |
| 27           | 92029014016560  | OXFORD VALLEY ROAD | 2MI.N.LANGHORNE 37K07    |
| 28           | 97409999100250  | CONNECT PA32&NJ29  | MORRISVILLE BORO. 39D04  |