



MSHA's Accident Prevention Program Miner's Tip

**SAFETY
IS A
VALUE!**


Mowboard/Moldboard Repairs

Category : [Maintenance](#)

Mine Type: [All Surface](#)

When cutting bolts out of mowboards (also called a moldboard) on scrapers, dozers, blades or rubber tired dozers (RTD's*) be sure to stand to the side of the bolt. The pressure from the dirt that is built up between the mowboard and the cutting edge can shoot the bolt out like a bullet. Make sure the area is clear of foot traffic. Be aware of your surroundings when in the process of cutting these bolts free.

*Rubber Tired Dozer



Reissued: **04/30/2002**

Tag # **AP2002-M034**

Remember - Safety is a Value that you can LIVE with!