

Actions	Compliance	Procedures
(1) Do not operate any airplane that has a turbine engine installed per: STC No. SA3777NM, SA09866SC, or SA09857SC and DOES NOT have a new elevator servo-tab and redundant control linkage per STC No. SA01059SE.	As of 3 calendar months or 250 hours time-in-service after the effective date of this AD, whichever comes first.	Not Applicable.
(2) You may install at the same time a turbine engine per STC No. SA3777NM, SA09866SC, or SA09857SC and a new elevator servo-tab and redundant control linkage per STC No. SA01059SE.	Prior to further flight as of the effective date of this AD.	Per STC No. SA3777NM and American Aeromotives, Inc. DHC-3 Otter Service Letter No. AAI-DHC3-02.01, Revision No. IR, dated April 9, 2002.
(3) You may operate an affected airplane installed with a turbine engine per STC No. SA3777NM, SA09866SC, or SA09857SC if you install a new elevator servo-tab and redundant control linkage per STC No. SA01059SE.	Within 3 calendar months or 250 hours time-in-service after the effective date of this AD, whichever occurs first.	Per American Aeromotives, Inc. DHC-3 Otter Service Letter No. AAI-DHC3-02.01, Revision No. IR, dated April 9, 2002.
(4) Do not install a turbine engine per STC No. SA3777NM, SA09866SC or SA09857SC, unless you have installed a new elevator servo-tab and redundant control linkage per STC No. SA01059SE.	As of the effective date of this AD.	Not Applicable.

#### What About Alternative Methods of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.13. Send your request to the Manager, Seattle Aircraft Certification Office (ACO), FAA. For information on any already approved alternative methods of compliance, contact:

(1) For STC No. SA3777NM or STC No. SA01059SE: Richard Simonson, Aerospace Engineer, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue, SW, Renton, Washington 98055; telephone: (425) 917-6507; facsimile: (425) 917-6590.

(2) For STC No. SA09866SC: Richard Karanian, Aerospace Engineer, Special Certification Office, FAA, Rotorcraft Directorate, Special Certification Office, 2601 Meacham Boulevard, Fort Worth, Texas 76193-0190; telephone: (817) 222-5195; facsimile: (817) 222-5959.

(3) For STC No. SA09857SC: Peter W. Hakala, Aerospace Engineer, FAA, Special Certification Office, Rotorcraft Directorate, 2601 Meacham Boulevard, Fort Worth, Texas 76193-0190; telephone: (817) 222-5145; facsimile: (817) 222-5785.

#### How Do I Get Copies of the Documents Referenced in This AD?

(g) You may get copies of the documents referenced in this AD from (for STC No. SA3777NM) A.M. Luton, 3025 Eldridge Avenue, Bellingham, Washington, 98225; telephone (360) 671-7817; facsimile (360) 671-7820 (for STC No. SA09866SC) Texas Turbine Conversions, Inc., 8955 CR 135, Celina Texas 75009; telephone: (972) 382-4402; facsimile: (972) 382-4402; (for STC No. SA09857SC) Canada Turbine Conversions, Inc., Lot 16, 105081 Highway 11, Pine Falls MB ROE 1MO, Canada; and (for STC No. SA01059SE) American Aeromotives, Inc., 3025 Eldridge Avenue, Bellingham, Washington 98225, telephone: (360) 671-7817; facsimile: (360) 671-7820. You may view these documents at FAA, Central

Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106.

Issued in Kansas City, Missouri, on October 29, 2003.

**Dorenda D. Baker,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 03-27847 Filed 11-4-03; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2003-16147; Airspace Docket No. 03-AGL-17]

#### Proposed Modification of Class D Airspace; Rapid City, SD

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** This document proposes to modify Class D airspace at Rapid City, SD. Instrument Flight Rules (IFR) Category E circling procedures have become necessary at Ellsworth AFB, Rapid City, SD. Controlled airspace extending upward from the surface of the earth is needed to contain aircraft executing these approach procedures. This action would increase the area of the existing controlled airspace for Ellsworth AFB, Rapid City, SD.

**DATES:** Comments must be received on or before December 29, 2003.

**ADDRESSES:** Send comments on the proposal to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400

Seventh Street, SW., Washington, DC 20590-0001. You must identify the docket Number FAA-2003-16147/ Airspace Docket No. 03-AGL-17, at the beginning of your comments. You may also submit comments on the internet at <http://dms.dot.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527) is on the plaza level of the Department of Transportation NASSIF Building at the above address.

An informal docket may also be examined during normal business hours at the office of the Regional Air Traffic Division, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois 60018.

**FOR FURTHER INFORMATION CONTACT:** Denis C. Burke, Air Traffic Division, Airspace Branch, AGL-520, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois 60018, telephone (847) 294-7568.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this document must submit with those comments a self-addressed, stamped postcard on which the following statement is made:

"Comments to Docket No. FAA-2003-16147/Airspace Docket No. 03-AGL-17." The postcard will be date/time stamped and returned to the commenter. All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received. All comments submitted will be available for examination in the Rules Docket, FAA, Great Lakes Region, Office of the Regional Counsel, 2300 East Devon Avenue, Des Plaines, Illinois, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

#### Availability of NPRM's

An electronic copy of this document may be downloaded through the Internet at <http://dms.dot.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at <http://www.faa.gov> or the Superintendent of Document's Web page at <http://www.access.gpo.gov/nara>.

Additionally, any person may obtain a copy of this notice by submitting a request to the Federal Aviation Administration, Office of Air Traffic Airspace Management, ATA-400, 800 Independence Avenue, SW., Washington, DC 20591, or by calling (202) 267-8783. Communications must identify both docket numbers for this notice. Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking, (202) 267-9677, to request a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

#### The Proposal

The FAA is considering an amendment to 14 CFR part 71 to modify Class D airspace at Rapid City, SD, for Ellsworth AFB. Controlled airspace extending upward from the surface of the earth is needed to contain aircraft executing instrument approach procedures. The area would be depicted on appropriate aeronautical charts. Class D airspace areas extending

upward from the surface of the earth are published in paragraph 5000 of FAA Order 7400.9L dated September 2, 2003, and effective September 16, 2003, which is incorporated by reference in 14 the Class E designations listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an establishment body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore this, proposed regulation—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

#### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

#### **PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS**

1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40103, 40113, 40120, E.O. 10854, 24 FR 9565, 3 CFR 1959-1963 Comp., p. 389.

##### **§ 71.1 [Amended]**

2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9L, Airspace Designations and Reporting Points, dated September 2, 2003, and effective September 16, 2003, is amended as follows:

\* \* \* \* \*

*Paragraph 5000 Class D airspace.*

#### **AGL SDD Rapid City Ellsworth AFB, SD [Revised]**

Rapid City, Ellsworth AFB, SD  
(Lat. 44°08'42" N., long. 103°06'13" W.)  
Rapid City Regional Airport, SD  
(Lat. 44°02'43" N., long. 103°03'27" W)

That airspace extending upward from the surface to and including 5,800 feet MSL and within a 5.9-mile radius of Ellsworth AFB to the Rapid City Regional Airport 4.4-mile radius, excluding that airspace south of a line between the intersection of the Ellsworth AFB 4.7-mile radius and the Rapid City Regional Airport 4.4-mile radius. This Class D airspace is effective during the specific dates and times established in advance by a Notice to Airmen. The effective date and time will thereafter be continuously published in the Airport/Facility Directory.

\* \* \* \* \*

Issued in Des Plaines, Illinois on October 9, 2003.

**Nancy B. Shelton,**

*Manager, Air Traffic Division, Great Lakes Region.*

[FR Doc. 03-27752 Filed 11-4-03; 8:45 am]

**BILLING CODE 4910-13-M**

---

## DEPARTMENT OF THE TREASURY

### Internal Revenue Service

#### 26 CFR Part 1

[REG-146692-03]

RIN 1545-BC59

#### Mortgage Revenue Bonds

**AGENCY:** Internal Revenue Service (IRS), Treasury.

**ACTION:** Notice of proposed rulemaking and notice of public hearing.

**SUMMARY:** This document contains proposed regulations that provide guidance regarding the limitation on the effective rate of mortgage interest for purposes of mortgage revenue bonds issued by State and local governments. This document also contains a notice of public hearing on these proposed regulations.

**DATES:** Written or electronic comments must be received by January 7, 2004. Outlines of topics to be discussed at the public hearing scheduled for January 28, 2004, at 10 a.m., must be received by January 7, 2004.

**ADDRESSES:** Send submissions to CC:PA:LPD:PR (REG-146692-03), room 5203, Internal Revenue Service, POB 7604, Ben Franklin Station, Washington, DC 20044. Submissions may be hand delivered Monday through Friday between the hours of 8 a.m. and 4 p.m. to CC:PA:LPD:PR (REG-146692-03), Courier's Desk, Internal Revenue Service, 1111 Constitution Avenue, NW., Washington, DC. Alternatively, taxpayers may submit comments electronically to the IRS Internet site at <http://www.irs.gov/regs>. The public hearing will be held in the Auditorium,