

enr

U.S. CONSUMER PRODUCT SAFETY COMMISSION WASHINGTON, DC 20207

Todd A Stevenson
Deputy Secretary and
Freedom of Information Officer
Office of the Secretary

October 28, 1999

CERTIFIED MAIL

Scott Fry BTl Corporation 1937 E. Broadway Tempe, AZ 85202

Tel: 301-504-0785X1239 Fax: 301-504-0127

Email: tstevenson@cpsc.gov

Re: FOIA Request S9100110: Victor Automotive Products / Samples 9-830-3080/3201/3202/3203/3204 / Field File

Dear Mr. Fry:

Thank you for your Freedom of Information Act (FOIA) request seeking information from the Commission. The records from the Commission files responsive to your request have been processed and copies of the releasable responsive records are enclosed. The enclosed records include file information generated by the Commission itself or its contractors for regulatory or enforcement purposes. These records are identified as memoranda and other correspondence, notes and documents. The Commission has established management systems under which supervisors are responsible for reviewing the work of their employees or contractors. The file information materials are final and have been prepared and accepted by the Commission's staff under such review systems. The Commission believes that it has taken reasonable steps to assure the accuracy of the information.

We must withhold from disclosure other records responsive to your request that are contained in the Commission's law enforcement investigatory file pursuant to the FOIA Exemptions 3, and 4, 5 U.S.C. §§ 552(b)(3), and (b)(4), and sections 6(a)(2), and 6(b)(1) of the Consumer Product Safety Act (CPSA), 15 U.S.C. §§ 2055(a)(2), and 6(b)(1).

FOIA Exemption 3 provides for the withholding from disclosure of matters that are specifically exempted from disclosure by another statute. The files contain proprietary and confidential information that we must withhold pursuant to Exemptions 3 and 4 and section 6(a)(2) of the CPSA. Section 6(a)(2) prohibits the Commission from disclosing information that is exempt from disclosure under Exemption 4 of the FOIA. That exemption protects trade secrets and confidential commercial information directly related to a firm's business that the firm

has not made public and whose disclosure could give a substantial commercial advantage to a competitor. Specifically, we are withholding: confidential financial information from portions of pages 12 and 14; supplier and formulation information from portions of pages 17, 18, 19, 20, 21, 22, and entire pages 71, 80, 86, 91, 111, 135, 144, 152, 159, and 161; and sales figures from portions of page 20.

We are also relying in part to section 6(b)(1) of the CPSA to withhold an unconfirmed reported incident from entire pages 172-183. Section 6(b)(1) of the CPSA prohibits the Commission from disclosing information about a consumer product that identifies a manufacturer or private labeler unless the Commission has taken "reasonable steps" to assure that the information is accurate, that disclosure is fair in the circumstances, and that disclosure will be reasonably related to effectuating the purposes of the laws that the Commission administers. See Commission regulation, 16 C.F.R. § 1101.32. The Commission's policy is to withhold each consumer complaint and reported incident unless: (1) the Commission has conducted an investigation of the complaint and reported incident, and the investigation corroborates the substance of the complaint and reported incident; (2) the Commission has conducted or obtained a technical, scientific, or other evaluation of the product that is the subject of the complaint and reported incident, and evaluation corroborates the substance of the information contained in the complaint and reported incident; or (3) the consumer or person reporting or submitting the incident confirms the accuracy of the information. The Commission did not take any of these steps with regard to this certain consumer complaint and reported incident at pages 172-183.

According to the Commission's regulations implementing the FOIA at 16 C.F.R. § 1015.7, a partial denial of access to records may be appealed to the General Counsel of the Commission within thirty (30) days of your receipt of this letter. An appeal must be in writing and addressed to: FOIA APPEAL, General Counsel, ATTN: Office of the Secretary, U.S. Consumer Product Safety Commission, Washington, D.C. 20207.

Processing this request, performing the file searches and preparing the information, cost the Commission \$90.00. In this instance, we have decided to waive all of the charges.

Sincerely,

Todd A. Stevenson

Enclosures



U.S. CONSUMER PRODUCT SAFETY COMMISSION WASHINGTON, DC 20207

Todd A. Stevenson Deputy Secretary and Freedom of Information Officer Office of the Secretary

UUT 12 1999

Tel: 301-504-0785X1239 Fax: 301-504-0127 Email: tstevenson@cpsc.gov

CERTIFIED MAIL

Paul R. Thomson, III, Esq.
Michie, Hamlett, Lowry, Rasmussen & Tweel
2320 Electric Road • Suite A
Roanoke, VA 24018

Re: FOIA Request S9070095: Victor Automotive Products / Samples 9-830-3080/3201/3202/3203/3204 / Field File

Dear Mr. Thomson:

Thank you for your Freedom of Information Act (FOIA) request seeking information from the Commission. The records from the Commission files responsive to your request have been processed and copies of the releasable responsive records are enclosed. The enclosed records include file information generated by the Commission itself or its contractors for regulatory or enforcement purposes. These records are identified as memoranda and other correspondence, notes and documents. The Commission has established management systems under which supervisors are responsible for reviewing the work of their employees or contractors. The file information materials are final and have been prepared and accepted by the Commission's staff under such review systems. The Commission believes that it has taken reasonable steps to assure the accuracy of the information.

We must withhold from disclosure other records responsive to your request that are contained in the Commission's law enforcement investigatory file pursuant to the FOIA Exemptions 3, and 4, 5 U.S.C. §§ 552(b)(3), and (b)(4), and sections 6(a)(2), and 6(b)(1) of the Consumer Product Safety Act (CPSA), 15 U.S.C. §§ 2055(a)(2), and 6(b)(1).

FOIA Exemption 3 provides for the withholding from disclosure of matters that are specifically exempted from disclosure by another statute. The files contain proprietary and confidential information that we must withhold pursuant to Exemptions 3 and 4 and section 6(a)(2) of the CPSA. Section 6(a)(2) prohibits the Commission from disclosing information that is exempt from disclosure under Exemption 4 of the FOIA. That exemption protects trade secrets and confidential commercial information directly related to a firm's business that the firm

Paul R. Thomson, III, Esq. Michie, Hamlett, Lowry, Rasmussen & Tweel Page 2

has not made public and whose disclosure could give a substantial commercial advantage to a competitor. Specifically, we are withholding: confidential financial information from portions of pages 12 and 14; supplier and formulation information from portions of pages 17, 18, 19, 20, 21, 22, and entire pages 71, 80, 86, 91, 111, 135, 144, 152, 159, and 161; and sales figures from portions of page 20.

We are also relying in part to section 6(b)(1) of the CPSA to withhold an unconfirmed reported incident from entire pages 172-183. Section 6(b)(1) of the CPSA prohibits the Commission from disclosing information about a consumer product that identifies a manufacturer or private labeler unless the Commission has taken "reasonable steps" to assure that the information is accurate, that disclosure is fair in the circumstances, and that disclosure will be reasonably related to effectuating the purposes of the laws that the Commission administers. See Commission regulation, 16 C.F.R. § 1101.32. The Commission's policy is to withhold each consumer complaint and reported incident unless: (1) the Commission has conducted an investigation of the complaint and reported incident, and the investigation corroborates the substance of the complaint and reported incident; (2) the Commission has conducted or obtained a technical, scientific, or other evaluation of the product that is the subject of the complaint and reported incident, and evaluation corroborates the substance of the information contained in the complaint and reported incident; or (3) the consumer or person reporting or submitting the incident confirms the accuracy of the information. The Commission did not take any of these steps with regard to this certain consumer complaint and reported incident at pages 172-183.

According to the Commission's regulations implementing the FOIA at 16 C.F.R. § 1015.7, a partial denial of access to records may be appealed to the General Counsel of the Commission within thirty (30) days of your receipt of this letter. An appeal must be in writing and addressed to: FOIA APPEAL, General Counsel, ATTN: Office of the Secretary, U.S. Consumer Product Safety Commission, Washington, D.C. 20207.

Processing this request, performing the file searches and preparing the information, cost the Commission \$90.00. In this instance, we have decided to waive all of the charges.

Sincerely,

Todd A. Stevenson

Enclosures

Who was

U.S. CONSUMER PRODUCT SAFETY COMMISSION

Central Regional Center 230 South Dearborn Street **Suite 2944** Chicago, Illinois 60604 (312) 353-8260

February 4, 1997

MFR/PRVLBR NOTIFIED No Comments ma

Comments attached

(Comments attached)

(Comments attached)

(Comments attached) firm has not requested further notice

Michael Brawerman

Z 166 425 246

Receipt for

Certified Mail No Insurance Coverage Provided

Do not use for International Mail (See Reverse)

0016

Products, Inc.

 Automotive Products : Samples 97-830-3080/3201/3202/3203/3204

Michael Braverman Street and No 501 S. Wolf Ra O . State and ZIP Code
Des Plaines, IL 60016 Ś Certified Fee Special Delivery Fee Restricted Delivery Fee Return Receipt Showing to Whom & Date Delivered Return Receipt Showing to Whom Date, and Addressee's Address TOTAL Postage Ś Postmark or Date

umer Product Safety Commission (CPSC) analyzed otive products repackaged and distributed by alyses show that these five products are us substances, and distribution of these ited. The Commission staff has no objection to ting its remaining inventory of these products. that the labeling be corrected on future

in question are Victor V-500 Pressurized Lock -830-3080, Victor V-502 Pressurized Lock De-:0-3201, Victor VB-58 Bicycle Tire Emergency ·830-3202, Victor V-301 Vinyl Adhesive, sample 'ictor Rubber Cement 3/8 oz., sample 97-830these products were collected by a Commission ig an inspection of your company.

The samples were evaluated for compliance with the labeling requirements of the Federal Hazardous Substances Act (FHSA). For your reference, copies of the laboratory reports, the FHSA regulations, Part 1500 to 1512, and a Compilation of Statutes Administered by CPSC, which contains the FHSA, are enclosed.

Examination of the five products found that they are not in compliance with the FHSA regulations.

U.S. LINSUMER PRODUCT SAFETY COMMISSION

Central Regional Center 230 South Dearborn Street Suite 2944 Chicago, Illinois 60604 (312) 353-8260

February 4, 1997

Michael Braverman
President
Victor Automotive Products, Inc.
501 S. Wolf Road
Des Plaines, IL 60016

RE: Five Automotive Products CPSC Samples 97-830-3080/3201/3202/3203/3204

Dear Mr. Braverman:

The U.S. Consumer Product Safety Commission (CPSC) analyzed samples five automotive products repackaged and distributed by your firm. The analyses show that these five products are misbranded hazardous substances, and distribution of these products is prohibited. The Commission staff has no objection to your company depleting its remaining inventory of these products. The staff requests that the labeling be corrected on future production.

The products in question are Victor V-500 Pressurized Lock De-Icer, sample 97-830-3080, Victor V-502 Pressurized Lock De-Icer, sample 97-830-3201, Victor VB-58 Bicycle Tire Emergency Repair, sample 97-830-3202, Victor V-301 Vinyl Adhesive, sample 97-830-3203, and Victor Rubber Cement 3/8 oz., sample 97-830-3204. Samples of these products were collected by a Commission investigator during an inspection of your company.

The samples were evaluated for compliance with the labeling requirements of the Federal Hazardous Substances Act (FHSA). For your reference, copies of the laboratory reports, the FHSA regulations, Part 1500 to 1512, and a Compilation of Statutes Administered by CPSC, which contains the FHSA, are enclosed.

Examination of the five products found that they are not in compliance with the FHSA regulations.



Michael Braverman February 4, 1997 Page Two

VICTOR V-500 AND V-502 PRESSURIZED LOCK DE-ICER

The Material Safety Data Sheet (MSDS) for these products does not list isopropyl alcohol as a component although isopropyl alcohol is listed on the containers as a component. The MSDS indicates that this product may be a skin irritant. The labels do not have the signal word and statements of hazard placed before the other cautionary information. These products appear to require the following minimum warnings:

WARNING - FLAMMABLE CONTENTS UNDER PRESSURE IRRITANT Contains aliphatic hydrocarbonS and ethylene glycol Monobutyl Ether. Do not puncture or incinerate container. Do not use near heat or flame. Do not expose to heat or store at temperatures above 120°F.

Avoid contact with eyes or prolonged contact with skin. In case of contact flush skin or eyes thoroughly with water for 15 minutes. For eyes, get prompt medical attention.

Keep out of the reach of children.

These statements may remain in a vertical position on the container per 16 C.F.R. Part 1500.121(b)(1) for cylindrical containers with a narrow diameter. These warning statements "WARNING-FLAMMABLE CONTENTS UNDER PRESSURE IRRITANT" and a statement to see other cautions on the back panel should be placed on the front of the blister card. Although the containers are visible through the display window of the card, the containers can turn making the statement to be unable to be read.

VICTOR VB-58 BICYCLE TIRE EMERGENCY REPAIR

The MSDS for this product lists the hazardous components as perclene and chlorodiflouromethane. Perclene is a name for perchloroethylene. This product appears to require the following minimum warning:

(FRONT PANEL LABELING)

DANGER: EXTREMELY FLAMMABLE VAPOR HARMFUL CONTENTS UNDER PRESSURE. See other cautions on back panel.

V

Michael Braverman February 4, 1997 Page Three

(BACK PANEL LABELING)

Contains perchloroethylene.
Use only in a well ventilated area. Avoid prolonged breathing of vapor or contact with skin.
Do not puncture or incinerate container.
Do not expose to heat or store at temperatures above 120°F.
Keep out of the reach of children.

The statement "DANGER - EXTREMELY FLAMMABLE VAPOR HARMFUL CONTENTS UNDER PRESSURE See other cautions on back panel" should be placed on the front of the blister card. Again, the containers are visible through the display window of the card but the containers may turn making the statements unable to be read.

VICTOR V-103 VINYL ADHESIVE

The MSDS for this product lists the hazardous ingredients as 19-20% synthetic resins, 48-50% acetone, 28-30% methyl ethyl ketone, and 3-4% cyclohexanone. The MSDS lists a flash point of -40F. This product appears to require the following minimum warnings:

FRONT: DANGER - EXTREMELY FLAMMABLE

INJURIOUS TO EYES

See cautions on back panel.

BACK: Contains acetone, methyl ethyl ketone, and

synthetic resins.

Do not store or use near heat, sparks, or flame.

Use only in a well ventilated area.

Avoid contact with eyes and prolonged contact on

the skin.

In case of eye contact, flush with water for 15

minutes.

Get medical attention.

Keep out of the reach of children.

9

Michael Braverman February 4, 1997 Page Four

These statements are required to be as close to the dispensing end of the tube as possible by 16 C.F.R. Part 1500.121(e), and not at the bottom of the tube as they currently are.

VICTOR RUBBER CEMENT 3/8 OZ

The MSDS for this product lists the hazardous components as 92% Heptane and 1% ethyl alcohol and a flash point of 25°F. This product appears to require the following minimum warnings.

FRONT: WARNING-FLAMMABLE

See other cautions on back panel.

BACK: Contains heptane.

Do not use near heat or flame. Keep out of the reach of children.

As with the vinyl adhesive label, these statements are required to be as close to the dispensing end of the tube as possible.

The minimum type size to be used on these labels depend on the size of the containers principal display panel. Please refer to 16 C.F.R. Part 1500.121. This section lists the prominence, placement, and conspicuousness requirements as well as required type sizes.

Distribution, sale, or importation of a misbranded hazardous substance is prohibited under section 4 of the FHSA. As a result of these violations, you could be subject to fines of up to \$1.5 million and/or imprisonment for not more than one year, or both. Please review Chapter 1 of the enclosed Regulated Products Handbook (Handbook) for details of the penalties.

Although the Commission staff does not object to your company depleting your remaining inventory of these five products within a reasonable time frame, the staff requests the labeling be corrected on future production.

 $\sqrt{}$

Michael Braverman February 4, 1997 Page Five

Sections 15 and 37 of the CPSA contain requirements for reporting to the Commission information on certain products you manufacture, import, or distribute. Chapter 4 of the <u>Handbook</u> describes the reporting requirements applicable to your firm. To assure you of the confidential treatment of information you submit, please review Chapter 7 of the <u>Handbook</u>.

Please respond in writing within 10 days from the date you receive this letter, outlining the specific corrective actions you plan to take to address the hazard associated with these products. Please direct your response to Robert B. Johnston, Compliance Officer, at the address and telephone number above.

We appreciate your cooperation.

Sincerely,

Eric B. Ault

Director

Central Regional Office

CERTIFIED MAIL

EBA: RBJ: gfp

Enclosures: A/S

35¢

Chicago/Suburbe 80¢ Elementers For home delivery

Late Sports Final

Lying about logo is a legal no-no

PY CAM SIMPSON .
DERAL COURT REPORTER

Some people think "Made in America" is a meaningless label in today's global economy. Those people have never heard of Michael Braverman.

The Des Plaines corporate chief faces up to six months

in prison after being convicted of an obscure federal crime that forbids people from removing labels showing where foreign product are made and replacing them with "Made in the U.S.A." logos.

Employees at Braver man's company, Victo

Turn to next page

Label

Continued from previous page

Automotive Inc., were told to remove made-in-Taiwan labels from 420,000 tire-pressure gauges; they replaced them with "Made in the U.S.A." labels, put them in packages that also said "Made in the U.S.A.," and shipped them to Kmart for resale, according to court records.

Prosecutors believe Braverman is the first person here to be convicted for violating the almost 70-year-old statute. Only one person nationwide was convicted of the crime last year, according to Justice Department records analyzed by TRAC, a Syracuse University data bank.

"This is the kind of thing that should have been handled administratively, not criminally," said attorney Robert Breisblatt, who is representing Braverman and Victor. The company and its chief both pleaded guilty late last month to violating the Tariff Act of 1930. "This is fraud," said Bill Anthony of the U.S. Customs Service in Washington. "There are many reasons why consumers want made-in-the-U.S.A. goods."

Braverman will be sentenced Oct. 14. He faces a fine of \$40,000 and up to six months in prison. Separately, his company, which employs about 150 people at its Des Plaines facility, has agreed to pay \$80,000.

Braverman's company sells auto accessories to retailers.

His troubles began in late 1993 when he entered into a national contract with Kmart, according to court records. He promised he would stock Kmart stores nationwide with

tire-pressure gauges sold under the "Monkey Grip" trademark. And he specifically promised, in writing, that they'd be made in the United States.

"Linable to locate cheap gauges domestically, Braverman ordered thousands from Taiwan. The Taiwanese label was engraved on a pocket clip slipped around each gauge. Braverman had his employees slip off the clips and replace them with ones sporting the American-made designation, he admitted in court.

U.S. Customs agents raided Victor in late 1994 and found 37,000 tire gauges in U.S.A. packages. They said 420,000 had already been shipped. The gauges retailed for about \$1.99 apiece, said Assistant U.S. Attorney Daniel Parish.

"My clients have clearly recognized that what they did was wrong, and it was an isolated incident," Breisblatt said.

Breisblatt said the gauges were recalled. He also said Kmart remains a Victor customer.

The federal statute that Braverman ran afoul of has been enforced sparingly with criminal charges since it went into effect.

James Didia, a Seattle shopkeeper, was convicted in the 1930s for having employees remove "Made in Japan" labels from at least 639 products in his store.

Bernard Mersky, a musical instrument dealer, was charged in New York in the 1950s for removing violin labels that said made in "Soviet-Occupied Germany" and replacing them with "Made in Germany" labels. A judge tossed out the case.

In Pittsburgh in 1989, 10 executives were named in a 30-count indictment because their company allegedly removed foreign labels from rubber hoses.



is	your j	RETUR	N ADE	RESS	com	plete	d o	n the	re -	ver	50 S	ide?
PS Form 3811. December 1994	 Signature: (Addressee or Agent) X 	5. Received By: (Print Name)	Des Plaines, IL 60016	Victor Automotive Prods., Inc. 501 S. Wolf Road	4	man	3. Article Addressed to:	The Return Receipt will show to whom the article was delivered and the date delivered.	permit. •Write "Return Receipt Requested" on the mailpidos below the article number.	card to you. **Attach this form to the front of the mailplece, or on, the back if space does not	ame 3,	v 2 for additional services.
Domestic Return Receipt		8. Addressee's Address (Only if requested and fee is paid)	7. Date of Delivery	☐ Return Receipt for Merchandse ☐ COD	☐ Registered Ki Certified Ki	Z 166 425 246	4a. Article Number	C	se number. 2. Restricted Delivery	ce does not 1. 🔲 Addressee's Address 😴	e can return this (extra fee):	The loss series the

R

VICTOR

MONKEY@GRIP	•
-------------	---


Victor Products, Inc. 501 South Wolf Road Des Plaines, IL 60016 USA Phone: 847-298-8870

Fax: 847-298-2573 Toll Frae: 1-800-423-4201 FAX

COVE

. .

4/21/97 Total pages including cover Date From ENSUMER DUTLINED V502 ARE REVIEW ATMCHED CONES 298-8924





0





19×72 Tobe 56460 1 mil arch





WARNING — FLAMMABLE SEE OTHER CAUTIONS ON BACK PANEL



NET 1/2 FL OZ (14.7mL)

Contains Heptane. Do not use near heat or Flame. Keep out of the reach of Children.

DIRECTIONS
OLEAN AREA AROUND PUNCTURE. BUFF AND WIPE CLEAN, APPLY RUBBER CEMENT TO BUFFED AREA. WORK WELL INTO THE RUBBER AND ALLOW TO DITY. VICTOR PRODUCTS, INC., DES PLAINES, IL 60016



AICH UBBER CEMENT

FOR ALL RUBBER REPAIRS . NET 1 PL OZ (29.4mL)



VICTOR PRODUCTS, INC., DES PLAINES, IL 60016



VICTOR PRODUCTS, INC.
501 S. Wolf Road • Des Plaines, Illinois 60016
Fax (708) 298-2573
Tel (708) 298-8870

February 21, 1997

Mr. Robert B. Johnson U.S. Consumer Products Safety Commission Central Regional Center 230 S. Dearborn Street-Suite 2944 Chicago, Illinois 60604

Dear Mr. Johnson:

We are in receipt of correspondence dated February 4, 1997, regarding the Consumer Product Safety Commission findings of non-compliance of five Victor Automotive Products.

After reviewing the findings from Mr. Ault, it is our intention to fully comply and implement the requisite changes in compliance with the FHSA regulations. The following corrective actions have been taken immediately and will be implemented for all future productions:

- All packaging design and suppliers have been notified and are making the necessary labelling changes as required on both blister card and tubes.
- 2.) All production orders for these items are on hold until revisions have been included into the production.
- 3.) All proofs and chromolins will be forwarded to your attention for review and approval. Proofs should be made available in approximately 45 to 60 days.

We are appreciative of the Commission staff's decision allowing Victor to deplete its remaining inventory.

Should you have any questions please contact Pete Calhoun or the undersigned at your convenience.

Sincerely,

Michael Braverman

President

Victor Products Inc.

MB:la

	FIELD A	ACTIVITY COV	/ERSHEET			
1. REGION/STATE FOCR/WI	2. OPERATION (Check One) (X) Inspection () Telephone Contact (() Other [() Estable) Investigation]	ishment Visit	3. DATE 12/04/96 4. NUMBER (For RO Use)		
Address [501 :	Automotive Products, Inc. S. Wolf Road] nes] State [IL] Zip [600		312-298-8870]	<u></u>		
6. RELATED FIRM () Parent () Headquarters () Subsidiary () Other Name [] City [] State []						
7. PRODUCTS COVERED [automotive/bicycle	repair chemical products]	* OTHER CONSUMER PRODUCTS [other auto accessories]				
	E or () Importer (X) Own Label Distributor (X) Repackager]	10. ANNUAL PRODUCTION Product Covered Units [See narrative] Other Products \$. Units []				
	12. SAMPLES COLLECTED 97-830-3080; 3201 thru	u 3204.	13. MIS CODE 33567	14. HOURS Activity [8.0] Traval [4.0]		
15. REASON FOR ACTIVI	Y (Assignment Reference) ance (observed labeling vio	olations during h	ardware store visit)			
16. ANNOUNCED () UNANNOUNCED ()	Rationale for Announced Inspectio	P				
17. EMPLOYEE'S NAME Dennis R. Blasius		TITLE Inv.	SIGNATURE			
appeared to be violat		rveillance report rements.	stating that the firm	's "LOCK-DE-ICER" product		
maintenance and bic		products are man	sufactured to Victor	Automotive's specifications		
19. REVIEWER'S NAME John R. Vece						
20. REVIEW DATE 12-17-96	21. DISTRIBUTION O: FOCR; CC: CRM, M. TORO;	CC: MKE-RP.		\\		

Victor Automotive Products
Des Plaines, IL. 60016

ENDORSEMENT CONTINUED:

During this inspection 5 of the firm's products were reviewed and found to have potential FHSA labeling violations. This included the firm's "LOCK DE-ICER" which initiated this inspection. Samples of all 5 products were collected and sent to LSHL.

F/U: REFER TO COMPLIANCE.

7

SUMMARY OF FINDINGS:

This inspection of Victor Automotive Products, Inc. was conducted on 12/04/96 as a follow up to surveillance conducted by a Kansas City Investigator on 8/14/96 at a local Ace Hardware Store; that surveillance determined that a lock de-icer product distributed by Victor Automotive did not have warning labeling required by the Federal Hazardous Substances Act.


A review of the firm's model #V-500 and model #V-502 lock de-icer products confirmed several labeling violations. A brief examination of the hundreds of automotive and bicycle repair products distributed by the firm was also made. Victor brand #V-301 vinyl adhesive, 3/8 ounce size tubed rubber cement, and Victor brand model #VB-58 bicycle tire aerosol repair products all were found to have multiple labeling violations.

The above products were collected as samples, 97-830-3080; 97-830-3201 thru 3204. The samples were sent to HSHL for chemical analysis as may be directed by FOCR Compliance.

This firm was last inspected on 5/23/88, and many of the identical labeling violations were noted during that inspection. Please refer to that inspection report for additional detail.

PERSONS INTERVIEWED:

Credentials were shown and a Notice of Inspection issued to Ms. Toni Ciccone, Office Manager, during the unannounced inspection visit conducted on 12/04/96. All information contained in this report was obtained from Ms. Ciccone or Peter Calhoun, Purchasing Manager and Henry Janus, Plant Supervisor. A copy of the Notice of Inspection is attached as Exhibit "A."



The firm is a distributor of numerous automotive and bicycle repair products such as lock de-icer, tire patch kits, adhesives for various auto applications, first aid and emergency car kits, etc. These products are manufactured by outside vendors to Victor Automotive specifications, shipped to Victor Automotive Products for final (own label and private label) packaging, and then shipped to retailers nationwide.

A copy of the firm's product catalog depicting some of their many products is attached as Exhibit "B." A vendor (wholesale) price listing is included.

COMPLAINT FILES:

The Office Manager, Ms. Ciccone, has maintained a formal complaint file for the past twelve months; complaints were typically responded to and the associated paperwork discarded before that time. The complaint file was personally reviewed by this investigator. None of the approximately 20-25 complaints were of a safety or injury related nature. Most had to do with the customer not being satisfied with the performance of a product. There were several complaints suggesting that the firm's tire repair products either further damaged the tire or did not fix flats adequately.

Ms. Ciccone has worked at the firm for the past three years. She stated that she was unaware of the firm ever being involved in any type of civil liability action because of a defective product.

PRODUCT EXAMINATION AND DESIGN:

The company has a large display area in their offices, and Ms. Ciccone stated that most every product distributed by the firm is currently on display. Many of the products are tools, tire pressure gauges, and other items without chemical products, however a number of the items also use glues, adhesives, or other solvents which would require warning labeling. In a brief review, many of those products did appear to be properly labeled; however, the following items were selected as samples for a more detailed review.

1) Victor brand model #V-500 pressurized lock de-icer: this product is advertised as an automobile lock de-icer and lubricant. The aerosol tip is inserted in the lock and the main cartridge then pushed, expelling the container contents into the lock. Photographs of the packaged product and the actual container are attached as Exhibit "C."

The contents are reportedly an isopropyl alcohol mixture manufactured by the Ashland Chemical Co., Columbus, OH. however this was not confirmed. The MSDS is attached as Exhibit "D." The container is actually filled by the Ultramotive Corporation, Bethel, VT.; an invoice showing Victor Automotive's purchase of a quantity of the filled de-icer units from the Ultramotive Corp. is attached as Exhibit "E." The filled containers are then individually labeled and put in the hang tag style packaging by Victor Automotive employees, and then distributed directly to retailers directly from the Des Plaines, IL. plant.

The container is 3" high and 7/8" diameter; the principle display panel is 2.7 inches. All labeling is printed vertically on the container. The principle display panel contains the brand name information "Victor pressurized V-500 Lock De-Icer" and is printed together with a subtitle "automatically thaws frozen locks. See precautions on back. Net wt. 5/8 oz. (18g)." If the container is then rotated 180 degrees, the warnings "Warning-Flammable. Contents under pressure. Do not use near heat or open flame. Avoid contact with eyes. In case of contact, flush thoroughly with water. If irritation persists, get medical attention. Do not puncture or incinerate container. Do not expose to heat or store at temperatures above 120 degrees. Keep out of reach of children." At another location on the container is the statement "contains isopropyl alcohol."

A number of violations of 16 CFR 1500.121 are apparent. First, the statement of principle hazard should be displayed on the principle display panel, not on the back. Second, this information must be displayed horizontal to the base of the container, yet all labeling is vertical. (Note: this size cylinder may be eligible for an exemption under 1500.121). Third, The product container itself can spin or turn within the bubble display window of the packaging, and the labeling on the container would thus be displayed randomly. For this reason, the statement of principle hazard must be displayed on the front of the display card, not on the back side of the hang card packaging as it is presently.

Twelve units of the model #V-500 de-icer were collected as sample #97-830-3080. The product also comes in a larger size, model #V-502. This model has the same labeling violations as the #V-500, so sample #97-830-3201 was collected of that model also.

2) Victor brand model #VB-58 Bicycle Tire Emergency Repair: this product is advertised as an aerosol product that "repairs tires instantly." Photographs of the packaged product and the actual container are attached as Exhibit "F."

(6

The hazardous ingredients in this product are

The container is 4 1/4" high and 2" in diameter; the principle display panel is 8.5 inches. The principle display panel contains the brand name information "Victor Bicycle Tire Emergency Repair" and is printed together with the subtitles "seals and inflates," and "repairs tires instantly." "Net wt. 4 oz. (113g)." The warning labeling on the front panel states "Danger. Extremely flammable. Contents under pressure. Read back panel carefully." The back panel has the warnings "Caution: Keep away from heat, sparks, and open flame. Do not puncture or burn container. Exposure to heat or prolonged exposure to sun may cause bursting. Do not expose to heat above 120 degrees F. Avoid prolonged contact with skin and breathing of vapor or spray mist. Do not take internally. Keep out of reach of children."

This investigator did not have adequate reference materials to determine whether the signal wording and first aid treatment cautions were adequate. The warning "do not take internally" may suggest that directions whether or not to induce vomiting may be missing.

A number of violations of 16 CFR 1500.121 are apparent on this product. First, the product container itself can turn within the bubble display window of the packaging, and the labeling on the can would thus be displayed randomly. For this reason, the statement of principle hazard must be displayed on the front of the display card itself. The statement of principle hazard is included on the front of the display card; however, due to the placement of the container in the packaging half of the wording is covered by the can and/or the bubble window and is not visible. Second, the statement of principle hazard type size is in 5/64" type, not the required 3/32" size type. Third, the rear panel cautions are in 3/64" type, not the required 1/16" size type.

Twelve units of the model #V-B-58 "Victor Bicycle Tire Emergency Repair" product were collected as sample #97-830-3202.

3) Victor brand model #V-301 vinyl adhesive: this product is

advertised as a vinyl adhesive that "repairs all leather or vinyl," and "for home or auto." Photographs of the packaged product and the actual container are attached as Exhibit "I."

The hazardous ingredients in this product a


The tube style container is 4 1/2" high and 1 1/8" wide; the principle display panel is 5.85 inches. The principle display panel contains the brand name information "Victor Vinyl Adhesive" and is printed together with the subtitles "for all vinyl and leather repairs." "Net wt. 1.5 oz." The warning labeling on the front display panel of the tube states "Danger. Extremely flammable. Harmful or fatal if swallowed. Vapors harmful. See back panel." The back panel has the warnings "Danger. Contains acetone and tetrahydrofuran. Do not use near heat, sparks, and open flame. Keep container closed when not in use. If swallowed, do not induce vomiting. Avoid prolonged breathing of vapors. Use with adequate ventilation. Avoid contact with skin or eyes. In case of eye contact, flush with plenty of water and call physician. Keep out of reach of children."

This investigator did not have adequate reference materials to determine whether the signal wording and first aid treatment cautions were adequate. Tetrahydrofuran typically requires a first aid direction to give 1 or 2 glasses of water and induce vomiting, yet the opposite is listed on the tube. Further evaluation will be necessary to determine which is correct, given the combination of hazardous ingredients in this product.

There are some clear violations of 16 CFR 1500.121 regarding this product. First, the signal word and principle statement of hazard on the product tube itself are all in 5/64" type size instead of the required 5/32" size type. Second, the display card has the statement "Caution: extremely flammable. See back panel." The appropriate signal word should be "Danger" instead of "Caution." The remainder of the statements of principle hazard listed on the tube should also be repeated on the display packaging card. Further, the signal word should be in 5/32" size type rather than the current 1/8" type size currently being used. Also the

product is packaged in a collapsible metal tube and the warnings are not at the dispensing end as is required. Four units of the model #V-301 vinyl adhesive product were collected as sample #97-830-3203.

4) Victor brand rubber cement: 3/8 ounce size tube. This product is used in a number of the firm's Victor brand tire repair kits, including #'s V-56, V-101, V-402, V-103, V-104, V-106, V-107, V-108, V-410, V-414, V-417, V-418 and V-420. Please refer to the color brochure of these products in Exhibit "B" for further reference. Photographs of the actual product tube are attached as Exhibit "L."



The tube style container is 2 1/4" high and 3/4" wide; the principle display panel is 1.7 inches. The principle display panel contains the brand name information "Victor Rubber Cement" and is printed together with the subtitle "for all rubber repairs." "3/8 fl. oz.(12ml)." The warning labeling on the front display panel of the tube states "Danger. Extremely flammable, harmful or fatal if swallowed, vapors harmful. See back panel." The back panel of the tube has usage directions and distributor identification information only; there are no further cautionary statements and no first aid information at all.

No reference materials suggesting the proper caution and first aid information for heptane was available to this investigator. The ingredient ethyl alcohol typically requires the signal word and principle statement of hazard "Warning- Flammable," with the additional caution statements "contains denatured alcohol. Do not use near heat or flame. Avoid contact with eyes. In case of eye contact, flush thoroughly with water. If irritation persists, get medical attention. Keep out of reach of children." None of this information was present on the tube itself, though it presumably might be listed on the hang card packaging of the various tire repair kits the rubber cement is placed inside. This was not confirmed. Also the warnings are not at the dispensing end of this collapsable metal tube as required.

EIR 12/04/96

Victor Automotive Products 501 S. Wolf Road Des Plaines, IL. 60016

Four units of the Victor brand rubber cement, 3/8 ounce tube product were collected as sample #97-830-3204. Due to the large numbers of products containing this cement, the individual tube itself was selected for sampling rather than each model unit the cement is contained in.

7


The labeling design is done in-house by Victor Automotive personnel, in consultation with an outside artist. The personnel contacted during this inspection did not know when the labeling content for these sampled products was last reviewed. They were apparently unaware that several of these products had been found to contain many of the exact same labeling violations during a 5/23/88 inspection of the firm. Please refer to that inspection report for further detail. It is not known what compliance action was taken by the CPSC at that time.

SAMPLE DOCUMENTATION:

A sample collection receipt was issued to Ms. Ciccone for the samples collected; a copy of that receipt is attached as Exhibit "O." There was no charge for the samples. Ms. Ciccone also provided a number of invoices to show the sale of the sample products to out-of-state retailers; that information is attached in Exhibit "P." A brief affidavit obtained from Ms. Ciccone is attached as Exhibit "Q." Copies of the five sample collection reports, 97-830-3080 and 97-830-3201 thru 3204 are attached as Exhibit "R."

DISTRIBUTION:

Mr. Calhoun provided the following sales figures for the sampled products:



DISCUSSION WITH MANAGEMENT:

The personnel contacted were cooperative throughout the inspection visit. The office personnel were extremely busy answering telephones, etc. as this in the peak of their sales season making it difficult to conduct the inspection; despite this Victor personnel did search files to locate the documentation necessary for this inspection. At the close of the visit Ms. Ciccone asked "if any fines would be issued." It was explained to her that unlike some other federal regulatory agencies the CPSC did not issue on the spot penalties; instead the information collected during the visit would be reviewed by CPSC Compliance personnel and a formal notice to make corrections would be issued to the firm in writing. Ms. Ciccone was told that any decisions regarding civil penalties would be made by CPSC Compliance personnel at a later time. As the personnel contacted did not know that the firm had been previously inspected by the CPSC, no mention was made of the previous labeling violations noted on many of these products.

ATTACHMENTS:

Exhibit "A" - Notice of Inspection issued on 12/04/96.

Exhibit "B" - Product catalog and wholesale pricing information.

Exhibit "C" - Photos of the Victor brand model #V-500 lock de-icer (5/8 oz. size) and display packaging.

Exhibit "D" - MSDS for #V-500 and #V-502 de-icer products.

Exhibit "E"

Exhibit "F" - Photos of the Victor brand model #VB-58
Bicycle Tire Emergency Repair product.

Exhibit "G" - MSDS for #VB-58 Bicycle Tire Emergency Repair product.

Exhibit "

Exhibit "I" - Photos of the Victor brand model #V-301 vinyl adhesive product.

Exhibit "J" - MSDS for the model #V-301 vinyl adhesive.

Exhibit

Exhibit "L" - Photos of the Victor brand rubber cement

Exhibit "M" - MSDS for the rubber cement.

product.

Exhibit "N" - Inneice aboute Winter Winter See

Exhibit "O" - Sample collection receipt issued on 12/04/96.

Exhibit "P" - Invoices showing Victor Automotive's sale of the sampled products to an out-of-state retailer.

Exhibit "Q" - Affidavit obtained from Ms. Ciccone.

Exhibit "R" - Sample collection reports #'s 97-830-3080; 97-830-3201 thru 3204.

Exhibit "S" - Original investigation request.

Dennis R. Blasius

Investigator

MKE-RP

 \mathcal{N}



~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~							
	U.S. CONSUMER PRODUCT SAFETY COMMISSION						
	NOTICE OF INSPECTION						
1. DATE	3. FROM (Area Office and Address)						
12/14/16	EPST - M - WALLE RESIGNAT post						
2. TIME	Walte Real Williak Oge Com						
1 11)	WAUKISHA WI 53,88						
P.M.							
A. NAME AND TITLE OF INDIVIDUAL							
Tom Ciccone, OKANO MARKONE							
B. FIRM NAME							
Norther Automoth	on property our						
4. TO C. NUMBER AND STREET A							
SU 5 WOLF I							
D. CITY, STATE AND ZIP CO	DE						
Des pinnes,	TL. 60016						
Notice of Inspection is hereby giv	en pursuant to:						
• Flammable Fabrics Act (	15 U.S.C. 1191 et seq.);						
Federal Trade Commission	on Act (15 U.S.C. 41 et seq.);						
l							
<ul> <li>Sections 16, 19 and 27 o</li> </ul>	f the Consumer Product Safety Act (15 U.S.C. 2065, 2068 and 2076)						
<ul> <li>Section 704(a) of the Federal Food, Drug, and Cosmetic Act (21 U.S.C. 374(a)) [Authority for inspections in connection with the Poison Prevention Packaging Act of 1970 (15 U.S.C. 1471 et seq.)] and/or</li> </ul>							
Gradien 11(h) afaba Fad	The state of the s						
Section 11(b) of the Fed	eral Hazardous Substances Act as Amended (15 U.S.C. 1270(b)).						
6. FREEDOM OF INFORMATION RE	QUIREMENTS						
	·						
Those from whom information	n is requested should state whether any of the information submitted is believed						
to contemp of letate to a flade a	ecret or other matter which should be considered by the Commission to be						
commential and Austrel any o	the information is believed to be entitled to exemption from disclarus, but the						
Commission ander the bloatto	IS OF the Freedom of Information Act (15 115 C 552) Approximation according						
this dami of confidentiality must be in writing, and any request for exemption of the information from dis							
closure must be made in accordance with the Commission's Freedom of Information Act regulations, 16 CFR Part 1015.							
Ĭ							
	·						
7. SIGNATURE (Authorized CPSC Offi							
Olding one inumorized CPSC Offi							
Our Blean Dr	THURSTER BOASINS						
	-77.57 67704						

CPSC Form 296 (9/79)

1

±U.S. GPO: 1993-359-414/9/376



## JULY 1, 1996

SUPERSEDES ALL PREVIOUS PRICE LISTS

## VICTOR PRODUCTS, INC.

501 South Wolf Road Des Plaines, Illinois U.S.A. 60016

TELEPHONE: (847) 298-8870

TOLL FREE: (800) 423-4201

FAX: (847) 298-2573

## PRICES THIS PRICE LIST SUPERSEDES ALL OTHERS AND IS SUBJECT TO CHANGE WITHOUT NOTICE.

TERMS
NET 30 DAYS.

#### MINIMUM ORDERS \$250.00.

## FREIGHT PREPAID ON SHIPMENTS OF \$750.00 OR MORE WITHIN CONTIGUOUS U.S.A.

## GUARANTEE UNCONDITIONALLY GUARANTEED AGAINST DEFECTS IN MATERIAL AND WORKMANSHIP.

## RETURN GOODS APPROVAL MUST BE SECURED FROM VICTOR AND/OR MONKEY GRIP BEFORE MERCHANDISE WILL BE ACCEPTED.

MOTE

MONKEY GRIP MAY BE COMBINED WITH VICTOR PRODUCTS
TO MEET FREIGHT REQUIREMENTS.

VICTOR PRODUCTS, INC.
501 South Wolf Road
Des Plaines, Illinois U.S.A. 60016
Telephone (847) 298-8870
Toll Free (800) 423-4201
FAX (847) 298-2573



### **JOBBER** PRICE SHEET

JULY 1, 1996 SUPERSEDES ALL PREVIOUS PRICE LISTS

Monkey Grip, Inc.

501 S. Wolf Road • Des Plaines, IL 60016

Phone: (847) 298-8870 • Toll Free: 800-423-4201

Fax: (847) 298-2573



## NOTE: MONKEY GRIP MAY BE COMBINED WITH VICTOR PRODUCTS TO MEET FREIGHT REQUIREMENTS.

PRICES: This price list supersedes all others and is subject to change without notice.

TERMS: Net 30 days.

MINIMUM ORDERS: \$250.00

FREIGHT: Freight prepaid on shipments of \$750.00 or more within contiguous U.S.A.

GUARANTEE: Unconditionally guaranteed against defects in material and workmanship.

RETURN GOODS: Approval must be secured from Monkey Grip and/or Victor before merchandise

will be accepted.

Monkey Grip, Inc.

501 S. Wolf Road • Des Plaines, IL 60016

Phone: (847) 298-8870 • Toll Free: 800-423-4201

Fax: (847) 298-2573



# LOCK DE-ICER DISPLAYS

V500 LOCK DE-ICER AND LUBRICANT AUTOMATICALLY THAWS FROZEN LOCKS.

625 FL.OZ. (18q)

## LOCK DE-ICER

& LUBRICANT

LOCK DE-ICER

LOCK DEHCER

4

LOCK DEJCER

1

toen he keb

LOCK DEJCER

LOCK DEMCER

1

LOCK DEVICER

N.

LOCK DE ICER

LOCK DESCER LOCK DESCER

भूतम् १६

וסלה טביוננט

¥

.



V502 SUPER SIZE LOCK DE-ICER 1 25 FL 0Z. (36g)

## SUPER SIZE LOCK



## V5005K LOCK DE-ICER DISPL Designed as sidekick or wing dis be used on peg heoks any where

DOCK DE-ICER DISPLAY

Designed as sidekick or wing display at can
be used on peg flooks anywhere in your store

Dimensions: 13-1-2 wide x 50 high x 9 deep

Contains 144 packages of V500 Lock De Icer

#### V502SK SUPER SIZE LOCK DE-ICER DISPLAY

Designed as sidekick or wing display, it can be used an neg hooks anywhere in your store. Dimensions 13.1.2 uide x.50 high x.9 deep. Captains 141 necknoor of 1502 kings. See half the keep.



3

2

## VICTOR PRODUCTS, INC. DES PLAINES, IL 60016 PHONE 708-298-8870

FAX 708-298-2573 1-800-423-4201

## VICTOR

## Tire Repair

















Asili Padibasili II. seesa gilialasagaa alayiliswa asi Miziraja































A SECULLARY



AAKULEINENDE Soorenalis

Sidewəli

Repair Kit





VICTOR COMPANY TIRE REPAIR HIT



Calledia (1907) (Dan eritanila) (Dan eritanila)



V-416 STEEL BELTED RADIAL SIDEWALL REPAIR KIT Super Strong Tyrek Cord















CALL BOTTON ACC



#### SOYOUSIIRE REPAIR



V-56 BICYCLE PATCH KIT For All Rubber Repair



VB-58 EMERGENCY BICYCLE TIRE REPAIR Inflates And Seals



V-602 BIKE & MOTORCYCLE TIRE SEALER Seals & Prevents Leaks In All Bicycle or Motorcycle Tires



A THE THE PARTY OF THE PARTY OF



PLOTE SSIONAL BICYCLE TUBE PATCH KIT
PROFESSIONAL BICYCLE TUBE PATCH KIT
Professional Facial For All
IUSpenial School &
All Terrain Beycles



V-55 SUPER THINS NO THUMPING PATCHES For Al Bicycle Tires

### ADHESIVES

#### **ADHESIVES**



V-250 ALL PURPOSE E-Z FIX EPOXY 2-5 FL Oz. Tubes



V-251 ALL PURPOSE CONTACT CEMENT 1.5 Fl. Oz. Tubo



V-252 GAS TANK LEAK SEALER 1.5 Fl. Oz. Tubo



V-253 WINDOW AND WINDSHIELD SEALER 1.5 Oz. Not Wt. Tube



V-254 BATTERY ANTI-CORROSION GEL 15 FL Oz. Toba



V-255 RUBBER REPAIR AND SEALER 15 FL Oz. Tobe



V-256 ALUMINUM REPAIR 1,5 Fl. Oz. Tubo



V-257 NO. 1 HARD SETTING GASKET CEMENT 1.5 Fl. Oz. Tube



V-258 NO. 2 NON-HARDEN-ING GASKET CEMENT 1.5 FL. Oz. Tube



V-259 STEEL REPAIR 15 FL Oz. Tube



Y-260 WEATHER STRIP ADHESIVE 1.5 Oz. No. Wr. Tubo



V-261 LICUID SOLDER 1.5 FL Oz. Tube



V-262 CLEAR SELICONE SEALER LS Dz. No Wr. Tube



Y-263 WHITE SELCOME ADHESIVE 1.5 Oz. No. WI. Tube



YMYL ADMESHE 15 R. Or. No.



V-912 REAR VIEW MIRROR ADHESIVE 1-.02 Fl. Oz. Primer, 1-.02 Fl. Oz. Adhesive



V-913 EPOXY REPAIR SYSTEM SMALL Not Wr. 33 Oz.



VEX-914 EPOXY REPAIR SYSTEM LARGE Nor Wr. 1.4 Oz.



V-915 GAS TANK REPAIR KIT Net Wr. 33 Oz



V-916 AUTO TRIM ADHESIVE 2-.02 Fl. Oz. Primer, 1-.02 fl. Oz. Adhesive



V-270 RTV BLUE SILICOME GASKET MAKER 3 Oz. Noi Wt. Tubo



V-271 HI-TEMP RED SILICONE GASKET MAKER 3 Oz. Not Wt. Tube



V-910 SUPER GLUE 11 Oz (3 g) Net Wt.



V-911 Super Gel Plus Ji Oz (3 g) Not Wit



V-275 WHITE LITHIUM GREASE LUBRICANT 2.1 Go. No. Tabi




EZZE WHITE STICT LIGHT CANTENINE SELCONE LEGETE IN THE











#### VILL



### VICTOR EXHAUST SYSTEM REPAIR PRODUCTS

V-803 MUFFLER



MUFFLER BANDAGE

المنافعة الأواري

Y-806 EXHAUST PIPE REPAIR KIT 2"×24"



MUFFLER MENDER and Exhaust System Sealer

• 6 oz. tube



V-808 MUFFLER MENDER KIT end Exhaust System Sealer

6 oz. tube sealer

64 sq. inch fiberglass patch



MUFFLER MENDER and Exhaust System Seale WE SOL



ROCKCAST EXHAUST SYSTEM

UNIVERSAL TAIL

PIPE HANGER

- REPAIR KIT • 4 az. bottle hardener
- 270 sq. inch bandage



METAL STRAPPING KIT

• 5 ft. strapping
• 2 nuts and boits

MUFFLER CLAMPS

V-825 1%

V-826 11/1"

V-827 2" V-828 21/4" V-829 21/2"



EXHAUST SYSTEM REPAIR KIT

• 48 sq. inch repair

- 5 ft. strapping
  2 nuts and bolts
  3 oz. tube sealer



V-813 ROCKCAST ECHAUST BANDAGE REPAIR KIT



Y-802 MR. SILENCER EXHAUST SYSTEM



MEDIL STRAPPIN



- 80 sq. inch repoir 72 sq. inch screen







MR. SILENCER' MUFFLER REPAIR KIT

### AND MONKEY GRIDE

TIRE GAUG

V885D ▼ VICTOR TIRE GAUGE DISPLAY

### TIRE GAUGE

• EACH DISPLAY CONTAINS 24 PREMIUM GAUGES



• REFILLS AVAILABLE IN 12 COUNT BULK PACKS

PROPER
TIRE PRESSURE
INCREASES
IMPROVES
AND PROLONGS



ÜŠÄ

- FOR PASSENGER CARS, VANS, MOTORCYCLES, TRAILERS, BICYCLES
- 10-50 PSI WITH EASY TO READ MEASURE AND POCKET CLIP
- IMPORTANT TIRE PRESSURE INFORMATION PRINTED ON DISPLAY.
- EACH GAUGE INDIVIDUALLY UPC LABELED.
- MADE IN USA



M8861D ▲ MONKEY GRIP

TIRE GAUGE DISPLAY

T. M. ME.




1994

VICTOR PRODUCTS, INC.
DES PLAIMES IL 60016 • PHONE 708 198 8370
FAX 708 298 2573 • 1-806 423-4201


USA

## ACTUR TAPES (S. HOLD) DOWNS



# VICTOR EMERGENCY ROAD KITS

Great gifts for every motorist. Perfect for all holiday seasons. Ideal promotional items.



VICTOR

PRODUCTS, INC

015 PLAINIS II 500 PHONE 298-29<del>8-1</del>1

1-800-423-420

### ACCESSORIES

MINI DOWNS

DETAILING
DUST
BRU!

VISOR ORGANIZER

RESICTOR
DOOR S

GLO LIGHT FELLOW
2 POR 12 POR
SAFETY LIGHTS

SAFETY LIGHTS

SAFETY LIGHTS

VISOR ORGANIZER

VISOR WALLET



WHISTLE

PULL-APART Key Chair UTILITY KNIFE KFY CHAIN PLASTIC COIL KEY HOLDER POCKE KILLE

COIN HOLDEN

IGHTER







**VICTO**?

V-5142

ESID FE SIN COMM ESID SIN COMM

V 5146 ELEMENT for hadren from law Swel Act Good

V-5160 ELEMENT Short Length for Chevrole

N-5145 ELEMENT For Redister Type Short Shed Acts Guard Short Shed Acts Guard

V-5172 POP OUT Was Shart Cartains Knob for Charmond Armends Addrey, Compile

V-5144 ELEMENT Standard Langth



FOR ON LAND CO

COMPLETE UGHTER
THE SOT Knob for Compact
Led Imports

V-5154 COMPLET LIGHTE COMPLET COMPLETE HIM SHOT COMPLETE Address American

V-5152 POP 0011 POP 0



V.SI 4 POP OUT For Debas/More For Debas/More



SION SOUTH STATES





Commontain





V-5107 DOMEST ON US LEATHER AN VISE DUME AN VISE (C.D.)

LIGHTER ADAPTER
TOFT EXTENSION



N.5101 BALLE PLUG LIGHTER ADAPTER Indicated Plug For Indicated Plug For Indicated Application



Constitution to the Constitution of the Consti







# MERGENCY

For travel and everyday emergencies









V-237 REFLECTIVE TAPE

Ino 12 x 3/4 self adhesive strips





**▼ V-320 EMERGENCY** FAN BELT

Adjustable fan belt with cutter pliers fastener



TRIANGLE

Universally recognized signal for help. Extra

▲ V-782 SIPHON PUMP





V-660 BOOSTER CABLES 8 foot length

V-661 HEAVY DUTY BOOSTER CABLES

12 foot length



EMERGENCY AUTO
BANNERS

V-206 **EMERGENCY** BANNERS

2 vinyl banners with fasteners (ALL TOW and CALL POLICE



V-739 A SECURITY ALERT WHISTLE With key ring



#### ▲ V-316 HEATER HOSE REPAIR KIT

clamps and coment





▲ V-234 REFLECTORS

V-235 REFLECTORS Two red 3 industry reflectors

V-236 REFLECTORS



#### V-209 EMERGENCY ROAD KIT

#### V-211 EMERGENCY ROAD KIT

two flores pressumed their florer in dean and lack

#### DELUXE EMERGENCY ROAD KIT



1991 VICTOR PRODUCTS, INC. DES PLAIMES IL 60016

PHONE 708 298 8870 FAX 708 298 2573

1-800-423-4201



**HOSE CLAMPS** 


6 clamps, assorted sizes

▲ V-315 RADIATOR HOSE REPAIR KIT Includes 3 couplers, 2 clamps

## INTERIOR INT



MONKET



#### MONKEY GRIP INNER TUBES

Full line of high quality auto inner tubes for radial or bias tires. Instructions and application guide included. Available in 8 popular sizes:

- F/FR13 VALVE TR13
- K/KR14 VALYS TRIS
- G/GR13 VALVE TR13
- K/KR15 VALVE TR13

VICTOR
PRODUCTS, INC.

1995


- G/GR14 VALVE TR13
- M/MR15— VALVE TR13

- DES PLAINES -11 60016 PHONE 708 298 8870 LAX 708 293 2573
- G/GR15 VALVE TR13
- 700/75 OR 15/16 VALVE
- 1-800-423-4201

TR 150

#### V977 Sports inner tube

15 inch tube with complete rubber repair kit, including patches, cement, buffer. For floating, splashing river tubing, water towing, snow sledding.



# VIETOR AUTOMOTIVE ACCESSORIES






TISSUE HOLDER With Tissue



SHOE SAVERS V-937 Red V.934 Grey V-938 Blue V-935 Black V-936 Brown



TO 13

VICTOR

ELECTRONIC

CAR MAT TAPE 4 sets books a os, Z'×21/4"

ā ū

122 000

7



KEY CHAINS: V-729 BELT CLIP y-73Î للكنية LEATHER



y-730 DELUXE LEATHER V-732 MIRROR V-733 MAGNETIC y-735 RETRACTABLE PULL-APART



KY HODER SAN WITH BLADE LENEVER STI

ASH TRAYS V-780 Saul Pro V-781 Gal Tre V-784 Fly Top MELICE 

មាធា

ជាជា ជា 🕮

000



LICENSE FRAMES V-760 Reflective Pink, V-761 Non-reflective Charcoal, V-762 Reflective Purple, V-763 Reflective Blue, V-764 Reflective Clear, V-765 Reflective Red, V-766 Reflective Amber



DOOR SAVERS 2 per card V-703 Chrome, Wide 27" V-704 Chrome, Nerrow 27" V-705 Black, Narrow 27" V-706 Block, Narrow 6" Y-707 Black, Wide 6" V-708 Clear, Wide 6"



TORX TRIM SCREWS Headlight and taillight, 8 per card



**Stick** 

**A**?

LICENSE PLATE **FASTENERS** V-772 White nylon, 4 per card V-744 Deluxe White nylon, 4 per card



Headlight & Trim Screudriver Set

TORX HEADLIGHT AND TRIM DRIVER SET 1 #115, 1 #120



TORX SCREWDRIVER SET 5 sizes: T10, T15, T20, T25, T30



LIGHTED VISOR MIRROR Cip-on

> WIDE ANGLE MIRROR Stick-on



V-749

Clip-on

DUAL LIGHT

VISOR MIRROR

BLIND SPOT MIRRORS V-755 2" Round V-756 3" Round N-757 MIRRORS V-757 3%" Round BUG SCREEKS Fiberglass, 6 strings, 2 hooks V-904 24"×70" V-906 24" × 84"



VISOR MIRRORS
V-750 Ramovable, 3½" × 5½"
V-751 Stick-on, 3½" × 5½"
V-752 Factors 2 maps, 4" × 9½

VICTOR

PRODUCTS, INC. Des Plaines, IL 60016 1-800-423-4201

**AUTOMOTIVE** 



## AIR PUMPS



STIRRUPS

• FOR ANY INFLATABLE

VICTOR
PRODUCTS, INC.,
DES PLAINES, IL 60016
PHONE 708-298-8870
FAX 708-298-2573
1-800-423-4201

• FOR ANY INFLATABLE

### MONKE GRIP

m PROFESSIONAL TIRE REPAIR PRODUCTS A FULL LINE OF PROFESSIONAL QUALITY AUTO TIRE REPAIR AND MAINTENANCE PRODUCTS MONKE STRIP MONKE MONKE GRIPIONKE GRIP MUGE DUAL FOOT *NONKE : F JRIP MONKE GRIP MONKE: SRIP MONKETA MONKE : A JRIP MONKETTE SRIP USA USA MONKET SIRIP STEEL BEITED HEVAL FOR ALL RUBBER REPAIRS PHONE 708-298-8870, FAX

IRE /	AND RUBBER REPAIR			
<b>1-802</b> 0	TUBELESS TIRE PLUG REFILLS BLACK, 100 - 5/16", 50 - 1/4" PER BOX			
I-8021	RADIAL TIRE PLUG REFILLS RED, 100 - 1/4" PER BOX			10C:
A-8023	VULCA STRIP KIT 72 - 1/4: X 2' VULCA STRIPS, 1-M8083 TIRE RASP, 1 - M8085 INSERTING TOOL, 1/2 PT, CEMENT		7(1)	GRIP OF
A-8024	VULCA STRIPS 50 - 1/4" X 2" PER BOX		間	
4-8026	STEEL BELTED HEAVY DUTY TIRE REPAIR KIT  1 - T HANDLE RASP, 1 - T HANDLE INSERTING TOOL, 1 - 1/2 PT. CEMENT, 20 - HEAVY DUTY BROWN REPAIR STRINGS - 4" LENGTH		Super Tree	
<b>4-8027</b>	STEEL BELTED TIRE REPAIR STRINGS, BROWN HEAVY DUT	SUF	्र विधिय	5
<b>4-8028</b>	TRUCK TIRE REPAIR STRINGS EXTRA HEAVY DUTY 50 PER BOX - 7-14" LENGTH	J PILL	Zuber 1	-JEF
M-8029	STEEL BELTED TIRE REPAIR KIT 25 - STRING REPAIRS & LENGTH: 1 - M8083 RASP. 1-M8085 INSERTING TOOL: 1 OZ. RUBBER CEMENT	2 6 6	C.JE.	U.
M-8030	STEEL BELTEN THE REPAIR STRINGS, BLACK	10000		Plur
M-8031	SUPER SEAL TIRE REPAIR STRINGS 5-7/8" LENGTH - 52 PER BOX	2001 010 70 M	adial paor	Er
M-8036	RADIAL TIRE PATCHES 2-7/16" DIAMETER ROUND, 30 PER BOX	og. doldi		radil -1
M-8037	RADIAL TIRE PATCHES 3-1/8" DIAMETER ROUND, 20 PER BOX	£a. ( <b>\</b>	radial radial rad	hal ra
M-8040	STEEL BELTED RADIAL SIDEWALL PATCHES 10 - 1-3/4" X.3" PATCHES PER BOX	on le	redial redial	l redir
M-8041	STEEL BELTED RADIAL SIDEWALL PATCHES  10 - 2-1/4" X 4-1/2" PATCHES PER BOX	· ·	raoidi	
M-8044	CROSS-FLEX TIRE PATCHES 3' X 4" 2 PLY, 10 PER BOX CROSS-FLEX TIRE PATCHES	\		
M-8045 M-8046	CROSS-FLEX TIRE PATCHES 4"X 5" 2 PLY, 10 PER BOX CROSS-FLEX TIRE PATCHES		, V ;	1
M-8047	5-1/2" X 7-1/4" S PLY, 10 PER BOX  CROSS-FLEX TIRE PATCHES			
M-8051	6-34" X 8-3/8" 4 PLY, 10 PER BOX CHEMICAL PATCHES		4	
M-8052	1-58" DIAMETER ROUND, 40 PER BOX			, R C
M-8053	2-1/4" DIAMETER ROUND, 30 PER BOX CHEMICAL PATCHES 3-1/8" DIAMETER ROUND, 20 PER BOX			
M-8056	and the second of the second o		Translation of the state of the	
M-8057				
N-8060	20 DIAMOND, MEDIUM SIZE			
M-8064	COLD PATCH KIT - BOX - 12 M-8065 PER SLEEVE EACH BOX CONTAINS 3 -1; X 1; - 1 - 2 X 3° PATCHES, CEMENT, BL	JFFER		
M-8065	COLD PATCH KIT - BOX 3:1"X1", 1-2 X3" PATCHES, CEMENT, BUFFER			

M-88	19 TRUCK TUBELESS TIRE KIT HEAVY DUTY. 5 - 7-1/4" STRINGS, 2 T HANDLE TOOLS, CEMENT
M-88	20 REFILL KIT FOR M-8819 5 STRINGS, CEMENT MONKEY
M-88	MONTH AND THE PROPERTY OF THE
M-88	
, M-88	23 LEAK PROOF TIRE SEALANT 6 OUNCE PLUS VALVE CORE REMOVER
M-88	24 BIKE & MOTORCYCLE PUNCTURE SEALANT KIT 4 OUNCE PLUS VALVE CORE REMOVER
M-88	25 RADIAL TIRE PATCHES 4 MEDIUM
M-88	TIRE REPAIR KIT 2 - 3" x 4" PATCHES, BUFFER, CEMENT
M-88	27 FARM & HIGHWAY TIRE PATCHES
M-88	
M-88	
M-86	
. M-88	
M-88	
M-88	33 VALVE EXTENSIONS - 1-1/4"
M-8	THE STATE OF THE S
M-81	35 VALVE TOOL - 4 WAY
M-84	MONKEY SR
M-8	37 VALVE CAPS - HEX, CHROME
M-8	MONKEYES
M-8	The state of the s
M-8	41 VALVE SLEEVES - CHROME
M-8	MALVE CLEEVES CUROME
M-8	The state of the s
M-8	
M-8	
	10 : 50 LBS.; U.S.A.
M-8	49 TIRE GAUGE, AIR & LIQUID FOR TRACTOR
M-8	The state of the s
	20. 120 LBS, U.S.A.
M-8	51 TIRE GAUGE LOW PRESSURE
W-8	TO CHE CAUCE SUPER CAUCE
<b>H</b> •	

三里 三型 三

#### **CHEMICALS**

M-8062

RUBBER CEMENT

1/2 PINT

M-8063

M-8066

RUBBER CEMENT

QUART

**BOOT CEMENT** 

1/2 PINT

M-8067 **BOOT CEMENT** 

QUART

M-8069 LIQUID BUFFER

& CLEANSER SOAPSTONE REMOVER



#### **MISCELLANEOUS TOOLS**

M-8080

洼

TIRE MARKING CRAYONS YELLOW - 12 PER BOX

M-8083

TIRE RASP - HEAVY DUTY

SCREWDRIVER HANDLE - 12 PER BOX

M-8085

INSERTING TOOL - HEAVY DUTY OPEN EYE NEEDLE, SCREWDRIVER

HANDLE - 12 PER BOX

M-8089

T HANDLE TIRE RASP, PROFESSIONAL 12 PER BOX

M-8091

T HANDLE INSERTING TOOL -OPEN EY PROFESSIONAL 12 PER BOX

M-8095

BUFFER - STITCHER COMBINATION

12 PER BOX

M-8097

ROLLER STITCHER TOOL

M-8099

**WIRE BRUSH BUFFER** 

#### TIRE HARDWARE

M-8110 **VALVE CAPS** 

DOME TYPE, PLASTIC, 50 PER BOX

M-8112

**VALVE CORES** SHORT - 50 PER BOX

M-8113

VALVE CAPS, SLOTTED HEAD

METAL - 50 PER BOX

M-8115

4-WAY VALVE TOOL 12 PER BOX

M-8117

VALVE EXTENSIONS, PLASTIC

3/4" - 24 PER BOX

M-8119

VALVE EXTENSIONS, PLASTIC

1-1/4" - 24 PER BOX

M-8121

VALVE EXTENSIONS, PLASTIC

1-3/4" - 24 PER BOX

M-8125

SNAP-IN TIRE VALVES (TR413) .453" X 1-1/4" - 24 PER BOX

M-8128

SNAP-IN TIRE VALVES (TR415)

.625" X 1-1/4" - 24 PER BOX

M-8131

SNAP-IN TIRE VALVES (TR418) .453" X 2" - 24 PER BOX

SNAP-IN TIRE VALVES (TR423) .453" X 2-1/2" - 24 PER BOX I-8134

M-8137 SNAP-IN TIRE VALVES (TR425)

.625" X 2" - 24 PER BOX



#### CARDED FOR RETAIL

(i	
ispinced way of notures	
延	• <b> </b>  .
疆	

TUBELESS TIRE VALVE SET - CHROME M-4134 SHORT - 4 PER CARD (TR413), SLEEVES & CAPS

TUBELESS TIRE VALVE SET - CHROME M-4184 LONG - 4 PER CARD (TR418), SLEEVES & CAPS

**TUBELESS TIRE VALVES, SNAP-IN** M-4130 2 PER CARD (TR413)

**TUBELESS TIRE VALVES, SNAP-IN M-4**150 2 PER CARD (TR415)

**TUBELESS TIRE VALVES, SNAP-IN** M-4180 2 PER CARD (TR418)

TUBELESS TIRE VALVES, SNAP-IN M-4230 2 PER CARD (TR423)

**TUBELESS TIRE VALVES, SNAP-IN** M-4250 2 PER CARD (TR425)

CHEMICAL PATCHES - MEDIUM M-8796 25 PER CARD

**HOT PATCHES** M-8798 **8 DIAMOND PATCHES** 

HOT PATCH KIT M-8799 "C" CLAMP, 3 PATCHES, BUFFER

STEEL BELTED TIRE STRING REPAIR M-8800 30 BROWN STRINGS. 4":

TUBELESS TIRE REPAIR KIT M-8801 8 ROUND PLUGS, NEEDLE, CEMENT

M-8802 TUBELESS TIRE REPAIR KIT 8 STRINGS, NEEDLE

TUBELESS TIRE REPAIR KIT M-8803 RADIAL, 6 PLUGS, NEEDLE, CEMENT

STEEL BELTED TIRE REPAIR KIT M-8804 3 BLACK STRINGS, NEEDLE, RASP, CEMENT

**REFILL KIT FOR M-8804** M-8805 5 BLACK STRINGS, CEMENT

HEAVY DUTY TIRE REPAIR KIT, ALL TIRES M-8806 5 HEAVY DUTY BROWN STRINGS, 2 T HANDLE TOOLS, CEMENT

REFILL KIT FOR M-8806 M-8807

5 HEAVY DUTY BROWN STRINGS, 4", CEMENT

T HANDLE TIRE RASP - PROFESSIONAL M-8808

T HANDLE INSERTING TOOL - PROFESSION. M-8809

TUBE PATCH KIT, FEATHEREDGE M-8810 1 OVAL, 4 ROUND FOIL BACK PATCHES CEMENT, BUFFER

E-Z FIX RUBBER PATCH KIT M-8811 3 - 1" x 1", 3 - 2" x 1", 2 - 2" X 3" PATCHES, CEME

E-Z FIX BIKE PATCH KIT M-8812

3 - 1" X 1", 1 - 2" X 3" PATCHES, CEMENT, BUFFER

CHEMICAL SEAL PATCH KIT M-8813

3 SMALL, 2 LARGE ROUND PATCHES, CEMENT, BUFFE

SHOP PATCH KIT, CARDED CAN, BUFFER CAP, 24 - 1" X 1". 4 M-8814

PATCHES, CEMENT

SUPER THIN PATCH KIT M-8815 SMALL, 2 LARGE ROUND PATCHES, CEVEN

RADIAL TIRE PATCH KIT **M-88**16

SMALL I LARGE PATCHES CENENT BART

THE REPORT








M-8901 INNER TUBE, RADIAL & BIAS - F/FR13
M-8902 INNER TUBE, RADIAL & BIAS - G/GR13
M-8904 INNER TUBE, RADIAL & BIAS - G/GR14
M-8905 INNER TUBE, RADIAL & BIAS - K/KR14
M-8907 INNER TUBE, RADIAL & BIAS - K/KR15
M-8908 INNER TUBE, RADIAL & BIAS - M/MR15
M-8909 INNER TUBE, RADIAL & BIAS - G/GR15

#### MONKEY GRIP, INC.

DES PLAINES, IL 60016, PHONE 708-298-8870, FAX 708-298-2573

1-800-423-4201





- QUALITY PRODUCTS
- COMPLETE PROGRAM
- SPACE SAVING CARD SIZE
- EYE CATCHING PACKAGING



FUSE ASST. AMERICAN/ JAPANESE CARS A.T.C. Type, 1 Ea. 10, 15, 20, 25, 30 Amps



AGC-1 1 AMP A.G.C. GLASS **FUSES** 5 Per Card



28 AMP A.T.C. TYPE **FUSES** 5 Per Card



V-563 **FUSE ASSORTMENT** AMERICAN CARS Glass Type, 1 Ea. S.F.E. 14, 20 1 Ea. A.G.C. 10, 15, 30 Amps



AGC-5 5 AMP A.G.C. GLASS FUSES 5 Per Card



AT-30 30 AMP A.T.C. TYPE FUSES 5 Per Card



V-564 **FUSE ASSORTMENT** JAPANESE CARS Glass Type, 1 Ea. A.G.C. 5, 10, 15, 20, 30 Amps



AGC-20 20 AMP A.G.C. GLASS **FUSES** 5 Per Card



4 AMP S.F.E. GLASS **FUSES** 5 Per Card



V-565 **FUSE ASSORTMENT** UNIVERSALS USE Glass Type, 1 Ea. S.F.E. 20 1 Ea. A.G.C. 10, 15, 20, 30 Ampo



AT-5 5 AMP A.T.C. TYPE FUSES 5 Per Card



SFE-71/3 71/2 AMP S.F.E. GLASS FUSES. 5 Per Card



Y-566 **FUSE ASSORTMENT** EUROPEAN CARS Ceramic Type, 2 Ea. G.B.C. & 1 Ea. G.B.C. 20, 16, 25 Arispa



AT-10 10 AMP AT.C. TYPE **FUSES** 5 Per Card



38 AMP S.F.E GLASS **FUSES** 





AIR CONDITIONING for All S.M. Cars, 1 Per Card

Constitutes AIR CONDITIONING



- SE2 (1) AUTO FLASHER Heavy Duty, 1 Per Card



V-572 IN LINE FUSE HOLDEN