

V-1157. AUTO BULBS 2 Per Card



V-1157MA AUTO BULBS 2 Per Card



V-1156 **AUTO BULBS** 2 Per Card



V-2067 AUTO BULBS 2 Per Card



1311 Pilipi dini sa Maragana



V-97 **AUTO BULBS** 2 Per Card



V-194 **AUTO BULBS** 2 Per Card

HEAVY DUTY

V-90

AUTO BULBS

2 Per Card



V-554 AUTO BULB



REPLACEMENT KIT 2 Ea. 1157, 1157/NA, 1156, 2 Ea. 194





V-211-28 AUTO BULBS. Moodlights - Blue 2 Per Card



V-1004 **AUTO BULBS** 2 Per Card



V-1895R AUTO BULBS Moodlights - Red 2 Per Card



V-1948 AUTO BULBS Moodlights - Blue 2 Per Card




V-194R AUTO BULBS Moodlights - Red 2 Per Card



Auto Bulbs Auto Fuses

V-63	AUTO BULBS — 2 Per Card	V-555	AUTO EMERGENCY ELECTRICAL KIT — V-563 Glass Fuse Asst., 1 Ea. 194, 211-2, 1156, 1157, 1157 NA Buids
V-89	AUTO BULBS — 2 Per Card	V-556	AUTO EMERGENCY ELECTRICAL KIT — V-562 Blade Type
V-90	AUTO BULBS — 2 Per Card		Fuse Asst., 1 Ea. 194, 211-2, 1156, 1157, 1157, NA Bulbs
V-97	AUTO BULBS — 2 Per Card	V-557 🌁	TRUCK EMERGENCY ELECTRICAL KIT — V-562 Blade Type
V-168	AUTO BULBS — 2 Per Card		Fuse Asst., 1 Ea. 552 Flasher, 194, 211-2, 1156, 1157, 1157, NA Bulbs
V-194	AUTO BULBS — 2 Per Card	V-558	TRUCK EMERGENCY ELECTRICAL KIT — V-563 Gene Fuse
V-194R	AUTO BULBS — Moodlights - Red 2 Per Card		Asst., 1 Ea 552 Flasher, 194, 211-2, 1156, 1157, 1157, NA Bulbs
V-194B	AUTO BULBS — Moodlights - Blue 2 Per Card	V-559	AUTO EMERGENCY ELECTRICAL KIT — V-563 Glass Fose
V-211-2	AUTO BULBS — 2 Per Card	• 000	Asst., 1 Ea. 552 Flasher, 194, 211-2, 1156, 1157, 1157, NA
V-211-2R	AUTO BULBS — Moodlights - Red 2 Per Card	W 560	Bulbs
V-211-2B	AUTO BULBS — Moodlights - Blue 2 Per Card	V-560	AUTO EMERGENCY ELECTRICAL KIT — V-562 Blade Type Fuse Asst. 1 Ea. 552 Flasher, 194, 211-2, 1156, 1157
V-906X	AUTO BULBS — 2 Per Card		1157 NA Bulbs
V-921	AUTO BULBS — 1 Per Card	V-562	FUSE ASSORTMENT-AMERICAN JAPANESE CARS —
V-1003	AUTO BULBS — 2 Per Card	V-563	ATC Type, 1 Ea 10, 15, 20, 25, 30 Amps FUSE ASSORTMENT-AMERICAN CARS — Glass Type.
V-1004	AUTO BULBS — 2 Per Card	-305	1 Ea S F E 14, 20 — 1 Ea A G C 10, 15, 30 Amps
V-1141	AUTO BULBS — 2 Per Card	V-564	FUSE ASSORTMENT-JAPANESE CARS — Glass Type.
V-1154	AUTO BULBS — 2 Per Card	W ECE	1 Ea A G C 5, 10 15, 20, 30 Amps FUSE ASSORTMENT-UNIVERSALS USE — Glass Type
V-1156	AUTO BULBS — 2 Per Card	V-565	1 Ea S F E 20 — 1 Ea A G.C 10, 15, 20, 30 Amps
V-1157	AUTO BULBS — 2 Per Card	V-566	FUSE ASSORTMENT-EUROPEAN CARS — Ceramic
V-1157NA	AUTO BULBS — 2 Per Card		Type, 2 Ea. G.B.C. 8 — 1 Ea. G.B.C. 20, 16, 25 Amps.
V-1160	AUTO BULB — 1 Per Card	V-570 V-572	FUSE PULLER — For AT C. & Glass Type Fuses IN LINE FUSE HOLDER — Black Housing, Red 18 Guage
V-1195	AUTO BULB — 1 Per Card	V-312	8" Wire
V-1445	AUTO BULBS — 2 Per Card	V-909	AIR CONDITIONING FUSE — For All G M. Cars, 1 Per Card
V-1895	AUTO BULBS — 2 Per Card	AGC-1	1 AMP GLASS A.G.C. FUSES — 5 Per Card
V-1895R	AUTO BULBS — Moodlights - Red 2 Per Card	AGC-2	2 AMP GLASS A.G.C. FUSES — 5 Per Card
V-1895B	AUTO BULBS — Moodlights - Blue 2 Per Card	AGC-3	3 AMP GLASS A.G.C. FUSES — 5 Per Card 5 AMP GLASS A.G.C. FUSES — 5 Per Card
V-2057	AUTO BULBS — 2 Per Card	AGC-5 AGC-10	10 AMP GLASS A.G.C. FUSES — 5 Per Card
V-2057NA	AUTO BULBS — 2 Per Card	AGC-15	15 AMP GLASS A.G.C. FUSES — 5 Per Card
V-3022	AUTO BULBS — 2 Per Card	AGC-20	20 AMP GLASS A.G.C. FUSES — 5 Per Card
V-3175	AUTO BULBS — 2 Per Card	AGC-25	25 AMP GLASS A.G.C. FUSES — 5 Per Card
V-550	AUTO FLASHER — Heavy Duty, D O T.	AGC-30	30 AMP GLASS A.G.C. FUSES — 5 Per Card
V-552	AUTO FLASHER — Heavy Duty DOT.	AT-5	5 AMP A.T.C. TYPE FUSES — 5 Per Card
V-552BX	AUTO FLASHER — Heavy Duty D O T Boxed	AT-10	10 AMP A.T.C. TYPE FUSES — 5 Per Card
V-554	AUTO BULB REPLACEMENT KIT — 2 Ea 1157.	AT-15 AT-20	15 AMP A.T.C. TYPE FUSES — 5 Per Card 20 AMP A.T.C. TYPE FUSES — 5 Per Card
	194, 1 Eal, 1156, 1157 NA	AT-25	25 AMP A.T.C. TYPE FUSES — 5 Per Card
		AT-30	30 AMP A.T.C. TYPE FUSES — 5 Per Card
		SFE-4	4 AMP GLASS S.F.E. FUSES — 5 Per Card
		SFE-71/2	712 AMP GLASS S.F.E. FUSES — 5 Per Card
		SFE-9	9 AMP GLASS S.F.E. FUSES — 5 Per Card
		SFE-14	14 AMP GLASS S.F.E. FUSES — 5 Per Card
		SFE-20	20 AMP GLASS S.F.E. FUSES — 5 Per Card
		SFE-30	30 AMP GLASS S.F.E. FUSES — 5 Per Card





· 102

VICTOR TIRE HARDWARE



TIRE VALVE **ACCESSORIES**

13/4" VALVE EXTENSIONS



VALVE CAPS



CHROME HEX VALVE CAPS



















.my TIRE

VALVE TOOL















AIR TOOL ACCESSORIES












Exhibit "C"
Victor Automotive Products
12/04/96 Inspection



Photos of the Victor brand model #V-500 lock de-icer product; the larger size .V-502 has identical labeling. These are samples #97-830-3080 and 97-830-3201.





Exhibit "C"
Victor Automotive Products
12/04/96 Inspection



Photos of the Victor brand model #V-500 lock de-icer product; the larger size V-502 has identical labeling. These are samples #97-830-3080 and 97-830-3201.








Exhibit "C"
Victor Automotive Products
12/04/96 Inspection



Photos of the Victor brand model #V-500 lock de-icer product; the larger size V-502 has identical labeling. These are samples #97-830-3080 and 97-830-3201.



MATERIAL SAFETY DATA SHEET



ASHLANU CHEMICAL, INC. Sobsidiary Of Ashland Oil Inc P.O. BOX 2219 COLUMBUS, OHIO 43216 (614) 889-3333

24-HOUR Emergency Telephone 1(800) 274-5263 or 1(800) ASHLAND

RECEIVED FEB 0 6

TECTYL 482 002732~

Page: 1

De

THIS MSDS COMPLIES WITH 29 CFR 1910.1200 (THE HAZARE & 4/10; + "D"

12/04/16 Euspechien

Data Sheet No: Prepared: U1

0223605-007.005 01/18/95 11/21/94 01/28/95 Supersedes: Print Date:

PRODUCT: 7432488 INVOICE: 128145 INVOICE DATE: 01/22/85 TO: ULTRAMOTIVE CORP CUSTANIO BLVD 98THEL

05 50 074 9199410-

VT 05032

ULTRAMOTIVE CORP PO BOX 58 BETHEL

VT D5032

ATTN: PLANT MGR. / SAPETY DIR.

SECTION I-PRODUCT | DENTIFICATION

General or Generic IO: PETROLEUM BASED RUST PREVENTATIVE

SECTION 11 - COMPUNENTS

THE COMPOSITION OF THIS PRODUCT IS BEING WITH-ELD AS A TRADE SECRET.

NTP AND OSMA CARCINOGENS AND CHEMICALS SUBJECT TO THE REPORT-OF SARA TITLE III SECTION 313 ARE IDENTIFIED IN THIS SECTION. SEE DEPINITION PAGE FOR CLARIFICATION IF PRESENT, IARC, N'ING REQUIREMENTS OF

INGREDIENT .	Percent	PEL .	TLV	Note
CORROSION INHIBITOR	10-25	5 M3/M3	5 MG/M3	.(1)
ANTI-WEAR ADDITIVE	1-5		•	(2)
DISPERSANT SPIKE ADDITIVE	1-5			(3)
ALIPHATIC HYDROCARBON MIXTURE CAS #: 64742-63-8	55-70	5 Mg/M3	5 MG/M3	(4)
ETHYLENE CLYCOL MONOBUTYL ETHER CAS #: 111-78-2	5-10	25 PPM - SKIN	25 PPM - SKIN	(5)

Notes:

- (1) PEL/TLY 15 FOR OIL MIST. ACGIH SHORT TERM EXPOSURE LIMIT (STEL) FOR OIL MIST IS 10 MG/CUM. THIS PROPRIETARY MATERIAL CONTAINS A METAL SULFONATE. RECENT INFORMATION INDICATES THAT SUCH SULFUNATES HAVE THE POTENTIAL TO CAUSE ALLERGIC SRIN REACTIONS.
- (2) PEL/TLV NOT ESTABLISHED FOR THIS MATERIAL THIS PRODUCT CONTAINS 80-80% ZINC C1-C14 ALKYLDITHIOPHDSFHATE (CAS #68648-42-3). ZINC COMPOUNDS ARE REPORTABLE UNDER SECTION 313 OF SARA TITLE 111.
- (3) PEL/TLY NOT ESTABLISHED POR THIS MATERIAL THIS PRODUCT CONTAINS 50% ANTINONY DIALKYLDITHIOCARBAMATE.ANTINONY COMPOUNDS ARE REPORTABLE UNDER SECTION 313 OF SARA TITLE III.
- (4) PEL/TLV IS POR OIL MIST, ACGIH SHORT TERM EXPOSURE LIMIT (STEL) FOR OIL MIST IS 10 MG/CUM.
- (5) SKIN ABSORPTION MAY CONTRIBUTE TO THE OVERALL ABSORPTION OF THIS MATERIAL. APPROPRIATE MEASURES SHOULD BE TAKEN TO PREVENT ABSORPTION SO THAT THE TLY AND/OR PEL ARE NOT INVALIDATED. SEE SECTION V. THIS CHEMICAL IS SUBJECT TO THE REPORTING REQUIREMENTS OF SECTION 313 OF SARA TITLE 111. NIOSH RECOMMENDS A LINIT OF 5 PPM TWA FOR A 10 HOUR WORKDAY AND 40 HOUR WORKWEEK.

	SEC	TLON I	II-PHYSICAL DAIA		
Boiling Paint	for COMPONENT(5-10%)		\$	336.00 Deg F 168.88 Deg C) 760.00 mm Hg
Vapor Pressure	for COMPONENT(5-10%)		•,	0.68 cm Ho 77.00 Deg P 25.00 Deg C)
Specific Vapor Density	AIR # 1				> 1.00
Specific Gravity		•		•(77,00 Deg F 25.00 Deg C)
Percent Volutiles			•.		1-10%
Evaporation Rate				SLC	WER THAN ETHER
Appearance					NOT SPECIFIED
State			•		LIQUID
Form					HETER SOLIA

MATERIAL SAFETY
DATA SHEET



ASHLAND CHEMICAL, INC.
Subsidiary of Ashiene Dit. Inc.
P.O. BOX 2219
COLUMBUS, OHIO 43216
(614) 889-3333

24-HOUR -Emergency Telephone 1(800) 274-5263 or 1(800) ASHLAND

002732

TECTYL 482

Page:

SECTION VII-SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED;

SMALL SPILL: ABSORB LIQUID ON VERMICULITE, FLOOR ABSORBENT OR OTHER ABSORBENT MATERIAL.

LARGE SPILL, ELIMINATE ALL IGNITION SOURCES (FLARES, FLAMES INCLUDING PILOT LIGHTS, ELECTRICAL SPARKS), PERSONS
NOT WEARING PROTECTIVE EQUIPMENT SHOULD BE EXCLUDED FROM AREA OF SPILL UNTIL CLEAN-UP HAS BEEN COMPLETED.
STOP SPILL AT SOURCE, PREVENT FROM ENTERING DRAINS, SEWERS, STREAMS OR OTHER BODIES OF WATER PREVENT FROM
SPREADING, IF RUNDERS, NOTIFY AUTHORITIES AS REQUIRED. PHMP OR VACUUM TRANSFER SPILLED PRODUCT TO
CLEAN CONTAINERS FOR RECOVERY. ABSORD UNRECOVERABLE PRODUCT. TRANSFER CONTAMINATED ABSORBENT, SOIL AND
OTHER MATERIALS TO CONTAINERS FOR DISPOSAL.

PREVENT RUN-OFF TO SEWERS, STREAMS OR OTHER BODIES OF WATER. IF RUN-OFF OCCURS, NOTIFY PROPER AUTHORITIES AS REQUIRED, THAT A SPILL HAS OCCURED.

WASTE DISPOSAL METHOD:

SMALL SPILL: DISPOSE OF IN ACCORDANCE WITH ALL LOCAL, STATE AND FEDERAL REGULATIONS.

LARGE SPILL: DISPOSE OF IN ACCORDANCE WITH ALL APPLICABLE LOCAL, STATE AND FEDERAL REGULATIONS.

SECTION VILL-PROTECTIVE EQUIPMENT TO BE USED

RESPIRATORY PROTECTION: IF WORKPLACE EXPOSURE LIMIT(S) OF PRODUCT OR ANY COMPONENT IS EXCEEDED (SEE SECTION II) A NIOSH/MS-M APPROVED AIR SUPPLIED RESPIRATOR IS ADVISED IN ABSENCE OF PROPER ENVIRONMENTAL CONTROL. OS-M REQULATIONS ALSO PERMIT OTHER NIOSH/MS-M RESPIRATORS (NEGATIVE PRESSURE TYPE) INDEX SPECIFIED CONDITIONS (SEE YOUR INDUSTRIAL HYGIENIST). ENGINEERING OR ADMINISTRATIVE CONTROLS SHOULD BE IMPLEMENTED TO REDUCE EXPOSURE.

VENTILATION: PROVIDE SUFFICIENT MECHANICAL (GENERAL AND/OR LOCAL EXHAUST) VENTILATION TO MAINTAIN EXPOSURE BELOW TLV(S).

PROTECTIVE CLOVES: WEAR RESISTANT GLOVES SUCH AS:, NEOPRENE, NITRILE RUBBER

EVE PROTECTION: CHEMICAL SPLASH GOGGLES IN COMPLIANCE WITH OSHA REGULATIONS ARE ADVISED: HOWEVER, DSHA REGULATIONS ALSO PERMIT OTHER TYPE SAFETY GLASSES. CONSULT YOUR SAFETY REPRESENTATIVE.

OTHER PROTECTIVE EQUIPMENT: TO PREVENT REPEATED OR PROLONGED SKIN CONTACT, WEAR IMPERVIOUS CLOTHING AND BOOTS.

SECTION IX-SPECIAL PRECAUTIONS OR OTHER COMMENTS

CONTAINERS OF THIS MATERIAL MAY BE HAZARDOUS WHEN EMPTIED, SINCE EMPTIED CONTAINERS RETAIN PRODUCT RESIDUES (VAPOR, LIQUID, AND/OR SOLID), ALL HAZARD PRECAUTIONS GIVEN IN THIS DATASHEET MUST BE OBSERVED.

THE INFORMATION ACCUMULATED HEREIN IS BELIEVED TO BE ACCURATE BUT IS NOT WARRANTED TO BE WHETHER ORIGINATING WITH THE COMPANY OR NOT, RECIPIENTS ARE ADVISED TO COMPIRM IN ADVANCE OF NEED THAT THE INFORMATION IS CURRENT, APPLICABLE, AND SUITABLE TO THEIR CIRCUMSTANCES.

SECTION X-LABEL INFORMATION

WARNING!

COMBUSTIBLE LIQUID AND VAPOR

MAY CAUSE EYE AND SKIN IRRITATION.

COMPONENT(S) MAY BE ABSORBED THROUGH SKIN IN TOXIC AMOUNTS.

IN-MLATION OF VAPOR MAY CAUSE IRRITATION OF NASAL AND RESPIRATORY PASSAGES.

SWALLOWING MAY CAUSE IRRITATION OF MOUTH, ESOPHAGUS, AND GASTROINTESTINAL SYSTEM AND MAY BE FATAL. HANDLING & STORAGE:

KEEP AWAY FROM HEAT, SPARKS, AND OPEN PLANE. USE OR STORE ONLY WITH ADEQUATE VENTILATION, AVOID CONTACT WITH EYES AND SKIH, WEAR SAFETY GLASSES OR GODGLES, RESISTANT GLOVES, AND OTHER APPROPRIATE PROTECTIVE EQUIPMENT ESSENTIAL FOR YOUR OPERATION, MINIMITE EXPOSURE THROUGH GOOD HYGIENIC PRACTICES. DO NOT TRANSFER TO UNLABELED CONTAINER. DO NOT USE CUTTING OR WELDING TORGH ON THIS CONTAINER (EVEN EMPTY). FOR INDUSTRIAL USE ONLY

FIRST AID:

EYES; FLUSH THOROUGHLY WITH WATER. GET MEDICAL ATTENTION IMMEDIATELY.

SKIN: WASH THOROUGHLY WITH SOAP AND WATER.

INHALATION: IF AFFECTED, REMOVE TO FRESH AIR. IF BREATHING IS DIFFICULT, GET MEDICAL ATTENTION.

INGESTION: DO NOT INDUCE VONITING, CALL A PHYSICIAN OR POISON CONTROL CENTER IMMEDIATELY.

CHRONIC INFORMATION:

CONTAINS MATERIAL(S) WHICH MAY CAUSE BLOOD ABMORMALITIES, CENTRAL MERVOUS SYSTEM REPEATORY SYSTEM, EVE. KIDNEY AND/OR LIVER DAMAGE. CONTAINS; PETROLEUM DIL AND ETHYLEME GLYCOL MONOBUTYL ETHER(ÉGNBE).

*** COMPONENTS APPEAR IN SECTION 11 ***

MATERIAL SAFETY DATA SHEET



ASHLANU CHEMICAL, INC. Subsidiary DI Ashlend Oil. Inc P.O. BOX 2219 COLUMBUS. OHIO 43216 (614) 889-3333

Z4-HUUR Emergency Telephone 1(800) 274-5263 or 1(800) ASHLAND

002732

TECTYL 482

Page: 2

SECTION IV-FIRE AND EXPLOSION INFORMATION

FLASH POINT (PMCC)

160.0 - 170.0 Dep F

71.1 -

EXPLOSIVE LIMIT

(LOWEST VALUE OF COMPONENT) LOWER -

EXTINGUISHING MEDIA: REGULAR FOAM OR CARBON DIOXIDE OR DRY CHEMICAL

MAZARDOUS DECOMPOSITION PRODUCTS: MAY FORM TOXIC MATERIALS:, CARBON DIOXIDE AND CARBON MONOXIDE, VARIOUS HYDROCARBONS, ETC., SULFUR COMPOUNDS, CALCIUM OXIDE

FIREFIGHTING PROCEDURES: WEAR SELF-CONTAINED BREATHING APPARATUS WITH A FULL FACEPIECE OPERATED IN THE POSITIVE PRESSURE DEMAND MODE WHEN FIGHTING FIRES.

SPECIAL FIRE & EXPLOSION HAZARDS: NEVER USE WELDING OR CUTTING TORCH ON OR NEAR DRUM (EVEN EMPTY) BECAUSE PRODUCT (EVEN JUST RESIDUE) CAN IGNITE EXPLOSIVELY.

VAPORS ARE HEAVIER THAN AIR AND MAY TRAVEL ALONG THE GROUND OR SE MOVED BY VENTILATION AND IGNITED SY HEAT, PILOT LIGHTS, OTHER PLAMES AND IGNITION SOURCES AT LOCATIONS DISTANT FROM MATERIAL HANDLING POINT. ALL FIVE GALLON PAILS AND LARGER METAL CONTAINERS INCLUDING TANK CARS AND TANK TRUCKS SHOULD BE GROUNDED AND/OR BONDED WHEN MATERIAL IS TRANSFERRED.

HFPA CODES:

HEALTH- 1

FLAMMABILITY- 2

REACTIVITY- 0

SECTION V-HEALTH HAZARD DATA

PERMISSIBLE EXPOSURE LEVEL: NOT ESTABLISHED FOR PRODUCT. SEE SECTION 11.

***FECTS OF ACUTE OVEREXPOSURE:**

EYES - EXPOSURE CAUSES EYE IRRITATION. SYMPTOMS MAY INCLUDE STINGING. TEARING, REDNESS, AND SWELLING.

SKIN - EXPOSURE CAUSES SKIN IRRITATION. PROLONGED OR REPEATED EXPOSURE MAY DRY THE SKIN. SYMPTOMS MAY INCLUDE REDNESS, BURNING, DRYING AND CRACKING, SKIN BURNS AND SKIN DAMAGE.PRE-EXISTING SKIN DISCROERS MAY BE AGGRAVATED BY EXPOSURE TO THIS MATERIAL.

SKIN ABSORPTION IS POSSIBLE. AND MAY CONTRIBUTE TO SYMPTOMS OF TOXICITY PROM OTHER ROUTES OF EXPOSURE.

BREATHING - EXPOSURE TO VAPOR OR MIST IS POSSIBLE.

SHORT-TERM IN-ALATION TOXICITY IS LOW. BREATHING SMALL AMOUNTS DURING NORMAL HANDLING IS NOT LIKELY TO CAUSE HARMFUL EFFECTS; BREATHING LARGE AMOUNTS MAY BE HARMFUL.

SYMPTOMS MAY INCLUDE:

-IRRITATION (NOSE, THROAT, RESPIRATORY TRACT) - PRE-EXISTING LUNG DISCROERS, E.G. ASTHMA-LIKE CONDITIONS, MAY BE AGGRAVATED BY EXPOSURE TO THIS MATERIAL.

-CENTRAL HERVOUS SYSTEM DEPRESSION (DIZZINESS, DROWSINESS, WEAKNESS, FATIGUE, NAUSEA, HEADACHE, UNCONSCIOUSNESS)
SWALLOWING - SINGLE DOSE ORAL TOXICITY IS LOW, SWALLOWING SMALL AMOUNTS DURING NORMAL HANDLING IS NOT LIKELY TO CAUSE HARMFUL EFFECTS; SMALLOWING LARGE AMOUNTS MAY BE HARMFUL.

SYMPTOMS MAY INCLUDE:

-CASTROINTESTINAL IRRITATION (NAUSEA, VOMITING, DIARRHEA)
THIS MATERIAL CAN ENTER THE LUNGS DURING SMALLOWING OR VOMITING AND CAUSE LUNG INFLAMMATION AND/OR DAMAGE.

FIRST AID:

IF ON SKIN, REMOVE CONTAMINATED CLOTHING, WASH EXPOSED AREA WITH SOAP AND WATER. IF SYMPTOMS PERSIST, SEEK MEDICAL ATTENTION. LAUNDER CLOTHING BEFORE REUSE.

IF IN EYES: IF SYMPTOMS DEVELOP, MOVE INDIVIDUAL AWAY FROM EXPOSURE AND INTO FRESH AIR. FLUSH EYES GENTLY WITH WATER WHILE HOLDING EYELIDS APART. IF SYMPTOMS PERSIST OR THERE IS ANY VISUAL DIFFICULTY, SEEK MEDICAL ATTENTION.

IF SWALLOWED: DO NOT INDUCE VOMITING, KEEP PERSON WARM AND QUIET, AND GET MEDICAL ATTENTION.

REATHED: IF SYMPTOMS DEVELOP, IMMEDIATELY MOVE INDIVIDUAL AWAY FROM EXPOSURE AND INTO FRESH AIR. SEEK IMMEDIATE MEDICAL ATTENTION: KEEP PERSON WARM AND OUIET, IF PERSON IS NOT BREATHING, BEGIN ARTIFICIAL RESPIRATION, IF BREATHING IS DIFFICULT, ADMINISTER OXYGEN.

PRIMARY ROUTE(\$) OF ENTRY;

INHALATION, SKIN CONTACT, SKIN ABSORPTION

EFFECTS OF CHICAIC OVEREXPOSURE:

ETHYLENE GLYCOL MONOBUTYL ETHER (GLYCOL ETHER EB) CAUSES HARM TO THE FETUS IN LABORATORY ANIMAL STUDIES. TO THE FETUS OCCURS ONLY AT EXPOSURE LEVELS THAT HARM THE PREGNANT ANIMAL. THE RELEVANCE OF THESE FINDINGS TO HUMANS IS UNCERTAIN.

OVEREXPOSURE TO THIS MATERIAL (OR ITS COMPONENTS) HAS BEEN SUGGESTED AS A CAUSE OF THE FOLLOWING EFFECTS IN LABORATORY ANIMALS, AND MAY AUGRAVATE PRE-EXISTING DISORDERS OF THESE ORGANS IN HUMANS: ANEMIA, LIVER ABNORMALITIES, KIDNEY DAMAGE, LUNG DAMAGE, BLOOD ASMORMALITIES, TESTIS DAMAGE, SPLEEN DAMAGE

OVEREXPOSURE TO THIS MATERIAL (OR ITS COMPONENTS) HAS BEEN SURGESTED AS A CAUSE OF THE FOLLOWING EFFECTS IN HUMANS, AND MAY AGGRAVATE PRE-EXISTING DISCADERS OF THESE ORGANS:, CENTRAL NERVOUS SYSTEM EFFECTS


SECTION VI-REACTIVITY DATA

MAZARDOUS POLYMERIZATION: CANNUT OCCUR

STABILITY: STABLE

INCOMPATIBILITY: AVOID CONTACT WITH: STRONG OXIDIZING AGENTS

Exhibit "F"
Victor Automotive Products
12/04/96 Inspection



Various photos of the Victor brand model #VB-58 Bicycle Tire Emergency Repair product, sample #97-830-3202.




Exhibit "F"
Victor Automotive Products
12/04/96 Inspection





Various photos of the Victor brand model #VB-58 Bicycle Tire Emergency Repair product, sample #97-830-3202.





Various photos of the Victor brand model #VB-58 Bicycle Tire Emergency Repair product, sample #97-830-3202.





Various photos of the Victor brand model #VB-58 Bicycle Tire Emergency Repair product, sample #97-830-3202.

SNAP PRODUCTS, INC. 501 SOUTH BASINGER ROAD, PANDORA, OH 45877 * (419) 384 - 3241

MATERIAL SAFETY DATA SHE

Exhia: + "G" Victor Automotive

12/04/96 INSPECTION

EMERGENCY PHONE NUMBER: (919) 286 - 4446

PRODUCT NAME: SNAP FIX-A-FLAT

PRODUCT NUMBER: 8 277, 5 455, 8 457

FIRE - 0 HEALTH - 2

REACTIVITY - 0

1. HAZARDOUS INCREDIENTS MATERIAL CAS REG. NO. TLV/UNITS SOURCE % 127 - 18 - 4 PERCLENE 25 PPM AHZO \ HZOIK N/A CHLORODIFLUOROMETHANE 75-45-6 1000 PPM ACGIH N/A

PHYSICAL PROPERTIES

NO DISTINGUISHING PATTERN AND TYPICAL ODOR APPEARANCE AND ODOR:

SOLUBILITY IN HO: TRACE SCIFIC GRAVITY $(H_2O = 1)$: 1.555

VAPOR PRESSURE: BOILING POINT F (C): N/A APP. 165 PSIG (MAX, @ 130 F)

N/A N/A % VOLATILES BY VOLUME: FREEZING POINT 'F ('C):

N/A **EVAPORATION RATE:** >1.0 VISCOSITY Sus @ 100 F: (BUTYL ACETATE = 1)

pH AS IS: NONE VAPOR DENSITY (AIR = 1): HEAVIER

FIRE AND EXPLOSIVE HAZARDS

FLAMMABLE LIMITS: LEL/URL - N/A FLASH POINT: NONE

METHOD'USED: N/A

EXTINGUISHING MEDIA: CARBON DIOXIDE, FOAM, WATER FOG.

ACIAL FIREFIGHTING PROCEDURES: KEEP CONTAINER COOL. USE EQUIPMENT OR SHIELDING TO

> PROTECT PERSONNEL AGAINST BURSTING, RUPTURING OR VENTING CONTAINERS. USE SELF CONTAINED BREATHING

APPARATUS.

UNUSUAL FIRE AND EXPLOSION HAZARDS: AEROSOL CANS MAY RUPTURE OR BURST ABOVE 130 F.

NONE OTHER SPECIAL HAZARDS:

FIRE NFPA CODE:

DOT FLAME EXTENSION: NON-FLAMMABLE

PACE 2 OF 4

SNAP PRODUCTS, INC. MATERIAL SAFETY DATA SHEET

PRODUCT NAME: SNAP FIX-A-FLAT

PRODUCT NUMBER: \$ 277, \$455, \$457

REACTIVITY DATA

STABILITY:

STABLE

CONDITIONS TO AVOID:

N/A

INCOMPATIBILITIES:

NONE WITH COMMON MATERIALS.

HAZARDOUS DECOMPOSITION: CARBON MONOXIDE, TRACÉ PHOSGENE, HYDROFLUORIC ACID, TRACE CHLORINE.

CARBON DIOXIDE.

HAZARDOUS POLYMERIZATION: WILL NOT OCCUR.

5 HEALTH HAZARD SUMMARY

EYES:

ACUTE EXPOSURE MAY CAUSE MILD IRRITATION.

KIN CONTACT:

ACUTE EXPOSURE MAY CAUSE A BURNING SENSATION, MILD IRRITATION, SLIGHT

DERMATITIS, OR DEFATTING.

SKIN ABSORPTION:

 LD_{50} RABBIT > 10,000 MG / KG.

INHALATION:

MAJOR POTENTIAL ROUTE OF EXPOSURE, LIGHT HEADEDNESS, DIZZINESS. HEADACHE, VERTIGO, DROWSINESS, NARCOSIS, IF TLV IS SUBSTANTIALLY EXCEEDED, UNCONSCIOUSNESS, OR DEATH MAY OCCUR IN EXTREME CASES. LC50 RAT 5040 PPM. AT HIGH LEVELS, MAY DEPRESS PLOOD PRESSURE.

INGESTION: .

AEROSOL CONTAINER, INGESTION IS NOT CONSIDERED PROBABLE. HOWEVER IF INGESTED, LD CO RAT 2.6 GM/KG. PRODUCT HAS LOW LEVEL TOXICITY. BEWARE OF

CHEMICAL PNEUMONIA IF INCESTED.

THRESHOLD LIMIT VALUE:

25 PPM BASED ON TLV OF PERCLENE.

MEDICAL CONDITION AGGRAVATED:

NONE KNOWN.

OWN OR SUSPECTED CARCINOGEN:

NTP / NIOSH SUSPECT CARCINGGEN: PERCLENE.

RECOMMENDED FIRST AID TREATMENT

EYES:

FLUSH WITH WATER FOR AT LEAST 15 MINUTES. CONTACT PHYSICIAN.

SKIN:

REMOVE CONTAMINATED CLOTHING AND FLUSH WITH WATER.

INHALATION:

MOVE TO FRESH AIR. IF BREATHING HAS STOPPED. ADMINISTER ARTIFICIAL RESPIRATION OR GIVE

OXYGEN IF AVAILABLE. CONTACT PHYSICIAN.

INGESTION:

CALL PHYSICIAN AND OBTAIN MEDICAL ATTENTION IMMEDIATELY.



PAGE3 OF 4

SNAP PRODUCTS, INC. MATERIAL BAFETY DATA SHEET

PRODUCT NAME: SNAP FIX.A.FLAT

PRODUCT NUMBER: 8 277, S453, 8457

7. SPECIAL PROTECTION INFORMATION

GENERAL VENTILATION:

SUFFICIENT

LOCAL EXHAUST:

RECOMMENDED

RESPIRATION PROTECTION:

IF TLV IS EXCEEDED, USE NIOSH / OSHA APPROVED RESPIRATOR WITH

CARTRIDGES FOR ORGANIC VAPORS.

MECHANICAL:

N/A

GLOVES:

TYPE

NONE IN NORMAL USE. MAY USE NEOPRENE, VITON, OR POLYVINYL COATED

GLOVES OR EQUIVALENT.

EYE PROTECTION:

NONE IN NORMAL USE. MAY USE SAFETY GLASSES OR GOGGLES.

OTHER:

DO NOT INTENTIONALLY INHALE FUMES. READ AND FOLLOW THE DIRECTIONS ON

THE PRODUCT LABEL. THEY ARE BEST GUIDE FOR USAGE IN MOST EFFECTIVE WAY.

TAKE NECESSARY SAFETY PRECAUTIONS.

SPILL OR LEAK PROCEDURES

CONTAINMENT PROCEDURES:

VENTILATE. AVOID BREATHING VAPORS. CONTAIN SPILL.

PROTECTIVE CLOTHING:

CHEMICAL RESISTANT BOOTS AND AN APRON IF SPLASHING IS A PROBLEM.

WASTE DISPOSAL PROCEDURES: DISPOSE IN ACCORDANCE WITH FEDERAL, STATE AND LOCAL REGULATIONS.

9. STORAGE AND HANDLING REQUIREMENTS

HANDLING PROCEDURES:

AVOID CONTACT WITH SKIN AND AVOID BREATHING VAPORS. PIPE VENTS

OUTDOORS. STORE IN A COOL DRY, VENTILATED AREA. VAPORS ARE HEAVIER:

THAN AIR AND WILL COLLECT IN LOW AREAS.

SNAP PRODUCTS, INC.

MATERIAL SAFETY DATA SHEET PRODUCT NAME: SNAP FIX-A-FLAT PRODUCT NUMBER : \$ 277, 8455, \$ 457 DOT SHIPPING INFORMATION - NOT TO BE USED AS TRANSPORTATION DOCUMENT PROPER SHIPPING NAME: ORM-D DOMESTIC HAZARD CLASS: 70 DOT LABEL: NON-FLAMMABLE GAS. AEROSOLS. DOT CLASS OR DIVISION: 2.2 UN / NA NUMBER : UN 1950 ERG GUIDE NUMBER : 12 INTERNATIONAL HAZARD CLASS: 2.2. CLASS 9, IF CERTIFIED FOR INTERNATIONAL SHIPPING AND DADO CODE IN ACCORDANCE WITH 49 CFR 171.12. IMDG PACKAGING GROUP: VESSEL STOWAGE CATEGORY: IMDG CODE PAGE: SEE 9022 IMO LABEL: NON-FLAMMABLE GAS. IF CERTIFIED FOR INTERNATIONAL SHIPPING AND IMOD CODE IN ACCORDANCE WITH 49 CFR 171.12, NO LABLES REQUIRED. PACKAGES SHOULD BE MARKED "AEROSOLS". SHIPPING LIMIT: 125 KG PER WOOD BOX / 55KG PER FIBERBOARD BOX (GROSS WEIGHT). ADDITIONAL INFORMATION: IMO PSN: AEROSOL DISPENSERS UN 1950. REGULATORY INFORMATION SPECIFY THE FOLLOWING:
OSHA - WHICH CHEMICAL(S) APPEAR ON HAZARDOUS SUBSTANCE LIST: PERCLENE,
RCRA HAZARDOUS WASTE CODE U210. RCRA REPORTABLE QUANTITIES AS A HAZARDOUS WASTE: NOT APPLICABLE THIS PRODUCT CONTAINS PERCLENE, CAS 127-18-4, A CHEMICAL SUBJECT TO SARA TITLE III REPORTING. SARA REPORTING REQUIREMENTS: TSCA (PCBS, ASBESTOS, NEW CHEMICALS) STATUS: NONE

NOTE: THE INFORMATION CONTAINED HEREIN IS BASED ON DATA CONSIDERED, ACCURATE, HOWEVER NO WARRANTY IS DIPPESSED OR IMPLIED REGARDING ACCURACY OF THE DATA OR RESULTS TO BE OSTABLED FROM THE USE THERBOF, IT IS USER'S OBLIGATION TO DETERMINE CONDITIONS OF SAFE USE OF THE PRODUCT AND WE ASSUME NO RESPONSEBLITY FOR ITS USE.

MANUFACTURER'S CONTACT / REVISED BY : DINESH J. PAREKH


REVISION DATE: 10-12-93

END MSDS.


Exhibit "I"
Victor Automotive Products
12/04/96 Inspection



Various photos of the Victor brand model #V-103 vinyl adhesive, sample #97-330-3203.







Various photos of the Victor brand model #V-103 vinyl adhesive, sample #97-330-3203.







Exhibit "I"
Victor Automotive Products
12/04/96 Inspection



NEGATIVES

6M









GREAT NORTHERN RESEARCH, INC. • (612) 379-9248 2901 S.E. 4th St. • Minneapolis, Minnesota 55414

MATERIAL SAFETY DATA

Lagrance Control and the Control of the Control of

I. Product Information

Date

May 9, 1991

Tradename

VA-1 Vinyl Adhesive

Chemical Name and Synonyms

N/A

Chemical Family

N/A

CAS Registry No. See below **EMERGENCY ASSISTANCE**

612-379-9248 OR 612-755-3861

HMIS Hazard Rating

Least (♦) Health 2

() Flammable 3 Slight

Moderate 2 (近) Reactivity 0

High

Extreme

II. Hazardous Ingredients

Principal Hazardous Components (Chemical And Common Names)

	CAS REG. NO.	%/WT APPROX.	TLV OSHA
Synthetic Resins	N/A	19 - 20%	N/A
Acetone	67 - 64 - 1	48 - 50%	1000 ppm
Methyl Ethyl Ketone	78 - 93 - 3	28 - 30%	200 ppm
Cyclohexanone	108 - 94 - 1	3 - 4%	200 ppm

III. Physical Data

Softening Point, R & B (°F/°C) N/A .

Specific Gravity ($H_2O=1$) .89 Boiling Point (F/C) 135°F. - 175°F.

Solubility in Water Miscible

Appearance and Odor Clear viscous liquid

Ether like odor

Percent Volatile (by Volume) 80%

Evaporation Rate (N. Ruty) Ac=1) 7.7

Vapor Pressure (mm Hg.) 82 - 186 MM Hg @ 25°F.

Vapor Density (Air - 1) 2.4

IV. Fire and Explosion Hazard Data

-4° TCC F. Flash Point.

Flammable Limits Lei 2.8Uei 13.2

Extinguishing Media dry Chem., CO, Foam Autoignition Temperature 400°F. +
Special Fire Fighting Procedures Do not enter confined fire space without proper protective equipment including a MIOSH approved SCBA. Use water spray to cool fire exposed surfaces and to protect personnel. Unusual Fire and Explosion Hazards

RESPIRATORY PROTECTION REQUIRED FOR FIRE FIGHTING PERSONNEL

(Caramad on Reverse Side)

NA - Not Applicable NDA - No Data Available

V. Health Hazard Data

Threshold Limit Value 200 ppm Methyl Ethyl Ketone, Cyclohexanone, 1000 ppm Acetone Signs and Symptoms of Exposure:

- 1. Acute Overexposure Irritation of eyes, nose, throat. Liquid may damage eye tissue.
- 2. Chronic Overexposure Headache, dizziness, skin dermatitis, anestetic nature, vomiting. Medical Conditions Generally Aggrevated by Exposure N/A

Primary Routes of Entry:

1. Oral LD₅₀ 7 gm/kg (rat)

- 4. Eye Irritation irritant
- 2. Dermai LD 4 gms/kg (rabbit)
- 5. Skin Irritation irritant

3. Inhalation LDsc NIDA

Chemical Listed as Carcinogen or Potential Carcinogen

National Toxicology Program Yes □ No 🗓 I.A.R.C. Monographs Yes □ No 🖹 OSHA Yes □ No 🗓

OSHA Permissible Exposure Limit 200 PPM TWA

ACGIH Threshold Limit-Value 200 ppm

Other Exposure Limit Used N/A Emergency and First Aid Procedures:

- 1. Inhalation Remove victim to fresh air and provide oxygen if breathing is difficult.
- 2. Eyes Flush eyes with copious quantities of water while holding eye lids open. If irritation persists, consult a physician.
- 3. Skin Wash skin with soap and water. Use emollient skin creams. If irritation persists, consult a physician.
- 4. Ingestion Do not induce vomitting. Get medical attention.

VI. Reactivity Data

Stability — Unstable Stable Conditions to Avoid

Hazardous Polymerization — May Occur 🗆 Will Not Occur 🖾

Incompatibility (Materials to Avoid)

Hazardous Decomposition Products

Strong acids, bases or oxidizers

Thermal decomposition may yield Carbon Monoxide

VII. Spill or Leak Procedures

Steps to be Taken in Case Material is Released or Spilled
Stay upwind and away from spill. Keep away from fire and flame. Universal type foam will suppress vapors. Use Sand on small spills, do not flush with water, use absorbant pads. Ventilate if indoors.

Waste Disposal

Dispose of in accordance with Local, County, State and Federal regulations

VIII. Special Protection Information

Respiratory Protection Use NIOSH Approved gas mask or respirator if above exposure limits

VentilationUse ventilation to mailtain below established exposure limits, use approved ventilat.

Protective Gloves Yes if repeated skin contact is probable. Chemical gloves

Eye Protection Chemical splash goggles to prevent eye damage, irritation

Other Protective Equipment it is suggested that a source of clean water be available in work

area for flushing eyes and skin. Impervious clothing should be worn if needed.

IX. Special Precautions


Precautions to be Taken in Handling and Storing Keep cool, dry and away from sources of ignition.

Use and store with adaquate ventilation. Do not pressurize, cut, weld, or in any other manner expose container to heat, sparks, flame, etc.

Other Precautions All handling equipment should be electrically grounded.

Walter Gorbunow Great Northern Research, Inc. TOTAL P.03

Exhibit "L"
Victor Automotive Products
12/04/96 Inspection



Photos of the Victor brand rubber cement, sample #97-830-3204.





HENKEL AL Exhibit "m" victor Automotive 12/04/86 INSPECTION



HENKEL ADHESIVES CORP/EL 740 TOLLGATE ROAD ELGIN IL 60123 708-931-9980

V600 RUBBER CEMENT

VICTOR AUTOMOTIVE 501 S. WOLF RD. DES PLAINES

IL 60016

INVOICE#:

DATE:

07/19/96

PAGE:

24-HOUR EMERGENCY PHONE NO: CHEMTREC, 800/424-9300

MATERIAL SAFETY DATA SHEET

CHEMICAL NAME:

NONE

TRADE NAME: HENKEL# RC-7818

CHEMICAL FAMILY:

POLYMER SOLUTION (FLAMMABLE)

FORMULA: MIXTURE

HAZARD CLASS:

U.N. NUMBER:

PACKING GROUP:

1133

NAME: HEPTANE

CAS NUMBER:

142-82-5

* BY WEIGHT:

92.00

ACGIH TLV: 400 PPM OSHA PEL: 500 PPM OSHA STEL: 500 PPM

NAME: ETHYL ALCOHOL

'AS NUMBER:

64-17-5

* BY WEIGHT:

1.00

ACGIH TLV: 1000 PPM OSHA PEL: 1000 PPM

OSHA STEL:

***************** PHYSICAL PROPERTIES DATA ***********

BOILING POINT: 200 F SPECIFIC GRAVITY: 0.7

VAPOR PRESSURE (mm HG AT 20 DEG C): 76

INVOICE#:

DATE:

07/19/96

PAGE:

MATERIAL SAFETY DATA SHEET

(HENKEL #: RC-7818

CONDITIONS TO AVOID: OPEN FLAME AND EXCESSIVE HEAT INCOMPATIBILITY: STRONG OXIDIZING AGENTS HAZARDOUS DECOMPOSITION PRODUCTS: CARBON MONOXIDE, CARBON DIOXIDE, HYDROCARBONS AND OTHER ACRID PRODUCTS OF COMBUSTION. HAZARDOUS POLYMERIZATION: WILL NOT OCCUR CONDITIONS TO AVOID:

SPILL PROCEDURES: EXTINGUISH ALL SOURCES OF IGNITION. COLLECT ON SAFETY ABSORBENTS AND DISPOSE OF PROPERTY.

DISPOSAL PROCEDURES:

TREAT AS A FLAMMABLE WASTE IN COMPLIANCE WITH THE EPA REGULATIONS. DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE AND 'FEDERAL REGULATIONS.

VENTILATION: RECOMMENDED RESPIRATORY PROTECTION: CHEMICAL FILTER MASK CARTRIDGE TYPE IS REQUIRED IF TLV IS EXCREDED. PROTECTIVE CLOTHING: CHEMICALLY RESISTANT GLOVES SUCH AS NEOPRENE RUBBER.

EYE PROTECTION: OSHA APPROVED FULL FACE MASK.

**************** SPECIAL PRECAUTIONS *************

HANDLING & STORAGE PRECAUTIONS: TREAT AS A FLAMMABLE LIQUID. STORE IN ACCORDANCE WITH FEDERAL. STATE, LOCAL AND INSURANCE REGULATIONS AS PRESCRIBED CLASS I/GROUP D FLAMMABLE LIQUIDS. KEEP AWAY FROM SOURCES OF HEAT SUCH AS DIRECT SUN, BOILERS ETC. AVOID SPARKS AND OPEN 'FLAMES.

SPECIAL COMMENTS:

NON-HAZARDOUS INGREDIENTS WITHHELD UNDER PA TRADE SECRET STATUS.

EPA SARA TITLE III HAZARD CLASS: FLAMMABUE

THIS PRODUCT CONTAINS THE FOLLOWING CHEMICALS SUBJECT TO THE REPORTING REQUIREMENTS OF EPA SARA TITLE III SECTION 313 (40CFR372):

CHEMICAL NONE

CAS NUMBER WEIGHT PERCENT

INVOICE#:

DATE:

07/19/96

PAGE:

MATERIAL SAFETY DATA SHEET

(HENKEL #: RC-7818)

PERCENT VOLATILE: 89%
VAPOR DENSITY: 3.5
EVAPORATION RATE: 5.6
SOLUBILITY IN WATER: NIL

pH: N/A

APPEARANCE AND ODOR: LIGHT YELLOW LIQUID WITH SOLVENT ODOR.

FLASH POINT & METHOD: 25 F

FLAMMABLE LIMITS: N/A

LELY: 1.2 UELY: 7.5

EXTINGUISHING MEDIA: CARBON DIOXIDE, DRY CHEMICAL, FOAM.

SPECIAL FIRE FIGHTING PROCEDURES:

WEAR SELF-CONTAINED BREATHING APPARATUS WITH A FULL FACE MASK.

UNUSUAL FIRE & EXPLOSION HAZARDS:

VAPORS ARE HEAVIER THAN AIR AND MAY TRAVEL ALONG THE GROUND. THIS COULD CAUSE IGNITION BY PILOT LIGHT, SPARKS, HEATERS, SMOKING, ELECTRIC MOTOR, STATIC DISCHARGE OR OTHER IGNITION SOURCES. NEVER WELD OR CUT EMPTY DRUMS.

THRESHOLD LIMIT VALUE: NOT KNOWN

PRIMARY ROUTES OF EXPOSURE:

EYE CONTACT: TEARING, BLURRED VISION

SKIN CONTACT: DRIED SKIN, IRRITATION POSSIBLE

INHALATION: HEADACHE, NAUSEA, VOMITING, NARCOSIS

INGESTION: NAUSBA

CHRONIC EFFECTS OF EXPOSURE:

ANEMIA, LIVER ABNORMALITIES, KIDNEY DAMAGE, LUNG DAMAGE

EYE FIRST AID:

FLUSH WITH WATER FOR 15 MINUTES. SEEK MEDICAL ATTENTION. SKIN PIRST AID: WASH THOROUGHLY WITH SOAP AND WATER. IF IRRITATION PERSISTS, SEEK MEDICAL ATTENTION.

INHALATION FIRST AID: REMOVE TO FRESH AIR. IF BREATHING IS

DIFFICULT, SEEK MEDICAL ATTENTION.

INGESTION FIRST AID:

IF CONSCIOUS, INDUCE VOMITING - SEEK MEDICAL ATTENTION.

*********************** REACTIVITY DATA ***************

STABLE OR UNSTABLE: STABLE



Exhibit o'
victor Automotive
12/14/96 Fispection



U.S. CONSUMER PRODUC SAFETY COMMISSION	T	CP 28 - 10	こうじ パメフト	11337010ge 11337010ge	e+1 7 (N.
2. NAME OF INDIVIDUAL Tous Consule		F INDIVIDUAL	•R		4. DATE ///6
5. FIRM NAME US to A Stomstake place to.	. + ~ (6. SAMPLE NUMBER
7. NUMBER AND STREET		8. CITY AND	STATE (Include ?	Zip Code) Logotto	
9. SAMPLES COLLECTED (Describe fully. List lot, serial, i	model numbers	and other posit	ive identification)		
The following samples were collected by the Consum Product Safety Act (15 U.S.C. 2076(f) and/or Section 11 tions 5(c) and (d) of the Flammable Fabrics Act (15 Cosmetic Act (21 U.S.C. 374(c)) [Authority for sample 1970 (15 U.S.C. 1471 et seq.)], and receipt for said samp this form.	1(b) of the Fede U.S.C. 1194(c) a collections mad ples is hereby a	eral Hazardous and (d) and/or de in connectio cknowledged.	s Substances Act r Section 704(c) on n with the Poison Sections cited are	(15 U.S.C. 1270(b) of the Federal Food Prevention Packa e quoted on the rev	and/or Sec- I Drug and ging Act of erse side of
12 - Victor ERMIN 4 VB- 5					
12 - V. tor como # V-500 97-830-3080 -625 FL DZ. Contains	T K				ericust.
97-830-3203 1-> 4- VILLE GAMO #V-301		o coment	. 31; FL.	oz Tice S	. z C
97-830-3204 12- VIELUE GENIO # V. S 12- VIELUE GENIO # V. S 12-830-3201	soz pr	o isua. TRC	, isch D	ne terk and	LUGA. COM
					•
10. SAMPLES	I 11 SAMP	LES WERE	12.	COLLEC	TOP

10.	SAMPLES	11. SAMPLES WERE	12.	COLLECTOR	
a. AMOUNT REC	EIVED FOR SAMPLE	PURCHASED	a. NAME (Print or typ		$\overline{\zeta}$
b. SIGNATURE (Person from whom sample received)	BORROWED (To he returned)	b. SIGNATURE	6les-	4

VICTOR AUTOMOTIVE PRODUCTS. INC.

501 S. Wolf Road * Des Plaines, Illinois 60016

(708) 298–8870 * Telex: 253–105 * D-U-N-S 00-508–9016 * FAX (708) 298–2573

Exhibit "p" victor Automotiva 12/04/96 INSPECTION



KEYSTONE AUTOMOTIVE WAREHOUSE 44 TUNKHANNOCK AVENUE

EXETER PA 18643

KEYSTONE AUTOMOTIVE WAREHOUSE SLOCUM AVENUE

EXETER, PA. 18643

UR ORDER NO.	DATE SHIPPED	SHIPPED VIA	FREIGHT	TERMS
54919		ARKBSTFT	PREPAID	10TH PROX
is to the		****	With the second second	
1	40	OTEC DELTER LIR	DEDATE WIT	2 240
X	12 V106	STEEL BELTED HD	AD'	3.310 39. 0.510 18
	7000			7.0
- E Y	367 4 510	EMERGENCY RUAD K	-·	1.650
222	6 V211 12 V212	EMERGENCY ROAD K		15. 000
	3.120215	THE WEST WAR	2000年11月1日 1900年11月1日 11日本中国共和国共和国共和国共和国共和国共和国共和国共和国共和国共和国共和国共和国共和国	化学的基础 自由
A STATE OF THE STA	24 V309	TENS REPAIR TAPE		0.580
10 RO	44 <u>V330</u> 24 <u>V332</u>	ANTI FREEZE TEST		0. 380 5 4. 1. 580 37
A Distance	V2100	्रिक्षणां । स्वान्य वर्षस्य ५०० व	THE WAR	To find the first
12/	50 A A A A	EDCK FIEAT		0.420
137	36 V504 12 V507	LOCK LUBE HOLD DOWN STRAP	15_CARD_USA	0. 420 15
	ELECTION OF THE PARTY OF THE PA		THE REPORT OF THE PROPERTY OF	
10 X markets	#87 WV9 14 18	COMPRETENANTO-UT		14860
17X	12 V5144 6 V5152	AUTO LIGHTER ELEI		0. 930 11.
	A CONTRACTOR			
TO X THE REAL PROPERTY.	61 V5158	AUTO ETGATER PUP	3	1.010
211	6 V5170	AUTO LIGHTER WIR	ING KIT	1.060 6. 0.400 4
See	BES BUSATO	resident des la constante de l		OF THE PARTY OF THE
	24 V614	ELECTRO-START		0.630
25 K	12 V627	BATTERY TRAY-LARG		2. 250 27.
	12 - V628	ATTERY HOLD BOW		0.850
	15 × 0935	HOED DOWN BOLTS	こうかいき ニュー・コール・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・	0.790
39 X	24 V637	HOLD DOWN BOLTS-	10" J HOOK	0. 790 18.
10/2/	ERSIS G	COLUMN TOP		
10 m			WARRAN SHR	BATARCARE
ECVG. 1	HRS. 8 AM.	BPM 6 39 CTNS-	1010 485 717	-655-4514
-	。2000年在1965年的ASSESSOR			
7. FF			L'ANDERS LO /A	HELICALIES
11 51	10WING "T	HIS IS PIECE OF GOO	15 54PA" 1)A	TICE

Reignt Policy:

WILL BE SHIPPED PREPAID.
WILL BE SHIPPED F.O.B. CHICAGO.

• ALL ORDERS OVER • ORDERS LESS THAN • SOME ORDERS WILL BE INCREASED TO MEET FREIGHT REQUIREMENTS.

SAME AS "SOLD TO" UNLESS OTHERWISE INDICATED

KEYSTONE AUTOMOTIVE WAREHOUSE 44 TUNKHANNOCK AVENUE EXETER PA 18643

S H T I O P KEYSTONE AUTOMOTIVE WAREHOUS SLOCUM AVENUE EXETER, PA. 18643

YOUR OR		DATE SHIPPED	SHIPPE				į	REIGHT		TERMS
- 54	919		AKK	BSTFT			PHI	EPAID	10TH	2 %
No.	a awm	PRODUCT	NO.		A STATE OF THE	TO THE STATE OF	0	The Care	enter Vale	
×30		i i		1	TERMINAL		τ		0. 440	79.
X32	X 1	2 V647			TERMINAL DESTERM: R		TS	120		
¥33		2 V651 2 V975			TERM ADA MO PAD W/		e. riskilikister i	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	1. 630 1. 500	18.
734		Level and the second								Barrier and and
							A property of			
								THE TANK		
							व्यक्ष्म्ब्रह्मसम्बद्धाः स्टब्स्य स्टब्स्य स्टब्स्य पुरस्कृतिकाः स्टब्स्य पुरस्कृतिकाः स	The state of the s		
								1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
				-J.D.T.A		, A				

ASE PAY THIS INVOICE WHEN DUE. NO MONTHLY STATEMENT WILL BE RENDER

The Policy:

ALL ORDERS OVER \$750.00 WILL BE SHIPPED PREPAID.

ORDERS LESS THAN \$750.00 WILL BE SHIPPED F.O.B.CHICAGO.

SOME ORDERS WILL BE INCREASED TO MEET FREIGHT REQUIREMENTS.



KEYSTONE AUTOMOTIVE WAREHOUSE

44 TUNKHARSISICK AVENUE

VICTOR AUTOMOTIVE PRODUCTS, INC.

501 S. Wolf Road * Des Plaines, Illinois 60016 (708) 298-8870 * FAX (708) 298-2573

D-U-N-S 00-508-9016

INVOICE NO.

TALITOTE CONTRACTOR

SAME AS "SOLD TO" UNLESS OTHERWISE INDICATED

KEYSTONE AUTOMATE & MAPPER &= SLOCUM AVENUE

UR ORDER NO.	DATE SH	IPPED	SHIPPED	VIA	$-\mathcal{A}$	7		FRE	IGHT		TERMS	
54919	C	1/05/96	ABF	39CTN 1	010#	11		PRE	41b	tülti	PROX	
			1. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.		1	ा स्थान इ.स.च					Sanda Sanda	
1		106					AIR KIT			310		39.
					TAPE U	40			1.0	250		
	6	211		EMERGE		AD KIT-	DELLIYE			650 (00)		FO.
		212					O PC DI	Parameter 1	15	550	Market State	777 777
	建设设	707 C		9 4 4 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2					648	730 580		
5	144 V	/330				TESTER		ļ		390		54
	建 有關					TESTER-				330		
in and	700-1	5 03		LOCK H	JEAT					420		50
10	34	/504		LOCK I			AS TO SAME	(1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-		420		50. 15
	. الأناك استمرال العالم										18 (1)	
16	6 4	5141				C LIGHT				860		II.
17		15144		AUTO	IGHTER	EL EMEN				930		
				AUTO	1 but co	POP OU				920	ąπ	
	6 5	/5158 /5170				WIRING				310. 060		7. <u> </u>
20	6	5410		AUTO L	IGHTER	WELL	154		0	750		5 .
C. P. A. J. J. A.				e e e					daying the		Jare Mare	Sept 200
		H 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1									N.A.	in the second
				, i	1 12	9/32			180	.79	can	_
			7						2.4%			
											t unit de la	

INVOICE WHEN DUE.

Freight Policy:

- ALL ORDERS OVER
- ORDERS LESS THAN

WILL BE SHIPPED PREPAID. WILL BE SHIPPED F.O.B. CHICAGO

• SOME ORDERS WILLEE INCREASED TO MEET FREIG

SAME AS "SOLD TO" UNLESS OTHERWISE INDICATED. KEYSTONE AUTOMOTIVE WAREHOUSE KEYSTONE AUTOMOTIVE WAREHOUSE 44 TUNKHANNOCK AYENUE SLOCUIT AVENUE EXETER PA 18643 EXETER, PA. 18643 OUR ORDER NO. DATE SHIPPED SHIPPED VIA .. FREIGHT TERMS ABF 39CTN 1010# PROX . 54919 01/05/96 PREPAID 10TH 7. ELECTRO START V614 0.850 20.40 BATTERY TRAV-LARCE HOLD DOWN BOLTS-10" L HOOK **V635** 0.790 **7.48** HOLD DOWN ROLTS-10" J HOOK 790 D 01 V647 BATT SIDE TERM REPL. BOLTS 0. 540 BATTERY TERM ADAPTER KIT 129/32 FREIGHT CHARGES 0. 0 SPECIAL CHARGES/CREDIT TOTALE NO MONTHLY STATEMENT WILL BE RENDERED THIS INVOICE WHEN DUE. • ALL ORDERS OVER •750 00 WILL BE SHIPPED PREEAU • ORDERS LESS THAN •750 00 WILL BE SHIPPED PREEAU • SOME ORDERS WILL BE INCREASED.



VICTOR AUTOMOTIVE PRODUCTS. INC. INVOICE NO. 69015

501 S. Wolf Road * Des Plaines, Illinois 60016 (708) 298-8870 * FAX (708) 298-2573

D-U-N-S 00-508-9016

VK11014-18643106

						SAME AS "SOLD T	O" UNLESS OTHERWISE	INDICATED
8 0 T L O D		STONE AUTOMO TUNKHANNOCK ER PA 188	AVENU		s H	KEYSTONE SLOCUM AV EXETER, P	ENUE	WAREHOUSE
YOUR ORD	DER NO.	ATE SHIPPED	SHIPPED VIA	1 /		FR	EIGHT	TERMS
550	386	02/01/96	ABF 2	6CTN 8354	11	PRE	PAID 10TH	PROX
TOWN.					To proceed the second	्र स्थाप्त सम्ब		
1	72	V101		TUBELESS TI	RE PLUG KIT	e de la	0. 750	54. OC
2	12	V102			RE KIT STRI		Ø. 870	10, 44
							0 8603 1 8303	
ن نا	24	V105		PLUG REFILL			0. 920	55 0E
4	36	V106		STEEL BELTE	D HD REPAIR	KIT	3. 310	119.16 200E
		TVIES SE	多數學	行發展對對			FF 0: 5101	
7	36	V209	•	EMERGENCY RO			11. 950	430, 20
	12	V220	A STORY	FIRST AID K			1.850	22. 2C
				首的可能的學習	TENEDA IN		*************	##E430.72
13	12 24	V301 V302		VINYL ADHES: HOSE BANDAG!			0. 760 0. 580	7, 12 13, 92
							*** O 550	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$
17	288	V308		LENS REPAIR	TAPE-PED		0. 580 0. 580	167. 04
.18	. 72	V305		LENS REPAIR		!	0. 580	41. 76
							5 0 580	
(12	. V320		EMERGENCY F	AN BELT REP	. KIT	3. 500	42. OC
52	0	V331		PROF ANTI-FR	REEZE HYDRO	METER	1. 070	v. oc
					र्भ साहित् हैं। यास्त्री हैं तु है। स्टब्सिक से स्टब्सिक विकास			
	12	V332		#** REORI	DER ITEM	***		
-9			Althor to the	a rovered to some a	•	\$ \$25 G.\$34d		BIOTOXICS REPVICED WAS
						65	47.48	1
\$		· · · · · · · · · · · · · · · · · · ·	Wall to Horse		30077	and the second deli	30-95-25	
							物ができ	
*	,			11 1 0-7	7.00	67	7. 6. 3	
			ALC: NOTE:					

Freight Policy:

• ALL ORDERS OVER

• ORDERS LESS THAN

PLEASE PAY THIS INVOICE WHEN DUE

WILL BE SHIPPED PREPAID. WILL BE SHIPPED F.O.B. CHICAGO. • SOME ORDERS WILLIE INCREASED TO MEET FREIGHT REQUIREMENTS.

LO .	44 T	TONE AUTOMO UNKHANNOCK ER PA 186	VENUE // HJ SLOCUM AVENU	
700R ORDER NO. /	DA		BF 26CTN 835# 11 PREPAI	t t
ALCOHOL VICTORIAN DESCRIPTION	ANS protection	THE TRANSPORT CARRESTON OF THE	Process many organizates and the second states and the second states and the second states are second st	
REAL PROPERTY.	119	Marchasia (
24	24	V407	SMALL PATCH KIT BOX	0.460 11.04
25	12 3459	V412	BRONZE SEAL RAD SEALER	0. 450 5. 40
				017 ac 1802 18 20 6
58	12	V501	TIRE REPAIR KIT 2/CD	0. 920 11. 04
29	720	V502	LOCK DE-ICER SUPER SIZE	0. 750 540. 00
	244	3504		· 1000 1000 1000 1000 1000 1000 1000 10
32	%48 ≸ 36	V508	HOLD DOWN STRAP 31 CARD USA	0.870 31.32
33	12	V509	HOLD DOWN STRAP 9" CARD USA	0. 530 6. 36
Children and the control of the cont	112	V510	SEE MUNICIPALITY OF SEE AND THE SEE	40.790
	1247	AND IT L		11.860 A 14.64
§ 3	24 30	V5141	COMPLETE AUTO LIGHTER 12V AUTO LIGHTER FOP OUT	1. 860 44. 64
37		V5142	AND LIGHTER FOR OUT	1. 160 34. 80
				0.50
40 .	6	V5146	AUTO LIGHTER ELEMENT	0. 700 5, 88
41	6	V5147	AUTO LIGHTER POP OUT	1. 580 7. 48
44	6	V 3136	AUTO LIGHTER POP DUT	1. 310 7. 86 .
\45	6	V5160	AUTO LIGHTER ELEMENT	0. 950 5. 70
建筑分 级。	1	SALEMON SALE	\$\$P\$6660 P\$6660 P\$66	050
		37/3237 83	REAL PROPERTY OF THE PROPERTY	之0.400和22年代最初
48	24	V5410	AUTO LIGHTER WELL	0. 950 22. 80
**************************************	o to kind	rocke kalendar		
				27-47
3.6			130077	30.95 cack
	Sugar v S	en er sakkere er best		
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				14054 1888
<i>i</i> i		CHARLES CONTROL CONTRO		TO THE PROPERTY OF THE PARTY OF
*			<u>'</u>	
1.00.20				
*		l	4	
PLEASE	PAY :	THIS INVOICE	WHEN DUE. NO MONTHLY STATEMENT W	ILL BE RENDERED
Freigl	ALL O ORDE SOME	Olicy: RDERS OVER RS LESS THA ORDERS WI	WILL BE SHIPPED PREPAID. WILL BE SHIPPED F.O.B.CHICA E INCREASED TO MEET FREIGHT REQUIRE	
			OFFICE	

KEYSTONE AUTOMOTIVE WAREHOUSE SLOCUM AVENUE EXETER, PA. 18643

			la: ====		· · · · · · · · · · · · · · · · · · ·			 -			T-2-2-2-	
YOUR ORDER NO.	DA	TE SHIPPED	SHIPPE			· }		1	EIGHT	1070	TERMS	
55386	ļ	02/01/96	ABF	26CTN	835#	11		HE	PAID	IOTH	PROX	
					<u></u>	V		Щ.		<u> </u>	7.	
AL CONTRACTOR	1118	The state of the s	1	e de las de las deservados de las deservados de las de La portanta de las d	3	a lighting.			被推 的	CE AND		
49	36	V614		ELEC.	TRO STA	RT	•		O.	850	. 30	. 60
50	12	V623		BATT	ERY CAR	RYING ST				820		. 84
5.										7.0		謎
53	48	V633		RATT	EBY HUI	D DOWN-C	ROSS BAR	ETENED!	がを開きる	180	104	- A4
54	36	V634		BATTI		LER-DELU				900	l .	. 40
		经数据的							THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.	7/70	The second secon	
	332	And 1102-120-120-120-120-120-120-120-120-120	SE			is a second to a		74e 8		790	CANADA CANDIDAN	
§ 57	12	V638				OLTS-12"			l	880	P .	. 5
58	24	V645	Cotton !	BAII	CONTRACTOR OF THE PARTY OF THE	ROMETER	Carrier Hager & Total			150	7)	. 6(
	5		6.5		16.00	ent a representative			37 - 17 - 17 - 17	250		
01	12	V650				E TERM B	OLT EXT	BASSA ARTON		660	7	9:
# 62	12	V710			E · CORES					410	4	. 91
			157 - A	The state of the state of	را با در دوره را دولود ا				24.27	360		
	2125	TV/22		AND DESCRIPTION OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUM		The second second second	是是是是是第一个			410		9:
65	12 12	V714 V716			E TOOL	4 WAY CHROME H	IFY			410 720	, ·). 7.). 6.
	r sīr	Wiebs Vist	10 C	THE RESERVE OF THE PERSON NAMED IN COLUMN 2 IN COLUMN		DADETOR		30				
		W604 - W44			ALC: NO				200	640F		5
2 69	12	V805	-	MUFF	LER BAN	DAGE 3"	X 40"			700		4
70	36	V804		EXHA	ر اللهاوي د البحاس د .	E REPAIR	KIT	55 E		540	19	4.
		ALE VERY							**************************************	640		O
73	12	VB10		ROCK	CAST FX	HAUST RE	PAIR KIT	2012()·		7 60		. 2
3 1 2	£ 65 .	1 4320	•	10011	2101 21				_	200		
				15 / 16 / 16 / 16 / 16 / 16 / 16 / 16 /					A PA			
			F				计算图像		3 147	148		
- ·			•			13007	<i>'</i> 7 ·	إ	1 30	. 957	- Care	
	315.17.6	5-25-64-86-12 Sept. 5								SEE SA		
			18 2 V			and the same			404	93	亚洲	7.7
200												
							No. 2 Control of the State of t	(2)	C. Transport	A TAIL STREET		
			in the second						1 10 2			1.7
18.75 (S. 75) (S. 75)		SCHOOL STANS				المستراد المستردة المرادات		1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	建水油(水)地流水	水 成为 的规则	会と会議の	- A
		<u>.</u>										
PLEASE	PAY	THIS INVOIC	E WŁ	IEN DU	E. NO	нтиом с	LY STATEM	ENI	WILL	BER	ENDERED	
- LAGE								المند				

eight Policy:

• ALL ORDERS OVER

WILL BE SHIPPED PREPAID.

ORDERS LESS THAN

SOME ORDERS WILL

WILL BE SHIPPED F.O.B.CHICAGO. E INCREASED TO MEET FREIGHT REQUIREMENT REQUIREMENTS.

OFFICE

e, -
35.8
0 L D

KEYSTONE AUTOMOTIVE WAREHOUSE 44 TUNKHANNOCK AVENUE EXETER PA 18643

KEYSTONE AUTOMOTIVE WAREHOUSE SLOCUM AVENUE EXETER, PA. 18643

					`1· ·	<u> </u>				
YOUR ORDER NO.	DA	TE SHIPPED	SHIPPEC				FREIGHT		TERMS	
\$35386		02/01/96	ABF	26CTN 835#	11	PF.	EPAID	10TH	PROX	
					1		<u></u>	<u></u>	7 %	
	18-17				: अंगिक्सिक्	1200 1200	110			
74	12	V812		EXHAUST SYST				. 630	t	31. 56
75	24	V813	Child to the same of	ROCKCAST EXH		GE		. 570		13. 68
	1						THE RESERVE OF THE PARTY.	34		
78	12	V907		FILTER WRENC		LTER		. 940		11. 28
79	12	V910		SUPER GLUE	•	•	0.	. 390		·4. 68
					المرافظة بالسائي والمتعاط وما		選供 し 強いを まさす			
82	36	V930		VALTAPE			State American strategies	2 800 2	CARLO DA COMPANSA	21.24
83	24	V946		TORX SCREWDR	IVER SET 2	PC.		. 570	1	37. <u>6</u> 8
							2	500		
										4 12 137
1 A	٠						1		l	-
										THE WAY
				建筑市场地域的	Control of the second					1-42
	<i>:</i> .			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					}	* :
FAR 17		是工作的 类型医疗	Work.	William Control	a gradi garaktar a karagaga (j. 1821). Barga Barra (j. 1821).	A STATE OF THE STATE OF				ing at
The same of the sa		各本人的								
					高级的技术			-		A
	100		35.5					Oran es		
										10 mg/s
					V.	- 1 - 1				
	1.57									1/2/2
			14.0					是交通	3-18-32	
	*** •				130017		11 30	1.55	برمص د	1
7884			\ F		A STATE OF THE STA	" b	*			ন , জনস্থানীয়
	•	: .	•	FREIGHT	CHARGES				a	0. 00 0. 00
	9 (17 d) (144年	SPECIAL	CHARGES/C	KED1·T	- 15 ST 15 S	180 C 180 C		U. UD.
in and a			ngh Ang sin		Add as A					
		•		TOTAL		r i			2.9	51, 16
STEACH.		THIS INVOIC	E W	TEN DITE NO	MONTHLY		NT WIL	RE P		

PLEASE PAY THIS INVOICE WHEN DUE. NO MONTHLY STATEMENT WILL BE RENDERED.

- **reight Policy:

 ALL ORDERS OVER **750.00 WILL BE SHIPPED PREPAID.

 ORDERS LESS THAN **750.00 WILL BE SHIPPED F.O.B.CHICAGO.

 SOME ORDERS WILL E INCREASED TO MEET FREIGHT REQUIREMENTS. OFFICE 1 1 m

INVOICE NO. VICTOR AUTOMOTIVE PRODUCTS, INC.

501 S. Wolf Road * Des Plaines, Illinois 60016 VK11014-18643106

(708) 298-8870 * Telex: 253-105 * D-U-N-S 00-508-9016 * FAX (708) 298-2573

		69015
		SOLD TO" UNLESS OTHERWISE INDICATED
& TO KEYSTONE AUTOMO		NE AUTOMOTIVE WAREHOUSE
44 TUNKHANNOCK EXETER PA 186	AVENUE 10 SLUCUM	AVENUE , PA. 18643
4		
YOUR ORDER NO. DATE SHIPPED	SHIPPED VIA	FREIGHT TERMS
55386	ARKBSTFT	PREPAID 10TH PROX
A CALL OF THE PARTY OF THE PART	The second of th	Mary Services of S
72 V101 28 12 V102	TUBELESS TIRE PLUG KIT TUBELESS TIRE KIT STRINGS	0. 750 54. 00 0. 870 10. 44
_ 24 V105	PLUG REFILL FOR V104	0. 920 22. 08
6k 36 V106	STEEL BELTED HD REPAIR KIT	3.310 119.16
- 9 X 36 V209	EMERGENCY ROAD KIT	11. 950 430. 20
=10 x ~ 2 V220	FIRST AID KIT	1.850 3.70
Property of the second		OZCO ZECO
- 13k ~ 12 V301 - 14k ~ (24 V302	VINYL ADHESIVE HOSE BANDAGE	0. 760 2. 28 0. 580 13. 92
		6 9 9
• 1712 PV 202 V308	LENS REPAIR TAPE-RED	0. 580 146. 16
- 18k 72 V309	LENS REPAIR TAPE-AMBER	0. 580 41. 76 0. 580 580
-21 /~ 2 V316	EMERGENCY FAN BELT REP. KIT	3. 500 10. 50
22. 8 V331 RO.	PROF ANTI-FREEZE HYDROMETER	1.070 3.21
WWW. 11 95 14 V40 7 14 V40	SENAR DE LA CIENTA DEL CIENTA DE LA CIENTA DEL CIENTA DE LA CIENTA DEL CIENTA DEL CIENTA DE LA CIENTA DE LA CIENTA DEL CIENTA DE LA CIENTA DEL CIENTA D	306480
25 V 12 V412 26	BRONZE SEAL RAD SEALER RADIATOR REPAIR KIT	0. 450 5. 40 0. 660 1. 98
V-Solver		0 7E0
29 K 720 V502	LOCK DE-ICER SUPER SIZE	0. 750 540. 00
AU ADNI CADO 757 A	C-4514 2-Pallet - 21-	
	255-9514 2-Pallet - 26-c	5/2
The state of the s	1 Way	
PLEASE PAY THIS INVOICE	WHEN DUE. NO MONTHLY STATEM	ENT WILL BE RENDERED.

Freight Policy:

• ORDERS LESS THAN

WILL BE SHIPPED PREPAID. WILL BE SHIPPED F.O.B. CHICAGO.

SOME ORDERS WILL BE INCREASED TO MEET FREIGHT REQUIREMENTS.

SAME AS "SOLD TO" UNLESS OTHERWISE INDICATED

\$. 0 T L O D

and the second

KEYSTONE AUTOMOTIVE WAREHOUSE 44 TUNKHANNOCK AVENUE

EXETER PA 18643

S H T I O P

KEYSTONE AUTOMOTIVE WAREHOUSE

SLOCUM AVENUE

o SLUCUM AV

EXETER, PA. 18643

ORD ORD	ER NO.	DATE SHIPPED	SHIPPED VIA	FREIGHT	TERMS
550			ARKBSTFT		PROX
55.	386		AKKBSIFI	FREFAID IOIF	2 %
					
12 .eq .vi	all outputs				
- 30	X 24	V504	LOCK LUBE	0. 420	10.08
-31	48	V507	HOLD DOWN STRAP 15 C	ARD USA 0.610	
£32 .	X 36	, y508	the second of the second of the second	《《···································	The state of the s
~33	X系统规则12		AND THE PROPERTY OF THE PROPER		
- 34		5		ARD USA 0.790	
35	24	大人 医多种性 化二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十	COMPLETE AUTO LIGHTE		
:-36.	K		COMPLETE AUTO CICHTE		
-37			*** MAUTOSEIOHTER POREDUI	1.160 0.930	
7	12	3	AUTO LIGHTER ELEMENT AUTO LIGHTER ELEMENT		
200		THE PROPERTY OF MANY PLANTS OF THE PERSON ASSESSED.	AUTO EIGHTER ELEMENT		
		· "我们是我们的一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个	AUTO ETORTER POP OUT	(1997年 - 1997年 - 1997	· 大水、大型、大水、大水、大水、大水、大水、大水、
- 42	× 18		AUTO LIGHTER POP OUT		1
-43			COMPLETE AUTO LIGHTE	•	
3		2 × V5158	ME MORO ENCHIER ROPSOUT		Continues State of Continues of the Cont
		V5160	WAUTOTET CHTER ELEMENT	0.950	第 5.70
46	-		AUTO LIGHTER WIRING		X
47	12	CONTRACTOR OF THE PROPERTY OF	ANTI FDG CLOTH	0.400	
7,9	THE RESERVE OF THE PERSON OF T	Marie Control of the	AUTO-LEOCHUER WEILS	0.950	
	X4		VELECTROUSIARIE	O. 850	· · · · · · · · · · · · · · · · · · ·
-50			BATTERY CARRYING STR		
-51;	(* 24 Van 1944)	V625	BATTERY TRAY-SMALL P	THE PARTY OF THE P	45.84
		A SEAVE	PARTER PROPERTY.		
~ 54	K 36		BATTERY FILLER-DELUX		
-(k 24		HOLD DOWN BOLTS-10"		
a de	XXXXXXXXXX	STALL A LINEAR COMMISSION, DAVIS AT HELD STREET STREET	HOLD DOWN HOLD SALOUD		
	(图) 图12		A POED DOWN BOOTS 121	O BBO	
~ 58	x 24	V645	BATTERY HYDROMETER P	ROFESS. 1.150	27. 60
	"这个人 "	A SANGER OF STREET			
5			1		
N	A STREET				The base of the second second
, le; · · ·		AND AND PARTY OF PARTY PROPERTY.			
	1				

Freight Policy:

• ALL ORDERS OVER

PLEASE PAY THIS INVOICE WHEN DUE.

WILL BE SHIPPED PREPAID.

NO MONTHLY STATEMENT WILL BE RENDERED.

• ORDERS LESS THAN WILL BE SHIPPED F.O.B.CHICAGO.

• SOME ORDERS WILL BE INCREASED TO MEET FREIGHT REQUIREMENTS.



SAME AS "SOLD TO" UNLESS OTHERWISE INDICATED

KEYSTONE AUTOMOTIVE WAREHOUSE 44 TUNKHANNOCK AVENUE EXETER PA 18643

TO FE A DESCRIPTION OF THE PARTY OF THE PART

KEYSTONE AUTOMOTIVE WAREHOUSE SLOCUM AVENUE **EXETER, PA. 18643**

VOUE COS		DATE BUILDING	lowers	D.WIA	T==	FIGUE		I TPM 10	
YOUR ORDE		DATE SHIPPED	SHIPPE		1	EIGHT		TERMS	
553	86		ARKI	BSTFT	PRE	PAID	10TH	PROX	
***************************************					丄			2 %	
STEWN STATES	CYTTHAND	PRODUCT NO		除了的情况,我们有用的证		* 1 PR	CE WA	A MOUNT	100
一 59×	12	2 4647		BATT SIDE TERM REPL. BOLTS). 5 40	6.	4:
- 60X	12		to a desire	BATT TOP TERM REPL BOLTS			250	3.	٥ć
HAIX	W 15 12	V650		BATTERY SIDE TERMS BOLT EXTE			0.660	7	9.
#62 X	ーーレス	7710	SHOOL STATE	VALVE CORES TO A STATE OF THE S). 410		2:
- 63K	/~~E			VALVE EXTENSIONS-3/4" PLAST		1). 380		90
- 64 K	12		REPLANT	VALVE EXTENSIONS-1 1/4 PLAS	THE PROPERTY.		410	4.	
THE STATE OF		- V714		J. VALVESTODIS AFWAY AFFECT TO		AND NOT THE OWNERS). 410	党国和大学区	
1366X	744		Second Second	VALVETCAPS-CHROMERHEX TO THE VALVETCAPS	S. S. W. P.	· -	720	公司公司会会日1	
- e · v	24	1		MUFFLER BANDAGE 2" X 40"		1). 470		2:.
	12		52.77	MR. SILENCER METAL STRAP KIT	Section	THE WASHINGTON	640	7.	A1-0-00
1000000		The state of the s	7.4	MUFFLER BANDAQETS! X140 " EXHAUST FIRE REPAIR K IT). 700). 540	Contract Con	
- 71V	72	· · · · ·	and the second	MUFFLER MENDER-6 DZ TUBE	There's of). 640	46.	-
- 72	24			MUFFLER MENDER KIT). 760	40. 18.	
		Maritimeter - Compared and Comp	FIX 4 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	ROCKCAST EXHAUST REPAIR KIT		The property of the party of th	1.75 TO TO THE P.	13.	
		V812		EXHAUST SYSTEM REPAIR KIT		Pri 44 C 05-860	2. 430	A STATE OF THE PARTY OF THE PAR	V
- 75k	24	· •	and a large	ROCKCAST EXHAUST BANDAGE	for term). 570	13.	
- 76	24	1		TIRE GAUGE-RADIAL			970	23.	
M		V899		THE CAUCE DEVELONG HUCK	Take.		690	203	
	**************************************	V907		FILTER WRENCH-LARDES FILTERS			940	建设建设	2
- 79k	ノング	V910		SUPER GLUE			. 390	0.	7 :
- 80 X	12	V915		GAS TANK REPAIR). 630	7.	54
B Bix	312	V929		HOME & Addition DROWN CERTAIN			800	可能够可谓	6 تِ
2	11 1 1 3 E	7 V930 1	电路 图像	TO VALTAPE TO THE TOTAL TO THE TOTAL TO THE TOTAL TO THE TOTAL TOTAL TO THE TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TO THE TOTAL T			590	11.24	
3 7 83	ζ 24	1 ' ' -		TORX SCREWDRIVER SET 2 PC.			. 570	37.	
	12	V975		AUTO MEMO PAD W/PEN		1	. 500	18.	OC.
						10		THE REAL PROPERTY.	
\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$		Bearing the second	**************************************			ALC: UNITED BY	建筑的		
						İ			
341	Carlot need						25602	Sala in the Salar	
					1				
(A)		Same Darling States & Calendar	A SHARING MY TON			STAN PROPERTY	mark XX	一种的一种种的一种种的一种	13-1
				TOTALS		1		7 700	
	के के महिला है।	LI DESCRIPTION SAVE	100		F-54-12 -40	ASOV MAN	25300	2,799.	76 Se
			例例						
		War Thurst and all all additional with health and the	Anile d'Establis	And the second of the control of the	THE PARTY OF	(1975年) (1976 年)	WHAT STREET	THE RESERVE OF THE PARTY OF THE	
100	lte.	1				ł	1		

PLEASE PAY THIS INVOICE WHEN DUE. NO MONTHLY STATEMENT WILL BE RENDERED

reight Policy:

• ALL ORDERS OVER \$750.00 WILL BE SHIPPED PREPAID.

• ORDERS LESS THAN \$750.00 WILL BE SHIPPED F.O.B.CHICAGO.

• SOME ORDERS WILL BE INCREASED TO MEET FREIGHT REQUIREMENTS

INVOICE NO. VICTOR AUTOMOTIVE PRODUCTS, INC. 501 S. Wolf Road * Des Plaines, Illinois 60016 VK11014-18643107 (708) 298-8870 * Telex: 253-105 * D-U-N-S 00-508-9016 * FAX (708) 298-2573 SAME AS "SOLD TO" UNLESS OTHERWISE INDICATED 2-23 KEYSTONE AUTOMOTIVE WAREHOUSE KEYSTONE AUTOMOTIVE WAREHOUSE 44 TUNKHANNOCK AVENUE SLOCUM AVENUE EXETER, PA. 18643 EXETER PA 18643 B YOUR ORDER NO. DATE SHIPPED FREIGHT IPROX ARKBSTFT PREPAID **10TH** 55878 2 % 0.750 200 V101 TUBELESS TIRE PLUG KIT 150. 00 48 V104 BELTED REPAIR KIT 1.830 87.84 V106 94 VINYL TAPE U.L., 60' 0.510 48, 96 V166 1.750 34 **V207 BOXED FLARES** 63.00 Z V202 09586 -17 V305 VINYL & LEATHER REP. 2. 650 2. 65 0. 580 204 **V30B** ENS REPAIR TAPE-RED 118. 32 1~ 20 V331 PROF ANTI-FREEZE HYDROMETER 1.070 10.70 V332 1. 580 ANTI FREEZE TESTER-DIAL 15.80 0,450 48 **V507** HOLD DOWN STRAP 15 CARD USA 0. 610 29. 28 **V508** HOLD DOWN STRAP 31 CARD USA 0.870 20.88 24 0.530 45140 V5142 TIE DOWN CORD SO' 1.29 0.620 11.16 18 V5144 AUTO LIGHTER ELEMENT 0.930 11.16 COMPLETE AUTO LIGHTER 12V 1.860 22.32 12 V5156 AUTO LIGHTER POP OUT 12 1.310 15.72 भूषिक राज्यार अञ्चलक्ष V5410 AUTO LIGHTER WELL 0. 950 11.40 PLEASE PAY THIS INVOICE WHEN DUE. STATEMENT WILL BE RENDERED. ALL ORDERS OVER WILL BE SHIPPED PREPAID.

SOME ORDERS WILL BE INCREASED TO MEET FREIGHT REQUIREMENTS.

WILL BE SHIPPED F.O.B.CHICAGO.

ORDERS LESS THAN

KEYSTONE AUTOMOTIVE WAREHOUSE 44 TUNKHANNOCK AVENUE 18643 EXETER PA

KEYSTONE AUTOMOTIVE WAREHOUSE SLOCUM AVENUE

EXETER, PA. 18643

TERM8 YOUR ORDER NO. DATE SHIPPED SHIPPED VIA FREIGHT PREPAID 10TH PROX ARKBSTFT 55878 2 % 0. 550 39. 6 RUBBER CEMENT 1 OZ. 72 **V600** 24 13 0.960 BATTERY MAINTENANCE KIT **V610** 23. 04 0.750 SHENY A Auta Marain Charle Marchall Charles V612 BATTERNACORROSIONEREMOVER BATTERY WASHERS SIDE TERM. 0.300 7. 20 24 V613 0.850 40. 80 ELECTRO START 48 **V614** PAGEN BELIEVE AND AND BEAUTO 0. 250 V618 V625 2. 250 27.00 12 V627 BATTERY TRAY-LARGE PLASTIC BATTERY HOLD DOWN-SIDE MT 0.850 10.20 **Y429** SHOW OF THE STATES SSZCT. V632 2.3180 BATTERYZHOCDEDOWN-CROSSEBA 0. 900 10.80 **V634** BATTERY FILLER-DELUXE 12 HOLD DOWN BOLTS-10" L 0.790 37. 92 V635 48 HOLDS TO WAS BORDED SHELL TO BOWN 0.740 0.790 36 J.F.E. 等べへり業をつう **V637) HOLD DOWN BOLTS-12" J HOOK 0.880 10. 54 12 **866V** BATTERY TERMINAL-MARINE 0.880 8. 80 **V441** HEN TERMINALEET DES 0.440 V645 1.580 18. 95 12 V646 BATTERY TESTER-DIAL 0. 590 **V648** SIDE TERMINAL CHARGING POST 28. 32 48 **V649** र्वा अस्ति । स्थापना स्थापना । 0 250 SA BEPLASION AND VALVE EXTENSIONS-1 1/4 PLAS 0.410 4. 92 12 V712 **V716** 0.720 VALVE CAPS-CHROME HEX 8.64 0.538 V733 **VB04** RESILENCERMETALESTRAPERIT 58 V805 MUFFLER BANDAGE 3" X 40" 0.700 8.40 12

PLEASE PAY THIS INVOICE WHEN DUE. NO MONTHLY STATEMENT WILL BE RENDERED

eight Policy:

- ALL ORDERS OVER
- ORDERS LESS THAN

WILL BE SHIPPED PREPAID.

WILL BE SHIPPED F.O.B. CHICAGO. SOME ORDERS WILL BE INCREASED TO MEET FREIGHT REQUIREMENTS.

KEYSTONE AUTOMOTIVE WAREHOUSE

A4 TURN HANNOCA AVENT

E:ETE F4 (5543

S VEYSTONE AUTOMITTUE WAPFHINGE

AND THE PERSON OF THE PERSON O

		A. WARRA ALIA	FREIGHT	TERMS
YOUR ORDER NO.	DATE SHIPPED	SHIPPED VIA ARKBSTFT PR	EPAID 19TH	4 PPOX
55878		AKKBSIFI		27
and the same	ST CONTRACTOR OF THE PARTY OF T	The first with the second of t		the state of the second
—59 X 12	V806	EXHAUST PIPE REPAIR KIT	0. 540	6. 4
-60 x 36	V808	MUFFLER MENDER KIT	0.760 1.100	27. S
12	The state of the s	ROCKOASI EXHAUST BEPAIR KUT	13240	14 E
-63 \ 24	V902	TIRE GAUGE-AUTO	0. 800	19. 2
-64 X 96	V912	REAR VIEW MIRROR ADHESIVE	0. 650	62. 4
P 9 12	N929	FORES ANTORORORIST SERVICE	0.800	7.6
1 6X 48	,	VALTAPETALAN	0.590	728. 3
-67 X 24	V946	TORX SCREWDRIVER SET 2 PC.	1. 570	37. 6
	atter Santiga ander Cours der sen innå til sættjig stil get i se i	- ************************************	ale annuacinal addition has a member	
	数据证据的表现的专案的记录	· · · · · · · · · · · · · · · · · · ·	100 (400) 中线线	The state of the s
<u>.</u>				
	经验的证据			
-				
	e officers of the real files.		AND CONTRACTOR SECTION	
				POTAL CO
	The Section American Commission Commission Commission	があれた。 1. こうようたが マン・ステング こんのこう はんたいかい はんかい かいしょ かいしょ (1995年) (1995年) (1995年) (1995年) (1995年) (1995年) (1995年) (19	Section of the second	· 國際的國際
10000000000000000000000000000000000000				
	A CONTRACTOR OF THE PROPERTY O		A REAL PROPERTY.	
			ļ	
			300000000000000000000000000000000000000	
				数数数
		The second secon		
		TOTALS	No. of the state o	1, 835. 92
	Contract Contract			
			AND THE PROPERTY OF THE PARTY.	《李明》《李明》

Freight Policy:

PLEASE PAY THIS INVOICE WHEN DUE.

• ALL ORDERS OVER \$750.00 WILL BE SHIPPED PREPAID.

• ORDERS LESS THAN \$750.00 WILL BE SHIPPED F.O.B. CHICAGO.

• SOME ORDERS WILL BE INCREASED TO MEET FREIGHT REQUIREMENTS.



NO MONTHLY STATEMENT WILL BE RENDERED.



VICTOR AUTOMOTIVE PRODUCTS, INC. INVOICE NO. 69716 501 S. Wolf Road * Des Plaines, Illinois 60016 (708) 298-8870 + FAX (708) 298-2573 D-U-N-S 00-508-9016

VK11014-1864310

SAME AS "SOLD TO" UNLESS OTHERWISE INDICATED

KEYSIONE AUTOMOTIVE WAREHOUSE 44 TUNKHANNOCK AVENUE

many and a second se

EXETER PA 18643

KEYSTONE AUTOMOTIVE WAREHOUSE SLOCUM AVENUE EXETER, PA. 18643

•						\\		•		•	
YOUR OR	DER NO.	DATE SHIPPED	SHIPPE	D VIA				1	FREIGHT		TERMS
_ 558	378	02/29/96	ABF	15CTN	530#		11	PR	PAID	10TH	. 1
THE WAY			tai				13.7%	17.24 17.24	145. 1 1 1 2 4 112 (v - 1)	Section 1	Company of the second s
1	300	V101 V104		TUBEL		TIRE PLO			0	. 750 _830	225. 0 87. 8
				31E4		TOTAL PROPERTY OF THE PROPERTY	: 13 1; 13:			946	
5	96	V166 ·			-	E U. L. ,	60 [']		0	. 510	48. 7
		V302 L1		17		VE - S				750 580 370	27.8 27.8
. 9	12	V305				EATHER I		Γ	2	. 650	31 8
		206 V309 V310		LENB	REFA	I TASE	S. VIII			580 580	
13	12	V331					HYDROME	ETER	1	. 070	12.84
	60	V332 V309		ERCAL	EEE	ZE TEST	是人民			580 450 540	18 92
17	48	V507		HOLD	DOWN	STRAP	15 CARD		0	. 610	29. 28
	- A	V508 V509 VX		Later Control of the Control	TOA		CAED CARO	A THE RESERVE THE PARTY OF THE		870 530 860	20 BE
1.	18	V514/2				TER POP		216 ,	1	. 290	. 23.22
		V5144 V5.45XV4		AUTE					o	930 920 160	
25	12	V5156		COMPL	ETE	AUTO LIG	SHTER 12	iv.	1	. 850	22. 32
									7.2	, Z.J.	
										5	
		· · ·							A SOLDING		

• ALL ORDERS OVER

• ORDERS LESS THAN
• SOME ORDERS WILL

PLEASE PAY THIS INVOICE WHEN DUE.

WILL BE SHIPPED PREPAID. WILL BE SHIPPED F.O.B. CHICAGO. E INCREASED TO MEET FREICH

NO MONTHLY STATEMENT WILL BE RENDERED.

KEYSTONE AUTOMOTIVE WAREHOUSE SLOCUM AVENUE EXETER, PA. 18643

YOUR ORD	PER NO.	DATE SHIPPED	SHIPPE	D VIA				FR	EIGHT		TERMS	
558	78	02/29/96	BF	15CTN	530#	1	1	PREP	AID	10TH	PROX	
			<u></u>							2	7.	
		A Marcocking				इन-गाउँ	61.0	117.5			i i	g gargers. To dee with
. 59	12				LIGHTER				1.	310		15.7
27	12	THE RESERVE OF THE PARTY OF THE		TO 100 100 100 100 100 100 100 100 100 10	HIGHTER	AN AND REPORT OF THE PARTY OF			8.6	060		
255	24.2	205410		XUID	HOTER	2458				450		, R
30	72	1			ER CEMEN' ERY MAIN'				6	550 960		39. 6 23. 0
1632	24			THE PARTY OF THE PARTY	Bulletin (C. L. Control of Control	The second second			2 Part 150	950	ij(M• <u>≠</u>	
133	5 94 12		- FLAC				REHOVER			380.4		
34 _35	24 48	1			TRO STAR		IDE TERM.		1	300 850		7. 2(10: 8(
	112	2 V618		BATT				36	. O.	65.0		
	W 52412		A BELLEY		• • • • • • • • • • • • • • • • • • • •		E PLASTIC		t .	250	Egi.	
38	12	1	. ya., a	1			-SIDE MI	-	•	850	1	10-20
, dao	12	V6324"		100 CT 1 10 CT 10			E E E E E E E			4101		
42	12		A. AMARATA	1	ERY FILL		ECRUSSIBIAR Luxe	इत्यादित 👫	ı	180 900		O. BC
43	49		i elektriker	HOLD	DOWN BO	LIS-1	O" L HOOK	era vener	0	790		17. 9.
	36	30536 30537 2083					A SALEDAK			740		
-	60		- and and a state of	1	** REDRD			avanasenije.	ATTENDED TO	PRIZAL PLANT	•	
40.	12	V438	gers cors	12872 504 3640		Table 1975 A. C. C.	S., THOOK			880		0.3
		W V641 4 (6)				AND CONTRACTOR	2.47 李宗的一个一个一个一个			890% 445		
49	36	ł					R PROFESS.	· /		150	• • •	11.4
						空間的影響				145/25/20	Tree of the	
							(2011年)		31.01		KEN T	45
`:		1.			•			•	4.0	7 "		
						K in the			100	E ST		
						S. W. W.		8				
· .						•					i	
					Comment of the second							
				2.5		al delimination	A STATE OF THE STA		新 基本	71.5	1	
					· A							
P	LEASE PA	Y THIS INVOIC	E WI	HEN DU	JE. NO	MON	THLY STATE	MEN.	TWIL	LBER	ENDE	RED

Freight Policy:

• ALL ORDERS OVER

• ORDERS LESS THAN
• ORDERS LESS THAN
• SOME ORDERS WILLE IR INCREASED TO MEET FREIGHT REQUIREMENTS.

OFFICE

KEYSTONE AUTOMOTIVE WAREHOUSE 44 TUNKHANNOCK AVENUE EXETER PA 18643

KEYSTONE AUTOMOTIVE WAREHOUSE SLOCUM AVENUE EXETER, PA. 18643

UR ORDER NO.	DATE SHIPPED	SHIPPED VIA		FREIGHT	TERMS
•					1
55878	02/29/96	ABF 15CTN 530#	11 PR	EPAID 10TH	PROX 2 %
	N. 18 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·		
		The American State of the State	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	- Craix	The second secon
· · · · · · · · · · · · · · · · · · ·	2 V646	BATTERY TESTER	CHARGING POST	1.580 0.590	18. 76 28. 32
	公司				
	2 V709	VALUE EXTENSI		0.410	
		VALVE EXTENSI	ONS-1 1/4 PLAS	0. 410 0. 720	4. 92 8. 64
	D V714			F1000302	A STATE OF LOT
58	2 V805	MUFFLER BANDA		0. 700	8.40
	2 VB04	EXHAUST PIPE	REPAIR KIT	0.700	8. 40 5. 48
	is the same of				
62	2 VS97	TIRE GAUGE-DI	AL TYPE	1. 240	14: 88
	2 V877	TIRE GAUGE-AU		0 BOO	19 20
				C	
66	8 V930	VALTAPE		0.590	28. 32
* 1 -	V730	TORY SCREWDRI	VER SET 2 PC	1.570	37.68
		Section 1	经生态的数据的数		
FIRM					
			大学的 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
\$. 3. 3. 4					
			CHARGES		0. 00
27 1 X2.8 7 A. C	· 英語 (14.10年)	SPECIAL	CHARGES/CREDIT	W SOUTH CARRY	0.00
		TOTAL	The state of the s		1, 948. 50
Parket				<u></u>	

PLEASE PAY THIS INVOICE WHEN DUE. NO MONTHLY STATEMENT WILL BE RENDERED.

reight Policy:

• ALL ORDERS OVER \$750.00 WILL BE SHIPPED PREPAID.

• ORDERS LESS THAN \$750.00 WILL BE SHIPPED F.O.B.CHICAGO.

• SOME ORDERS WILL E INCREASED TO MEET FREIG REQUIREMENTS.



C	PSC Surveillance	= 12/04/96 #15/E	etio ~
1. Reporting Office FOCR	2. Home Office FOCR	3. Date 8/14/96	4. Product Code 1133
5a. Product Name LOCK DE-ICER		5b. Model VICTOR #V-	500 AMOUNT UNK
5c. Product Description & Identification LOC PACKAGE.	CK DE-ICER, UNDER PE	RESSURE, SMALL META	AL TUBE IN BLISTER
Attachment: ()Label ()Photo	()Literature ()Other	,	· · · · · · · · · · · · · · · · · · ·
5d. Manufacturer/Importer - Name and Addres VICTOR AUTOMOTIVE PRODUCT I DES PLAINES, IL. 60016			
6a. Suspected Problem/Violation (X) FHSA - Labeling, Banned () PPPA - No CRP, Ineffective CRP () FFA - Labeling, Fails Std., Cert. () CPSA - Possible Sec. 15, Fails Std., Cert. () RSA - Noncompliance () Other - Refer to other Federal of	Std., Cert.		
7. Establishment Where Encountered - Name WESTLAKE ACE HARDWARE 15225 87TH ST. LENEXA, KS. 66219	end Address	•	
8. Reported by (Type Name & Title) ROBERT B. WADSWORTH JR. INVESTIGATOR	9. Employee No. 8158	10. Signature Robert B W	8/16/56
11. Reporting Office Action () Referred to Home Office () Referred to HO ()	12. Reviewing Official		
() Official Sample Collected (Sample #)	13. Title 5/55	14. Signature	Fenk
() El at Dealer () Other () None; If none, why:	5/55 15. Date 9/4/96	16. Distribution: 0: FOCE	- locali

Adapted for WP for Windows 6/93 [Epson LQ-1170 Printer 10/93]

exturit x Victor Automotive

(000)

_					12/04/96			
			onsumer Pi SAMPLE C		•	•		
1.	Sample Flag		2. Date Co 12/4/96			Type and	Number: 97	
	Product Name CK DE-ICER		4b Model V-500 VIC		4c NEISS 0955		5. Assignmen	
6.	Complete for Import Samples		V-JUV VIL	TUR	7. MIS		• Usure	
	Port of Entry:				7. MIS	82M	I .	ctivity 1
1	Country of Origin:				9a Home F			
1	Entry No. and Date: Customs Contact:				FOCR	KU	9b Collecting FOCR	3 KU
10	Sample Cost	L4 100	roice Value	of Lot	1001	149 8	ze of Lot	Units
	Sample Cost	11. 11.	Cice value	OI LO		12. 31	Ze of Lot	unt
	Manufacturer/Importer # VIC019	1.	ipper/Forei	ign Man	ufacturer		ealer/Import B	kroker #
	TOR AUTOMOTIVE PRODUCT	SEE #	113			SEE	#13	
	S. WOLF RD.	}				-		
DE	S MCINE6, IL 60016	1						
14.	Supporting documents attached:	<u></u>			 	L		
	Invoice No. and Date: #1332	5		1	0/4/96	Date Shipp	ped:	
	Shipping Record and Date:			· · · · · · · · · · · · · · · · · · ·	0/ 7/ 00			
	Affidavit Signer's name, title and date	: SIG	NED BY TO	ONI COC	CONE, OF	C. MGR, 1	2/04/96.	
17.	Product Identification:							
	Product is described as	s a .	625 flui	id oun	ce pres	surize	d containe	er of
	Victor brand model #V-5	500 lo	ock de-i	icer.	Contain	er has	black and	
	label, red injector tip							
18.	Reason for collection/analysis nee					FFA	O PPPA	() RSA
19	F/U to FOCR KAN-RP surv Summary of Field Screening:	/еттта	ince- su	spect	Tabelli	nd Aro	lations.	
•	Product container and a	CCOME	anving	packa	aina bot	h have	several	
	labeling violations, se	_		_				LSHL-
	please conduct analysis	-			_			
20.	Sample size/Method of Collection:							
	Sample was collected du	ring						
	was collected at random							
	current inventory number	r una	vailabl		mple rem ntification o			stody or
	Identification on sample: 830-3080	DRB	12/4/96 "		iunceuon o 3080 Denni		d cate:	12/4/96 *
	Sample delivered to:			23b Dat			ord Sent to:	
SA	MPLE CUST VIA RPS			12/10/9				
25.	Laboratory/Office: LSHL X LSE	L	CRM	CCA	_ Ott	ner		
26.	Remarks:							 : :
	Copy of narrative report					davit a	and origin	nal
	inspection request incl	luded	with sa	ample.			•	
27. R	telated Samples: 97-830-3201 thru	3204.						
28a (Collector's name/title:			28b Co	lector's sig	inature/da	rte:	
Denr	nis Blasius Resident	Investig	ator	(h	mis R. B.	d		12/9/96
29a I	Reviewer's name/title:				riewer's sig		ate:	
	(0)(0)(0)			, , , , , , , , , , , , , , , , , , ,		,		

11

packaging.

FIELD SUMMARY

ingredients and flashpoint.

METHOD OF COLLECTION

in the locked CPSC office from time of collection until later shipment to the Sample Custodian on 12/10/96. Samples were labeled as ID'd in #21, and shipped in a box sealed as ID'd in #22.



	U.S. Consumer Product SAMPLE COLLECT		ion 			
1. Sample Flag	2. Date Collected 12/4/96	3. Sample Type and Number: 97-830-3201 Physical Documentary				
4a. Product Name LOCK DE-ICER	4b Model V-502 VICTOR	4c NEISS 0955	5. Assignme	ent Number		
6. Complete for Import Samples Port of Entry: Country of Origin:		7. MIS 32626 3356		Activity1 Travel		
Entry No. and Date: Customs Contact:		9a Home RO FOCR	9b Collection FOCR	cting RO		
10. Sample Cost	ple Cost 11. Invoice Value of Lot			Units unt		
13. Manufacturer/Importer # VIC019 VICTOR AUTOMOTIVE PRODUCT 501 S. WOLF RD. DES MOINES, IL 60016	14. Shipper/Foreign Man SEE #13	· · · · · · · · · · · · · · · · · · ·	15. Dealer/Import SEE #13	Broker #		
16. Supporting documents attached: Invoice No. and Date: #1332	S.	0/4/96 Date	Shipped:			
Shipping Record and Date: Affidavit Signer's name, title and date						
17. Product Identification: Product is described as Victor brand model #V-! label, red injector tip	502 lock de-icer.	Container	has black a			
18. Reason for collection/analysis need F/U to FOCR KAN-RP surv				RSA		
9. Summary of Field Screening: Product container and a labeling violations, se conduct analysis to con	accompanying packa se narrative repor	ging both t for deta	have several ils. LSHL- p	lease		
20. Sample size/Method of Collection Sample was collected du was collected at random current inventory number	: uring inspection on from stock on ha	conducted o	n 12/04/96. 's warehouse	Sample		
21. Identification on sample: ' 97-830-3201	22. ide	ntification on se -3201 Dennis Bl	eal and date:	12/4/96		
23a. Sample delivered to: SAMPLE CUST VIA RPS	23b Da 12/10/9	6 FOCR	t/Record Sent to:			
25. Laboratory/Office: LSHL_X_ LSI	EL CRM CCA	Other_				
26. Remarks: Copy of narrative reposinspection request inc	rt, MSDS, invoicing luded with sample.	ng, affidav	rit and orig	inal		
27. Related Samples: 97-830-3080; 320	2 thru 3204.					
28a Collector's name/title: Dennis Blasius Resident	Investigator	ollector's signations of Black		12/9/96		

packaging.

FIELD SUMMARY

flashpoint.

METHOD OF COLLECTION

in the locked CPSC office from time of collection until later shipment to the Sample Custodian on 12/10/96. Samples were labeled as ID'd in #21, and shipped in a box sealed as ID'd in #22.



 										
	(nsumer P				sion			
					3. Sample Type and Number: 97-830-3202 Physical Documentary					3202
4a. Product Name BICYCLE TIRE REPAIR 6. Complete for Import Samples Port of Entry:					4c NEISS			5. Assignment Number		
				7. MIS 3 262 6 <i>3.356</i>			8. Hours Activity Travel		_1	
Country of Origin: Entry No. and Date: Customs Contact:					9a Home RO FOCR			9b Collecting RO FOCR		
10. Sample Cost		11. lnv	oice Value	of Lot	1		12. Si	ize of Lot	Un unt	
13. Manufacturer/Importer # VI VICTOR AUTOMOTIVE PRODUC 501 S. WOLF RD. DES MOINES? IL 60016	T	14. Shi SEE #1	pper/Fore	ign Man	ufactu	rer	15. D	ealer/impor #13	rt Broker	#
16. Supporting documents atta Invoice No. and Date: Shipping Record and Date: Affidavit Signer's name, title a	#16742		NED BY TO		/17/96 CONE		e Ship			
17. Product Identification: Product is describ Emergency Repair" black, yelow, whit	ingre e and	dient brow	n labe	or bra l and	nd, a wh	model ite p	#VB last	-58. Car ic cap.	n has Packa	a ged
18. Reason for collection/analy F/U to FOCR KAN-RP				CF Ispect		○ FFA eling		igcup PPPAlations.	<u> </u>	RSA
19. Summary of Field Screening Product container a labeling violations conduct analysis to	y: and ac s, see	ccomp e nar	anying rative	packa repor	ging t fo	both r deta	have	e severa . LSHL-	ıl please	
20. Sample size/Method of Coll Sample was collected at re	ection: ed du andom	ring from	inspect stock	ion c	ondu nd i	cted on firm	on 12 n's v	2/04/96. warehous	Samp	le
current inventory : 21. Identification on sample: 97-830-3202		r una DRB	12/4/96 "	22. Ide	ntificat	tion on s Dennis E	eal ar	id date:	ustoa	12/4/96 "
23a. Sample delivered to: SAMPLE CUST VIA RPS				23b Da 12/10/9	6 1	4. Repo FOCR	rt/Rec	ord Sent to	:	
25. Laboratory/Office: LSHL_X	LSEI	L 0	CRM	CCA	_	Other				<u> </u>
26. Remarks: Copy of narrative inspection request	repor incl	t, MS uded	DS, inwith sa	voicin	ıg, a	ffida	vit	and orig	ginal	
27. Related Samples: 97-830-308	30; 320 <u>1</u>	, 3203,	and 3204.							
28a Collector's name/title: Dennis Blasius Re	esident I	nvestiga	ator			's signa <i>e. Bl</i> a		ate:		12/9/96
29a Reviewer's name/title:						's signa		ate:		

in blister packaging. UPC #7723100058.

FIELD SUMMARY

flashpoint.

METHOD OF COLLECTION

in the locked CPSC office from time of collection until later shipment to the Sample Custodian on 12/10/96. Samples were labeled as ID'd in #21, and shipped in a box sealed as ID'd in #22.

	·	U.S. Consumer		Safety Commis	sion			
1.	Sample Flag		Collected					
	Product Name YL ADHESIVE	4b Mode #V-301	el	4c NEISS 0909		5. Assignment Number		
6.	Complete for Import Samples Port of Entry: Country of Origin:			7. MIS 32626 33562 9a Home RO FOCR		8. Hours Activity 1 Travel 3		
	Entry No. and Date: Customs Contact:					9b Collecting RO FOCR		
10.	Sample Cost	11. Invoice Valu	oice Value of Lot			Size of Lot Units unt		
VIC 501 DES	Manufacturer/Importer # VIC019 TOR AUTOMOTIVE PRODUCT S. WOLF RD. S. MOINES, IL 60016	14. Shipper/For SEE #13	reign Man	ufacturer	15. De SEE #	aler/Import E 13	Broker #	
16.	Supporting documents attached: Invoice No. and Date: #00919 Shipping Record and Date: Affidavit Signer's name, title and date			/22/96 Date	e Shipp			
	Product Identification: Product is described as vinyl adhesive. Tube is a black screw-on cap. U	white and PC #772310	yellow 0301.	with red	, bla	ck lette	ring and	
18.	Reason for collection/analysis nee F/U to FOCR KAN-RP surv			SA FFA		O PPPA ations.	RSA	
19.	Summary of Field Screening: Product container and a labeling violations, se conduct analysisi to co	ccompanying e narrative	g packa e repor	ging both t for deta	have	several LSHL- p		
20.	Sample size/Method of Collection: Sample was collected du was collected at random current inventory numbe	ring inspec	ction c	onducted ond in firm	on 12 m's w	/04/96.	Sample	
97	Identification on sample: -830-3203	DRB 12/4/96	22. ide: "97-830-	ntification on s 3203 Dennis E	seal and Blasius	d date:	12/4/96	
SA	Sample delivered to: MPLE CUST VIA RPS		23b Da 12/10/9	6 FOCR	rt/Reco	ord Sent to:		
25.	Laboratory/Office: LSHL_X LSE	L CRM	_ CCA	_ Other	· · · · · · · · · · · · · · · · · · ·			
26.	Remarks: Copy of narrative reportinspection request incl	t, MSDS, i	nvoicin sample.	g, affida	vit a	and origi	nal	
27. 1	Related Samples: 97-830-3080; 3201	l, 3202 and 3204						
ľ	Collector's name/title: nis Blasius Resident	Investigator	\perp	llector's signa		TE:	12/9/96	
29a	Reviewer's name/title:			viewer's signa		ite:		

1/8

FIELD SUMMARY

flashpoint.

METHOD OF COLLECTION

in the locked CPSC office from time of collection until later shipment to the Sample Custodian on 12/10/96. Samples were labeled as ID'd in #21, and shipped in a box sealed as ID'd in #22.

19

										
	U.S. Consumer Product Safety Commission SAMPLE COLLECTION REPORT									
1.				ollected	3. Sample Physic		d Number: 97-830-3204 O Documentary			
ı	4a. Product Name RUBBER CEMENT				4c NEISS 0909		5. Assignment Number			
6. Complete for Import Samples Port of Entry:					7. MIS 3 262 6 23	562	8. Hours Activit			
	Country of Origin: Entry No. and Date: Customs Contact:				9a Home R FOCR		9b Collecting RG FOCR)		
10.	Sample Cost	11. Invoice Value of				12. S 4		Units unt		
VIC 501 DES	Manufacturer/importer # VIC019 TOR AUTOMOTIVE PRODUCT S. WOLF RD. S MOINES, IL 60016	14. Shipper/Foreign Manufacturer SEE #13 15. Dealer/Import Broker SEE #13					er#			
16.	Supporting documents attached:									
1	Invoice No. and Date: #61005	9-00		1	<u>0/8/96 </u>	Date Ship	ped:			
	Shipping Record and Date: Affidavit Signer's name, title and date	: SIG	NED BY TO	ONI COC	CONE, OF	MGR 1	12/04/96			
17.	Product Identification:									
	Product is described as a 3/8 fluid ounce tube of rubber cement, Victor brand. Tube is green, white and yellow with black lettering. Tube has warning on front stating "Danger: Extremely harmful or fatal									
18.	B. Reason for collection/analysis needed: FHSA CPSA FFA PPPA RSA F/U to FOCR KAN-RP surveillance- suspect labeling violations.									
19.	Summary of Field Screening:			•			_	-		
	Product container and a									
l	labeling violations, se conduct analysis to con									
20.	Sample size/Method of Collection:		percent	age o	I nazaro	ious II	ngreatents a	na		
1	Sample was collected during inspection conducted on 12/04/96. Sample was collected at random from stock on hand in firm's warehouse; current inventory number unavailable. Sample remained in my custody or									
21.	Identification on sample:	ı uııc	IVATIANI	22. Ider	ntification o	n seal ar	nd date:	dy OI		
		DRB	12/4/96 "		3204 Denni			12/4/96		
SAI	Sample delivered to: MPLE CUST VIA RPS			23b Dat 12/10/9			ord Sent to:			
25.	Laboratory/Office: LSHL_X_ LSE	L	CRM	CCA	_ Oth	er				
26. Remarks: Copy of narrative report, MSDS, invoicing, affidavit and original inspection request included with sample.										
27. F	27. Related Samples: _{97-830-3080;} 3201, 3202 and 3203.									
28a	28a Collector's name/title: 28b Collector's signature/date:									
Dennis Blasius Resident Investigator						Prairie !		12/9/96		
29a Reviewer's name/title:					viewer's sig	nature/d	ate:			

~

if swallowd, vapors harmful. See back panel." Back of tube has use instructions and Victor Automotive Products name, address.

FIELD SUMMARY

flashpoint.

METHOD OF COLLECTION

in the locked CPSC office from time of collection until later shipment to the Sample Custodian on 12/10/96. Samples were labeled as ID'd in #21, and shipped in a box sealed as ID'd in #22.

1~