

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 36

National Average: 43

2x National Average: 86

National Median: 21

Average for Selected Dockets: 36

---

**Facility Name: Oyster Creek Docket (050- 00219)**

Details	Department	Work Type	Docket/Report
<b>Communications / IR</b>			
53 - Communication LTA	H - Health Physics	A - Administrative	050-00219/2003-005
53 - Communication LTA	H - Health Physics	A - Administrative	050-00219/2003-005
<b>Number of Items for this Docket: 2</b>			
<b>Percent of Total for this Docket: 6</b>			

<b>Management and Supervision / IR</b>			
40 - Individual Corrective Action LTA	C - Chemistry	M - Maint / Repair	050-00219/2004-006
40 - Individual Corrective Action LTA	G - Engineering	M - Maint / Repair	050-00219/2003-005
40 - Individual Corrective Action LTA	G - Engineering	P - Procedure Dev	050-00219/2004-006
40 - Individual Corrective Action LTA	G - Engineering	Q - Fire Protection	050-00219/2004-006
40 - Individual Corrective Action LTA	I - Instrumentation & Control	M - Maint / Repair	050-00219/2004-006
40 - Individual Corrective Action LTA	M - Mechanical	M - Maint / Repair	050-00219/2004-006
40 - Individual Corrective Action LTA	O - Operations	B - Bal of Plant Ops	050-00219/2004-006
40 - Individual Corrective Action LTA	P - Procedure Writers	P - Procedure Dev	050-00219/2004-002
40 - Individual Corrective Action LTA	P - Procedure Writers	P - Procedure Dev	050-00219/2004-006
40 - Individual Corrective Action LTA	T - Training	O - Control Room Ops	050-00219/2004-006
41 - Action not begun or untimely	B - Plant Management	M - Maint / Repair	050-00219/2004-006
41 - Action not begun or untimely	E - Electrical	V - Troubleshooting	050-00219/2004-007
41 - Action not begun or untimely	G - Engineering	M - Maint / Repair	050-00219/2004-004
47 - Root Cause LTA	G - Engineering	Q - Fire Protection	050-00219/2004-006
47 - Root Cause LTA	G - Engineering	V - Troubleshooting	050-00219/2003-005
47 - Root Cause LTA	G - Engineering	V - Troubleshooting	050-00219/2004-006
<b>Number of Items for this Docket: 16</b>			
<b>Percent of Total for this Docket: 44</b>			

<b>Procedures and Reference Document / IR</b>			
12 - Procedure technical content LTA	P - Procedure Writers	P - Procedure Dev	050-00219/2004-002
12 - Procedure technical content LTA	P - Procedure Writers	P - Procedure Dev	050-00219/2004-002
12 - Procedure technical content LTA	P - Procedure Writers	P - Procedure Dev	050-00219/2004-002
12 - Procedure technical content LTA	P - Procedure Writers	P - Procedure Dev	050-00219/2004-004
<b>Number of Items for this Docket: 4</b>			
<b>Percent of Total for this Docket: 11</b>			

---

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 36

National Average: 43

2x National Average: 86

National Median: 21

Average for Selected Dockets: 36

---

**Facility Name: Oyster Creek Docket (050- 00219)**

Details	Department	Work Type	Docket/Report
<b>Training / IR</b>			
04 - Task Qualification	T - Training	O - Control Room Ops	050-00219/2004-006
<b>Number of Items for this Docket:</b> 1			
<b>Percent of Total for this Docket:</b> 3			
<b>Work Factors / IR</b>			
83 - Work practice or craft skill LTA	E - Electrical	V - Troubleshooting	050-00219/2004-007
83 - Work practice or craft skill LTA	H - Health Physics	A - Administrative	050-00219/2004-002
83 - Work practice or craft skill LTA	M - Mechanical	M - Maint / Repair	050-00219/2004-003
83 - Work practice or craft skill LTA	O - Operations	S - Surveillance	050-00219/2003-005
83 - Work practice or craft skill LTA	Q - QA/QC	H - Health Physics	050-00219/2004-003
84 - Non-conserv. decision / Questioning LTA	O - Operations	H - Health Physics	050-00219/2004-002
93 - Awareness or attention LTA	I - Instrumentation & Control	M - Maint / Repair	050-00219/2004-003
94 - Log-keeping or review LTA	O - Operations	V - Troubleshooting	050-00219/2004-003
94 - Log-keeping or review LTA	O - Operations	V - Troubleshooting	050-00219/2004-003
<b>Number of Items for this Docket:</b> 9			
<b>Percent of Total for this Docket:</b> 25			
<b>Management and Supervision / LER</b>			
41 - Action not begun or untimely	G - Engineering	F - Modification	050-00219/2004-005-00
<b>Number of Items for this Docket:</b> 1			
<b>Percent of Total for this Docket:</b> 3			
<b>Procedures and Reference Document / LER</b>			
12 - Procedure technical content LTA	O - Operations	O - Control Room Ops	050-00219/2004-007-00
<b>Number of Items for this Docket:</b> 1			
<b>Percent of Total for this Docket:</b> 3			
<b>Work Factors / LER</b>			
81 - Work Package Quality LTA	M - Mechanical	M - Maint / Repair	050-00219/2004-001-00
83 - Work practice or craft skill LTA	M - Mechanical	M - Maint / Repair	050-00219/2004-001-00
<b>Number of Items for this Docket:</b> 2			
<b>Percent of Total for this Docket:</b> 6			
<b>Total Items for this Docket:</b> 36			

---