

RESET 11N AUDIT OUT

LOCATION	SYSTEM	Part No.	Serial No.	CONFIG.	CONFIG.	OTHER(property#, notes, etc.)
SMET	TRH	HMP_____	53740006	V 991018.00		
	WND1	05106/08234	3110315318	V 991018.00		
	WND2	05106/08234	28399155531	V 991018.00		
	ORG	ORG-115-DA	03317-C7	V 991018.00		
	DAQ MET	ZENO-3200	300	V 991018.00		
GNDRAD	NET	REBS Q*7.1	Q95063	V 000704.00		
	PSP	PSP	31279F3	V 000704.00		
	PIR	PIR	31390F3	V 000704.00		
	IRT	KT 19 85	863	V 000704.00		
	DAQ GND	ZENO-3200	034	V 000704.00		
SKYRAD	PSPG	PSP	31274F3	V 00629.00		
	PIRG	PIR	31301F3	V 00629.00		
	UVB	501A V3	2870	V 00629.00		
	MFRSR	MFR7-HEAD	Head:210 Unit:46070	V 00629.00		
	IRT	KT 19.85	868	V 00629.00		
	TRK	INTRA II	WD 24187	V 00629.00		
	NIP	NIP	31346 E6	V 00629.00		
	PSPD	PSP	31275F3	V 00629.00		
	PIRD	PIR	30167F3	V 00629.00		
DAQ SKY	ZENO-3200	303	V 00629.00			
STAND ALONE	CEIL	CT25K	P2710015			
	CEIL Cmptr		no change			
	MWR	WVR-1100	15			
	MWR Cmptr		no change			
	AERI	AERI-06	8			
	WSI	EHT02	no change			
	CIMEL		?			

SITE:Nauru

DATE:7/20/00

AUDITOR: Porch

OMS ID- AUDIT(ARCS2)-0010

RESET 11N AUDIT OUT

LOCATION	SYSTEM	Part No.	Serial No.	CONFIG.	CONFIG.	OTHER(property#, notes, etc.)
----------	--------	----------	------------	---------	---------	-------------------------------

IVAN	MPL		gone			
	MPL Controlr		gone			
	MPL Computr		gone			
	MMCR		15K6			
	WSI	WSI-E/06-B	Unit 6			

EVAN	BBSS	__-MW15G	no change	BBSS 00707.49		
	BBSS Cmptr					
	FAX Machine					
	Obsrvr Cmptr					
	EMWIN					

SAFETY	FIRST AID					

SPARES						

OTHER						
						SITE:Nauru

DATE:7/20/00

RESET 11N AUDIT OUT

LOCATION	SYSTEM	Part No.	Serial No.	CONFIG.	CONFIG.	OTHER(property#, notes, etc.)

Audit Out Philosophy

1. Check the part number and correct if necessary. Enter serial number for all instruments. They can be found on the OMS label or the instrument. Sometimes the label (OMS or manufacturer) is in a non-obvious or hard to see location, so you may have to search it out). An agency property number is also needed, and should be noted in the "OTHER" column. This is important if the serial number can't be found.
2. Record the final configurations of instruments as applicable (i.e. Loggers, BBSS). This may be a file, filename or printout.
3. Inventory spares (instruments, not supplies) in the storage or ARCS vans. Be sure to include non-instrument items deemed necessary to track; use your best RESET judgement. Use the part numbers on the items, or from the form; include serial number and location.
4. Enter the part number, model number (e.g. IBM 380XD), and serial number from equipment that is associated with listed instruments (e.g. the MWR computer). Use the 'OTHER' rows if necessary. You may also enter the agency property number if no other identification can be found. This information should be entered in the OTHER column for the associated instrument.