

Combined IR/ER/LER Report
Docket: 50-237 DRESDEN 2

Total Number of Hits in Date Range: 89
From 01/01/2003 to 01/01/2004
2x National Average: 85

Details	Department	Work Type	Docket/Report
Communications IR			
Number of items: 2			
Percent of total: 2.25			
53-Communication LT G-Engineering	R-Refueling	50-237/2003002	
	G-Engineering		
53-Communication LT O-Operations	O-Control Room Ops	50-237/2003006	
	O-Operations		
Communications ER			
Number of items: 0			
Percent of total: 0			
Communications LER			
Number of items: 0			
Percent of total: 0			
Human-System Interface and Environm IR			
Number of items: 0			
Percent of total: 0			
Human-System Interface and Environm ER			
Number of items: 0			
Percent of total: 0			
Human-System Interface and Environm LER			
Number of items: 0			
Percent of total: 0			
Management and Supervision IR			
Number of items: 17			
Percent of total: 19.1			
41-Action not begun E-Electrical	V-Troubleshooting	50-237/2002017	
41-Action not begun O-Operations	Q-Fire Protection	50-237/2002017	
41-Action not begun G-Engineering	V-Troubleshooting	50-237/2003002	
47-Root Cause LTA G-Engineering	M-Maint / Repair	50-237/2003002	
33-Management expec O-Operations	R-Refueling	50-237/2003002	
42-No action planne O-Operations	O-Control Room Ops	50-237/2003002	
42-No action planne O-Operations	O-Control Room Ops	50-237/2003002	
47-Root Cause LTA G-Engineering	M-Maint / Repair	50-237/2003002	
47-Root Cause LTA G-Engineering	M-Maint / Repair	50-237/2003002	
40-Individual Corre G-Engineering	M-Maint / Repair	50-237/2003002	
41-Action not begun G-Engineering	M-Maint / Repair	50-237/2003007	
47-Root Cause LTA G-Engineering	M-Maint / Repair	50-237/2003007	
43-Operating Experi G-Engineering	G-Design	50-237/2003008	
41-Action not begun G-Engineering	F-Modification	50-237/2003008	
41-Action not begun G-Engineering	M-Maint / Repair	50-237/2003008	
47-Root Cause LTA G-Engineering	M-Maint / Repair	50-237/2003008	
40-Individual Corre G-Engineering	M-Maint / Repair	50-237/2003008	
Management and Supervision ER			
Number of items: 0			
Percent of total: 0			
Management and Supervision LER			
Number of items: 3			
Percent of total: 3.37			
42-No action planne P-Procedure Writers	P-Procedure Dev	50-237/200300100	
Page: 1	Date:05/24/2004		

Combined IR/ER/LER Report
Docket: 50-237 DRESDEN 2

Total Number of Hits in Date Range: 89

From 01/01/2003 to 01/01/2004
2x National Average: 85

Details	Department	Work Type	Docket/Report
Management and Supervision LER			
Number of items: 3			
Percent of Total: 3.37			
47-Root Cause LTA	P-Procedure Writers	P-Procedure Dev	50-237/200300100
36-Scheduling and p	I-Instrumentation & M-Maint / Repair		50-237/200300700
Organizational Issues IR			
Number of items: 0			
Percent of total: 0			
Organizational Issues ER			
Number of items: 0			
Percent of total: 0			
Organizational Issues LER			
Number of items: 0			
Percent of total: 0			
Procedures and Reference Document IR			
Number of items: 4			
Percent of total: 4.49			
11-No procedure / r	G-Engineering	G-Design	50-237/2003002
12-Procedure techni	M-Mechanical	T-Testing	50-237/2003010
12-Procedure techni	G-Engineering	G-Design	50-237/2003010
13-Procedure has hu	G-Engineering	G-Design	50-237/2003010
Procedures and Reference Document ER			
Number of items: 0			
Percent of total: 0			
Procedures and Reference Document LER			
Number of items: 6			
Percent of total: 6.74			
12-Procedure techni	I-Instrumentation & C-Calibration		50-237/200300100
12-Procedure techni	I-Instrumentation & C-Calibration		50-237/200300100
12-Procedure techni	M-Mechanical	M-Maint / Repair	50-237/200300400
12-Procedure techni	O-Operations	O-Control Room Ops	50-237/200300600
12-Procedure techni	O-Operations	O-Control Room Ops	50-237/200300600
11-No procedure / r	M-Mechanical	M-Maint / Repair	50-237/200300700
Training IR			
Number of items: 8			
Percent of total: 8.99			
06-Simulator fideli	T-Training	O-Control Room Ops	50-237/2002017
06-Simulator fideli	T-Training	O-Control Room Ops	50-237/2002017
03-Training process	T-Training	O-Control Room Ops	50-237/2002017
05-Individual knowl	E-Electrical	M-Maint / Repair	50-237/2003002
02-Training LTA	T-Training	M-Maint / Repair	50-237/2003002
03-Training process	T-Training	O-Control Room Ops	50-237/2003006
03-Training process	T-Training	O-Control Room Ops	50-237/2003006
03-Training process	T-Training	O-Control Room Ops	50-237/2003006
Training ER			
Number of items: 0			
Percent of total: 0			
Training LER			
Number of items: 0			
Percent of total: 0			
Work Factors IR			
Number of items: 48			
Percent of total: 53.93			
91-Verification / p	O-Operations	Q-Fire Protection	50-237/2002017
Page: 2		Date:05/24/2004	

Combined IR/ER/LER Report

Docket: 50-237 DRESDEN 2

Total Number of Hits in Date Range: 89

From 01/01/2003 to 01/01/2004

2x National Average: 85

Details	Department	Work Type	Docket/Report
Work Factors IR			
Number of items: 48			
Percent of Total: 53.93			
84-Non-conserv. dec	T-Training	V-Troubleshooting	50-237/2002017
83-Work practice or	U-Unknown	Q-Fire Protection	50-237/2002017
84-Non-conserv. dec	M-Mechanical	M-Maint / Repair	50-237/2003002
83-Work practice or	M-Mechanical	M-Maint / Repair	50-237/2003002
84-Non-conserv. dec	O-Operations	V-Troubleshooting	50-237/2003002
84-Non-conserv. dec	B-Plant Management	V-Troubleshooting	50-237/2003002
84-Non-conserv. dec	G-Engineering	V-Troubleshooting	50-237/2003002
84-Non-conserv. dec	G-Engineering	M-Maint / Repair	50-237/2003002
83-Work practice or	O-Operations	O-Control Room Ops	50-237/2003002
93-Awareness or att	G-Engineering	O-Control Room Ops	50-237/2003002
84-Non-conserv. dec	G-Engineering	M-Maint / Repair	50-237/2003002
93-Awareness or att	G-Engineering	A-Administrative	50-237/2003002
91-Verification / p	G-Engineering	M-Maint / Repair	50-237/2003002
83-Work practice or	Q-QA/QC	G-Design	50-237/2003002
93-Awareness or att	G-Engineering	A-Administrative	50-237/2003002
83-Work practice or	G-Engineering	A-Administrative	50-237/2003002
86-Work untimely	G-Engineering	A-Administrative	50-237/2003002
86-Work untimely	G-Engineering	A-Administrative	50-237/2003002
91-Verification / p	I-Instrumentation &	C-Calibration	50-237/2003002
93-Awareness or att	G-Engineering	G-Design	50-237/2003004
93-Awareness or att	G-Engineering	G-Design	50-237/2003004
93-Awareness or att	G-Engineering	G-Design	50-237/2003004
93-Awareness or att	G-Engineering	G-Design	50-237/2003004
93-Awareness or att	G-Engineering	G-Design	50-237/2003004
93-Awareness or att	G-Engineering	G-Design	50-237/2003004
93-Awareness or att	O-Operations	O-Control Room Ops	50-237/2003006
94-Log-keeping or r	O-Operations	O-Control Room Ops	50-237/2003006
93-Awareness or att	O-Operations	O-Control Room Ops	50-237/2003006
93-Awareness or att	O-Operations	O-Control Room Ops	50-237/2003006
93-Awareness or att	O-Operations	O-Control Room Ops	50-237/2003006
93-Awareness or att	O-Operations	O-Control Room Ops	50-237/2003006
93-Awareness or att	O-Operations	O-Control Room Ops	50-237/2003006
93-Awareness or att	O-Operations	O-Control Room Ops	50-237/2003006
93-Awareness or att	O-Operations	O-Control Room Ops	50-237/2003006
93-Awareness or att	O-Operations	O-Control Room Ops	50-237/2003006
93-Awareness or att	O-Operations	O-Control Room Ops	50-237/2003006
93-Awareness or att	O-Operations	O-Control Room Ops	50-237/2003006
93-Awareness or att	O-Operations	O-Control Room Ops	50-237/2003006
93-Awareness or att	O-Operations	O-Control Room Ops	50-237/2003006
93-Awareness or att	O-Operations	O-Control Room Ops	50-237/2003006
93-Awareness or att	E-Electrical	M-Maint / Repair	50-237/2003006
91-Verification / p	E-Electrical	M-Maint / Repair	50-237/2003006
93-Awareness or att	O-Operations	Q-Fire Protection	50-237/2003006
83-Work practice or	I-Instrumentation &	Q-Fire Protection	50-237/2003007
84-Non-conserv. dec	I-Instrumentation &	Q-Fire Protection	50-237/2003007
85-Team interaction	I-Instrumentation &	Q-Fire Protection	50-237/2003007
86-Work untimely	G-Engineering	V-Troubleshooting	50-237/2003008
93-Awareness or att	G-Engineering	M-Maint / Repair	50-237/2003010
93-Awareness or att	G-Engineering	A-Administrative	50-237/2003010
93-Awareness or att	G-Engineering	A-Administrative	50-237/2003010

Work Factors ER

Number of items: 0

Percent of total: 0

Work Factors LER

Number of items: 1

Percent of total: 1.12

83-Work practice or G-Engineering

G-Design

50-237/200300100

Page: 3

Date:05/24/2004