

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 28

National Average: 43

2x National Average: 86

National Median: 21

Average for Selected Dockets: 28

---

**Facility Name: Calvert Cliffs 2 Docket (050- 00318)**

Details	Department	Work Type	Docket/Report
<b>Management and Supervision / IR</b>			
41 - Action not begun or untimely	G - Engineering	M - Maint / Repair	050-00318/2003-006
47 - Root Cause LTA	G - Engineering	V - Troubleshooting	050-00318/2004-008
47 - Root Cause LTA	M - Mechanical	M - Maint / Repair	050-00318/2003-006
48 - Audits or problem identification LTA	O - Operations	O - Control Room Ops	050-00318/2004-008
<b>Number of Items for this Docket: 4</b>			
<b>Percent of Total for this Docket: 14</b>			
<hr/>			
<b>Procedures and Reference Document / IR</b>			
11 - No procedure / reference documents	P - Procedure Writers	O - Control Room Ops	050-00318/2004-008
12 - Procedure technical content LTA	G - Engineering	F - Modification	050-00318/2004-008
12 - Procedure technical content LTA	G - Engineering	G - Design	050-00318/2004-002
12 - Procedure technical content LTA	G - Engineering	G - Design	050-00318/2004-005
12 - Procedure technical content LTA	G - Engineering	Q - Fire Protection	050-00318/2004-003
<b>Number of Items for this Docket: 5</b>			
<b>Percent of Total for this Docket: 18</b>			
<hr/>			
<b>Training / IR</b>			
03 - Training process problem	T - Training	O - Control Room Ops	050-00318/2004-008
<b>Number of Items for this Docket: 1</b>			
<b>Percent of Total for this Docket: 4</b>			
<hr/>			
<b>Work Factors / IR</b>			
83 - Work practice or craft skill LTA	I - Instrumentation & Control	F - Modification	050-00318/2004-008
83 - Work practice or craft skill LTA	I - Instrumentation & Control	P - Procedure Dev	050-00318/2004-008
83 - Work practice or craft skill LTA	O - Operations	O - Control Room Ops	050-00318/2004-008
84 - Non-conserv. decision / Questioning LTA	G - Engineering	F - Modification	050-00318/2004-002
84 - Non-conserv. decision / Questioning LTA	G - Engineering	F - Modification	050-00318/2004-008
84 - Non-conserv. decision / Questioning LTA	G - Engineering	M - Maint / Repair	050-00318/2003-006
84 - Non-conserv. decision / Questioning LTA	O - Operations	O - Control Room Ops	050-00318/2004-008
84 - Non-conserv. decision / Questioning LTA	O - Operations	O - Control Room Ops	050-00318/2004-008
84 - Non-conserv. decision / Questioning LTA	O - Operations	O - Control Room Ops	050-00318/2004-008
88 - Tag outs LTA	O - Operations	M - Maint / Repair	050-00318/2004-004
88 - Tag outs LTA	O - Operations	M - Maint / Repair	050-00318/2004-004
88 - Tag outs LTA	O - Operations	M - Maint / Repair	050-00318/2004-004
88 - Tag outs LTA	O - Operations	M - Maint / Repair	050-00318/2004-004

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 28

National Average: 43

2x National Average: 86

National Median: 21

Average for Selected Dockets: 28

---

**Facility Name: Calvert Cliffs 2 Docket (050- 00318)**

Details	Department	Work Type	Docket/Report
<b>Work Factors / IR</b>			
94 - Log-keeping or review LTA	Q - QA/QC	F - Modification	050-00318/2004-002
<b>Number of Items for this Docket:</b> 14			
<b>Percent of Total for this Docket:</b> 50			
<b>Communications / LER</b>			
53 - Communication LTA	G - Engineering	V - Troubleshooting	050-00318/2004-001-00
53 - Communication LTA	G - Engineering	V - Troubleshooting	050-00318/2004-001-00
<b>Number of Items for this Docket:</b> 2			
<b>Percent of Total for this Docket:</b> 7			
<b>Management and Supervision / LER</b>			
42 - No action planned	E - Electrical	M - Maint / Repair	050-00318/2004-001-00
43 - Operating Experience Review LTA	E - Electrical	M - Maint / Repair	050-00318/2004-001-00
<b>Number of Items for this Docket:</b> 2			
<b>Percent of Total for this Docket:</b> 7			
<b>Total Items for this Docket: 28</b>			

---