

April 18, 2002

MEMORANDUM TO: John A. Nakoski, Chief, Section 1
Project Directorate II
Division of Licensing Project Management

FROM: Gordon E. Edison, Senior Project Manager, Section 1/*RA*/
Project Directorate II
Division of Licensing Project Management

SUBJECT: CONFERENCE CALL RE: SURRY UNIT 2 REACTOR VESSEL HEAD
INSPECTION RESULTS (TAC NO. MB4584)

On April 4, 2002, a conference call was held with Virginia Electric and Power Company (VEPCO) to discuss the results of their recent inspection of the Surry Unit 2 reactor vessel head within the control rod drive mechanism (CRDM) shroud. VEPCO stated that a qualified visual bare metal inspection was completed for 100 percent of the head surface within the CRDM shroud. VEPCO reported that 1) there were no fixed boric acid deposits that prevented clear, unobstructed inspection of the head, 2) there was no evidence of throughwall leakage observed for any penetration, and 3) there was no degradation of the head surface observed. These results confirmed the same inspection findings from an earlier, similar inspection in late November 2001. There were some small amounts of loose debris (e.g., metal shavings and insulation) on the head. At the conclusion of the inspection, the head was pressure washed.

Based on the preliminary findings from Davis-Besse, the inspections performed by the licensee, and the susceptibility of the Surry Unit 2 reactor vessel head to nozzle cracking, the NRC staff did not identify any issues that needed additional followup prior to plant restart. The staff will document its formal review after receiving the licensee's NRC Bulletin 2002-01 response.

Docket No. 50-281

Attachment: Teleconference Participants

MEMORANDUM TO: John A. Nakoski, Chief, Section 1
Project Directorate II
Division of Licensing Project Management

April 18, 2002

FROM: Gordon E. Edison, Senior Project Manager, Section 1/RA/
Project Directorate II
Division of Licensing Project Management

SUBJECT: CONFERENCE CALL RE: SURRY UNIT 2 REACTOR VESSEL HEAD
INSPECTION RESULTS (TAC NO. MB4584)

On April 4, 2002, a conference call was held with Virginia Electric and Power Company (VEPCO) to discuss the results of their recent inspection of the Surry Unit 2 reactor vessel head within the control rod drive mechanism (CRDM) shroud. VEPCO stated that a qualified visual bare metal inspection was completed for 100 percent of the head surface within the CRDM shroud. VEPCO reported that 1) there were no fixed boric acid deposits that prevented clear, unobstructed inspection of the head, 2) there was no evidence of throughwall leakage observed for any penetration, and 3) there was no degradation of the head surface observed. These results confirmed the same inspection findings from an earlier, similar inspection in late November 2001. There were some small amounts of loose debris (metal shavings, insulation) on the head. At the conclusion of the inspection, the head was pressure washed.

Based on the preliminary findings from Davis-Besse, the inspections performed by the licensee, and the susceptibility of the Surry Unit 2 reactor vessel head to nozzle cracking, the NRC staff did not identify any issues that needed additional followup prior to plant restart. The staff will document its formal review after receiving the licensee's NRC Bulletin 2002-01 response.

Docket No. 50-281

Attachment: Teleconference Participants

Distribution:

PUBLIC	MCase	SBloom
PDII-1 R/F	BSheron	WBateman
GEEdison	WKane	MMorgan
EDunnington	LReyes	LGarner
JNakoski	KLandis	JBlake
SCollins	MCCOY	WBearden
JJohnson	KKarwosky	
WBorchardt	SCoffin	

ADAMS Accession Number:ML021230617

OFFICE	PDII-1/PM	PDII-2/LA	PDII-1:SC	
NAME	GEEdison:mw	EDunnington	JNakoski	
DATE	04/17/02	04/16/02	04/18/02	05/ /02

OFFICIAL RECORD COPY

Participants in April 4, 2002
Teleconference Related to Surry Unit 2
Inspection Results for Reactor Vessel Head

<u>Name</u>	<u>Organization</u>
G. Edison	NRC
K. Karwoski	NRC
M. Morgan	NRC/Region II
G. McCoy	NRC/Region II
L. Garner	NRC/Region II
J. Blake	NRC/Region II
W. Bearden	NRC/Region II
R. Blount	VEPCO (Dominion)
M. Adams	VEPCO (Dominion)
S. Sarver	VEPCO (Dominion)
J. Bischof	VEPCO (Dominion)
L. Spain	VEPCO (Dominion)
B. Foster	VEPCO (Dominion)
T. Shaub	VEPCO (Dominion)
G. Miller	VEPCO (Dominion)
E. Brennan	VEPCO (Dominion)
B. Garber	VEPCO (Dominion)
P. Quarles	VEPCO (Dominion)
J. Bennetch	VEPCO (Dominion)