


NTSB National Transportation Safety Board


Effects of Commuting on Pilot Fatigue: An NTSB Perspective


Mark R. Rosekind, Ph.D. Board Member

National Research Council Presentation November 22, 2010














Go! Flight 1002



• early starts, multiple segment days, sleep apnea



Honorable John K. Lauber:

No Accident ≠
Safe Operation



Guantanamo Bay Cuba

First NTSB aviation accident to cite fatigue as probable cause



acute sleep loss, sleep debt, circadian disruption




NTSB Recommendations

MOST WANTED since 1990

150+ fatigue recommendations




Complex Issue: Requires Multiple Solutions




- Scheduling Policies and Practices
- Education
- Organizational Strategies
- Raising Awareness
- Healthy Sleep
- Vehicle and Environmental Strategies
- Research and Evaluation



Fatigue Indicators








After Traveling Eastward

Sleep periods




Individuals



Home Destination



After Traveling Westward





Home Destination



Continental Connection (Colgan Air) Buffalo NY (February 12, 2009)



• 50 fatalities; commuting, acute sleep loss NTSB



Crew Fatigue Factors

- Captain
 - acute sleep loss (lounge, interrupted)
 - cumulative sleep debt (6 12 hrs)
 - awake at least 15 hrs
 - landing at normal bedtime
- First Officer
 - commuted overnight from Seattle
 - 8.5 hrs sleep in previous 34 hrs (in-flight, crew room)







Geographic Distribution of Colgan Air Pilots Based at Newark, New Jersey

137 EWR pilots: 93 (68%) commuted

Less than 100 miles: 45 Connecticut, New Jersey, New York, Pennsylvania

100 to 199: 13 Maryland, Massachusetts, New York, Pennsylvania, Rhode Island

200 to 399: 29 Maine, Massachusetts, New Hampshire, New York, North Carolina, Pennsylvania, Virginia

400 to 999: 20 Florida, Georgia, Illinois, Iowa, Michigan, Ohio, SouthCarolina, Tennessee, West Virginia

1,000 or more: 29 California, Colorado, Florida, Louisiana, Minnesota, Nevada, Texas, Utah, Washington



NTSB Findings

- 24. The pilots' performance was likely impaired because of fatigue, but the extent of their impairment and the degree to which it contributed to the performance deficiencies that occurred during the flight cannot be conclusively determined.
- 25. All pilots, including those who commute to their home base of operations, have a personal responsibility to wisely manage their off-duty time and effectively use available rest periods so that they can arrive for work fit for duty; the accident pilots did not do so by using an inappropriate facility during their last rest period before the accident flight.
- 26. Colgan Air did not proactively address the pilot fatigue hazards associated with operations at a predominantly commuter base.
- 27. Operators have a responsibility to identify risks associated with commuting, implement strategies to mitigate these risks, and ensure that their commuting pilots are fit for duty.



NTSB Recommendation

Require all 14 Code of Federal Regulations Part 121, 135, and 91K operators to address fatigue risks associated with commuting, including identifying pilots who commute, establishing policy and guidance to mitigate fatigue risks for commuting pilots, using scheduling practices to minimize opportunities for fatigue in commuting pilots, and developing or identifying rest facilities for commuting pilots. (A-10-16)



Commuting Considerations

- Complexity
 - fatigue science/physiology/individuals
 - operational demand/experience/history
 - mutual benefits/shared responsibility
 - economics
 - lifestyle
- Definition?
- Scheduling
 - W coast crew commuting for E coast flying



Commuting Considerations

- Science
 - data available/needs
 - methodologies
 - peer review process
- Fitness for Duty
- Regulatory vs advisory approach
- Prevent recurrence?





NTSB