

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 33

National Average: 56

2x National Average: 112

National Median: 25

Average for Selected Dockets: 33

---

**Facility Name: San Onofre 2 Docket (050- 00361)**

Details	Department	Work Type	Docket/Report
<b>Human-System Interface &amp; Environmnt / IR</b>			
170 - HSI or information availability / quality LTA	Z - Other / Unknown	Z - Other / Unknown	050-00361/2005-004
<b>Number of Items for this Docket: 1</b>			
<b>Percent of Total for this Docket: 3</b>			
<hr/>			
<b>Procedures &amp; Reference Document / IR</b>			
111 - Procedure / reference document technical content	I - Instrumentation & Control	S - Surveillance	050-00361/2005-004
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00361/2005-002
<b>Number of Items for this Docket: 2</b>			
<b>Percent of Total for this Docket: 6</b>			
<hr/>			
<b>Problem Identification &amp; Resolution / IR</b>			
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00361/2005-003
144 - Audit / self-assessment / effectiveness review LTA	E - Electrical	T - Testing	050-00361/2004-005
144 - Audit / self-assessment / effectiveness review LTA	G - Engineering	G - Design	050-00361/2005-004
144 - Audit / self-assessment / effectiveness review LTA	M - Mechanical	M - Maintenance / Repair	050-00361/2005-004
144 - Audit / self-assessment / effectiveness review LTA	O - Operations	O - Control Room Ops	050-00361/2005-002
147 - Individual corrective action LTA	M - Mechanical	M - Maintenance / Repair	050-00361/2005-002
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00361/2005-002
149 - No action planned	G - Engineering	G - Design	050-00361/2005-004
149 - No action planned	I - Instrumentation & Control	S - Surveillance	050-00361/2005-004
149 - No action planned	M - Mechanical	M - Maintenance / Repair	050-00361/2005-004
150 - Programmatic deficiency	B - Management	O - Control Room Ops	050-00361/2005-002
<b>Number of Items for this Docket: 11</b>			
<b>Percent of Total for this Docket: 33</b>			
<hr/>			
<b>Training / IR</b>			
102 - Individual knowledge LTA	F - Fuel Handling	R - Refueling	050-00361/2005-004
<b>Number of Items for this Docket: 1</b>			
<b>Percent of Total for this Docket: 3</b>			
<hr/>			
<b>Work Planning &amp; Practices / IR</b>			
182 - Work package quality LTA	F - Fuel Handling	R - Refueling	050-00361/2005-004
188 - Work practice or craft skill LTA	F - Fuel Handling	R - Refueling	050-00361/2005-004
188 - Work practice or craft skill LTA	G - Engineering	G - Design	050-00361/2005-004
188 - Work practice or craft skill LTA	I - Instrumentation & Control	S - Surveillance	050-00361/2005-004
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00361/2005-002

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 33

National Average: 56

2x National Average: 112

National Median: 25

Average for Selected Dockets: 33

---

**Facility Name: San Onofre 2 Docket (050- 00361)**

Details	Department	Work Type	Docket/Report
<b>Work Planning &amp; Practices / IR</b>			
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00361/2005-004
188 - Work practice or craft skill LTA	O - Operations	O - Control Room Ops	050-00361/2005-003
188 - Work practice or craft skill LTA	Z - Other / Unknown	S - Surveillance	050-00361/2005-004
188 - Work practice or craft skill LTA	Z - Other / Unknown	V - Troubleshooting	050-00361/2005-004
188 - Work practice or craft skill LTA	Z - Other / Unknown	Z - Other / Unknown	050-00361/2005-004
190 - Failure to stop work / non-conservative decision making	G - Engineering	G - Design	050-00361/2005-004
190 - Failure to stop work / non-conservative decision making	M - Mechanical	M - Maintenance / Repair	050-00361/2005-003
190 - Failure to stop work / non-conservative decision making	M - Mechanical	M - Maintenance / Repair	050-00361/2005-004
190 - Failure to stop work / non-conservative decision making	M - Mechanical	T - Testing	050-00361/2005-002
191 - Team interactions LTA	O - Operations	B - Bal of Plant Ops	050-00361/2005-003
191 - Team interactions LTA	O - Operations	O - Control Room Ops	050-00361/2005-003
198 - Worker distracted / interrupted	M - Mechanical	M - Maintenance / Repair	050-00361/2005-003
198 - Worker distracted / interrupted	O - Operations	O - Control Room Ops	050-00361/2005-002

**Number of Items for this Docket:** 18**Percent of Total for this Docket:** 55

---

**Total Items for this Docket:** 33
 

---