

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 39

National Average: 56

2x National Average: 112

National Median: 25

Average for Selected Dockets: 39

Facility Name: South Texas 1 Docket (050- 00498)

Details	Department	Work Type	Docket/Report
Communication / IR			
160 - No communication / information not communicated	H - Health Physics	H - Health Physics	050-00498/2005-002
160 - No communication / information not communicated	M - Mechanical	H - Health Physics	050-00498/2005-002
160 - No communication / information not communicated	O - Operations	G - Design	050-00498/2005-002
160 - No communication / information not communicated	O - Operations	G - Design	050-00498/2005-002
Number of Items for this Docket: 4			
Percent of Total for this Docket: 10			
<hr/>			
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00498/2005-003
173 - Physical conditions LTA	H - Health Physics	H - Health Physics	050-00498/2005-002
173 - Physical conditions LTA	H - Health Physics	H - Health Physics	050-00498/2005-002
Number of Items for this Docket: 3			
Percent of Total for this Docket: 8			
<hr/>			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	G - Engineering	S - Surveillance	050-00498/2005-003
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00498/2005-003
111 - Procedure / reference document technical content	P - Procedure Writers	P - Procedure Dev	050-00498/2004-011
Number of Items for this Docket: 3			
Percent of Total for this Docket: 8			
<hr/>			
Problem Identification & Resolution / IR			
142 - Operating experience (OE) review LTA	G - Engineering	O - Control Room Ops	050-00498/2005-002
144 - Audit / self-assessment / effectiveness review LTA	O - Operations	O - Control Room Ops	050-00498/2005-002
145 - Causal development LTA	G - Engineering	M - Maintenance / Repair	050-00498/2004-011
147 - Individual corrective action LTA	H - Health Physics	H - Health Physics	050-00498/2004-011
148 - Action not yet started or untimely	E - Electrical	M - Maintenance / Repair	050-00498/2004-011
148 - Action not yet started or untimely	E - Electrical	M - Maintenance / Repair	050-00498/2004-011
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00498/2005-004
148 - Action not yet started or untimely	O - Operations	O - Control Room Ops	050-00498/2005-002
148 - Action not yet started or untimely	O - Operations	O - Control Room Ops	050-00498/2005-002
150 - Programmatic deficiency	G - Engineering	M - Maintenance / Repair	050-00498/2004-011
150 - Programmatic deficiency	G - Engineering	V - Troubleshooting	050-00498/2004-011

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 39

National Average: 56

2x National Average: 112

National Median: 25

Average for Selected Dockets: 39

Facility Name: South Texas 1 Docket (050- 00498)

Details	Department	Work Type	Docket/Report
Problem Identification & Resolution / IR			
150 - Programmatic deficiency	M - Mechanical	M - Maintenance / Repair	050-00498/2005-002
Number of Items for this Docket: 12			
Percent of Total for this Docket: 31			
<hr/>			
Training / IR			
100 - Training LTA	O - Operations	O - Control Room Ops	050-00498/2005-006
Number of Items for this Docket: 1			
Percent of Total for this Docket: 3			
<hr/>			
Work Planning & Practices / IR			
188 - Work practice or craft skill LTA	A - Administrative Support	A - Administrative	050-00498/2005-003
188 - Work practice or craft skill LTA	G - Engineering	G - Design	050-00498/2005-002
188 - Work practice or craft skill LTA	H - Health Physics	H - Health Physics	050-00498/2005-002
188 - Work practice or craft skill LTA	H - Health Physics	H - Health Physics	050-00498/2005-002
188 - Work practice or craft skill LTA	H - Health Physics	H - Health Physics	050-00498/2005-002
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00498/2004-005
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00498/2005-003
188 - Work practice or craft skill LTA	O - Operations	O - Control Room Ops	050-00498/2005-002
190 - Failure to stop work / non-conservative decision making	G - Engineering	G - Design	050-00498/2005-002
190 - Failure to stop work / non-conservative decision making	O - Operations	O - Control Room Ops	050-00498/2004-011
190 - Failure to stop work / non-conservative decision making	O - Operations	O - Control Room Ops	050-00498/2005-006
190 - Failure to stop work / non-conservative decision making	O - Operations	Q - Fire Protection	050-00498/2005-006
195 - Logkeeping or log review LTA	M - Mechanical	M - Maintenance / Repair	050-00498/2005-003
198 - Worker distracted / interrupted	O - Operations	O - Control Room Ops	050-00498/2005-003
198 - Worker distracted / interrupted	Z - Other / Unknown	H - Health Physics	050-00498/2004-011
198 - Worker distracted / interrupted	Z - Other / Unknown	H - Health Physics	050-00498/2004-011
Number of Items for this Docket: 16			
Percent of Total for this Docket: 41			
<hr/>			
Total Items for this Docket: 39			
