

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 19

National Average: 41

2x National Average: 82

National Median: 24

Average for Selected Dockets: 19

---

**Facility Name: Turkey Point 4 Docket (050- 00251)**

Details	Department	Work Type	Docket/Report
<b>Communication / IR</b>			
162 - Communication Equipment LTA	F - Fuel Handling	R - Refueling	050-00251/2006-005
162 - Communication Equipment LTA	O - Operations	O - Control Room Ops	050-00251/2006-005
162 - Communication Equipment LTA	O - Operations	S - Surveillance	050-00251/2007-004
<b>Number of Items for this Docket:</b> 3			
<b>Percent of Total for this Docket:</b> 16			
<b>Problem Identification &amp; Resolution / IR</b>			
140 - Problem not completely or accurately identified	G - Engineering	S - Surveillance	050-00251/2006-005
140 - Problem not completely or accurately identified	O - Operations	S - Surveillance	050-00251/2007-004
142 - Operating experience (OE) review LTA	G - Engineering	S - Surveillance	050-00251/2006-005
146 - Evaluation LTA	G - Engineering	S - Surveillance	050-00251/2006-005
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00251/2006-005
148 - Action not yet started or untimely	O - Operations	S - Surveillance	050-00251/2007-004
<b>Number of Items for this Docket:</b> 6			
<b>Percent of Total for this Docket:</b> 32			
<b>Work Planning &amp; Practices / IR</b>			
185 - Procedural adherence LTA	F - Fuel Handling	R - Refueling	050-00251/2006-005
185 - Procedural adherence LTA	F - Fuel Handling	R - Refueling	050-00251/2006-005
185 - Procedural adherence LTA	M - Mechanical	T - Testing	050-00251/2007-004
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00251/2007-006
186 - Failure to take action / meet requirements	M - Mechanical	T - Testing	050-00251/2007-004
186 - Failure to take action / meet requirements	Q - Quality assurance / oversight	A - Administrative	050-00251/2007-004
186 - Failure to take action / meet requirements	Y - Shipping / transportation	Y - Shipping / transportatic	050-00251/2007-004
187 - Action implementation LTA	G - Engineering	Q - Fire Protection	050-00251/2007-006
196 - Independent verification / plant tours LTA	M - Mechanical	M - Maintenance / Repair	050-00251/2006-005
197 - Self-check LTA	Y - Shipping / transportation	Y - Shipping / transportatic	050-00251/2007-004
<b>Number of Items for this Docket:</b> 10			
<b>Percent of Total for this Docket:</b> 53			
<b>Total Items for this Docket: 19</b>			

---