

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

**Total Number of Hits: 3662**  
**National Average: 35**  
**2x National Average: 70**  
**National Median: 21**  
**Average for Selected Dockets: 35**

---

**Facility Name: Browns Ferry 1 Docket (050- 00259)**

<b>Details</b>	<b>Department</b>	<b>Work Type</b>	<b>Docket/Report</b>
<b>Communication / IR</b>			
160 - No communication / information not communicated	H - Health Physics	O - Control Room Ops	050-00259/2008-003
160 - No communication / information not communicated	O - Operations	H - Health Physics	050-00259/2008-003
<b>Number of Items for this Docket: 2</b>			
<b>Percent of Total for this Docket: 9</b>			
<hr/>			
<b>Human-System Interface &amp; Environmnt / IR</b>			
173 - Physical conditions LTA	H - Health Physics	H - Health Physics	050-00259/2008-003
<b>Number of Items for this Docket: 1</b>			
<b>Percent of Total for this Docket: 4</b>			
<hr/>			
<b>Oversight / IR</b>			
131 - Management expectations or directions LTA	G - Engineering	G - Design	050-00259/2008-003
<b>Number of Items for this Docket: 1</b>			
<b>Percent of Total for this Docket: 4</b>			
<hr/>			
<b>Problem Identification &amp; Resolution / IR</b>			
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00259/2007-007
143 - Tracking / trending LTA	X - Site-wide	X - Site-wide	050-00259/2008-003
143 - Tracking / trending LTA	X - Site-wide	X - Site-wide	050-00259/2008-003
146 - Evaluation LTA	G - Engineering	G - Design	050-00259/2007-007
146 - Evaluation LTA	G - Engineering	H - Health Physics	050-00259/2008-003
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00259/2007-007
147 - Individual corrective action LTA	M - Mechanical	M - Maintenance / Repair	050-00259/2007-007
<b>Number of Items for this Docket: 7</b>			
<b>Percent of Total for this Docket: 30</b>			
<hr/>			
<b>Work Planning &amp; Practices / IR</b>			
185 - Procedural adherence LTA	G - Engineering	G - Design	050-00259/2007-007
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00259/2008-003
186 - Failure to take action / meet requirements	G - Engineering	G - Design	050-00259/2007-007
186 - Failure to take action / meet requirements	H - Health Physics	H - Health Physics	050-00259/2008-003
186 - Failure to take action / meet requirements	H - Health Physics	H - Health Physics	050-00259/2008-003
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00259/2008-003
187 - Action implementation LTA	G - Engineering	G - Design	050-00259/2007-007
188 - Work practice or craft skill LTA	H - Health Physics	H - Health Physics	050-00259/2008-003
189 - Recognition of adverse condition / questioning attitude LTA	H - Health Physics	H - Health Physics	050-00259/2008-003

U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report

Total Number of Hits: 3662  
National Average: 35  
2x National Average: 70  
National Median: 21  
Average for Selected Dockets: 35

---

Facility Name: Browns Ferry 1 Docket (050- 00259)

Details	Department	Work Type	Docket/Report
<b>Work Planning &amp; Practices / IR</b>			
191 - Team interactions LTA	H - Health Physics	O - Control Room Ops	050-00259/2008-003
191 - Team interactions LTA	O - Operations	H - Health Physics	050-00259/2008-003
<b>Number of Items for this Docket:</b> 11			
<b>Percent of Total for this Docket:</b> 48			
<b>Problem Identification &amp; Resolution / LER</b>			
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00259/2008-001-00
<b>Number of Items for this Docket:</b> 1			
<b>Percent of Total for this Docket:</b> 4			
<b>Total Items for this Docket:</b> 23			

---