

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: South Texas 2 Docket (050- 00499)

Details	Department	Work Type	Docket/Report
Communication / IR			
160 - No communication / information not communicated	C - Chemistry	Z - Other / Unknown	050-00499/2008-003
160 - No communication / information not communicated	H - Health Physics	H - Health Physics	050-00499/2008-003
160 - No communication / information not communicated	L - Licensing / regulatory affairs	A - Administrative	050-00499/2007-005
160 - No communication / information not communicated	M - Mechanical	M - Maintenance / Repair	050-00499/2008-009
160 - No communication / information not communicated	O - Operations	O - Control Room Ops	050-00499/2007-005
160 - No communication / information not communicated	O - Operations	O - Control Room Ops	050-00499/2008-003
Number of Items for this Docket: 6			
Percent of Total for this Docket: 7			
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	D - Emergency Planning	Q - Fire Protection	050-00499/2008-008
170 - HSI or information availability / quality LTA	D - Emergency Planning	Q - Fire Protection	050-00499/2008-008
Number of Items for this Docket: 2			
Percent of Total for this Docket: 2			
Oversight / IR			
130 - Inadequate suprevison / command and control	F - Fuel Handling	R - Refueling	050-00499/2008-009
130 - Inadequate suprevison / command and control	M - Mechanical	M - Maintenance / Repair	050-00499/2008-009
131 - Management expectations or directions LTA	E - Electrical	M - Maintenance / Repair	050-00499/2008-003
Number of Items for this Docket: 3			
Percent of Total for this Docket: 4			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	E - Electrical	M - Maintenance / Repair	050-00499/2008-009
111 - Procedure / reference document technical content	M - Mechanical	T - Testing	050-00499/2007-005
111 - Procedure / reference document technical content	O - Operations	S - Surveillance	050-00499/2007-007
113 - Procedure / reference document development and maintenance L	I - Instrumentation & Control	S - Surveillance	050-00499/2007-007
Number of Items for this Docket: 4			
Percent of Total for this Docket: 5			
Problem Identification & Resolution / IR			
142 - Operating experience (OE) review LTA	C - Chemistry	M - Maintenance / Repair	050-00499/2007-005
142 - Operating experience (OE) review LTA	D - Emergency Planning	Q - Fire Protection	050-00499/2008-008
142 - Operating experience (OE) review LTA	E - Electrical	T - Testing	050-00499/2007-007
143 - Tracking / trending LTA	D - Emergency Planning	Q - Fire Protection	050-00499/2007-005
143 - Tracking / trending LTA	O - Operations	O - Control Room Ops	050-00499/2008-003

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662

National Average: 35

2x National Average: 70

National Median: 21

Average for Selected Dockets: 35

Facility Name: South Texas 2 Docket (050- 00499)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / IR			
185 - Procedural adherence LTA	I - Instrumentation & Control	S - Surveillance	050-00499/2008-009
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00499/2007-005
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00499/2007-005
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00499/2008-009
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00499/2008-009
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00499/2008-009
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00499/2008-003
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00499/2008-009
185 - Procedural adherence LTA	X - Site-wide	X - Site-wide	050-00499/2008-009
186 - Failure to take action / meet requirements	C - Chemistry	M - Maintenance / Repair	050-00499/2007-005
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00499/2007-005
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00499/2008-008
186 - Failure to take action / meet requirements	D - Emergency Planning	Q - Fire Protection	050-00499/2008-008
186 - Failure to take action / meet requirements	E - Electrical	T - Testing	050-00499/2007-007
186 - Failure to take action / meet requirements	H - Health Physics	H - Health Physics	050-00499/2008-003
186 - Failure to take action / meet requirements	L - Licensing / regulatory affairs	A - Administrative	050-00499/2007-005
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00499/2007-007
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00499/2008-009
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00499/2007-005
186 - Failure to take action / meet requirements	O - Operations	S - Surveillance	050-00499/2007-007
187 - Action implementation LTA	E - Electrical	G - Design	050-00499/2007-007
187 - Action implementation LTA	E - Electrical	G - Design	050-00499/2008-002
187 - Action implementation LTA	G - Engineering	G - Design	050-00499/2007-005
187 - Action implementation LTA	G - Engineering	G - Design	050-00499/2007-007
187 - Action implementation LTA	G - Engineering	G - Design	050-00499/2007-007
187 - Action implementation LTA	G - Engineering	G - Design	050-00499/2007-007
187 - Action implementation LTA	G - Engineering	G - Design	050-00499/2007-007
187 - Action implementation LTA	G - Engineering	S - Surveillance	050-00499/2007-007
187 - Action implementation LTA	I - Instrumentation & Control	T - Testing	050-00499/2007-007
188 - Work practice or craft skill LTA	H - Health Physics	H - Health Physics	050-00499/2008-003
190 - Failure to stop work / non-conservative decision making	G - Engineering	G - Design	050-00499/2007-007
190 - Failure to stop work / non-conservative decision making	G - Engineering	S - Surveillance	050-00499/2007-007

U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: South Texas 2 Docket (050- 00499)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / IR			
191 - Team interactions LTA	C - Chemistry	Z - Other / Unknown	050-00499/2008-003
191 - Team interactions LTA	H - Health Physics	H - Health Physics	050-00499/2008-003
191 - Team interactions LTA	O - Operations	O - Control Room Ops	050-00499/2008-003
197 - Self-check LTA	E - Electrical	S - Surveillance	050-00499/2008-009
197 - Self-check LTA	M - Mechanical	M - Maintenance / Repair	050-00499/2007-005
197 - Self-check LTA	M - Mechanical	M - Maintenance / Repair	050-00499/2008-009
Number of Items for this Docket: 52			
Percent of Total for this Docket: 62			

Total Items for this Docket: 84
