

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: Vermont Yankee Docket (050- 00271)

Details	Department	Work Type	Docket/Report
Communication / IR			
160 - No communication / information not communicated	L - Licensing / regulatory affairs	A - Administrative	050-00271/2008-004
160 - No communication / information not communicated	L - Licensing / regulatory affairs	A - Administrative	050-00271/2008-004
160 - No communication / information not communicated	O - Operations	O - Control Room Ops	050-00271/2008-004
160 - No communication / information not communicated	O - Operations	O - Control Room Ops	050-00271/2008-004
Number of Items for this Docket: 4			
Percent of Total for this Docket: 15			
Fitness for Duty / IR			
128 - Non-compliance	O - Operations	O - Control Room Ops	050-00271/2008-004
128 - Non-compliance	O - Operations	O - Control Room Ops	050-00271/2008-004
Number of Items for this Docket: 2			
Percent of Total for this Docket: 7			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	E - Electrical	M - Maintenance / Repair	050-00271/2008-008
111 - Procedure / reference document technical content	E - Electrical	M - Maintenance / Repair	050-00271/2008-008
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00271/2008-002
113 - Procedure / reference document development and maintenance L	E - Electrical	T - Testing	050-00271/2008-008
113 - Procedure / reference document development and maintenance L	I - Instrumentation & Control	T - Testing	050-00271/2008-008
Number of Items for this Docket: 5			
Percent of Total for this Docket: 19			
Problem Identification & Resolution / IR			
146 - Evaluation LTA	E - Electrical	T - Testing	050-00271/2008-008
148 - Action not yet started or untimely	F - Fuel Handling	R - Refueling	050-00271/2008-003
Number of Items for this Docket: 2			
Percent of Total for this Docket: 7			
Work Planning & Practices / IR			
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00271/2008-002
185 - Procedural adherence LTA	E - Electrical	T - Testing	050-00271/2008-008
186 - Failure to take action / meet requirements	E - Electrical	M - Maintenance / Repair	050-00271/2008-008
186 - Failure to take action / meet requirements	E - Electrical	M - Maintenance / Repair	050-00271/2008-008
186 - Failure to take action / meet requirements	E - Electrical	T - Testing	050-00271/2008-008
186 - Failure to take action / meet requirements	I - Instrumentation & Control	T - Testing	050-00271/2008-008
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00271/2008-004

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662

National Average: 35

2x National Average: 70

National Median: 21

Average for Selected Dockets: 35

Facility Name: Vermont Yankee Docket (050- 00271)

Details	Department	Work Type	Docket/Report
Work Planning & Practices / IR			
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00271/2008-004
187 - Action implementation LTA	E - Electrical	G - Design	050-00271/2008-008
187 - Action implementation LTA	E - Electrical	G - Design	050-00271/2008-008
Number of Items for this Docket: 10			
Percent of Total for this Docket: 37			
<hr/>			
Procedures & Reference Document / LER			
111 - Procedure / reference document technical content	F - Fuel Handling	R - Refueling	050-00271/2008-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			
<hr/>			
Training / LER			
100 - Training LTA	F - Fuel Handling	R - Refueling	050-00271/2008-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			
<hr/>			
Work Planning & Practices / LER			
185 - Procedural adherence LTA	F - Fuel Handling	R - Refueling	050-00271/2008-001-00
189 - Recognition of adverse condition / questioning attitude LTA	F - Fuel Handling	R - Refueling	050-00271/2008-001-00
Number of Items for this Docket: 2			
Percent of Total for this Docket: 7			
<hr/>			
Total Items for this Docket: 27			
