



**FAA
Airports**

Errata Sheet for Advisory Circular 150/5220-9A, Aircraft Arresting Systems on Civil Airports

Last Update: 8/16/2012

This errata sheet logs content and/or coding errors identified after the AC was signed on December 20, 2006. These errors have been corrected in the PDF version of the AC available on the FAA website.

#	Description of Correction	Location in Document	Rationale	Date Error Corrected
1	Corrected text referring to the Figure 1 15' dimension.	Page 3	Figure 1 dimension is correct, but the text was incorrect.	8/16/12