

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 32

National Average: 56

2x National Average: 112

National Median: 25

Average for Selected Dockets: 32

---

**Facility Name: Peach Bottom 3 Docket (050- 00278)**

Details	Department	Work Type	Docket/Report
<b>Oversight / IR</b>			
130 - Inadequate supervision / command and control	I - Instrumentation & Control	M - Maintenance / Repair	050-00278/2005-004
130 - Inadequate supervision / command and control	O - Operations	O - Control Room Ops	050-00278/2005-006
131 - Management expectations or directions LTA	B - Management	Z - Other / Unknown	050-00278/2004-005
<b>Number of Items for this Docket: 3</b>			
<b>Percent of Total for this Docket: 9</b>			
<hr/>			
<b>Procedures &amp; Reference Document / IR</b>			
112 - Procedure / reference document contains human factors deficienc	Z - Other / Unknown	Z - Other / Unknown	050-00278/2005-004
113 - Procedure / reference document development and maintenance L	M - Mechanical	M - Maintenance / Repair	050-00278/2005-006
<b>Number of Items for this Docket: 2</b>			
<b>Percent of Total for this Docket: 6</b>			
<hr/>			
<b>Problem Identification &amp; Resolution / IR</b>			
142 - Operating experience (OE) review LTA	G - Engineering	G - Design	050-00278/2005-003
144 - Audit / self-assessment / effectiveness review LTA	B - Management	O - Control Room Ops	050-00278/2005-002
145 - Causal development LTA	O - Operations	O - Control Room Ops	050-00278/2005-006
147 - Individual corrective action LTA	G - Engineering	G - Design	050-00278/2004-005
148 - Action not yet started or untimely	G - Engineering	G - Design	050-00278/2005-006
148 - Action not yet started or untimely	G - Engineering	Z - Other / Unknown	050-00278/2005-004
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00278/2005-006
150 - Programmatic deficiency	B - Management	Z - Other / Unknown	050-00278/2004-005
<b>Number of Items for this Docket: 8</b>			
<b>Percent of Total for this Docket: 25</b>			
<hr/>			
<b>Work Planning &amp; Practices / IR</b>			
181 - Inadequate staffing / task allocation	I - Instrumentation & Control	M - Maintenance / Repair	050-00278/2005-004
188 - Work practice or craft skill LTA	H - Health Physics	H - Health Physics	050-00278/2005-004
188 - Work practice or craft skill LTA	I - Instrumentation & Control	M - Maintenance / Repair	050-00278/2004-005
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00278/2005-002
188 - Work practice or craft skill LTA	O - Operations	O - Control Room Ops	050-00278/2005-004
188 - Work practice or craft skill LTA	O - Operations	O - Control Room Ops	050-00278/2005-006
190 - Failure to stop work / non-conservative decision making	A - Administrative Support	A - Administrative	050-00278/2005-002
190 - Failure to stop work / non-conservative decision making	A - Administrative Support	G - Design	050-00278/2005-002
190 - Failure to stop work / non-conservative decision making	G - Engineering	G - Design	050-00278/2005-003
190 - Failure to stop work / non-conservative decision making	O - Operations	O - Control Room Ops	050-00278/2005-006

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 32

National Average: 56

2x National Average: 112

National Median: 25

Average for Selected Dockets: 32

---

**Facility Name: Peach Bottom 3 Docket (050- 00278)**

Details	Department	Work Type	Docket/Report
<b>Work Planning &amp; Practices / IR</b>			
196 - Independent verification / plant tours LTA	O - Operations	O - Control Room Ops	050-00278/2005-006
196 - Independent verification / plant tours LTA	Q - Quality assurance / oversight	Z - Other / Unknown	050-00278/2005-003
198 - Worker distracted / interrupted	I - Instrumentation & Control	M - Maintenance / Repair	050-00278/2004-005
198 - Worker distracted / interrupted	M - Mechanical	M - Maintenance / Repair	050-00278/2004-005
198 - Worker distracted / interrupted	M - Mechanical	M - Maintenance / Repair	050-00278/2004-005
<b>Number of Items for this Docket:</b> 15			
<b>Percent of Total for this Docket:</b> 47			
<hr/>			
<b>Procedures &amp; Reference Document / LER</b>			
111 - Procedure / reference document technical content	I - Instrumentation & Control	M - Maintenance / Repair	050-00278/2005-002-00
111 - Procedure / reference document technical content	M - Mechanical	T - Testing	050-00278/2005-003-00
<b>Number of Items for this Docket:</b> 2			
<b>Percent of Total for this Docket:</b> 6			
<hr/>			
<b>Work Planning &amp; Practices / LER</b>			
188 - Work practice or craft skill LTA	Z - Other / Unknown	F - Modification	050-00278/2005-001-00
190 - Failure to stop work / non-conservative decision making	G - Engineering	F - Modification	050-00278/2005-002-00
<b>Number of Items for this Docket:</b> 2			
<b>Percent of Total for this Docket:</b> 6			
<hr/>			
<b>Total Items for this Docket:</b> 32			

---