

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 26

National Average: 43

2x National Average: 86

National Median: 21

Average for Selected Dockets: 26

---

**Facility Name: Robinson 2 Docket (050- 00261)**

Details	Department	Work Type	Docket/Report
<b>Management and Supervision / IR</b>			
40 - Individual Corrective Action LTA	E - Electrical	M - Maint / Repair	050-00261/2004-007
40 - Individual Corrective Action LTA	E - Electrical	M - Maint / Repair	050-00261/2004-007
40 - Individual Corrective Action LTA	E - Electrical	M - Maint / Repair	050-00261/2004-007
40 - Individual Corrective Action LTA	M - Mechanical	M - Maint / Repair	050-00261/2004-007
40 - Individual Corrective Action LTA	O - Operations	Q - Fire Protection	050-00261/2004-006
40 - Individual Corrective Action LTA	P - Procedure Writers	P - Procedure Dev	050-00261/2004-007
40 - Individual Corrective Action LTA	W - Work Control / Scheduling Outage Pla	M - Maint / Repair	050-00261/2004-007
40 - Individual Corrective Action LTA	Z - Other	M - Maint / Repair	050-00261/2004-007
47 - Root Cause LTA	G - Engineering	M - Maint / Repair	050-00261/2004-002
47 - Root Cause LTA	G - Engineering	Q - Fire Protection	050-00261/2004-006
47 - Root Cause LTA	G - Engineering	V - Troubleshooting	050-00261/2004-007
47 - Root Cause LTA	G - Engineering	V - Troubleshooting	050-00261/2004-007
47 - Root Cause LTA	U - Unknown	V - Troubleshooting	050-00261/2004-007
48 - Audits or problem identification LTA	G - Engineering	M - Maint / Repair	050-00261/2004-007
<b>Number of Items for this Docket:</b> 14			
<b>Percent of Total for this Docket:</b> 54			
<b>Organizational Issues / IR</b>			
21 - Staffing LTA	D - Emergency Planning	D - Emergency Drill	050-00261/2003-006
21 - Staffing LTA	D - Emergency Planning	D - Emergency Drill	050-00261/2003-006
<b>Number of Items for this Docket:</b> 2			
<b>Percent of Total for this Docket:</b> 8			
<b>Procedures and Reference Document / IR</b>			
11 - No procedure / reference documents	Z - Other	M - Maint / Repair	050-00261/2004-007
12 - Procedure technical content LTA	P - Procedure Writers	Q - Fire Protection	050-00261/2004-006
12 - Procedure technical content LTA	P - Procedure Writers	Q - Fire Protection	050-00261/2004-006
<b>Number of Items for this Docket:</b> 3			
<b>Percent of Total for this Docket:</b> 12			
<b>Work Factors / IR</b>			
83 - Work practice or craft skill LTA	H - Health Physics	H - Health Physics	050-00261/2004-003
84 - Non-conserv. decision / Questioning LTA	D - Emergency Planning	F - Modification	050-00261/2003-006
84 - Non-conserv. decision / Questioning LTA	G - Engineering	V - Troubleshooting	050-00261/2004-007
89 - Housekeeping LTA	Z - Other	M - Maint / Repair	050-00261/2004-007

**U.S. Nuclear Regulatory Commission  
Human Factors Information System (HFIS)  
IR/LER Category Analysis by Docket Report**

**Total Number of Hits: 26**  
**National Average: 43**  
**2x National Average: 86**  
**National Median: 21**  
**Average for Selected Dockets: 26**

---

**Facility Name: Robinson 2 Docket (050- 00261)**

<b>Details</b>	<b>Department</b>	<b>Work Type</b>	<b>Docket/Report</b>
<b>Work Factors / IR</b>			
91 - Verification / plant tours LTA	O - Operations	Q - Fire Protection	050-00261/2004-006
94 - Log-keeping or review LTA	G - Engineering	V - Troubleshooting	050-00261/2004-003
<b>Number of Items for this Docket: 6</b>			
<b>Percent of Total for this Docket: 23</b>			
<b>Procedures and Reference Document / LER</b>			
12 - Procedure technical content LTA	O - Operations	O - Control Room Ops	050-00261/2004-002-00
<b>Number of Items for this Docket: 1</b>			
<b>Percent of Total for this Docket: 4</b>			
<b>Total Items for this Docket: 26</b>			

---