

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662

National Average: 35

2x National Average: 70

National Median: 21

Average for Selected Dockets: 35

Facility Name: Beaver Valley 2 Docket (050- 00412)

Details	Department	Work Type	Docket/Report
Communication / IR			
161 - Communication LTA	O - Operations	O - Control Room Ops	050-00412/2008-003
Number of Items for this Docket: 1			
Percent of Total for this Docket: 2			
Fitness for Duty / IR			
128 - Non-compliance	O - Operations	O - Control Room Ops	050-00412/2008-004
128 - Non-compliance	O - Operations	O - Control Room Ops	050-00412/2008-004
Number of Items for this Docket: 2			
Percent of Total for this Docket: 5			
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	I - Instrumentation & Control	T - Testing	050-00412/2008-002
Number of Items for this Docket: 1			
Percent of Total for this Docket: 2			
Oversight / IR			
130 - Inadequate suprevison / command and control	O - Operations	O - Control Room Ops	050-00412/2008-003
131 - Management expectations or directions LTA	O - Operations	O - Control Room Ops	050-00412/2008-003
Number of Items for this Docket: 2			
Percent of Total for this Docket: 5			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	E - Electrical	M - Maintenance / Repair	050-00412/2008-004
111 - Procedure / reference document technical content	G - Engineering	G - Design	050-00412/2007-005
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00412/2008-003
111 - Procedure / reference document technical content	O - Operations	S - Surveillance	050-00412/2007-005
Number of Items for this Docket: 4			
Percent of Total for this Docket: 10			
Problem Identification & Resolution / IR			
141 - Problem not properly classified or prioritized	M - Mechanical	M - Maintenance / Repair	050-00412/2008-008
146 - Evaluation LTA	G - Engineering	G - Design	050-00412/2007-005
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00412/2008-008
147 - Individual corrective action LTA	M - Mechanical	M - Maintenance / Repair	050-00412/2007-005
148 - Action not yet started or untimely	E - Electrical	M - Maintenance / Repair	050-00412/2007-005
149 - No action planned	M - Mechanical	M - Maintenance / Repair	050-00412/2008-008

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662

National Average: 35

2x National Average: 70

National Median: 21

Average for Selected Dockets: 35

Facility Name: Beaver Valley 2 Docket (050- 00412)

Details	Department	Work Type	Docket/Report
Problem Identification & Resolution / IR			
150 - Programmatic deficiency	M - Mechanical	M - Maintenance / Repair	050-00412/2008-008
Number of Items for this Docket: 7			
Percent of Total for this Docket: 17			
<hr/>			
Work Planning & Practices / IR			
183 - Pre-job activities LTA	O - Operations	O - Control Room Ops	050-00412/2008-003
184 - Tag outs LTA	E - Electrical	M - Maintenance / Repair	050-00412/2008-004
185 - Procedural adherence LTA	E - Electrical	M - Maintenance / Repair	050-00412/2007-005
185 - Procedural adherence LTA	E - Electrical	M - Maintenance / Repair	050-00412/2008-004
185 - Procedural adherence LTA	I - Instrumentation & Control	T - Testing	050-00412/2008-002
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00412/2008-003
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00412/2008-003
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00412/2008-003
185 - Procedural adherence LTA	O - Operations	O - Control Room Ops	050-00412/2008-004
186 - Failure to take action / meet requirements	E - Electrical	M - Maintenance / Repair	050-00412/2007-005
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00412/2007-005
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00412/2008-003
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00412/2008-003
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00412/2008-003
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00412/2008-004
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00412/2008-004
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00412/2008-004
187 - Action implementation LTA	G - Engineering	G - Design	050-00412/2007-005
190 - Failure to stop work / non-conservative decision making	G - Engineering	G - Design	050-00412/2007-005
191 - Team interactions LTA	M - Mechanical	M - Maintenance / Repair	050-00412/2008-003
191 - Team interactions LTA	O - Operations	O - Control Room Ops	050-00412/2008-003
197 - Self-check LTA	I - Instrumentation & Control	T - Testing	050-00412/2008-002
Number of Items for this Docket: 21			
Percent of Total for this Docket: 50			
<hr/>			
Oversight / LER			
130 - Inadequate supervision / command and control	O - Operations	O - Control Room Ops	050-00412/2008-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 2			

U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: Beaver Valley 2 Docket (050- 00412)

Details	Department	Work Type	Docket/Report
Training / LER			
101 - Training process problem	O - Operations	O - Control Room Ops	050-00412/2008-001-00
103 - Simulator training LTA	O - Operations	O - Control Room Ops	050-00412/2008-001-00
Number of Items for this Docket: 2			
Percent of Total for this Docket: 5			
<hr/>			
Work Planning & Practices / LER			
183 - Pre-job activities LTA	O - Operations	O - Control Room Ops	050-00412/2008-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 2			
<hr/>			
Total Items for this Docket: 42			
