



APPENDIX F

Voluntary Corrective Action Plans and Product Recalls

VOLUNTARY CORRECTIVE ACTION PLANS AND PRODUCT RECALLS

Voluntary Corrective Action Plans and Recall of Products Subject to Product Safety Standards and Other Specific Regulations Exclusive of Section 15 of the Consumer Product Safety Act

The Directorate for Compliance and Administrative Litigation and the Regional Offices are jointly responsible for identification of consumer products which fail to comply with a specific product safety standard or other Commission product-related requirements mandated by statute or regulation. Commission staff works cooperatively with the responsible firms to obtain voluntary corrective action plans as appropriate to protect the public. Following is a list of these product recalls and corrective action plans monitored by the Commission staff during fiscal year 1990.

Consumers may find products on the market which resemble those appearing on this list. After manufacturers and importers correct violations, they may distribute complying versions of products which were recalled. CPSC monitors recalls to ensure that the noncomplying products have been removed from the market. It is unfair to responsible manufacturers and importers to conclude that toys and children's products on the list are still offered for sale.

Date	Product	Model	Violation	
10/89	Ghost Blaster		Banned	Small Parts
10/89	Wooden Shaky Head Rattle	#453105	Banned	Rattle
10/89	CB Antenna	Rocket - #CGP 1011S	Misbranded Labeling	
10/89	Pegs of Fun	#2423	Banned	Small Parts
10/89	Crib Pals Rattle	#SKN15-7198	Banned	Rattle
10/89	Siren Whistles	#SKN 08-1825 & 18-5892	Banned	Small Parts
10/89	Wooden Rocking Horse	#G-30	Banned	Small Parts
10/89	Charcoal Lighter Fluid		Misbranded	Hazardous Substance
10/89	Play-Learn Furn. Set	Bathroom Style #1411	Banned	Small Parts
11/89	Tambourine	#8152PT	Banned	Small Parts
11/89	Siren Whistle	#8631	Banned	Small Parts
11/89	1 Speed Strida Bicycle	#CSD600	Banned	Fails Standard
11/89	Sidewalk Bicycles	#121 & 124	Banned	Fails Standard
11/89	Slinky Toy	#440 Frog	Banned	Lead-in-Paint
	Slinky Toy	#200 Train	Banned	Lead-in-Paint
	Slinky Toy	#250 Worm	Banned	Lead-in-Paint
	Slinky Toy	#425 Seal	Banned	Lead-in-Paint
	Slinky Toy	#480 Kitten	Banned	Lead-in-Paint
11/89	Siren Whistle	#8748	Banned	Small Parts
11/89	16" Pixie Bicycles	#3425020	Banned	Fails Standard
11/89	Full Sized Cherry Crib	Jefferson Model #84202	Banned	Slat Spacing
	Full Sized White Crib	Jefferson Model #84205	Banned	Slat Spacing

FHSA - Federal Hazardous Substances Act
CFR - Code of Federal Regulations

Citation	Action	Manufacturer/Importer	City & State	Zip
16 CFR 1501	Recall	Hardee's Food System	Rocky Mount, NC	27802
16 CFR 1510	Recall	Toys "R" Us	Paramus, NJ	07652
16 CFR 1204 & 16 CFR 1402	Recall	TelRex Labs, Inc	Asbury Park, NJ	07712
16 CFR 1501	Recall	Toywrights, Ltd.	Hamden, CT	06517
16 CFR 1510	Recall	Toys "R" Us	Paramus, NJ	07652
16 CFR 1501	Recall	Toys "R" Us	Paramus, NJ	07652
16 CFR 1501	Recall	Cardinal Industries, Inc	Long Island City, NY	11101
FHSA - Sec. 2(p)(1)	Recall	The Lewis Bear Co.	Pensacola, FL	32522
16 CFR 1501	Recall	JA-RU, Inc	Jacksonville, FL	32207
16 CFR 1501	Recall	Dennis Foland, Inc	Campbell, CA	95008
16 CFR 1501	Recall	The Mitchell Import Co.	Lenexa, KS	66214
16 CFR 1512	Recall	Sharper Image	Emoryville, CA	94608
16 CFR 1512	Retrofit	Santa Fe Trading, Inc	Houston, TX	77036
16 CFR 1303 16 CFR 1303 16 CFR 1303 16 CFR 1303 16 CFR 1303	Recall Recall Recall Recall Recall	James Industries, Inc	Hollidaysburg, PA	16648
16 CFR 1501	Recall	Hayes Specialties Corp	Saginaw, MI	48601
16 CFR 1512	Retrofit	Schwinn Bicycle Co.	Chicago, IL	60606
16 CFR 1508 16 CFR 1508	Recall Recall	Spalding & Evenflo Cos.	Tampa, FL	33630

Date	Product	Model	Violation	
11/89	Plush Toy	#55-0079 Pink Bear	Banned	Small Parts
	Plush Toy	#55-5095 Pink Monkey	Banned	Small Parts
	Plush Toy	#55-0046 White Bear	Banned	Small Parts
	Plush Toy	#55-0038 Sm. Beige Bear	Banned	Small Parts
	Plush Toy	#55-0061 Beige Bear	Banned	Small Parts
	Plush Toy	#55-0368 Santa Bear	Banned	Small Parts
12/89	Forest Family	#31457 Crocodile	Banned	Small Parts
	Forest Family	#31458 Bear	Banned	Small Parts
	Forest Family	#31459 Elephant	Banned	Small Parts
	Forest Family	#31460 Gorilla	Banned	Small Parts
12/89	Funny Clown Doll	#619	Banned	Small Parts
12/89	Toy Tin Drum	#SKU100-847	Technical Guideline	Sharp Edges
12/89	Rotating Wood Train	#6947070	Banned	Small Parts
12/89	20" BMX Bicycles	#CI2001 & CI2001G	Banned	Fails Standard
12/89	Spray Paint	Fashion Flair-10 oz.Can	Banned	Lead-in-Paint
12/89	Li'l Baby Gift Set	#6640	Banned	Small Parts
	Melody Clock	#8608	Banned	Small Parts
	Sesame St Old Time Car	#8819	Banned	Small Parts
12/89	Merry Rattle	Item #1/53	Banned	Rattle
12/89	Brass Baby Cribs	#BT-007C & BT-007	Banned	Fails Standard
12/89	Squeaky Jack-in-Box	#2043	Banned	Small Parts
1/90	Little Triplets Doll	#299	Banned	Small Parts
1/90	Dressed Stuffed Monkey	#28750	Banned	Small Parts
1/90	Clacker Balls	#65131	Banned	Mechanical Hazard
1/90	Magnetic Board	#3306	Banned	Small Parts
1/90	In 'N Out School Bus	#8403	Banned	Small Parts
1/90	Pull-A-Long Train	#37599	Banned	Small Parts
1/90	Farm Puzzle	#SX4100	Banned	Small Parts
	Kitchen Puzzle	#SX4103	Banned	Small Parts

Citation	Action	Manufacturer/Importer	City & State	Zip
16 CFR 1501	Recall	San Francisco Music Box	Emoryville, CA	94608
16 CFR 1501	Recall	-		
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall	ABC Distributing, Inc	N. Miami Beach, FL	33181
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall	Oriental Trading Co	Omaha, NE	63137
16 CFR 1500.49	Recall	Pier 1 Imports	Fort Worth, TX	76102
16 CFR 1501	Recall	Self Help Crafts	Akron, PA	17501
16 CFR 1512	Recall	China Import Co.	Chicago, IL	60639
16 CFR 1303	Recall	Plasti-Kote Co., Inc	Medina, OH	44256
16 CFR 1501	Recall	Milton D. Myer	Carnegie, PA	15106
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1510	Recall	Esco Imports, Inc	San Antonio, TX	78219
16 CFR 1509	Recall	Babee Warehouse, Inc	Arlington, TX	76011
16 CFR 1501	Recall	Kay Bee Toy & Hobby Shops	Pittsfield, MA	01201
16 CFR 1501	Recall	Henry Gordy Int'l, Inc	Plainfield, NJ	07061
16 CFR 1501	Recall	Windsor Toys, Inc	Edison, NJ	08817
16 CFR 1500.18	Recall	Division Sales, Inc	Itasca, IL	60143
16 CFR 1501	Recall	Marlon Creations	Long Island City, NY	11106
16 CFR 1501	Recall	Illico Toy Co. USA, Inc	New York, NY	10010
16 CFR 1501	Recall	Consolidated Stores	Columbus, OH	43216
16 CFR 1501	Recall	Battat, Inc	Plattsburgh, NY	12901
16 CFR 1501	Recall			

Date	Product	Model	Violation	
1/90	8 Stuffed Animals	Jake, #7001A-Monkey	Banned	Small Parts
		Al E. Kat, #111-Cat	Banned	Small Parts
		Fritz, #2002-Dog	Banned	Small Parts
		Super Fritz, #9002-Dog	Banned	Small Parts
		Harris, #1115-Lion	Banned	Small Parts
		Patti, #1118-Panther	Banned	Small Parts
		Lovie, #8001-Lamb	Banned	Small Parts
		Petunia, #6001-Pig	Banned	Small Parts
1/90	Mini Skateboard Toy Loco w/Smoke Stack Wind-Up Animals Pull-back Toys	Panda-Monkey-Koala#N332	Banned	Small Parts
		#T255	Banned	Small Parts
		Jumping & Swimming #147	Banned	Small Parts
		Plane-Train-Truck - #76	Banned	Small Parts
1/90	Music Maker Elephant	#29/555	Banned	Small Parts
1/90	Jet Plane	#8883	Banned	Small Parts
1/90	Plastic Racers	#8830	Banned	Small Parts
1/90	Educational Clown	#2514P	Banned	Small Parts
1/90	Piano Phone Cake Organ Burger Organ	#CH888	Banned	Small Parts
		#WA880	Banned	Small Parts
		#98101	Banned	Small Parts
1/90	Alphabet Blocks	#7191	Banned	Small Parts
2/90	Pumper Truck Wrecker Truck Potpourri Baby Doll	My First Buddy - #4505N	Banned	Small Parts
		My First Buddy - #4500N	Banned	Small Parts
		#442	Banned	Small Parts
2/90	Activity Center	#BK-06	Banned	Small Parts
2/90	10 Stuffed Animals With Flowers	Bonny Bunny 15"-HE125GL	Banned	Small Parts
		Bonny Bunny 13"-HE125GM	Banned	Small Parts
		Bonny Bunny 9"-HE125GS	Banned	Small Parts
		Bunny 9.5"-HE128WM	Banned	Small Parts
		Bunny 7.5"-HE128WS	Banned	Small Parts
		Rosemary Bear6"-HV014WA	Banned	Small Parts
		White Bear 6"-PZ0077	Banned	Small Parts
		Blossom Bear 13"-H331GL	Banned	Small Parts
		Blossom Bear 6"-H331GS	Banned	Small Parts
		Wiskers Cat 10"-H317BM	Banned	Small Parts
2/90	Bib to Bowl Pacifiers Bib to Bowl Pacifiers	#1852037	Banned	Pacifier
		#1852045	Banned	Pacifier
2/90	Woodblock Pull Toy	#77791 (WP471)	Banned	Small Parts

Citation	Action	Manufacturer/Importer	City & State	Zip
16 CFR 1501	Recall	Ty, Inc	Oakbrook, IL	60522
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall	Cardinal Teen Toy	N. Miami Beach, FL	33179
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall	Assoc. Merchandising Corp	New York, NY	10017
16 CFR 1501	Recall	Unique Industries, Inc	Philadelphia, PA	19148
16 CFR 1501	Recall	Unique Industries, Inc	Philadelphia, PA	19148
16 CFR 1501	Recall	Wisconsin Toy	New York, NY	10010
16 CFR 1501	Recall	Chingmaw USA Corp	Hoboken, NJ	07030
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall	Int'l Marketing Source	Franklin Park, IL	60131
16 CFR 1501	Recall	Target Stores	Minneapolis, MN	55440
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall	Battat, Inc	Plattsburgh, NY	12901
16 CFR 1501	Recall	Trans Border	Buffalo, NY	14222
16 CFR 1501	Recall	Custom Broker		
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1511	Recall	Consolidated Stores	Columbus, OH	43216
16 CFR 1511	Recall			
16 CFR 1501	Recall	Division Sales, Inc	Itasca, IL	60143

Date	Product	Model	Violation	
2/90	Car-Roll-A-Way	#27342	Banned	Small Parts
2/90	Tots'N Toys in Cradle	#70620	Banned	Small Parts
2/90	Elephant Rattle	#114-53018-121	Banned	Rattle
2/90	Eggscavators Truck Set	#187	Banned	Small Parts
2/90	Activity Blanket	#5019	Banned	Small Parts
2/90	Press-N-Roll Boat	Unimax #2311	Banned	Small Parts
2/90	Ernie the Drummer	Sesame Street #8822	Banned	Small Parts
2/90	Big Bird Trike	Sesame Street #8820R	Banned	Small Parts
2/90	Truck Set	#50006 Asst#51010	Banned	Small Parts
2/90	Lollipop Rattle	#1313	Banned	Rattle
2/90	Lace Dress	Size Small	Banned	Small Parts
2/90	Wind-Up Circus	#9026W	Banned	Small Parts
	Rock N Rolling Band	#9081C	Banned	Small Parts
	Wonderful Plane	#6937	Banned	Small Parts
	Marching Monkey	#6930	Banned	Small Parts
	Baby Rattle	#B400	Banned	Rattle
2/90	Musical Orphan Dolls	#12848 thru #12853	Banned	Small Parts
2/90	Telephone Rattle	#745	Banned	Rattle
3/90	Colored Beads & Laces	#470	Banned	Small Parts
3/90	Refuse Bins		Banned	Unstable Refuse Bin
3/90	Toy Wooden Train	#78000	Banned	Small Parts
3/90	Wooden Goods Train	#27/46	Banned	Small Parts
	Wooden Alphabet Train	#27/58	Banned	Small Parts
3/90	Stuffed Clown Doll	#6159	Banned	Small Parts
	Stuffed Toy Dog		Banned	Small Parts
3/90	Formula Car	#63311	Banned	Small Parts
	Construction Copter	#63214	Banned	Small Parts
	Classic Car	#63312	Banned	Small Parts

Citation	Action	Manufacturer/Importer	City & State	Zip
16 CFR 1501	Recall	Jacobson Stores, Inc	Jackson, MI	49201
16 CFR 1501	Recall	Uneeda Doll Co.	Brooklyn, NY	11232
16 CFR 1510	Recall	N & P Sales	New Castle, DE	19720
16 CFR 1501	Recall	Henry Gordy Int'l, Inc	Plainfield, NJ	07061
16 CFR 1501	Recall	Commonwealth Toy & Novelty	New York, NY	10001
16 CFR 1501	Recall	Toys "R" Us	Paramus, NJ	07652
16 CFR 1501	Recall	Toys "R" Us	Paramus, NJ	07652
16 CFR 1501	Recall	Lionel Leisure, Inc	Philadelphia, PA	19114
16 CFR 1501	Recall	Lionel Leisure, Inc	Philadelphia, PA	19114
16 CFR 1510	Recall	Kids Corporation Int'l	Miami, FL	33176
16 CFR 1501	Recall	Doo Duds, Inc	Miami, FL	33147
16 CFR 1501	Recall	Mar-Ching Export Corp	Hialeah, FL	33014
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1510	Recall			
16 CFR 1501	Recall	ABC Distributing, Inc	N. Miami, FL	33181
16 CFR 1510	Recall	Stahlwood Mfg Co., Inc	Youngsville, NC	27956
16 CFR 1501	Recall	Media Materials, Inc	Baltimore, MD	21224
16 CFR 1301	Retrofit	Badger Disposal Service	Columbus, WI	53925
16 CFR 1501	Recall	Division Sales, Inc	Itasca, IL	60143
16 CFR 1501	Recall	Oriental Trading Co, Inc	Omaha, NE	68137
16 CFR 1501	Recall			
16 CFR 1501	Recall	Amazing Stores	Bloomfield, CT	06002
16 CFR 1501	Recall			
16 CFR 1501	Recall	Nikko America, Inc	Richardson, TX	75081
16 CFR 1501	Recall			
16 CFR 1501	Recall			

Date	Product	Model	Violation	
3/90	Old Time Car	#8819	Banned	Small Parts
3/90	Toy Stuffed Lamb	#99219	Banned	Small Parts
3/90	Super Locomotive	#626	Banned	Small Parts
	Wonderful Plane	#6937	Banned	Small Parts
3/90	Snoopy Wind-Up Train	#711	Banned	Small Parts
3/90	Giraffe	#T88	Banned	Small Parts
	Big Wheel Porter	#T89	Banned	Small Parts
3/90	Public Telephone	#WM3922	Banned	Small Parts
3/90	Happy Flapping Car	#8668, #8228	Banned	Small Parts
	Police Happy Tricycle	#636	Banned	Small Parts
	Cycling Bear	#6968	Banned	Small Parts
	Naughty Bear	#6967	Banned	Small Parts
	Ice Cream Van	#6973	Banned	Small Parts
3/90	Popeye Doll 11"	#P4200	Banned	Small Parts
3/90	Music Box Mobile	#3820B	Banned	Small Parts
3/90	Lovely Dolls	#D13/3	Banned	Small Parts
	Lovely Dolls	#C1372	Banned	Small Parts
3/90	Ring Ring Play Phone	#537/88	Banned	Small Parts
3/90	Magic Sox	#160	Banned	Small Parts
4/90	Riding Rabbit	#966-196	Banned	Small Parts
4/90	Tricky Fun String	#7501	Banned	Flammable Children's Article
4/90	Crawling Critter Toy	#791	Banned	Small Parts
4/90	Stuffed Baby Bear	#3737	Banned	Small Parts
4/90	Precious Playmate Doll	#905588	Banned	Small Parts
4/90	Play N Learn Phone	#31285	Banned	Small Parts
4/90	Lawn Darts	Perry Drug - #65260	Banned	Lawn Darts

Citation	Action	Manufacturer/Importer	City & State	Zip
16 CFR 1501	Recall	Illco Toy Co., Inc	New York, NY	10010
16 CFR 1501	Recall	Roman, Inc	Roselle, IL	60172
16 CFR 1501	Recall	Davis-Grabowski, Inc	Miami, FL	33138
16 CFR 1501	Recall			
16 CFR 1501	Recall	Target Stores	Minneapolis, MN	55440
16 CFR 1501	Recall	TDT Toy Co	Los Angeles, CA	90013
16 CFR 1501	Recall			
16 CFR 1501	Recall	Goldwell International	Los Angeles, CA	90021
16 CFR 1501	Recall	General Toys	Los Angeles, CA	90013
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall	Hamilton Gifts Ltd, Inc	Long Beach, CA	90810
16 CFR 1501	Recall	Inter-Mainland Corp.	Los Angeles, CA	90013
16 CFR 1501	Recall	Tai Tung Int'l, Inc	Los Angeles, CA	90013
16 CFR 1501	Recall			
16 CFR 1501	Recall	Tai Tung Int'l, Inc	Los Angeles, CA	90013
16 CFR 1501	Recall	Sox Land Int'l, Inc	New York, NY	10018
16 CFR 1501	Recall	Dan Brechner & Co., Inc	Floral Park, NY	11001
16 CFR 1500.3 (c)(6)(viii)	Recall	Topstone Ind., Inc	Danbury, CT	06810
16 CFR 1501	Recall	Steven Mfg. Co.	Hermann, MO	65041
16 CFR 1501	Recall	Soft Things, Inc	Brooklyn, NY	11205
16 CFR 1501	Recall	Bradlees	Braintree, MA	02184
16 CFR 1501	Recall	ABC Distributing, Inc	N. Miami, FL	33181
16 CFR 1306 & 16 CFR 1500.18	Recall	Bargain Center	Fairmont, WV	26554

Date	Product	Model	Violation	
4/90	String Confetti	#9518	Banned Children's Article	Flammable
4/90	Bo Bo Pacifiers	#HK-45	Banned	Nitrosamines in Pacifier
4/90	Pacifer Holder	#1026	Technical Guidelines	Sharp Points
4/90	Wind-Up Ernie Drummer	#8822	Banned	Small Parts
4/90	Crazy String	#1123	Banned Children's Article	Flammable
4/90	Caterpillar Pull Toy	#450	Banned	Small Parts
4/90	Goofy Flying String	#75501	Banned Children's Article	Flammable
4/90	Spinflower Rattle	#30945	Banned	Rattle
4/90	Ma & Baby Bunny	#BP8934	Banned	Small Parts
4/90	Ring Ring Play Phone	#537/88	Banned	Small Parts
4/90	Musical Ice Cream Car	#TT-28A	Banned	Small Parts
5/90	Bead Coaster	#8394	Banned	Small Parts
5/90	Streamer Spray	3.5 oz. Cans	Banned Children's Article	Flammable
5/90	Toy Wooden Dump Truck in 6 assortments	12013, 50006, 55006, 51010, 55010, 55030	Banned Banned	Small Parts Small Parts
5/90	Love-a-Bye Baby Doll		Banned	Small Parts
5/90	Boo Pumpkin		Banned	Small Parts
5/90	Siren Whistles	#C624	Banned	Small Parts
5/90	Stuffed Bears	#N35	Banned	Small Parts
	Stuffed Bears	#N37	Banned	Small Parts
	Stuffed Bears	#N395	Banned	Small Parts

Citation	Action	Manufacturer/Importer	City & State	Zip
16 CFR 1500.3 (c)(6)(viii)	Recall	Fun World, Inc	Carle Place, NY	11514
16 CFR 1500.3 (b)(4)	Recall	Bender & Sons, Inc	New York, NY	10010
16 CFR 1500.48	Recall	Baby Needs, Inc	Burlington, NC	27216
16 CFR 1501	Recall	Illco Toy Co. USA	New York, NY	10010
16 CFR 1500.3 (c)(6)(viii)	Recall	Masquerade, Inc	Brooklyn, NY	11207
16 CFR 1501	Recall	Sandberg Mfg. Co.	Chicago, IL	60612
16 CFR 1500.3 (c)(6)(viii)	Recall	Franco American Novelty	Glendale, NY	11385
16 CFR 1510	Recall	Small World Toys	Culver City, CA	90230
16 CFR 1501	Recall	Bee International	Commerce, CA	90040
16 CFR 1501	Recall	TDT Co.	Los Angeles, CA	90013
16 CFR 1501	Recall	Tai Tung Int'l, Inc	Los Angeles, CA	90013
16 CFR 1501	Recall	Assoc. Merchandising Corp	New York, NY	10018
16 CFR 1500.3 (c)(6)(viii)	Recall	Northeast Import	Central Falls, RI	02863
16 CFR 1501 16 CFR 1501	Recall	P.G.I. Toys Ltd.	Natick, MA	01760
16 CFR 1501	Recall	Hasbro, Inc.	Pawtucket, RI	02862
16 CFR 1501	Recall	Easy Aces, Inc	Providence, RI	02904
16 CFR 1501	Recall	Acme Premium Supply	St. Louis, MO	63108
16 CFR 1501 16 CFR 1501 16 CFR 1501	Recall Recall Recall	Creative Art Flowers, Inc	Hauppauge, NY	11788

Date	Product	Model	Violation	
5/90	Thick Super String	4 oz. Cans	Banned Children's Article	Flammable
5/90	Decoy Duck	#63002	Banned	Small Parts
5/90	Musical Crib Mobiles	Carousel - #555	Banned	Small Parts
	Musical Crib Mobiles	Mother Goose - #658	Banned	Small Parts
5/90	Futons/ Mattresses	#1	Fails Standard	Mattresses
5/90	Cutie Kid W/Pacifier	#10589	Banned	Small Parts
6/90	Water Color & Brushes	#LV8888	Banned	Lead-in-Paint
6/90	My Busy Book	#LV9314	Banned	Small Parts
6/90	Printed T-Shirt	youth size	Banned	Lead-in-Paint
	Printed T-Shirt	adult size	Banned	Lead-in-Paint
6/90	Pop Up Pals Toy	#8785 - SKN#214108	Banned	Small Parts
6/90	Roller Lisa Doll	#SK990	Banned	Small Parts
6/90	Happy Bear Tambourine	#KP353	Banned	Small Parts
	Froggy Maracas	#KP352	Banned	Small Parts
	Ducky Castanets	#KP350	Banned	Small Parts
6/90	Bib to Bowl Pacifier	#1852045	Banned	Pacifier
6/90	Music Master Xylophone	#SX-305 - SKN#421944	Banned	Lead-in-Paint
7/90	Stain Remover	#HP9000	Misbranded	Hazardous Substance
7/90	Baby Alice w/Bottle	#20989	Banned	Small Parts
	Baby Linda w/Bottle	#21173	Banned	Small Parts
	Comfy Karen w/Bottle	#21282	Banned	Small Parts
	Baby Bottle Toy	#21153	Banned	Small Parts
	Nursing Bottles	#21132	Banned	Small Parts
	Toy Telephone	#20930	Banned	Small Parts
	Toy Work Truck	#1908	Banned	Small Parts
	Car Transport w/2 Cars	#42124	Banned	Small Parts
7/90	Spring N' Bounce Car	#8941	Banned	Small Parts
7/90	Wind-Up Tubbables	#3047-1	Banned	Small Parts

Citation	Action	Manufacturer/Importer	City & State	Zip
16 CFR 1500.3 (c)(6)(viii)	Recall	E. Davis, Inc	Piscataway, NJ	08852
16 CFR 1501	Recall	Artsana of America, Inc	New York, NY	10010
16 CFR 1501 16 CFR 1501	Recall Recall	Stahlwood Mfg Co., Inc	Yongsville, NC	27956
16 CFR 1632	Recall	Troy Mattress Co.	Albany, NY	12204
16 CFR 1501	Recall	A.L. Investors, Inc	Denver, CO	80216
16 CFR 1303	Recall	Lillian Vernon Corp	Mt. Vernon, NY	10550
16 CFR 1501	Recall	Lillian Vernon Corp.	Mt. Vernon, NY	10550
16 CFR 1303 16 CFR 1303	Recall Recall	Samuel Holsberg & Co, Inc	Boston, MA	02210
16 CFR 1501	Recall	Toys "R" Us	Paramus, NJ	07652
16 CFR 1501	Recall	Lovee Doll & Toy Co.	Brooklyn, NY	11207
16 CFR 1501 16 CFR 1501 16 CFR 1501	Recall Recall Recall	International Playthings	Riverdale, NJ	07457
16 CFR 1511	Recall	Only One Dollar, Inc	Norfolk, VA	23513
16 CFR 1303	Recall	Toys "R" Us	Paramus, NJ	07652
FHSA - Sec. 2(p)(1)	Recall	Media Arts Int'l, Ltd	Philadelphia, PA	19127
16 CFR 1501 16 CFR 1501 16 CFR 1501 16 CFR 1501 16 CFR 1501 16 CFR 1501 16 CFR 1501 16 CFR 1501 16 CFR 1501	Recall Recall Recall Recall Recall Recall Recall Recall Recall	E. Fomil & Sons, Inc	Burlingame, CA	94010
16 CFR 1501	Recall	McCrorry	York, PA	17402
16 CFR 1501	Recall	Norman J. Lewis Assoc	New York, NY	10010

Date	Product	Model	Violation	
7/90	Bunny on Motor Scooter	#522	Banned	Small Parts
7/90	Wind-Up Turtle Toy	#581	Banned	Small Parts
7/90	Peek-A-Boo Ernie	#8810	Banned	Small Parts
7/90	Bird Whistle W/Candy	#SW187	Banned	Small Parts
	Tom-Tom Drums	#SK225	Banned	Small Parts
7/90	Sound & Shape Center	#14756	Banned	Small Parts
	Shape & Sound Tubes	#14757	Banned	Small Parts
	Puzzle Sound Tubes	#14758	Banned	Small Parts
7/90	Music Maker Elephant	#29/555	Banned	Small Parts
8/90	Wooden Trains	#13300	Banned	Small Parts
	Wooden Trains	#13602	Banned	Small Parts
	Fantasy Land Nessey	#13822	Banned	Small Parts
8/90	Clutch Rattle	"Fozzi" Bear, #B304	Banned	Rattle
8/90	Sesame St Rhythms Band	#3553	Banned	Small Parts
8/90	Mickey Mouse Tricycle	#8737	Banned	Small Parts
	Mickey Mouse Sea Plane	#8706	Banned	Small Parts
8/90	Dress Myself Clown	#52410	Banned	Small Parts
8/90	Streamer Spray	3.5 oz. Cans	Banned	Flammable
			Children's	
			Article	
8/90	Car Transport toy	#710	Banned	Small Parts
8/90	3in1 Colorful Keyhouse	#717563	Banned	Small Parts
8/90	Mops, brooms, sticks		Banned	Lead-in-Paint
8/90	Pull Out Peg Puzzle	#T238	Banned	Small Parts
8/90	Beaded Trumpet Rattle	#BB4941	Banned	Rattle
9/90	Pom Pom Pets Assmt		Banned	Small Parts
9/90	Sidewalk Bicycle	#JF-246B	Banned	Fails Standard
9/90	Clown Doll	#6159	Banned	Small Parts
9/90	Children's Sleepwear	#9477	Fails	Sleepwear
			Standard	

Citation	Action	Manufacturer/Importer	City & State	Zip
16 CFR 1501	Recall	Easter Creations	Danbury, CT	06810
16 CFR 1501	Recall	Easter Creations	Danbury, CT	06810
16 CFR 1501	Recall	Illco Toy Co.	New York, NY	10010
16 CFR 1501	Recall	Golden Country	Chicago, IL	60616
16 CFR 1501	Recall	Oriental Food		
16 CFR 1501	Recall	Barval Toys, Inc	Miami, FL	33172
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall	F.J. Strauss Co., Inc.	North Bergen, NJ	07047
16 CFR 1501	Recall	Darda, Inc USA	Baltimore, MD	21211
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1510	Recall	Wisconsin Toy Company	New York, NY	10010
16 CFR 1501	Recall	Lewco Corporation	New York, NY	10010
16 CFR 1501	Recall	Service Promotional Sales	New York, NY	10010
16 CFR 1501	Recall			
16 CFR 1501	Recall	C.V.P., Inc	Westbury, NY	11585
16 CFR 1500.3 (c)(6)(viii)	Recall	Cotraco, Inc	Hartford, CT	06103
16 CFR 1501	Recall	Henry Gordy Int'l, Inc	Plainfield, NY	07061
16 CFR 1501	Recall	B & E Merchandising Corp.	Livonia, MI	48152
16 CFR 1303	Recall	Nu-Cushion Product Mfg Co	Shawnee Mission, KS	66203
16 CFR 1501	Recall	A.J. Cohen	Brentwood, NY	11717
16 CFR 1510	Recall	Battat, Inc	Plattsburgh, NY	12901
16 CFR 1501	Recall	F.W. Woolworth Corp.	New York, NY	10279
16 CFR 1512	Recall	Kraemer Mercantile Corp.	New York, NY	10015
16 CFR 1501	Recall	Etna Worldwide (JSNY)	New York, NY	10010
16 CFR 1615	Recall	The Warren Featherbone Co	Gainsville, GA	30503

Date	Product	Model	Violation	
9/90	GreatGlass Crystalline 2 oz Bottles		Misbranded	Hazardous Substance
9/90	Spirit of '76 Fountain	#100	Banned	Fireworks
9/90	Construction Train Set	#7186	Banned	Small Parts
	Press N' Go Choo Choo	#20-192	Banned	Small Parts
	June & Julie Dolls	#120092	Banned	Small Parts
	Motor Mouse	#18-437	Banned	Small Parts
9/90	Clown Doll	#6159	Banned	Small Parts
9/90	Toy Car Premiums	Corvette, Jaguar, Lotus	Banned	Small Parts
		Porsche, Lambourgini	Banned	Small Parts

Citation	Action	Manufacturer/Importer	City & State	Zip
FHSA - Sec. 2(p)(1)	Recall	Plaid Enterprises	Norcross, GA	30091
16 CFR 1500.17	Recall	Bob Hale Fireworks Co	Buffalo, MO	65622
16 CFR 1501	Recall	House of Lloyd, Inc	Grandview, MO	64030
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall			
16 CFR 1501	Recall	Carol Wright Gifts	Lincoln, NE	68544
16 CFR 1501	Recall	Ralston Purina Company	St. Louis, MO	63164
16 CFR 1501	Recall			

Voluntary Corrective Action Plans Under
Section 15 of the Consumer Product Safety Act and
Section 15 of the Federal Hazardous Substances Act

Date	Firm and Product	Alleged Hazard	Remedy
10/89	Dreamline Mfg. Inc. Cabot, AR Bunk Beds	Ledges on side rails are the only means of support for mattress support system. The mattress support system may collapse causing death or injury to children on the beds or to children playing on the floor under the bed.	The firm provided point-of-purchase posters to all customers notifying consumers of the availability of free cross wire kits.
10/89	McCrorry Corporation York, PA Baby's First Gift Set with hanging crib toy, "Melody Bells"	Product presents a risk of strangulation to infants five months of age and older.	Consumers should return product to retailer for full refund.
10/89	Foster-Forbes Glass Division, American National Can Marion, IN 16 oz. Non-returnable glass flint soda bottles distributed 6/14/89 to 7/14/89	The glass soda bottle has the potential to explode once the soda has been packaged, stored and/or distributed.	The firm adjusted its packing machine and the bottler recalled all the defective bottles from consumers and the market place.

Date	Firm and Product	Alleged Hazard	Remedy
10/89	Southern Pine Manufacturing Co. Aliceville, AL Bunk Beds	Ledges on side rails are the only means of support for mattress support system. The mattress support system may collapse causing death or injury to children on the beds or to children playing on the floor under the bed.	The firm provided point-of-purchase posters to all customers notifying consumers of the availability of free cross wire kits.
10/89	Oakwook Furniture Co., Inc. Golden, MS Bunk Beds	Ledges on side rails are the only means of support for mattress support system. The mattress support system may collapse causing death or injury to children on the beds or to children playing on the floor under the bed.	The firm provided point-of-purchase posters to all customers notifying consumers of the availability of free cross wire kits.
10/89	Fine Pine Inc. Vinemont, AL Bunk Beds	Ledges on side rails are the only means of support for mattress support system. The mattress support system may collapse causing death or injury to children on the beds or to children playing on the floor under the bed.	The firm provided point-of-purchase posters to all customers notifying consumers of the availability of free cross wire kits.

Date	Firm and Product	Alleged Hazard	Remedy
10/89	<p>Mitchell Manufacturing Co. Milwaukee, WI</p> <p>Folding Mobile Tables, 50 inches or higher when folded.</p>	<p>When children move or play with folded mobile tables, the tables have the potential to tip over on them possibly resulting in death.</p>	<p>The firm joined a program to place permanent, uniform, warning labels on all tables distributed through out the country.</p>
10/89	<p>E-Z-Go Division Textron, Inc. Augusta, GA</p> <p>"E-Z-Go" brand Electric Golf Carts, Models X-400 & Model X-444, utilizing the Lester DC cordsets with either the red or black molded neoprene 2 prong plugs or the Lester 8020 hard yellow plastic plug and 8045 receptacle.</p>	<p>Normal operation may result in the internal components of the plugs breaking or short circuiting, possibly resulting in over heating or arcing with a fire potentially resulting.</p>	<p>The firm stopped using the Lester 8020 plug and 8045 receptacle and recalled those units sold with their golf carts. The firm also initiated a replacement program for the Lester red and black plug cordsets.</p>
10/89	<p>The Thermos Company Freeport, IL</p> <p>Thermos and Structo Brand Gas Grills</p>	<p>Some grills were assembled using defective hose and pressure regulator assemblies which could leak gas. If the gas ignites, it could present fire or explosion hazards.</p>	<p>Thermos offered replacement parts to consumers.</p>

Date	Firm and Product	Alleged Hazard	Remedy
10/89	China Pyrotechnics, Inc. Florence, AL Pulling Fireworks device	This device may self-ignite and explode during use or handling.	China Pyrotechnics, recalled this fireworks device from the retail market place.
10/89	Wilmington Coca-Cola Bottling Works, Inc. Wilmington, NC 16 oz. non-returnable glass flint bottles distributed 6/14/89 to 7/14/89	The glass soda bottle has the potential to explode once the soda has been packaged, stored and/or distributed.	The firm recalled all the defective bottles from consumers and the marketplace. Refunds or replacements are offered to consumers.
10/89	Noma Outdoor Products Inc. Des Moines, IA 45 inch riding mower decks	A 3 inch piece of broken blade could exit from under the riding mower deck and may cause injury to bystanders.	The firm initiated a corrective action program to replace the blades of the mowers.
10/89	Aeroquip Corporation Van Wert, OH FD67 Series (-6 size) liquid line valve for air conditioning system	Propelled valve may contact repairman or other persons in vicinity, causing facial or eye injury.	Retrofit valve cap assembly sent to distributors by firm, to be installed on all future valves for their home air conditioning systems.

Date	Firm and Product	Alleged Hazard	Remedy
10/89	<p>Caloric Corporation Topton, PA</p> <p>Certain 20" and 30" Freestanding Electric Ranges Brands: Glenwood, Grand, Welbilt, Sunray, Whirlpool, Caloric</p>	<p>In certain units a ground link was not properly attached. If other components failed, an electrical shock hazard could be created.</p>	<p>Consumers are being contacted directly for an "in-home" repair.</p>
10/89	<p>Honda Motor Corp., USA Gardena, CA</p> <p>Rubber fuel cock carburetor gasket</p>	<p>There is an extremely low possibility of a fire with an internal combustion engine at low environment temperatures. However, leakage stops after engine is warm and corrects problem.</p>	<p>The firm changed the material used to make the rubber petcock gasket.</p>
10/89	<p>National Presto Industries, Inc. Eau Claire, WI</p> <p>PRESTO HeatDish Parabolic Elec. Dish Heater Model No. 07905</p>	<p>Pinched internal wiring may allow current leakage which could create a shock hazard.</p>	<p>In Sept. 1989, all units in inventory and in the hands of customers were checked and reworked as necessary to meet all safety and operational requirements. These units have all been coded for future identification.</p>

Date	Firm and Product	Alleged Hazard	Remedy
11/89	Interkal, Inc. Kalamazoo, MI "Brunswick", "Vecta" "Interkal" manual, telescopic bleachers produced between 1966 &1979	If the bleachers are not maintained properly and/or not operated correctly, after a period of time the bleachers may collapse.	A joint press release was issued 11-89 advising consumers of this hazard. Also the firm implemented a mailing notice program to contact all the schools that received the problem bleachers.
11/89	Buddy L Corporation New York, NY Pepsi Cola Trucks, 1976 to 1989	A 4.3" long by .15" diameter, white plastic rod used to hold bottle cases on Pepsi Cola toy trucks can be inserted into and injure ears of small children.	Warning labels were placed on packaging for the trucks, advising parents to remove and discard the rod. The firm discontinued using the rod on the trucks.
11/89	Emerson Electric Company Hazelwood, MO Sears "Craftsman" 8 and 9 inch table saws 8" models: 113.221610, 113.221611, 113.221640	If the saw is operated with the blade safety guard raised, the guard may fall striking the blade. The operator could contact the blade as a result of a "startle reflex".	Consumers owning these saws may obtain a free redesigned blade guard by contacting Sears Roebuck and Company, or Emerson directly at 1-800-237- 8279.

Date	Firm and Product	Alleged Hazard	Remedy
12/89	<p>Black & Decker Towson, MD</p> <p>Sold in Puerto Rico only Hand-held Hair Dryers</p> <p>Models: Accent 27 I Accent 40 I Accent 50 I</p>	<p>May cause electrocution if dropped into water due to lack of immersion protection for the switch in the "off" position.</p>	<p>Consumers can return their units to the Black and Decker Center in Puerto Rico for a full refund of the purchase price.</p>
12/89	<p>CSC Consolidated Stores Columbus, OH</p> <p>String-to-string Toyo Christmas lights with TP-6 connector</p>	<p>The exposed, energized metal contacts on some TP-6 connectors present an electric shock or electrocution hazard.</p>	<p>Toyo will replace all string-to-string sets with TP-6 connectors with a new or repaired set.</p>
12/89	<p>RoI-FoI Table, Inc. Van Nuys, CA</p> <p>Folding Mobile Tables, 50 inches or higher when folded.</p>	<p>When children move or play with folded mobile tables, the tables have the potential to tip over on them possibly resulting in death.</p>	<p>The firm joined a program to place permanent, uniform, warning labels on all tables distributed through out the country.</p>
12/89	<p>Hamilton Industries, Inc. Two Rivers, WI</p> <p>Folding Mobile Tables, 50 inches or higher when folded</p>	<p>When children move or play with folded mobile tables, the tables have the potential to tip over on them possibly resulting in death.</p>	<p>The firm joined a program to place permanent, uniform, warning labels on all tables distributed through out the country.</p>

Date	Firm and Product	Alleged Hazard	Remedy
12/89	Sico, Inc. Minneapolis, MN Folding Mobile Tables, 50 inches or higher when folded	When children move or play with folded mobile tables, the tables have the potential to tip over on them possibly resulting in death.	The firm joined a program to place permanent, uniform, warning labels on all tables distributed through out the country.
12/89	Krueger International Green Bay, WI Folding Mobile Tables, 50 inches or higher when folded.	When children move or play with folded mobile tables, the tables have the potential to tip over on them possibly resulting in death.	The firm joined a program to place permanent, uniform, warning labels on all tables distributed through out the country.
12/89	Midwest Folding Products Chicago, IL Folding Mobile Tables, 50 inches or higher when folded	When children move or play with folded mobile tables, the tables have the potential to tip over on them possibly resulting in death.	The firm joined a program to place permanent, uniform, warning labels on all tables distributed through out the country.
12/89	Comfort Products, Inc. Carrollton, TX Comfort Float	In water depths greater than two inches, the float may become unstable allowing the infant user's face to be submerged in water.	The firm recalled all units offering consumers a full refund, credit or fair market value.

Date	Firm and Product	Alleged Hazard	Remedy
12/89	Hudson Standard Corporation Newark, NJ "4 in 1" Grill Waffler, Model No. 785	Improper assembly would energize the grill waffler housing with line voltage (120 VAC) to present a severe electric shock or an electrocution hazard.	J.C. Penney Co., Inc. contacted and recalled the grill wafflers from all catalog sales customers.
12/89	J.C. Penney Company, Inc. Dallas, TX Electric Garment Steamer No. 784-1008	The water fill plug on the garment steamer may pop out during use exposing users to hot water and steam. Users may sustain first and/or second degree burns.	J.C. Penney recalled the product offering refunds to consumers. A joint press release was issued 1/90 announcing the recall.
12/89	Daisy Manufacturing Company, Inc. Rogers, AR Plastic ring caps Nos. 4508, 4512 Sold only in Wal-Mart Stores	Caps may flare up if dropped or experiencing friction, presenting a potential fire or burn hazard.	For a refund and directions for disposing of caps, contact: Daisy Manufacturing Co., P.O. Box 220, Rogers, AR 72756 (800) 643-3458.
1/90	Toyo Industrial Co. Ltd. Taipei, Taiwan and Bangkok, Thailand String-to-string Toyo Christmas lights with TP-6 connector.	The metal contacts inside some TP-6 connectors may be pulled or pushed out, exposing them to contact by consumers. Energized, exposed contacts may present an electric shock or electrocution hazard.	Toyo will replace all string-to-string Christmas light sets with TP-6 connectors with new or repaired sets at no cost to consumers.

Date	Firm and Product	Alleged Hazard	Remedy
1/90	Kmart Troy, MI String to string Toyo Christmas lights with TP-6 connector	The exposed, energized metal contacts on some TP-6 connectors present an electric shock or electrocution hazard.	Toyo will replace all string to string sets with TP-6 connectors with a new or repaired set.
1/90	Walmart Bentonville, AR String-to-string Toyo Christmas lights with TP-6 connector.	The exposed, energized metal tabs on some TP-6 connectors present an electric shock or electrocution hazard.	Toyo will replace all string-to-string sets with TP-6 connectors with a new or repaired set.
1/90	Revco Twinsburg, OH String to string Toyo Christmas lights with TP-6 connector	The exposed, energized metal tabs inside some TP-6 connectors present an electric shock or electrocution hazard.	Toyo will replace all string-to-string sets with TP-6 connectors with a new or repaired set.
1/90	Alkco Lighting Company, Inc. Franklin Park, IL Linear Incandescent Lighting Fixture, (Lin Series 40 and 4000)	Contact with the exposed and energized <i>mounting connector</i> terminal would present a severe electric shock hazard.	The company will retrofit all Lin 40 and Lin 4000 light fixtures installed between March 15, 1988 and August 4, 1989 with a center disconnect switch.

Date	Firm and Product	Alleged Hazard	Remedy
01/90	<p>Raley's West Sacramento, CA</p> <p>Toyo string-to-string Christmas lights with TP-6 connectors</p>	<p>The metal contacts inside some Toyo TP-6 connectors may be pulled or pushed out and the exposed, energized contacts may present a shock or electrocution hazard.</p>	<p>Toyo offered replacement or cash refunds for the problem light sets.</p>
2/90	<p>Stephen Imports San Francisco, CA</p> <p>International Professional Styler, PW-708 and International Traveler 1250</p>	<p>These model hair dryers offer no immersion protection if dropped in water. This could cause electrocution.</p>	<p>Consumers can return their hair dryer to the place of purchase to receive a full refund.</p>
2/90	<p>Smith Corona Corporation Cortland, NY</p> <p>Smith Corona rechargeable power pack, stock number 67140</p>	<p>A charged battery pack may develop a short circuit in its internal wiring, resulting in overheating of the keyboard of the laptop word processor in which it is contained.</p>	<p>The firm redesigned the battery pack and recalled the product offering a free redesigned unit to consumers.</p>
2/90	<p>Lillian Vernon Corporation Mt. Vernon, NY</p> <p>Golden Bird Votive Candle</p>	<p>The outer terra cotta shell of the candle is likely to crack apart during use resulting in a potential fire hazard.</p>	<p>The candle was recalled by the firm and a refund of the purchase price was offered to consumers.</p>

Date	Firm and Product	Alleged Hazard	Remedy
2/90	Tsumura International Chaska, MN RIGAUD Candles Cythere and Cypress colors	Some of these candles have the tendency to flare-up possibly resulting in a minor burn and/or fire hazard.	The firm recalled all the Cythere and Cypress candles produced during the year 1989.
3/90	McCrorry Corporation York, PA Aqua Hex Aquarium, Item No. 951418	The electric cord light socket is not properly secured. Tightening a bulb in the light socket can cause a short circuit and ignition of the cord, presenting a fire hazard.	Owners should discontinue the use of the light cord set and return it to the store where purchased for a free replacement.
3/90	Schwinn Bicycle Co. Washington, DC All-Terrain Bicycle	The unstable bike may be difficult to steer causing the rider to lose control and fall.	Schwinn notified all it's customers of stability problems and replaced the fork assembly.
3/90	Sta-Rite Industries Delavan, WI Battery Operated Backup Sump Pump	Should the motor of the sump pump experience a locked rotor condition, the motor may overheat possibly resulting in a smoke or fire hazard.	Consumers are to contact Sta-Rite at 1-800-472- 0884 to receive replacement units free of the alleged hazard.

Date	Firm and Product	Alleged Hazard	Remedy
3/90	Arctco Thief River Falls, MN 1990 El Tigre EXT snowmobile carburetor spring	The vehicle may not slow down when the throttle is released.	The firm notified the carburetor's manufacturer to install correct springs and to change assembly and quality control procedures.
3/90	White Consolidated Industries, Inc. Cleveland, OH 18.6 and 20.6 cubic ft. refrigerators with freezer on top manufactured in March of 1989. Frigidaire, Gibson, Kelvinator, Signature, Coldspot, White Westinghouse	If the heating element is situated too close to the plastic liner it could cause melting or in an extreme case, it could lead to a fire.	Consumers who experience a problem should contact their local dealer.
3/90	Bondwell Industrial Co., Inc. Fremont, CA Remote Control Toys Quick Shot "Dudley Duck" and "Deenie Dino"	A battery may overheat and/or leak when one unit of four is placed in the battery compartment in the reversed polarity position. Leaking batteries may cause eye or skin irritations.	The firm placed warning labels on units in stock and redesigned new units to be placed only in correct positions.

Date	Firm and Product	Alleged Hazard	Remedy
4/90	Raffoler, Ltd. Westbury, NY Spring action rowing exerciser	Injury can occur from the spring or from the handle of the exerciser.	Consumers are to mail back the spring and handle grip for a full purchase price refund.
4/90	Walter Le Productions Sun Valley, CA Glass Curio Cabinet Models 1810,1820,1830	The adhesive holding the cabinet to the wall does not function properly allowing the cabinet to fall to the floor.	The firm recalled the cabinets offering a refund or exchange to consumers.
4/90	Landmark Imports, Inc. Memphis, TN 3-U Planter Floor Lamp, Model 4088	The screws used to attach the support legs to the center pole may be sufficiently long to penetrate or damage the power supply cord. An electrocution hazard could result.	The firm recalled the lamp and issued a press release asking consumers to return the lamps to the store where purchased for a refund.
4/90	Black & Decker (U.S.) Inc. Towson, MD Spacemaker Plus Drip Coffeemaker, Models PDC401 and PDC402	The water reservoir may not engage properly, causing one end of the heater tube to overheat during the brew cycle.	Owners may return their recalled unit for a replacement unit or a refund. Owners may call the Black & Decker toll free number 800-833-3396 for recall instructions.

Date	Firm and Product	Alleged Hazard	Remedy
4/90	McCrorry Corporation York, PA Folding Umbrella Stroller, SKU #129088, Model AT410	The restraining system does not fasten as tightly as required by the voluntary standard testing procedure. This may allow an unattended child occupant to "escape" from the stroller.	McCrorry destroyed all units in firm and retail inventory.
4/90	First Brands Corporation Danbury, CT SIMONIZE Quick Gloss	The product's aerosol metal container may rupture resulting in the metal dome of the container separating under pressure causing injury to the user or bystander.	The firm recalled the product offering refunds to consumers.
4/90	Fitness Quest Canton, OH "Step Lively" exercise climber	If the belt of the device breaks, the user may fall.	The belt was changed from 80% to 100% nylon to prevent any premature breakage. Consumers were offered replacement belts.
5/90	Scotsman Group, Inc. (Halsey Taylor) Vernon Hills, IL Drinking Water Coolers	Certain Halsey Taylor water cooler models were alleged to contain lead-lined water storage tanks. The Lead Contamination and Control Act (LCCA) was enacted due to concern that lead contamination of water coolers presents a public health risk.	The Commission accepted a Consent Order Agreement under the LCCA which provides for a comprehensive replacement or refund program for coolers that contribute more than 20 ppb lead to the drinking water.

Date	Firm and Product	Alleged Hazard	Remedy
5/90	Home Club Fallington, CA Glass Curio Cabinet Models 1810, 1820 & 1830	The adhesive holding the cabinet to the wall does not function properly allowing the cabinet to fall to the floor.	The firm recalled the cabinets offering a refund or exchange to consumers.
5/90	ASA, Inc. Elkhart, IN Magnavox 13 Inch Color Television Receiver, Model No. RJ4049	The internal chassis wiring is not isolated from the AC power supply which would present an electric shock hazard if contact is made with the external jack.	Consumers should contact the Consumer Affairs office of the Philips Electronics Company at (615) 475-0317 to arrange for the repair of their televisions at an authorized service center.
5/90	Glassworks Creations, Inc. Farmington Hills, MI Pecora Adhesive used to hang mirrors	The adhesive, used to mount the mirrors to the wall, may dry out allowing the mirrors to loosen or to fall to the floor.	The firm discontinued the use of the Pecora adhesive and rectified improper installations.
6/90	Dynamic Classics, Ltd. New York, NY "Rowing Action Exerciser" spring exerciser	The spring may break, the footbar can separate and the handlebar or spring may snap back causing serious facial and body injuries, i.e. lacerations, fractures, loss of teeth and concussions.	Firm provided consumers with a retrofit kit, consisting of metal clips for both ends of the spring, a new footbar with a longer connector and a new shorter cord.

Date	Firm and Product	Alleged Hazard	Remedy
6/90	Harrison-Hoge Industries Inc. Station, NY "Stomach Eliminator" exerciser	Springs, footpedals or clips may break during use and strike the user causing serious facial or body injuries, namely, fractures, concussion, loss of teeth and eyesight, or stitches to facial areas.	Firm provided a refund of \$15 or a credit of \$20 toward other Harrison-Hoge products to consumers who called their 800 number.
6/90	Deere and Company Moline, IL Model 14SB and 14PB Rotary Lawn Mowers	On some units the kick-back on the starter rope can result in a sprain or fracture to the user's arm.	Consumers owning these units can obtain free modification of the mower by contacting the local John Deere dealer.
6/90	Bianchi, USA, Inc. Francisco, CA "Randonneur" model bicycle	A rider could fall if fork were to crack and break during use.	On August 14, 1990 the firm issued a joint press release with the Commission announcing a recall.
6/90	Micromar Manufacturing Corporation London, Ontario Ceramic Disc Type Portable Electric Heater	Arcing across a crack in the disc may present a fire hazard.	Consumers are to return affected units to firm for repair or replacement.

Date	Firm and Product	Alleged Hazard	Remedy
6/90	McCrorry Corporation York, PA School/Craft supply "Value Pack"	Children may cut themselves when using the razor blade knife.	Consumers who purchased "mini-cutters" as part of a "Value Pack" before January 25, 1990, may return them for a \$.50 rebate.
6/90	Scotty's, Inc. Winterhaven, FL Tabletop propane grill	In some cases the control knob for the propane cylinder may catch fire resulting in a potential for fire or burns.	Scotty's is offering a replacement grill at no charge, or refund to consumers.
6/90	Sunbeam Appliance Co. Brown Deer, WI Deluxe 12-Speed Mixmaster Mixer	If the housing is contacted by internal parts it may be electrified and present an electric shock hazard.	Consumers are asked to return defective units to Sunbeam for free replacement.
6/90	Fu Cheong Industrial Ltd Tuen Mon, New Territory, Hong Kong Electric Sandwich Grill	The unit could overheat and cause a fire.	Consumers will be contacted directly by mail. Upon return of their unit to the firm, they will receive a free replacement.

Date	Firm and Product	Alleged Hazard	Remedy
6/90	Knoll International, Inc. East Greenville, PA Single piece, multi-curving sculptural arm chair and Spyder Table	The paint used on the furniture contains greater than 0.9% and 7.7% lead.	Consumers are being contacted directly by Knoll and repairs will be made in the home.
6/90	The Coleman Company Wichita, KS Model 3100 Crosman air rifle	The accidental discharge of the airgun could result in death or serious injury.	The firm recalled and re-designed the sear mechanism so it will not wear prematurely. Consumers should discontinue use and call the firm at (1-800-836-3100) for instructions on returning the airguns.
7/90	FREM Corporation Worcester, MA Stuff 'N Store Covered Box	A young child may suffocate if he were to become entrapped in the storage box.	The firm redesigned its product to include a permanent warning to consumers addressing the potential hazard.

Date	Firm and Product	Alleged Hazard	Remedy
7/90	Proctor-Silex, Inc. Glen Allen, VA Model A4 and A5 Stamped Plate Automatic Drip Coffeemakers	The firm believes that thermostats and thermal fuses purchased by Proctor-Silex for use in the coffeemakers may both malfunction causing overheating and a potential fire hazard.	The firm recalled the A4 and A5 coffeemakers and replaced them with A6 coffeemakers.
07/90	Kolcraft Enterprises Inc. Chicago, IL "Giggle-See" bumper pad for crib	The thin, plastic ties of the bumper pads may tear off and present a potential choking hazard to infants.	Firm issued a joint press release 7/9/90 advising consumers to cut off all plastic ties and send to firm for a refund of full purchase price.
7/90	The Coleman Company, Inc. Wichita, KS Cookin' Machine propane smoker/grill	The gas supply hose could disconnect and escaping gas could ignite and create a fire hazard.	Coleman has redesigned the hose to grill connection so that it is more secure. Coleman will provide free replacement hoses.
7/90	Toy Biz, Inc. Lynbrook, NY Toy action figure, "The Penguin"	Choking or aspiration of projectile.	Toy Biz redesigned the toy to meet ASTM Standards.

Date	Firm and Product	Alleged Hazard	Remedy
7/90	Hamilton Beach Inc. Washington, NC Under-the-Cabinet Drip Coffee Maker Model No. 816-2 and 816-3	The analog clock in the coffee maker has a defectively designed switch, which can cause uncontrolled arcing. Continued arcing can ignite the plastic switch housing and coffee maker enclosure, creating a fire hazard.	The firm recalled the coffee makers and offered consumers replacements.
7/90	Suntec Industries Inc. Rockford, IL Fuel unit consisting of a pump and valve for use on an oil furnace	An oil leak may cause odor and stain damage. A remote risk exists that the fuel oil would contact an ignition source.	Suntec recalled units from distribution chain and inventory to rework defective units as necessary.
8/90	Buckhorn Corp. Milford, OH STOW-AWAY Storage Boxes 12 gallon	A young child may suffocate if he were to become entrapped in the storage box.	The firm redesigned the storage box to include holes under the handles to provide ventilation inside the box.
8/90	Phillips Fung Ying Corp. Brooklyn, NY Electrical Transformer	When one plug is inserted into a wall receptacle first, the plug at the other end is electrically charged. Consumers could received severe electrical burns or be electrocuted if they touch the energized plug.	The firm cooperated in a joint press release with CPSC and the N.Y. Attorney's General's Office and will provide a full refund to consumers who purchased the product.

Date	Firm and Product	Alleged Hazard	Remedy
8/90	Tache-Haddad Enterprises New York, NY Electrical Transformer	When one plug is inserted into a wall receptacle first, the plug at the other end is electrically charged. Consumers could received severe electrical burns or be electrocuted if they touch the energized plug.	The firm cooperated in a joint press release with CPSC and the N.Y. Attorney's General's Office and will provide a full refund to consumers who purchased the product.
8/90	Saiko Enterprises Long Island City, NY Electrical Transformer	When one plug is inserted into a wall receptacle first, the plug at the other end is electrically charged. Consumers could received severe electrical burns or be electrocuted if they touch the energized plug.	The firm cooperated in a joint press release with CPSC and the N.Y. Attorney's General's Office and will provide a full refund to consumers who purchased the product.
8/90	Sprint International Brooklyn, NY Electrical Transformer	When one plug is inserted into a wall receptacle first, the plug at the other end is electrically charged. Consumers could received severe electrical burns or be electrocuted if they touch the energized plug.	The firm cooperated in a joint press release with CPSC and the N.Y. Attorney's General's Office and will provide a full refund to consumers who purchased the product.

Date	Firm and Product	Alleged Hazard	Remedy
8/90	Esaw Industries South River, NJ Electrical Transformer	When one plug is inserted into a wall receptacle first, the plug at the other end is electrically charged. Consumers could received severe electrical burns or be electrocuted if they touch the energized plug.	The firm cooperated in a joint press release with CPSC and the N.Y. Attorney's General's Office and will provide a full refund to consumers who purchased the product.
8/90	Solar Impex New York, NY Electrical Transformer	When one plug is inserted into a wall receptacle first, the plug at the other end is electrically charged. Consumers could received severe electrical burns or be electrocuted if they touch the energized plug.	The firm cooperated in a joint press release with CPSC and the N.Y. Attorney's General's Office and will provide a full refund to consumers who purchased the product.
8/90	MicroComputer Accessories, Inc. Los Angeles, CA Workmaster Task Lamp, Model No. 5550C	A defective ballast could overheat to about 175 degrees F, producing an odor and causing the ABS ballast housing to deform.	Owners should contact the company for free replacement of the #5550 Task Lamp.
8/90	Virco Mfg. Corporation Los Angeles, CA Series 8900 stacking chairs	The chairs have the potential to collapse due to structural flaws in the frames which could result in an occupant falling to the ground.	The firm will either retrofit or replace the defective chairs with safely designed chair frames.

Date	Firm and Product	Alleged Hazard	Remedy
9/90	<p>Graco Children's Products Elverson, PA</p> <p>Baby Strollers - Travel-Mate, Stroll-A-Bed, Elite, Brougham, Regency, Regency Ltd., Premier, and Premier Ltd.</p>	<p>The exposed recline brackets of these strollers may present a fingertip laceration, fracture or amputation hazard to children who place their fingers in the mechanism when the seat is raised by the parent or others.</p>	<p>The firm is providing free stroller retrofit kits to consumers.</p>
9/90	<p>O'Brien International Inc. Redmond, WA</p> <p>O'Brien Pro Flow Waterski bindings</p>	<p>Lacerations, abrasions or soft tissue injuries could result from binding and ski separation.</p>	<p>The firm issued joint press release, sent letters to distributors and did paid ads in Waterski magazine - recalling water bindings which were defective.</p>
9/90	<p>Graco Children's Products, Inc. Elverson, PA</p> <p>Infant Walkers ("Tot Wheels," "Tot Wheels II," "Tot Wheels III," "Wonder Walker," "Disney Babies")</p>	<p>Children chew, ingest, or temporarily choke on decorative plastic labels found on either the tray or base of the walkers.</p>	<p>Consumers were notified to remove all decorative labels from these products immediately.</p>
9/90	<p>Maytag Corporation Newton, IA</p> <p>Top mount and side by side refrigerator with water & ice dispensers</p>	<p>The small parts can present a choking hazard.</p>	<p>Maytag offered consumers a free redesigned replacement bin.</p>

Date	Firm and Product	Alleged Hazard	Remedy
9/90	Builders Square, Inc. San Antonio, TX Bay Breeze brand Ceiling Fans imported by Manufacturing Group of America, Inc.	If the bracket breaks and the blade flies off, it could injure anyone nearby it may strike.	Builders Square will refund purchase price to consumers. It is replacing defective blade brackets on inventory units with acceptable replacements.
9/90	Taco Bell Irvine, CA Taco Bell Restaurant Greg Lamond Water Bottle promotional item.	If the mouthpiece is swallowed, a choking hazard is presented.	Refunds being provided for the return of the water bottle.
9/90	Noma Outdoor Products Des Moines, IA Sears gas-powered edger/trimmer, Model 797530	Gas leaking from cracks in gas tank could ignite and injure users .	Noma replaced gas tanks on all firm's and Sears inventory.



APPENDIX G

Litigation and Settlements

LITIGATION AND SETTLEMENTS

This appendix summarizes the federal court cases to which the Commission was a party, civil penalty settlements, and consent agreements accepted by the Commission. Categorized by type, the following cases were pending in court during fiscal year 1990:

INJUNCTIONS

1. United States v. Charles Focht and Mark Focht, d/b/a Liberty Industries, Civil Action No. 88-1217 (W.D. Pa.) and No. 88-3781 (3d Cir.). On May 28, 1988 the government filed a complaint seeking an injunction against a mail order fireworks components supplier. Following a hearing on September 13, 1988, the District Court denied the preliminary injunction request, holding that the components distributed by the firm are not themselves necessarily components of banned fireworks. On August 8, 1989 the Court of Appeals reversed and remanded, holding (1) that the components at issue are banned hazardous substances and (2) that an objective test of how a product is intended to be used, rather than a subjective standard of intent, must be applied in determining whether otherwise harmless components are intended to be made into banned hazardous fireworks. On November 9, 1989 the government filed a pleading seeking resolution of the injunction issue by the District Court. The firm responded on December 8, 1989. Negotiations took place between the parties, but did not resolve the case. On March 1, 1990 the government moved for a permanent injunction which the Court ordered on June 7, 1990.

2. United States v. L.W. Loyd Co., Inc. and Lew W. Loyd, Civil Action No. 1-89-452 (D. Tenn.). On September 14, 1989 the government filed a complaint and motion for preliminary injunction against an importer of fireworks. Following expedited discovery, the Court conducted a consolidated hearing on a preliminary and permanent injunction on October 26 and 27, 1989. Both sides filed post-hearing briefs on November 10, 1989. On February 20, 1990 the Court issued a permanent injunction, requiring the firm to test 20 samples of every firework it imports and to notify the CPSC of all failures. The Court ruled that an affirmative testing order was within its broad equitable powers, and deferred to CPSC's judgment on the scope of such an order. The Court further ruled that CPSC was not unfairly discriminating against the firm and that the "vagaries of Chinese manufacturing" did not relieve the firm of its obligations under federal law. On

March 9, 1990 the government filed a motion seeking a modification of the Court's order to clarify that the injunction is not rulemaking under the Administrative Procedure Act. On May 8, 1990 the Court corrected the wording of its earlier memorandum "to avoid confusion."

3. United States v. B. J. Alan Company, Inc. and Bruce Zoldan, Civil Action No. 4:89 CV 1843 (N.D. Ohio). On September 25, 1989 the government filed a complaint and motion for preliminary injunction against an importer of fireworks. The firm moved for summary judgment on December 11, 1989. Based on an agreement between the parties, the Court issued a preliminary injunction on December 19, 1989. On January 10, 1990 the government filed a cross motion for summary judgment and response to the firm's motion. On March 7, 1990 the Court entered a consent decree of permanent injunction which requires the firm to test 15 samples of every firework it imports.
4. United States v. South Carolina Distributors, Inc. and Herbert Livingston, Civil Action No. 7-89 2281-3 (D.S.C.) On September 12, 1989 the government filed a complaint and motion for preliminary injunction against an importer of fireworks. On December 29, 1989 the Court issued a preliminary injunction against the firm. On March 12, 1990 the Court entered a consent decree of permanent injunction which requires the firm to test 15 samples of every firework it imports.
5. United States v. Winco Fireworks and David Collar, Civil Action No. 89-2400-S (D. Kan.). On September 11, 1989 the government filed a complaint and motion for preliminary injunction against an importer of fireworks. On October 4, 1989 the firm filed an answer to the complaint. On March 6, 1990 the Court entered a consent decree of permanent injunction which requires the firm to test 15 samples of every firework it imports.
6. United States v. Stonebraker Rocky Mountain Fireworks Co. and William Stonebraker, Civil Action No. 89-M-1555 (D. Colo.). On September 12, 1989 the government filed a complaint and motion for preliminary injunction against an importer of fireworks. On November 28, 1989 the firm filed a motion for summary judgment. On December 22, 1989 the government filed a cross motion for summary judgment and a response to the firm's motion. On April 2, 1990 the Court entered a consent decree of permanent injunction which requires the firm to test 15 samples of every firework it imports.

7. United States v. Red Rocket Fireworks Co., Inc. and Daniel Aycock, Civil Action No. 90-0363 (D. Colo.). On January 31, 1990 the government filed a complaint and motion for preliminary injunction against an importer of fireworks. On March 23, 1990 the Court entered a consent decree of permanent injunction which requires the firm to test 15 samples of every firework it imports.
8. United States v. Advanced Imports, Inc. and Gerald Dunnegan, Civil Action No. 90-1634 (D. Kan.). On July 3, 1990 the Court entered a consent decree of permanent injunction, which was filed simultaneously with the complaint and which requires the firm to test 15 samples of every firework it imports.
9. United States v. Clover Imports, Inc., Louis Casale and John Beckmann, Civil Action No. 90-1489 (MAC) (D.N.J.). On April 30, 1990 the Court entered a consent decree of permanent injunction, which was filed simultaneously with the complaint and which requires the firm to test 15 samples of every firework it imports.
10. U.S. v. O.K. Toys, Inc. and M. K. Chow, Civil Action No. 90-3970 - RJK (GHKx) (C.D. Cal.). On August 10, 1990 the Court entered a consent decree of permanent injunction, which was filed simultaneously with the complaint and which prohibits the firm from importing toys that fail to comply with CPSC requirements.
11. U.S. v. Toys R Us, Inc., Charles Lazarus, and Michael Goldstein, Civil Action No. 90-3315 (D.N.J.). On August 20, 1990 the government filed a complaint and motion for preliminary injunction against an importer of toys. Discovery began, with depositions taken on September 24, 26, and 28, 1990.
12. U.S. v. Illco Toy Co., USA and Martin Scheman, Civil Action No. 90-C-5405 (JFK) (S.D.N.Y.). On August 20, 1990 the government filed a complaint and motion for preliminary injunction against an importer of toys.
13. U.S. v. Lionel Leisure, Inc. and Michael J. Vastola, Civil Action No. 90-5417 (E.D. Pa.). On August 20, 1990 the government filed a complaint and motion for preliminary injunction against an importer of toys. A telephone status conference was held on September 7, 1990. Discovery began on September 17, 1990. A preliminary injunction hearing was scheduled for November 5, 1990.

14. U.S. v. Beachcombers International, Inc. and Harry Chernin, Civil Action No. 90-255-CIV-FTM-17D (M.D. Fla.). On August 20, 1990 the government filed a complaint and motion for preliminary injunction against an importer of toys. Status hearings were held on September 5 and 29, 1990.
15. U.S. v. Child World, Inc. and Dennis H. Barron, Civil Action No. 1:90 CV 1486 (N.D. Ohio). On August 20, 1990 the government filed a complaint and motion for preliminary injunction against an importer of toys.
16. U.S. v. Value Merchants, Inc. and Phillip Cohen, Civil Action No. 90-C-0824 (E.D. Wis.). On August 20, 1990 the government filed a complaint and motion for preliminary injunction against an importer of toys. A telephone status conference was held on August 30, 1990. Discovery began, with a closing date of November 1, 1990. A preliminary injunction hearing was scheduled for November 28, 1990.
17. U.S. v. Division Sales, Inc., Justen Products and Morton Marks, Civil Action No. 90-C-4837 (N.D. Ill.). On August 20, 1990 the government filed a complaint and motion for preliminary injunction against an importer of toys. A status hearing was held on September 7, 1990.
18. U.S. v. Hanstai International, Inc. and James Ou, Civil Action No. CV-90-4168 DWW (EX) (C.D. Cal.). On August 31, 1990 the government filed a complaint and motion for preliminary injunction against an importer of bicycles.

SEIZURE

United States v. 52,823 Children's Dolls, More or Less, Civil Action No. 89 Civ. 4643 (JFK) (S.D.N.Y.). On July 7, 1989, the government seized dolls that failed to comply with the CPSC's small parts regulation. Etna Worldwide Corp. and Etna Products Company, Inc. filed a claim for the dolls on July 21, 1989, and moved to quash the warrant of seizure and dismiss the case. Following a status conference on July 28, 1989, both sides filed briefs on issues raised by the motion. On November 13, 1989 the Court denied Etna's motion, (1) affirming the CPSC's authority to seize banned hazardous products under the Federal Hazardous Substances Act and Supplemental Rule C of the Federal Rules of Civil Procedure; (2) confirming that the small parts regulation is self-executing; (3) upholding CPSC's position that a manufacturer's label is not dispositive on whether the regulation applies; (4) agreeing with CPSC's position that an objective test applies to age determinations; and (5) refusing Etna's request for a

retraction of CPSC's press release, but finding that CPSC issued it improperly. On May 7, 1990 the Court entered a Consent Order and Default Judgment, ordering Etna to return the dolls to their foreign manufacturer.

CRIMINAL ACTION

The government presented to a grand jury information concerning possible violations of a CPSC statute. No details on this matter can be disclosed.

INSPECTION WARRANT

In the Matter of Establishment Inspection of Skil Corporation, Civil Action No. 86-M-263 (N.D. Ill.) and No. 88-1126 (7th Cir.). Upon CPSC's application, the U.S. Magistrate issued a warrant on November 14, 1986, pursuant to section 16 of the Consumer Product Safety Act, for inspection of books and records concerning Skil circular saws. The warrant was served on November 17, 1986, but Skil refused the CPSC access. The government filed a motion for an order to show cause why Skil should not be held in contempt. Skil filed an opposition and a motion to quash the warrant. Following a January 8, 1987 hearing, the Magistrate granted the government's motion and denied Skil's motion. The District Court affirmed the Magistrate, and then the Court of Appeals affirmed the District Court on May 13, 1988. The parties continued to disagree about the CPSC's right to certain documents that Skil claims are privileged. Skil filed a motion for a protective order on December 19, 1989. The government moved for contempt on January 30, 1990 and opposed Skil's motion on February 23, 1990. The Magistrate held status conferences on March 22, 1990 and July 11, 1990.

SUBPOENA ENFORCEMENT

United States v. Spa Products of America, Inc. and M. Richard Williamson, Civil Action No. 89-0080 (C.D. Cal.). Following a refused inspection, the CPSC issued to Spa Products a Special Order and Subpoena for Production of Documents. The firm failed to comply with the subpoena, and in January 1989 the government filed an action to enforce compliance. On March 27, 1989, the Court ordered Spa Products to comply with the subpoena. The firm was undergoing Chapter 11 reorganization, but complied with the subpoena on October 20, 1989.

FREEDOM OF INFORMATION

Reliance Electric Company and Challenger Electric Equipment Corporation v. CPSC, Civil Action No. CV-87-1478 (D.D.C.) and No. 89-5396 (C.A.D.C.). On May 29, 1987, the plaintiff firms filed a complaint and application for temporary restraining order, to enjoin the disclosure of information under section 6 of the Consumer Product Safety Act. After a June 2, 1987 hearing, the Court issued a TRO and ordered the parties to file cross-motions for summary judgment. Both parties did so in July 1987. On September 19, 1989, the Court ruled that the CPSC had followed the proper procedures and that most of the documents could be released. The firms noticed their appeal and, on September 26, 1989, the District Court stayed its order pending resolution of the appeal. The firms filed their appellate brief on August 20, 1990, and the government filed its appellate brief on September 19, 1990. Oral argument was scheduled for November 2, 1990.

OTHER CASES AGAINST THE COMMISSION

1. Kathryn O'Brien v. Anne Graham, Civil Action No. 89-1860-JH (D. Md.) and No. 90-3002 (4th Cir.). In March 1989, a former CPSC employee filed a complaint challenging the Merit Systems Protective Board and Equal Employment Opportunity Commission decisions which had upheld CPSC's termination of her employment. Originally filed in the District of Columbia, the Court ordered the case transferred to Maryland on May 31, 1989. The government filed a motion for summary judgment on July 31, 1989, which the Court granted on September 21, 1989. On appeal, both parties filed "informal" briefs. On March 19, 1990 the Court of Appeals dismissed the appeal as untimely and on April 17, 1990 denied Ms. O'Brien's petition for rehearing.
2. B.J. Alan Company, Inc. v. Nicholas Brady, et al., Civil Action No. 1:89-CV-02069 (N.D. Ohio). On October 25, 1989 the firm challenged a U.S. Customs Service/CPSC seizure of fireworks. The government filed a motion to dismiss on January 12, 1990. The parties settled the case and it was dismissed in February 1990.
3. Kellner's Fireworks, Inc. v. U.S. et al., Civil Action No. 90-176 Erie (W.D. Pa.). On July 27, 1990 a fireworks firm moved for a temporary restraining order against the obtaining of an inspection warrant. The Court dismissed the action following a hearing on July 31, 1990.

CIVIL PENALTY SETTLEMENT AGREEMENTS ACCEPTED BY THE COMMISSION

The following civil penalty agreements were accepted by the Commission in 1990:

1. In the Matter of Ames Department Stores, Inc., CPSC Docket No. 90-C0004. Ames agreed to pay a civil penalty of \$12,000 in settlement of Commission staff allegations that the retailer offered for sale, sold, and distributed in commerce, banned lawn darts in violation of 15 U.S.C. {{ 2068(a)(2) and (4)}. The Settlement also resolves staff allegations that Ames failed to report that its lawn darts failed to comply with a Consumer Product Safety Rule and thereby violated the reporting requirements of 15 U.S.C. { 2064(b)}. The staff alleged that an Ames store in Doylestown, Pennsylvania sold banned lawn darts to an undercover CPSC investigator more than three months after the product was banned. Ames denied that it distributed in commerce banned lawn darts and/or knowingly failed to make reports and provide required information concerning lawn darts, in violation of section 15(b) of the CPSA. The Commission accepted a settlement agreement on February 7, 1990.

2. In the Matter of Caldor, Inc., CPSC Docket No. 90-C0005. Caldor agreed to pay a civil penalty of \$50,000 in settlement of Commission staff allegations that the Connecticut chain store offered for sale, sold, and distributed in commerce banned lawn darts in violation of 15 U.S.C. {{ 2068(a)(2) and (4)}. The settlement also resolves staff allegations that Caldor failed to report that its lawn darts failed to comply with a Consumer Product Safety Rule and thereby violated the reporting requirements of 15 U.S.C. { 2064(b)}. The staff alleged that three Caldor stores sold or offered for sale a total of 64 sets of banned lawn darts over three months after the effective date of the ban. Caldor denied that it distributed in commerce banned hazardous products and/or knowingly failed to make reports and provide information concerning lawn darts, in violation of section 15(b) of the CPSA. The Commission accepted a settlement agreement on February 7, 1990.

3. In the Matter of Consumer Direct, Inc., CPSC Docket No. 88-C0009. Consumer Direct agreed to pay a civil penalty of \$130,000 in settlement of allegations by the Commission staff that the Ohio corporation failed to report defects in its "Gut Buster exercise device" which could create a substantial product hazard as required by 15 U.S.C. { 2064(b)}. The staff alleged that although Consumer Direct had received hundreds of consumer complaints alleging personal injury due to spring breakage of the Gut Buster, it failed to report that information to the Commission. The firm denied that the Gut Buster contained any

defect which could create a substantial product hazard within the meaning of section 15(b) of the CPSA. The firm also denied any obligation to report information to the Commission under section 15(b) of the CPSA. The Commission accepted a settlement agreement on April 25, 1990.

4. In the Matter of Etna Products Co., Inc., CPSC Docket No. 90-C0002. Etna agreed to pay a civil penalty of \$5,000 in settlement of allegations by the Commission staff that the company failed to report defects in its electric mousetrap which could create a substantial product hazard as required under 15 U.S.C. { 2064(b). The staff alleged that Etna was aware of the product's electrocution potential, and recalled the mousetraps from Wisconsin consumers, but failed to report this information to the CPSC. Etna denied that the imported electric mousetraps contained a defect which could create a substantial risk of injury. It further denied that it violated the reporting requirement of section 15(b) of the CPSA. The Commission accepted a settlement agreement on January 24, 1990.

5. In the Matter of Hedstrom Corp., CPSC Docket No. 90-C0010. Hedstrom Corp. agreed to pay a civil penalty of \$165,000 in settlement of allegations by the Commission staff that the firm failed to report a defect which could create a substantial product hazard involving several models of its backyard gym sets equipped with the "Glide Ride" attachment, as required under 15 U.S.C. { 2064(b). The staff alleged that Hedstrom knew or should have known that the hanging bracket holding the Glide Ride to the cross bar of these gym sets contained a dangerous pinching/crushing point, that constituted a defect which could create a substantial product hazard, but failed to report it in a timely manner. Specifically, 10 children over a three year period sustained pinched, lacerated, or partially amputated finger tips before Hedstrom reported the problem to the Commission on April 27, 1988. Hedstrom denied that its products contained a defect which creates or which could create a substantial product hazard under the CPSA. It further denied any obligation to report to the Commission under section 15(b) of the CPSA. It alleged that its products did not have a design defect under the CPSA and that the incidents were caused by unusual circumstances or possibly through inappropriate use by the user. The Commission accepted the settlement on May 22, 1990.

6. In the Matter of K Mart Corp., CPSC Docket No. 90-C0003. K Mart agreed to pay a civil penalty of \$60,000 in settlement of allegations by the Commission staff that the firm failed to report a defect which could create a substantial product hazard involving its School Days Scissors Desk Sets, as required under 15 U.S.C. { 2064(b). The staff alleged that the firm knew or should have known that the scissors desk sets

contained a razor blade cutting knife component and that this defect could result in children sustaining severe lacerations. K Mart denied that its product contained a defect which creates or which could create substantial product hazard; and denied that it had an obligation to report information to the Commission under section 15(b) of the CPSA. The Commission accepted a settlement agreement on January 24, 1990.

7. In the Matter of Toys "R" Us, Inc., CPSC Docket No. 90-C0001. Toys "R" Us agreed to pay a civil penalty of \$60,000 in settlement of allegations by the Commission staff that the firm failed to report a defect which could create a substantial product hazard involving its submarine stationery sets, as required under 15 U.S.C. { 2064(b). The staff alleged that the firm knew or should have known that the toy stationery sets contained a razor blade cutting knife component and that this defect could result in children sustaining severe lacerations. Toys R Us denied that its product contained a defect which creates or which could create substantial product hazard; and denied that it had an obligation to report information to the Commission under section 15(b) of the CPSA. The Commission accepted a settlement agreement on January 24, 1990.

8. In The Matter of Water Refining Company, Inc., CPSC Docket No. 90-C0012, Ecodyne Corporation, on behalf of its subsidiary Water Refining Company, Inc., and Guthrie North America, Inc., the previous owner of Water Refining Company, Inc., agreed to pay a civil penalty of \$300,000 in settlement of the staff's allegations that Water Refining Company, Inc. and Guthrie North America, Inc. failed to report a defect which could create a substantial product hazard involving two models of residential water softeners, as required under 15 U.S.C. { 2064(b). The defect was reported to the Commission by Ecodyne more than one year after it learned of the defect. The staff alleged that electrical shorts can occur in the solenoid coils that are used to start and stop various operations within the unit. The solenoids can fail unexpectedly and without warning. This defect may result in fire that can spread to surrounding combustibles. Although no personal injuries or deaths have been reported, the possibility exists that such a fire could result in serious personal injury or death to the occupant of the residence in which the water softener is located. Ecodyne and Guthrie denied that they knew or should have known of the defect and hazard associated with the solenoids, and any risk of injury allegedly presented by the water softeners, and denied the existence of any obligation to report any information regarding the water softeners to the Commission under 15 U.S.C. { 2064(b). The Commission accepted a settlement agreement on September 13, 1990.

CONSENT AGREEMENTS ACCEPTED BY THE COMMISSION

The following consent agreements were accepted by the Commission in 1990:

In the Matter of Sun Tui, LTD and Daniel S. Weiss, CPSC Docket No. 90-C0006. The Commission accepted a consent agreement containing a cease and desist order from Sun Tui and Weiss to settle the staff's allegations that the firm sold futon mattresses in violation of the Standard for the Flammability of Mattresses and Mattress Pads. The Commission accepted the agreement on February 22, 1990.

In the Matter of Contempo Futons, and David Butitta, CPSC Docket No. 90-C0007. The Commission accepted a consent agreement containing a cease and desist order from Contempo and Butitta to settle the staff's allegations that the firm sold futon mattresses in violation of the Standard for the Flammability of Mattresses and Mattress Pads. The Commission accepted the agreement on February 22, 1990.

In the Matter of Buddha's, Inc., and S. Trinity, CPSC Docket No. 90-C0008. The Commission accepted a consent agreement containing a cease and desist order from Buddha's and Trinity to settle the staff's allegations that the firm sold futon mattresses in violation of the Standard for the Flammability of Mattresses and Mattress Pads. The Commission accepted the agreement on February 15, 1990.



APPENDIX H

Advisory Opinions

ADVISORY OPINIONS

No.	Date of	From/To	Subject
311	04/16/90	Susan Birenbaum/ Bernie Reamer	Wolf-hybrid dog is not a "consumer product" as that term is defined in the Consumer Product Safety Act



APPENDIX I

Index of Products
Regulated by CPSC

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Acetaminophen	PPPA	special packaging exemption	1700.14(a)(16) 1700.14(a)(16)(i),(ii)
Acetic acid	HSA	labeling	1500.129(g)
Adhesives, containing methyl alcohol	HSA HSA	labeling exemption from labeling	1500.133 1500.83(a)(34)
nitrocellulose base	HSA	exemption from labeling	1500.83(a)(10)
floor covering	HSA	exemption from labeling	1500.83(a)(13)
extremely flammable contact	CPSA CPSA	ban to be regulated under CPSA	1302 1145.3
Aerosols (see self-pressurized products)	HSA	suggested labeling	1500.130
Aluminized polyester film kite	HSA	ban	1500.18(c)(1)
Ammonia, ammonia water (household), ammonium hydroxide	HSA	labeling	1500.129(g)
Antennas (CB base station and TV) (Omnidirectional CB base station)	CPSA CPSA	labeling requirement performance and certification	1402 1204
Antifreeze, ethylene glycol-base	HSA PPPA	labeling special packaging	1500.132 1700.14(a)(11)
Antiquing kits	HSA	exemption from labeling	1500.83(a)(25)
Appliances, coal and wood-burning	CPSA	provision of performance and technical data	1406
Architectural glazing materials	CPSA	safety standard	1201
Art materials	HSA	exemption from ban	1500.85(a)(4)
Artist's paints	CPSA	exemption from lead limit	1303.3(c)(2)
Asbestos-containing patching compounds	CPSA CPSA	ban to be regulated under the CPSA	1304 1145.4

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Asbestos-containing garments for general use	HSA	ban	1500.17(a)(7)
Asbestos-containing artificial emberizing materials	CPSA CPSA	ban to be regulated under the CPSA	1305 1145.5
Aspirin products	PPPA	special packaging effervescent tablet exemption unflavored powders exemption	1700.14(a)(1) 1700.14(a)(1)(i) 1700.14(a)(1)(ii)
Baby bouncers and walkers	HSA	standard and ban exemption from banning	1500.18(a)(6) 1500.86(a)(4)
Balloons, plastic mixtures	HSA	exemption from banning	1500.85(a)(4)
Bassinet legs	CPSA	to be regulated under the CPSA	1145.15
Batteries, storage, wet-cell	PPPA	exemption from special packaging	1700.14(a)(9)
Benzene (benzol)	HSA	special labeling	1500.14(b)(3)(i)
Benzene (paint solvents)	PPPA	special packaging	1700.14(a)(15)
Bergamot oil	HSA	labeling	1500.13(e)
Betamethasone	PPPA	exemption from special packaging	1700.14(a)(10)(viii)
Bicycles	HSA	ban safety requirements	1500.18(a)(12) 1512
Biological specimens, preserved	HSA	exemption from ban	1500.85(a)(4)
Blasting caps	HSA	exemption from labeling	1500.83(a)(35)
Butane in cigarette lighters	HSA	exemption from labeling	1500.83(a)(29)
Carbolic acid (phenol)	HSA	labeling	1500.129(d)
Carbon tetrachloride	HSA	ban	1500.17(a)(2)
Carpets and rugs (large)	FFA	standard (FF 1-70)	1630
Carpets and rugs (small)	FFA	standard (FF 2-70)	1631

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Caustic poisons	HSA	labeling	1500.129
potash	HSA	labeling	1500.129
soda	PPPA	special packaging	1700.14(a)(5)
	HSA	labeling	1500.29(j)
	PPPA	special packaging	1700.14(a)(5)
Cellulose sponges	HSA	exemption from labeling	1500.83(a)(15)
Cellulose insulation	CPSA	standard	1209
	CPSA	labeling	1404
Charcoal briquettes	HSA	classification as hazardous	1500.12(a)(1)
		special labeling	1500.14(b)(6)
Chemistry sets	HSA	exemption from labeling	1550.83(a)(23)
		exemption from banning	1500.85(a)(1)
Child-resistant packaging (and see special packaging)	PPPA	criteria and substances subject	1700
Chlorofluorocarbons, self- pressurized products containing	CPSA	labeling requirement	1401
Cholestyramine, anhydrous	PPPA	exemption from special packaging	1700.14(a)(10)(v)
Cigarette lighters	HSA	exemption from labeling	1500.83(a)(29)
		exemption from labeling	1500.83(a)(20)
Cleaning products	HSA	exemption from labeling	1500.83(a)(11)
Clothing (see wearing apparel, sleep- wear			
Coal burning appliances (see appliances)			
Colestipol	PPPA	exemption from special packaging	1700.14(a)(10)(xv)
Combustible hazardous substances	HSA	definition flashpoint testing	1500.3(c)(iii) 1500.43a
Conjugated estrogens tablets	PPPA	exemption from special packaging	1700.14(a)(10)(xvii)
Consumer product	CPSA	reporting of sub- stantial product hazards	1115

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Containers, consumer-owned (portable)	HSA	exemption from full labeling	1500.83(a)(14)
Controlled drugs	PPPA	special packaging	1700.14(a)(4)
Corrosive substances	HSA	definition	1500.3(b)(7), (c)(3)
Cosmetics	HSA	exemption	1500.81(d)
Crib hardware	CPSA	to be regulated under the CPSA	1145.14
Cribs (full-size)	HSA	ban safety requirements	1500.18(a)(13) 1508
Crib (non full-size)	HSA	ban safety requirements	1500.18(a)(14) 1509
Crib, mesh-sided	CPSA	to be regulated under the CPSA	1145.12
Cyanide salts	HSA	ban	1500.17(a)(5)
Dietary supplements, iron-containing	PPPA	special packaging	1700.14(a)(13)
Diethylene glycol	HSA	labeling special packaging exemption from labeling	1500.14(a)(1) 1500.14(b)(1) 1500.83(a)(15)
Diethylenetriamine	HSA	labeling	1500.13(c)
Diglycidyl ethers	HSA	labeling	1500.13(c)
Diphenhydramine preparations	PPPA	special packaging	1700.14(a)(17)
Disclaimer, deceptive use of	HSA	misbranded	1500.122
Drain cleaners, liquid	HSA PPPA	ban special packaging	1500.17(a)(4) 1700.14(a)(5)(9)
Drugs, controlled	PPPA	special packaging	1700.14(a)(4)
Drugs, oral prescription	PPPA	special packaging	1700.14(a)(10)
Except:			
Nitroglycerin tablets (sublingual)			1700.14(a)(10)(i)
Isosorbide dinitrate (10 mg. sublingual and chewable tablets)			1700.14(a)(10)(ii)

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Erythromycin ethylsuccinate (8 gm oral suspension and granules for oral suspensions)			1700.14(a)(10)(iii)
Erythromycin ethylsuccinate tablets (no more than 16 gm)			1700.14(a)(10)(xvi)
Cyclical oral contraceptives			1700.14(a)(10)(iv)
Anhydrous cholestyramine (powder form)			1700.14(a)(10)(v)
Postassium supplements (containing not more than 50 MEq potassium per unit dose package)			1700.14(a)(10)(vi)
Sodium fluoride (264 mg per package of liquid forms and tablet forms)			1700.14(a)(10)(vii)
Betamethasone (12.6 mg per package)			1700.14(a)(10)(viii)
Pancrelipase in tablet, capsule or powdered form			1700.14(a)(10)(ix)
Prednisone tablets (not more than 105 mg per package)			1700.14(a)(10)(x)
Mebendazole (600 mg per package)			1700.14(a)(10)(xiii)
Methylprednisolone tablets (not more than 84 mg per package)			1700.14(a)(10)(xiv)
Colestipol (packages containing not more than 5 grams of powder)			1700.14(a)(10)(xv)
Conjugated estrogens tablets (not more than 32 mg per package)			1700.14(a)(10)(xvii)
Norethindrone acetate tablets (not more than 50 mg per package)			1700.14(a)(10)(xviii)
Medroxyprogesterone acetate tablets			1700.14(a)(10)(xix)
Drugs, iron containing	PPPA	special packaging	1700.14(a)(12)
Dry-cleaning solvents	HSA	exemption from labeling	1500.83(a)(18)
Emberizing materials, artificial containing asbestos	CPSA	ban	1305
Epoxy resins	HSA	labeling	1500.13(c)
Erythromycin ethylsuccinate, suspension and granules for suspension	PPPA	exemption from special packaging	1700.14(a)(10)(iii)
chewable tablets			1700.14(a)(10)(xvi)
Ethylenediamine	HSA	labeling	1500.13(c)
Ethylene glycol in felt pads	HSA	exemption from labeling special labeling	1500.83(a)(28) 1500.14(b)(4)
Ethylene glycol	HSA	labeling special packaging	1500.14(a)(2), (b)(2) 1700.14(a)(11)

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Ethylene glycol antifreeze	HSA	labeling	1500.132
Expandable children's enclosures	CPSC	to be regulated under the CPSA	1145.13
Exports (noncomplying products)	All	reporting requirements	1019
Extremely flammable contents of self-pressurized containers	HSA	definition method to determine flashpoint testing exemp. from label.	1500.3(c)(6),(vii) 1500.45 1500.46 1500.83(a)(1)
Extremely flammable hazardous substances	HSA	definition testing method	1500.3(c)(6)(i) 1500.43a
Extremely flammable solids	HSA	definition testing method	1500.3(c)(6)(v) 1500.44
Eye irritants	HSA	testing method definition	1500.3(b)(8),(c)(4) 1500.42
Fabrics	FFA	flammability	1602-1632
Felt-tip marking devices	HSA	labeling exemption	1500.83(a)(9)
Ferrous oxalate	HSA	exemption from labeling	1500.83(a)(17)
Fertilizers, dry granular	HSA	exemption from labeling	1500.83(a)(21)
Fire extinguishers	HSA	exemption from labeling labeling, warning	1500.83(a)(24) 1500.15(a),(b)
Fireworks	HSA	ban (more than 2 grains pyrotechnic material for audible reports) exemption from labeling agricultural exemption exemption from classification special labeling ban (firecrackers more than 50 mg.) safety requirements	1500.17(a)(3) 1500.83(a)(27) 1500.17(a)(3) 1500.85(a)(2) 1500.14(b)(7) 1500.17(a)(8) & 9 1507
First Aid	HSA	policy for emesis labeling	1500.134

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Flammable contents of self-pressurized containers	HSA	definition method for determining flashpoint testing exemption from labeling	1500.3(c)(6)(viii) 1500.45 1500.46 1500.83(a)(1)
Flammable solids	HSA	definition testing method	1500.3(c)(6)(vi) 1500.44
Flammable substances	HSA	definition flashpoint testing	1500.3(c)(6)(iii) 1500.43a
Food	HSA	exemption from specific labeling	1500.81(a)
Formaldehyde	HSA	Labeling	1500.13(d)
Fuel	HSA	exemptions exemptions from banning special packaging	1500.81(b) 1500.85(a)(5) 1700.14(a)(7)
Fuel kits with difluorodichloromethane	HSA	exemption from banning warning label	1500.85(a)(12), (13)
Furniture, painted with lead-containing paint	CPSA	ban	1303
Furniture polish, liquid	PPPA	special packaging	1700.14(a)(2)
Furniture polish, paste	HSA	exemption from labeling	1500.83(a)(8)
Gasoline	HSA	exemption from labeling special labeling labeling	1500.83(a)(14) 1500.14(b)(3) 1500.14(a)(3)
Glazing compounds	HSA	exemption from labeling	1500.83(a)(13)
Hartshorn	HSA	Labeling	1500.129(1)
Heaters (see appliances)			
Highly toxic substances	HSA	definition testing method labeling	1500.3(e) 1500.40 1500.121
Household substances	HSA	definition	1500.3(c)(10)
Hydrochloric acid	HSA	Labeling	1500.129(a)

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Hypochlorous acid	HSA	labeling	1500.129(h)
Imported products & importers	ALL	policy	1009.3
Imports	HSA	various	1500.265-.272
Industrial supplies	HSA	exemption	1500.3(c)(10)(i)
Ink, cartridges	HSA	exemption from labeling	1500.83(a)(7) & (38)
dry concentrate containers	HSA	exemption from labeling	1500.83(a)(12)
Ink-marking devices	HSA	exemption	1500.83(a)(9)
Insulation, cellulose	CPSA	standard	1209
Iron preparations	PPPA	special packaging	1700.14(a)(12), (13)
Irritant substances	HSA	definition testing method	1500.3(g) 1500.41
Isobutane in cigarette lighters	HSA	exemption from labeling	1500.83(a)(29)
Isosorbide dinitrate, pre- scription sublingual and chewable forms	PPPA	exemption from special packaging	1700.14(a)(10)(ii)
Kerosene	HSA	labeling special labeling exemption from labeling special packaging	1500.14(a)(4) 1500.14(b)(3) 1500.83(a)(14) 1700.14(a)(7)
Kindling and illuminating preparations	PPPA	special packaging	1700.14(a)(7)
Kites, aluminized polyester film	HSA	ban	1500.18(c)(1)
Labels	HSA	requirements condensation informal comment on exemption from labeling	1500.121 1500.123 1500.128 1500.83(a)(5)
Laboratory chemicals, if educational	HSA	exemption from banning and labeling	1500.85(a)(4) 1500.85(a)(5)
Lacquers	HSA	exemption from labeling	1500.83(a)(13)
Lawn darts	HSA CPSA	ban ban	1500.18(a)(4) 1306

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Lawnmowers, power	CPSA	performance standard, labeling rule, and certification rule	1205
Lead in paint	HSA	ban over 0.5% (pre- 1978)	1500.17(a)(6)
	CPSA	ban over 0.06% (1978 and later)	1303
Lighter fluid, etc.	PPPA	special packaging	1700.14(a)(7)
Lunar caustic (silver nitrate)	HSA	labeling	1500.129(k)
Lye	HSA	labeling	1500.129(j)
	PPPA	special packaging	1700.14(a)(5)
Matchbooks	CPSA	standard	1202
Matches	HSA	exemption from flamma- bility labeling	1500.83(a)(2)
Mattresses	FFA	standard (FF 4-72)	1632
Mebendazole	PPPA	exemption from special packaging	1700.14(a)(10)(xiii)
Medroxyprogesterone acetate tablets	PPPA	exemption from special packaging	1700.14(a)(10)(xix)
Methyl alcohol (methanol)	HSA	exemption from labeling	1500.83(a)(10)
		labeling	1500.14(a)(4), (b)(4)
		exemption from labeling	1500.83(a)(19)
		exemption from labeling	1500.83(a)(34)
	PPPA	special packaging	1700.14(a)(8)
Methylprednisolone	PPPA	exemption from special packaging	1700.14(a)(10)(xiv)
Methyl salicylate	PPPA	special packaging	1700.14(a)(3)
Mineral oil (in toys)	HSA	exemption from labeling	1500.83(a)(33)
Mineral seal oil	HSA	labeling	1500.14(a)(3)
		special labeling	1500.14(b)(3)
	PPPA	special packaging	1700.14(a)(2)

PRODUCT	ACT	TYPE OF REGULATION	REFERENCE SOURCE TITLE 16 CFR PART NUMBER
Mineral spirits	HSA	labeling special labeling special packaging	1500.14(a)(3) 1500.14(b)(3) 1700.14(a)(15)
Mirrors	CPSA	exemption from lead limit	1303.3(c)(2)
Mixtures of hazardous substances	HSA	labeling	1500.5
Multiple hazard, substances with	HSA	labeling	1500.127
Naphtha	HSA	labeling special labeling	1500.14(a)(3) 1500.14(b)(3)
Nitric acid	HSA	labeling	1500.129(c)
Nitroglycerine, prescription, sublingual dosage	PPPA	exemption from special packaging	1700.14(a)(10)(i)
Norethindrone acetate tablets	PPPA	exemption from special packaging	1700.14(a)(10)(xviii)
Oral contraceptives, cyclical	PPPA	exemption from special packaging	1700.14(a)(10)(iv)
Orris root, powdered	HSA	labeling	1500.13(b)
Oxalic acid and salts of	HSA	labeling	1500.129(e), (f)
Packages, child-resistant (see child- resistant packaging)			
Packages, sample	PPPA	submission	1700.14(b)
Paint, lead in	HSA	ban over 0.5% (pre- 1978)	1500.17(a)(6)
	CPSA	ban over 0.06% (1978 and later)	1303
	CPSA	to be regulated under the CPSA	1145.2
Paint solvents	PPPA	special packaging	1700.14(a)(15)
Painting kits	HSA	exemption	1500.83(a)(25)
Pancrelipase	PPPA	exemption from special packaging	1700.14(a)(10)(ix)