

NTSB National Transportation Safety Board

Operational Discipline and Professionalism

Robert L. Sumwalt March 26, 2011

The NTSB

- Independent Federal Agency, charged by Congress to:
 - Investigate transportation accidents
 - Determine their probable cause
 - Issue safety recommendations to prevent similar accidents
 - Conduct safety studies






GA Accident Stats

	Accidents	Fatal accidents	Fatalities
2006	1515	303	698
2007	1652	288	496
2008	1566	275	494
2009	1474	272	474
2010	1329	249	417




Sunday






Thursday






Friday






Friday







Accident type in personal flying accidents, 2007-2009.



Rans S-10, October 19, 2003





Rans S-10, October 19, 2003

According to a witness:

- The 314-hour pilot made a pass over his front yard approximately 200 feet agl. While passing over the field, the pilot leaned out the right side of the cockpit and waved at his neighbors
- The airplane then pitched nose up, rolled to the right, and flew "straight into the ground" in a nose-down attitude




What was missing?

Operational discipline

Professionalism





Owatonna, MN July 31, 2008 8 fatalities





NTSB finding

 "The captain allowed an atmosphere in the cockpit that did not comply with well-designed procedures intended to minimize operational errors, including sterile cockpit adherence, and this atmosphere permitted ... inappropriate conversation; nonstandard terminology; and a lack of checklist discipline throughout the descent and approach phases of the flight."



What was missing?

Operational discipline

Professionalism



Colgan Air flight 3407

- February 12, 2009
- 10:17 pm Eastern Standard Time
- Colgan Air, Inc.
 - Operated as Continental Connection
- Bombardier DHC-8-400
- On approach to Buffalo, New York
- 50 fatalities
 - 2 pilots
 - 2 flight attendants
 - 45 passengers
 - 1 home resident killed



History of flight

- Crew engaged in almost continuous conversation throughout flight
 - Conversation mostly extraneous to flight operations
- Conversation preempted timely performance of flightrelated duties
 - Approach briefing, descent checklist, approach checklist





History of flight

- Approximately 3 miles from outer marker:
 - power was reduced to slow for approach
 - gear extended
 - props to max RPM
- Airspeed decreased 50 kts in 21 seconds



Stall, Upset, Loss of Control

- Stick shaker (stall warning) activated at 131 knots
- Autopilot disconnected
- Captain reacted with "startle and confusion"
- Captain pulled nose to 19 degrees nose up pitch
- Stall, extreme roll
- Stick pusher activated 3 times
 - countered by captain's actions of pulling
- Loss of control









NTSB

National Transportation Safety Board

Office of Research and Engineering

Flightpath

Loss of Control on Approach
Colgan Air, Inc., Operating as
Continental Connection Flight 3407
Bombardier DHC-8-400, N200WQ

Clarence Center, New York February 12, 2009 DCA09MA027

Board Meeting











Major Areas of Focus



Airspeed Selection Cockpit Discipline

Crew Reaction to Stall Warning and Stall





NTSB Finding

- The captain's failure to effectively manage the flight
 - enabled conversation that delayed checklist completion and conflicted with sterile cockpit procedures, and
 - created an environment that impeded timely error detection



What was missing?

Operational discipline

Professionalism



Pinnacle Airlines Flight 3701 Jefferson City, Missouri



- October 14, 2004
- Bombardier CL-600-2B19
- Repositioning flight
- Both flight crewmembers killed



What the investigation discovered

- Intentional activation of stall warning
- Swapping crew seats
- Rudder mishandling
- Climb to FL 410
 - "have a little fun"
- Automation mismanagement
- Airspeed loss, stall, loss of control, double engine failure
- Did not fully disclose real problem with ATC



NTSB's Probable Cause



 "the pilots' unprofessional behavior, deviation from standard operating procedures, and poor airmanship, which resulted in an in-flight emergency from which they were unable to recover..."



What was missing?

Operational discipline

Professionalism



Teterboro, NJ

Feb 2, 2005



NTSB finding

 "The pilots' failure to ensure that the airplane's weight and center of gravity were within approved takeoff limits was symptomatic of poor airmanship and a broader pattern of deficiencies in their crew resource management skills (specifically in the areas of leadership, workload management, communications/briefings, and crew coordination) that were exhibited on the day of the accident."



What was missing?

Operational discipline

Professionalism




Part 135 Operator

- Sundance Helicopters
- Air tour operator
- September 20, 2003
- Grand Canyon
- Aerospatiale AS350BA
- CFIT, 7 Fatalities





Accident Flight






Accident Flight





Previous flight





What was missing?

Operational discipline

Professionalism



Comair Airlines Flight 5191 Lexington, Kentucky

- Bombardier CRJ
- 49 Fatalities
- First officer severely injured
- Wrong runway takeoff







NTSB Finding

 "The flight crew's noncompliance with standard operating procedures, including the captain's abbreviated taxi briefing and both pilots' nonpertinent conversation, most likely created an atmosphere in the cockpit that enabled the crew's errors."



What was missing?

Operational discipline

Professionalism









Negative Publicity Avoidance

"You never know on which flight your career will be judged."







By Andrew Itkoff NDRUW JONES: 25 Rs and 100 RBI, 1C

DETROIT STUNS 49ERS 27-24 1,10C

LIONS WERE WINLESS ▶ REFS UNDER REVIEW, 1C ► NFL REPORT, 1,10,13C

ANDRUW JONES IS USA TODAY'S MINOR LEAGUE PLAYER OF THE YEAR

OUTFIELDER ANOTHER STAR IN ATLANTA CONSTELLATION, 1C

NO. 1 IN THE USA . . . FIRST IN DAILY READERS

HOME SALES HIT HIGHEST **POINT IN** 15 MONTHS 18

EVEN IF SURGE FALTERS, ECONOMY WILL GET BOOST

NEW FILMS FEATURE WOMEN AND ISSUES THEY FACE TOGETHER

SISTERHOOD TO OUTSHINE SHOWGIRLS, DRAG QUEENS, 1D WINO

TUESDAY, SEPTEMBER 26, 1995

NEWSLINE

A QUICK READ ON THE NEWS

WALL STREET: Dow Jones industrial average rises 5.78 points to 4769.93; Nasdaq index falls 7.24 to 1046.15; 30year Treasury bond yield remains at 6.58%. 1,3B.

CHILD BURIED: Stephanie Kuhen, 3, is buried; she died when the car she was in was hit by gunfire on Los Angeles dead-end street. Fourth suspect arrested. 4A.

BALANCING ACT: Clinton administration walks fine line to balance human rights commitment with pledge to make job protection heart of foreign relations. 9A.

NEW AIRLINE: British entrepreneur Sir Freddie Laker and a Texas oilman plan to launch U.S.-based trans-Atlantic airline with flights from Florida to Britain. 1B.

CHESS BATTLE: Challenger Viswanathan Anand,



DELANY DIES: Bessie Delany, second black female dentist in New York enhiert of

Your name here



Dead Calif

mont By Mimi Ha USA TODAY

Former i dential can said Monda porters are third nation


Such a p dramatic e presidential

Perot, on Live, said t dence Party voters who they don't f

Democrats "It will no special inte who got 199 he ran in

owned by (He told K that have to

ETERANS



Pilots' acts might have led to crash

■ Tail section of doomed jet found on ocean floor

By ERIC MALNIC, MATT SURMAN and MITCHELL LANDSBERG Los Angeles Times

PORT HUENEME, Cair. — Investigators are considering whether the pilots of Alaska Airlines Flight 261 unwittingly triggered their violent plunge into the Pacific Ocean by following prescribed procedures for an emergency landing, air safety officials said Thursday.

Late Thursday searchers found the tail of the jet after recovering the flight data recorder earlier in the day.

Underwater robots exploring the ocean floor found where the wreckage came to rest after the MD-83 ies, some of which are believed trapped under the debris.

National Transportation Safety Board officials raised the question about the pilots' actions after listening to a recording of the final 30 minutes that was contained in a cockpit voice recorder retrieved late Wednesday.

One NTSB official, speaking on condition of anonymity, said the investigation into the crash is increasingly focusing on the pilots' actions during their preparation for an emergency landing at Los Angeles International Airport.

In hindsight, investigators say, it appears possible that a by-the-book response to the mechanical problem reported by the pilots — a "horizontal stabilizer jam" — could have sent the plane into its wild, corkscrewing descent into the sea.















Take the Most Conservative Approach

What to do?

Take the most conservative approach

De-ice?

Divert?

Add more fuel?



Don't de-ice
Continue?
Risk min fuel
landing?





NTSB SOP Adherence

How SOPs relate to error

 LOSA data: crews that intentionally deviate from SOPs are approximately three times more likely to commit additional errors with consequential results

"Normalization of Deviance"





Be Professional

What is a professional?

- A mindset
 - Precise checklist usage
 - Precise callouts
 - Precise compliance with SOPs and regulations
 - Staying abreast and current with knowledge and skills
 - The ability and willingness to say "I don't know" or "I am wrong"



Professionalism

Doing the right things, even when no one is watching.







